



CAPABILITIES AND
FIXED PRICES CATALOGUE



ENGINE PARTS REPAIR SERVICES

Capabilities and Fixed Prices Catalogue 2025 for
CFM56-5B
valid until December 31, 2025

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
251	336-095-401-0	EASA;FAA;CAAC;ANAC	34	28	72-55-04	LOW PRESSURE TURBINE SHAFT - REAR ROTATING AIR/OIL S	Package A	CLN/INSP	CLEANING AND INSPECTION		765.00	SR Technics Switzerland
251	336-095-402-0	EASA;FAA;CAAC;ANAC			72-55-04		Package B	001	REPAIR OF THE LOCATING DIAMETER OF THE REAR ROTATING AIR/C DIA A		2935.00	SR Technics Switzerland
251					72-55-04		Package E	004	REPAIR OF THE LOCATING DIAMETER OF THE REAR ROTATING AIR/C DIA X		1785.00	SR Technics Switzerland
251					72-55-04		Package U	INSP-001	BLENDING REAR ROTATING AIR SEAL TEETH		460.00	SR Technics Switzerland
1459	301-298-909-0	EASA;FAA;CAAC;ANAC;CAA I	31	28	72-55-17	LOW PRESSURE TURBINE SHAFT - SLOTTED NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		235.00	SR Technics Switzerland
1459	337-112-901-0	EASA;FAA;CAAC;ANAC			72-55-17		Package B	001	REPAIR OF THE MATING FACE		2010.00	SR Technics Switzerland
1459					72-55-17		Package C	002	REPAIR OF THE SILVER PLATING		700.00	SR Technics Switzerland
1788			20	28	72-41-04	COMBUSTION CASE - FUEL MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION		540.00	SR Technics Switzerland
1788					72-41-04		Package B	INSP-001	BLENDING		970.00	SR Technics Switzerland
1788					72-41-04		Package B	INSP-001	PRESSURE TEST		970.00	SR Technics Switzerland
1788					72-41-04		Package D	002	REPAIR THE SILVER PLATE ON THE TUBE FITTING NUTS		475.00	SR Technics Switzerland
2055	336-009-801-0	EASA;FAA;CAAC;ANAC;CAA I	29	28	72-55-14	LOW PRESSURE TURBINE SHAFT - NO.4 BEARING FORWARD	Package A	CLN/INSP	CLEANING AND INSPECTION		630.00	SR Technics Switzerland
2055					72-55-14		Package B	001	RECONDITIONING OF THE 5 PERCENT NI-AL UNDERCOAT AND THE AL-SI-POLYESTER ABRADABLE COATII		2760.00	SR Technics Switzerland
2055					72-55-14		Package C	002	REPAIR OF RABBET DIAMETER A		2335.00	SR Technics Switzerland
2055					72-55-14		Package E	004	REPAIR MATING SURFACE		2120.00	SR Technics Switzerland
2200	1523M40G02	EASA;FAA;CAAC;ANAC	37	28	72-41-03	COMBUSTION CASE - HPT INNER STATIONARY SEAL	Package C	002	REPLACEMENT OF THE SEAL CLINCH NUTS		365.00	SR Technics Switzerland
2200	1808M56G01	EASA;FAA;CAAC;ANAC			72-41-03		Package SB01	72-0373	INTRODUCTION OF NEW HPT INNER STATOR STATIONARY SEAL HEAT SHIELD TO THE SPARE PARTS LIST		5415.00	SR Technics Switzerland
2200					72-41-03		Package SB02	72-0952-000	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2020-004	510.00	SR Technics Switzerland
2200					72-41-03		Package SB02	72-0952-000	REPAIR HPT INNER STATS SEAL HONEYCOMB	FAA AD 2021-10-0	510.00	SR Technics Switzerland
2200					72-41-03		Package SB02	72-0952-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	FAA AD 2021-10-0	510.00	SR Technics Switzerland
2200					72-41-03		Package SB02	72-0952-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2020-004	510.00	SR Technics Switzerland
2591	1559M40G02	EASA;FAA;CAAC;ANAC	48	28	72-33-01	COMPRESSOR REAR STATOR - CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		1730.00	SR Technics Switzerland
2591	1559M40G03	EASA;FAA;CAAC;ANAC			72-33-01		Package B	INSP-001	BLEND PATH PICK-UP		1350.00	SR Technics Switzerland
2591					72-33-01		Package B	INSP-001	REMOVAL OF HIGH METAL		1350.00	SR Technics Switzerland
2591					72-33-01		Package C	002	LEADING/TRAILING EDGES	72-33-02	890.00	SR Technics Switzerland
2591					72-33-01		Package F	005	REPAIR OF DAMAGED FLOW PATH SURFACES		7190.00	SR Technics Switzerland
2591					72-33-01		Package G	006	REPAIR OF FORWARD LIP OUTER DIAMETER (DIAMETER D)		6250.00	SR Technics Switzerland
2591					72-33-01		Package J	009	REPAIR OF FLOW PATH RUB LAND CRACKS IN THE INCOLOY 909 COMPRESSOR REAR STATOR CASE		6655.00	SR Technics Switzerland
2591					72-33-01		Package SB00	SB 72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CF AND CFM56-5B6/2 TO CFM56-5B6/2P		365.00	SR Technics Switzerland
2741	338-001-503-0	EASA;FAA;CAAC;ANAC	38	28	72-21-03	FAN AND BOOSTER - FAN DISK ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION	ROBOTIC EDDY CURRENT INSPECTI	5850.00	SR Technics Switzerland
2741	338-001-504-0	EASA;FAA;CAAC;ANAC			72-21-03		Package B	002	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS		745.00	SR Technics Switzerland
2741					72-21-03		Package C	SPEC PROC-001	ULTRASONIC INSPECTION		1890.00	SR Technics Switzerland
2741					72-21-03		Package G	006	SHOT-PEENING OF THE FAN DISK DOVETAILS		1485.00	SR Technics Switzerland
2741					72-21-03		Package M	012	BLEND REPAIR OF THE FAN DISK		2440.00	SR Technics Switzerland
2741					72-21-03		Package N	013	REPAIR OF THE FACE THAT MATES WITH THE SEALING FLANGE OF THE BOOSTER SPOOL		3500.00	SR Technics Switzerland
2741					72-21-03		Package Q	016	REPLACEMENT OF THE CRIMPED SPACERS		1170.00	SR Technics Switzerland
2741					72-21-03		Package SB00	AD 2002-13-03	DISK FLUORESCENT PENETRANT INSPECTION (FPI) AND DISK BORE AND DOVETAIL EDDY CURRENT INSF		3735.00	SR Technics Switzerland
2882	1795M36P01	EASA;FAA;CAAC;ANAC	42	28	72-52-03	HIGH PRESSURE TURBINE ROTOR - FRONT AIR ROTATING SE	Package A	CLN/INSP	CLEANING AND INSPECTION	EDDY CURRENT INSPECTION (ECI)	3575.00	SR Technics Switzerland
2882	1795M36P02	EASA;FAA;CAAC;ANAC			72-52-03		Package B	INSP-001 002	REMOVAL OF HIGH METAL		205.00	SR Technics Switzerland
2882	2116M20P02	EASA;FAA;CAAC;ANAC			72-52-03		Package C	002	REPAIR OF DIAMETER R		1405.00	SR Technics Switzerland
2882	2410M50P02	EASA;FAA;CAAC;ANAC			72-52-03		Package E	005	REPLACEMENT OF SEAL TEETH COATING		4705.00	SR Technics Switzerland
2882					72-52-03		Package G	006	EQUALISE	DIA B	4980.00	SR Technics Switzerland
2882					72-52-03		Package G	006	FORWARD AND AFT RABBET THERMAL SPRAY REPAIR	DIA B	4980.00	SR Technics Switzerland
2882					72-52-03		Package G	006	EQUALISE	DIA C	4980.00	SR Technics Switzerland
2882					72-52-03		Package G	006	FORWARD AND AFT RABBET THERMAL SPRAY REPAIR	DIA C	4980.00	SR Technics Switzerland
2882					72-52-03		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) AND EDDY CURRENT IN CONJUNCTION WITH PACKAGE A		605.00	SR Technics Switzerland
2882					72-52-03		Package SB02	72-1074	REPL. OF ROTATING AIR HPT FRONT SEAL PN 1795M36P02	AD EASA-2019-0146	405.00	SR Technics Switzerland
2882					72-52-03		Package SB05	72-0952-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	FAA AD 2021-10-0	510.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
2882					72-52-03		Package SB05	72-0952-001	REPAIR HPT INNER STATS SEAL HONEYCOMB	AD EASA-2020-004	510.00	SR Technics Switzerland
2882					72-52-03		Package SB06	72-EO-52905	REPLACEMENT OF AFFECTED ROTATING AIR HPT	FAA-2021-16-08	510.00	SR Technics Switzerland
3043	218920-1	EASA;FAA;ANAC	24	21	73-11-14	FUEL PUMP - MAIN GEAR HOUSING ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		240.00	SR Technics Switzerland
3043	219821-1	EASA;FAA;ANAC			73-11-14		Package M	012	NEW VALVE SEAT INSERT INSTALLATION		1250.00	SR Technics Switzerland
3043					73-11-14		Package N	013	REWORK MAIN GEAR HOUSING		1115.00	SR Technics Switzerland
3043					73-11-14		Package SB00	714900-73-108	INTRODUCTION OF NEW FUEL PUMP WITH NEW FILTER COVER ATTACHMENT		700.00	SR Technics Switzerland
3043					73-11-14		Package SB01	73-0111	REPLACEMENT OF THE CURRENT DEFECTIVE SIXTH ATTACHMENT C OF THE MAIN FUEL PUMP EQUIPPEC		220.00	SR Technics Switzerland
3044	217780-1	EASA;FAA;ANAC	10	21	73-11-13	MAIN GEAR HOUSING ASSEMBLY	Package B		TEST AND INSPECTION		285.00	SR Technics Switzerland
3044	219822-1	EASA;FAA;ANAC			73-11-13		Package E		REWORK MAIN GEAR HOUSING		980.00	SR Technics Switzerland
3044					73-11-13		Package E		REPLACEMENT OF DAMAGED STUDS		980.00	SR Technics Switzerland
3044					73-11-13		Package SB01	73-0111	REPL. OF CURRENT DEFECTIVE 6TH ATTACHMENT OF THE FUEL FILTER COVER		135.00	SR Technics Switzerland
3207	338-010-103-0	EASA;FAA;CAAC;ANAC	26	28	72-53-06	LOW PRESSURE TURBINE - NOZZLE SEGMENTS STG 1	Package B		BASIC REPAIR	TYPE 1/2/3	280.00	SRTAS
3207	338-010-104-0	EASA;FAA;CAAC;ANAC			72-53-06		Package B	INSP-001	VISUAL / DIMENSIONAL		280.00	SRTAS
3207	338-010-106-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C		MINOR REPAIR	TYPE 1/2/3	630.00	SRTAS
3207	338-010-107-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C	1	AIRFOIL BLEND REPAIR		630.00	SRTAS
3207	338-010-108-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C	5	REPAIR OF APVS COATING		630.00	SRTAS
3207	338-010-203-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C	55	OVERCOATING OF APVS PROTECTION		630.00	SRTAS
3207	338-010-204-0	EASA;FAA;CAAC;ANAC			72-53-06		Package C	INSP-001	VISUAL / DIMENSIONAL		630.00	SRTAS
3207	338-010-206-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D		MEDIUM REPAIR	TYPE 1	5950.00	SRTAS
3207	338-010-207-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D	1	AIRFOIL BLEND REPAIR		5950.00	SRTAS
3207	338-010-208-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D	17	FULL BRAZING REPAIR	INCLUDING CRACK REPAIR WITH NC	5950.00	SRTAS
3207	338-108-606-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D	5	REPAIR OF APVS COATING		5950.00	SRTAS
3207	338-108-607-0	EASA;FAA;CAAC;ANAC			72-53-06		Package D	INSP-001	VISUAL / DIMENSIONAL		5950.00	SRTAS
3207	338-108-608-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E		FULL REPAIR	TYPE 1	6085.00	SRTAS
3207	338-108-609-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	1	AIRFOIL BLEND REPAIR		6085.00	SRTAS
3207	338-108-614-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	17	FULL BRAZING REPAIR	INCLUDING ANY COMBINATION OF A	6085.00	SRTAS
3207	338-108-706-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	18	GAS PATH AREA RECONDITIONING BY DIFFUSION BRAZING		6085.00	SRTAS
3207	338-108-707-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	5	REPAIR OF APVS COATING		6085.00	SRTAS
3207	338-108-708-0	EASA;FAA;CAAC;ANAC			72-53-06		Package E	INSP-001	VISUAL / DIMENSIONAL		6085.00	SRTAS
3207	338-108-709-0	EASA;FAA;CAAC;ANAC			72-53-06		Package F		ADDITIONAL WORKSCOPE	TYPE 1	800.00	SRTAS
3207	338-108-714-0	EASA;FAA;CAAC;ANAC			72-53-06		Package F	72-0229	NEW PART RELEASE OR REWORK OLD PART. EDM HOLES IN AFT FL PERFORMED DURING ANY OF THE F		800.00	SRTAS
3207	340-256-251-0	EASA;FAA;CAAC;ANAC			72-53-06		Package G		ADDITIONAL WORKSCOPE	TYPE 1/2/3	1095.00	SRTAS
3207	340-256-252-0	EASA;FAA;CAAC;ANAC			72-53-06		Package G	22	WELD REPAIR OF SEAL SLOT BREAKOUT		1095.00	SRTAS
3207	340-256-254-0	EASA;FAA;CAAC;ANAC			72-53-06		Package H		ADDITIONAL WORKSCOPE	TYPE 1/2/3	3890.00	SRTAS
3207	340-256-351-0	EASA;FAA;CAAC;ANAC			72-53-06		Package H	12	AIRFLOW RESTORATION BY DIFFUSION BRAZING		3890.00	SRTAS
3207	340-256-352-0	EASA;FAA;CAAC;ANAC			72-53-06		Package K		MEDIUM REPAIR	TYPE 2/3	5950.00	SRTAS
3207	340-256-354-0	EASA;FAA;CAAC;ANAC			72-53-06		Package K	1	AIRFOIL BLEND REPAIR		5950.00	SRTAS
3207					72-53-06		Package K	27	FULL BRAZING REPAIR	CRACK REPAIR WITH NO BAFFLE. R	5950.00	SRTAS
3207					72-53-06		Package K	28	INNER PLATFORM COOLING AIR DUCT HOLES REPAIR		5950.00	SRTAS
3207					72-53-06		Package K	5	REPAIR OF APVS COATING		5950.00	SRTAS
3207					72-53-06		Package K	INSP-001	VISUAL / DIMENSIONAL		5950.00	SRTAS
3207					72-53-06		Package L		FULL REPAIR	TYPE 2/3	6085.00	SRTAS
3207					72-53-06		Package L	1	AIRFOIL BLEND REPAIR		6085.00	SRTAS
3207					72-53-06		Package L	18	GAS PATH AREA RECONDITIONING BY DIFFUSION BRAZING		6085.00	SRTAS
3207					72-53-06		Package L	27	FULL BRAZING REPAIR	INCLUDING ANY COMBINATION OF A	6085.00	SRTAS
3207					72-53-06		Package L	28	INNER PLATFORM COOLING AIR DUCT HOLES REPAIR		6085.00	SRTAS
3207					72-53-06		Package L	5	REPAIR OF APVS COATING		6085.00	SRTAS
3207					72-53-06		Package L	INSP-001	VISUAL / DIMENSIONAL		6085.00	SRTAS

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3207					72-53-06		Package N		GLOBAL AIRFLOW REPAIR BY DICA		10570.00	SR TAS
3207					72-53-06		Package N		ADDITIONAL WORKSCOPE	TYPE 2/3	10570.00	SR TAS
3473	336-024-704-0	EASA;FAA;CAAC;ANAC	48	28	72-56-06	LOW PRESSURE TURBINE REAR FRAME - OIL INLET COVER	Package A	CLN/INSP	CLEANING AND INSPECTION		1685.00	SR Technics Switzerland
3473	336-024-705-0	EASA;FAA;CAAC;ANAC			72-56-06		Package B	001	REPLACEMENT OF THE COATED RING OR REPLACEMENT OF THE ORIGINAL COATING BY A COATED RING		4955.00	SR Technics Switzerland
3473	336-024-706-0	EASA;FAA;CAAC;ANAC			72-56-06		Package C	002	REPAIR OF THE CRIMPED SELF-LOCKING NUTS		855.00	SR Technics Switzerland
3473	336-024-707-0	EASA;FAA;CAAC;ANAC			72-56-06		Package E	004	REPAIR OF SEAL TEETH BY WELD UP		2930.00	SR Technics Switzerland
3473	336-024-708-0	EASA;FAA;CAAC;ANAC			72-56-06		Package G	006	PLASMA REPAIR OF REAR CONTACT FACE		3180.00	SR Technics Switzerland
3473					72-56-06		Package SB00	79-0020	INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES		1205.00	SR Technics Switzerland
3473					72-56-06		Package SB01	72-0320	INTRODUCTION OF NEW OIL INLET COVER ASSY		1205.00	SR Technics Switzerland
3975	1358M80P04	EASA;FAA;CAAC;ANAC	28	28	72-51-10	HIGH PRESSURE TURBINE NOZZLE - EXTERNAL PRESSURE SI	Package A	CLN/INSP	CLEANING AND INSPECTION		505.00	SR Technics Switzerland
3975					72-51-10		Package B	001	REPAIR WEAR ON THE HPT NOZZLE EXTERNAL PRESSURE SEAL RETAINER		3605.00	SR Technics Switzerland
7808	301-546-107-0	EASA;FAA;CAAC;ANAC	26	28	72-55-16	LOW PRESSURE TURBINE SHAFT - PLUG	Package A	CLN/INSP	CLEANING AND INSPECTION		365.00	SR Technics Switzerland
7808	337-124-601-0	EASA;FAA;CAAC;ANAC			72-55-16		Package B	001	RECONDITIONING OF THE LOCATING DIAMETER WITH THE LPT SHAF DIA A		1600.00	SR Technics Switzerland
7808	337-124-620-0	EASA;FAA;CAAC;ANAC			72-55-16		Package C	001	RECONDITIONING OF THE LOCATING DIAMETER WITH THE LPT SHAF DIA B		1600.00	SR Technics Switzerland
7808	338-072-102-0	EASA;FAA;CAAC;ANAC			72-55-16		Package D	002	RECONDITIONING OF THE INNER LOCATING DIAMETER (DIA C) WITH THE CENTER VENT TUBE BY PLASM/		1605.00	SR Technics Switzerland
7808	338-072-103-0	EASA;FAA;CAAC;ANAC			72-55-16		Package E	003	REPAIR OF THE ANTI-ROTATION TANG BY WELD BUILD-UP		1155.00	SR Technics Switzerland
7808	340-310-501-0	EASA;FAA;CAAC;ANAC			72-55-16		Package F	004	CLEANING AND PACKAGING		220.00	SR Technics Switzerland
8457	238-0860-501	EASA;FAA;CAAC;ANAC	11	21	71-00-17	CFM56-5B FIRE DETECTOR SUPPORT TUBE	Package A	CLN/INSP	CLEANING AND INSPECTION		820.00	SR Technics Switzerland
8457	238-0861-501	EASA;FAA;ANAC			71-00-17		Package F	005	CRACK REPAIR FIRE DETECTOR		300.00	SR Technics Switzerland
8457	642-5861-501	EASA;FAA;CAAC;ANAC			71-00-17		Package G	006	RUPTURE REPAIR FIRE		350.00	SR Technics Switzerland
8457					71-00-17		Package H	007	GOUGE REPAIR FIRE DETECTOR		305.00	SR Technics Switzerland
8457					71-00-17		Package I	008	CLAMPS WELD REPLACEMENT		330.00	SR Technics Switzerland
8457					71-00-17		Package J	017	SUPPORT TUBE WELD REPAIR		505.00	SR Technics Switzerland
8521	1358M35G02	EASA;FAA;CAAC;ANAC	34	28	72-51-08	HIGH PRESSURE TURBINE NOZZLE - AFT INNER SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1055.00	SR Technics Switzerland
8521	1522M46G02	EASA;FAA;CAAC;ANAC			72-51-08		Package B	003	DIAMETER RESTORATION BY HEAT TREAT AND PLASMA SPRAY	WASPALLOY CONFIGURATION	6835.00	SR Technics Switzerland
8521					72-51-08		Package B	004	DIAMETER RESTORATION BY HEAT TREAT AND PLASMA SPRAY	RENE 41 CONFIGURATION	6835.00	SR Technics Switzerland
8521					72-51-08		Package C	001	REPAIR FOR THE HPT AFT INNER NOZZLE SUPPORT PIN REPLACEMENT		1940.00	SR Technics Switzerland
8521					72-51-08		Package SB00	72-0171	CONVERSION	CRACK INSPECTION PT "LINIE B"	300.00	SR Technics Switzerland
8527	301-297-812-0	EASA;FAA;CAAC;ANAC	9	28	72-22-12	CFM56 NO.1 BEARING SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		780.00	SR Technics Switzerland
8527					72-22-12		Package D	003	REMOVAL OF CORROSION ON THE CONTACT FACE WITH OIL DEFLEI AREA G		1170.00	SR Technics Switzerland
8527					72-22-12		Package D	003	REMOVAL OF CORROSION ON THE CONTACT FACE WITH OIL DEFLEI AREA L		1170.00	SR Technics Switzerland
13471	337-100-804-0	EASA;FAA;CAAC;ANAC	19	28	72-23-15	FAN FRAME ASSEMBLY - ACCESSORY DRIVE REAR CLEVIS MK	Package A	CLN/INSP	CLEANING AND INSPECTION		550.00	SR Technics Switzerland
13471	338-075-402-0	EASA;FAA;CAAC;ANAC			72-23-15		Package C	002	REPLACEMENT OF BUSHING		1175.00	SR Technics Switzerland
13471	340-077-601-0	EASA;FAA;CAAC;ANAC			72-23-15		Package D	003	SPOT TOUCH UP CLEVIS		435.00	SR Technics Switzerland
15175	2616M78G01	EASA;FAA;CAAC;ANAC	45	28	72-31-11	COMPRESSOR ROTOR - AIR DUCT	Package A	CLN/INSP	CLEANING AND INSPECTION		865.00	SR Technics Switzerland
15175	9514M54G05	EASA;FAA;CAAC;ANAC			72-31-11		Package C	002	REPAIR ILLEGIBLE PART IDENTIFICATION NUMBERS		190.00	SR Technics Switzerland
15175					72-31-11		Package G	006	REPLACEMENT OF COMPRESSOR ROTOR AIR DUCT SLEEVE		3255.00	SR Technics Switzerland
16715	1559M30G05	EASA;FAA;CAAC;ANAC	84	28	72-32-01	COMPRESSOR FRONT STATOR - CASE	Package A	ASSEMBLY-001	RE-MEASURE FLOW PATH		3470.00	SR Technics Switzerland
16715	1559M30G06	EASA;FAA;CAAC;ANAC			72-32-01		Package A	CLN/INSP	CLEANING AND INSPECTION		3470.00	SR Technics Switzerland
16715	1559M30G09	EASA;FAA;CAAC;ANAC			72-32-01		Package AB	027	REPAIR OF THE AFT FLANGE PITTING AND CORROSION		6240.00	SR Technics Switzerland
16715	1559M30G10	EASA;FAA;CAAC;ANAC			72-32-01		Package AG	032	BLEND CORROSION/PITTING NON-FLOWPATH AREA		1285.00	SR Technics Switzerland
16715	1559M30G11	EASA;FAA;CAAC;ANAC			72-32-01		Package AK		MEASURE NEW - / OVHLD PARTS		190.00	SR Technics Switzerland
16715	1559M30G12	EASA;FAA;CAAC;ANAC			72-32-01		Package B	INSP-001	BLEND HOT SPOTS		2225.00	SR Technics Switzerland
16715	1559M30G13	EASA;FAA;CAAC;ANAC			72-32-01		Package B	INSP-001	W/ET ABRASIVE BLAST CORROSION/DISCOLORATION		2225.00	SR Technics Switzerland
16715	1559M30G14	EASA;FAA;CAAC;ANAC			72-32-01		Package B	INSP-001	BLENDING FLOW, NICKS, ETC.		2225.00	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLEND CASE SURFACE		2225.00	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLEND CASE CORROSION/DISCOLORATION		2225.00	SR Technics Switzerland
16715					72-32-01		Package B	INSP-001	BLEND FLOW PATH	ATA 72-00-32	2225.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
16715					72-32-01		Package B	INSP-001	BLEND FLOW PATH PICKUP		2225.00	SR Technics Switzerland
16715					72-32-01		Package B	SPM	REMOVE BROKEN BOLTS		2225.00	SR Technics Switzerland
16715					72-32-01		Package C	001	REPAIR OF THREADED BOSSES AND PADS		2275.00	SR Technics Switzerland
16715					72-32-01		Package D	003	REPAIR OF BORESCOPE PORT THREADS		3295.00	SR Technics Switzerland
16715					72-32-01		Package D	003	REPAIR OF BORESCOPE PORT THREADS	RETAP THREADS	3295.00	SR Technics Switzerland
16715					72-32-01		Package E	004	REPAIR THE FORWARD AND AFT RABBIT DIAMETERS OF THE COMP DIA C		3835.00	SR Technics Switzerland
16715					72-32-01		Package E	004	REPAIR THE FORWARD AND AFT RABBIT DIAMETERS OF THE COMP DIA B		3835.00	SR Technics Switzerland
16715					72-32-01		Package G	002	LEADING/TRAILING EDGES	72-32-03	890.00	SR Technics Switzerland
16715					72-32-01		Package P	015	FLOW PATH REPAIR		11885.00	SR Technics Switzerland
16715					72-32-01		Package Q	016	WELD REPAIR OF LINEAR INDICATIONS AT THE HORIZONTAL SPLIT LINE		8910.00	SR Technics Switzerland
16715					72-32-01		Package R	017	INTRGRAL PILOT BRACKET (IPB) DIAMETER D REPAIR	DIA D	8510.00	SR Technics Switzerland
16715					72-32-01		Package SB01	72-0171	FAN & BOOSTER, MOD FROM -5B/2 TO -5B/2P		300.00	SR Technics Switzerland
16715					72-32-01		Package V	021	REAMING OF THE AFT FLANGE BOLT HOLES		11965.00	SR Technics Switzerland
16715					72-32-01		Package X	023	WELD REPAIR OF LINEAR INDICATIONS AT SPLITLINE BOLT HOLES AND BUSHING HOLES		11740.00	SR Technics Switzerland
16715					72-32-01		Package Y	024	WELD REPAIR OF DAMAGED MID FLANGE BOLT HOLES AND AFT FACE WEAR		2810.00	SR Technics Switzerland
18900	305-025-408-0	EASA;FAA;CAAC;ANAC	52	28	72-55-15	LOW PRESSURE TURBINE SHAFT - AIR/OIL SEPARATOR AND C	Package A	CLN/INSP	CLEANING AND INSPECTION		500.00	SR Technics Switzerland
18900	305-044-506-0	EASA;FAA;CAAC;ANAC			72-55-15		Package B	001	TOUCH-UP OF THE SURFACE PROTECTION ON THE AIR/OIL SEPARATOR		590.00	SR Technics Switzerland
18900	337-108-502-0	EASA;FAA;CAAC;ANAC			72-55-15		Package C	002	TOUCHUP OF SURFACE PROTECTION ON AIR/OIL SEPARATOR COVER		940.00	SR Technics Switzerland
18900	337-108-510-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-15		Package D	003	AIR/OIL SEPARATOR AND COVER REPAIR		2150.00	SR Technics Switzerland
18900	337-108-520-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-15		Package E	004	REPAIR OF THE LOCATING DIAMETER WITH LPT SHAFT		3820.00	SR Technics Switzerland
18900	337-108-551-0	EASA;FAA;CAAC;ANAC			72-55-15		Package F	005	REPAIR OF THE DIAMETER WHICH LOCATES THE CENTER VENT TUBE REAR EXTENSION DUCT		1615.00	SR Technics Switzerland
18900					72-55-15		Package G	006	REPAIR OF THREE WELD BEADS ON AIR/OIL SEPARATOR		1215.00	SR Technics Switzerland
18900					72-55-15		Package H	007	REPLACEMENT OF THE COVER OF THE AIR/OIL SEPARATOR		1375.00	SR Technics Switzerland
18900					72-55-15		Package I	008	FINAL CLEANING AND PACKAGING OF THE AIR/OIL SEPARATOR		185.00	SR Technics Switzerland
18900					72-55-15		Package SB03	72-0854	INTRODUCTION OF A NEW AIR/OIL SEPARATOR AND REWORK OF THE OLD ONE		1275.00	SR Technics Switzerland
21511	1558M31G03	EASA;FAA;CAAC;ANAC	52	28	72-31-04	COMPRESSOR ROTOR - SPOOL	Package A	CLN/INSP	CLEANING, FLUORESCENT PENETRANT INSPECTION (FPI) AND INSPECTION		2425.00	SR Technics Switzerland
21511	1558M31G04	EASA;FAA;CAAC;ANAC			72-31-04		Package B	INSP-001	REMOVAL OF HIGHMETAL		2415.00	SR Technics Switzerland
21511	1558M31G05	EASA;FAA;CAAC;ANAC			72-31-04		Package B	INSP-001	BLENDING RETAINER HOOKS		2415.00	SR Technics Switzerland
21511	1558M31G07	EASA;FAA;CAAC;ANAC			72-31-04		Package B	INSP-001	BLENDING INTERSTAGE SEAL		2415.00	SR Technics Switzerland
21511	1834M55G01	EASA;FAA;CAAC;ANAC			72-31-04		Package B	INSP-001	BLENDING STAGE 1 AREA M		2415.00	SR Technics Switzerland
21511					72-31-04		Package B	INSP-001	BLENDING FWD SEAL DIA DZ		2415.00	SR Technics Switzerland
21511					72-31-04		Package C	002	REPAIR OF ILLEGIBLE PART MARKINGS		120.00	SR Technics Switzerland
21511					72-31-04		Package E	004	REPAIR DIAMETER B		4460.00	SR Technics Switzerland
21511					72-31-04		Package F	005	REPAIR OF THE SEAL TEETH COATING	DIA E	6670.00	SR Technics Switzerland
21511					72-31-04		Package F	005	REPAIR OF THE SEAL TEETH COATING	DIA F	6670.00	SR Technics Switzerland
21511					72-31-04		Package G	006	APPLICATION OF MOLYDAG 254 COATING ON STAGES 1 AND 2 DOVETAILS		3235.00	SR Technics Switzerland
21511					72-31-04		Package H	007	REPAIR OF FRETTED SURFACE G		5575.00	SR Technics Switzerland
21511					72-31-04		Package SB00	72-0448	FPI OF HPC STAGE 1-2 SPOOL, STAGE 1 DOVETAIL SLOT BOTTOM		1085.00	SR Technics Switzerland
21511					72-31-04		Package SB02	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)		1550.00	SR Technics Switzerland
21512	1590M59P01	EASA;FAA;CAAC;ANAC	42	28	72-31-05	COMPRESSOR ROTOR - DISK STAGE 3	Package A	CLN/INSP	CLEANING AND INSPECTION		1580.00	SR Technics Switzerland
21512	2116M23P01	EASA;FAA;CAAC;ANAC			72-31-05		Package B	INSP-001	DISK BLENDING PAD AREA E		840.00	SR Technics Switzerland
21512	9940M55P18	EASA;FAA;CAAC;ANAC			72-31-05		Package C	002	REPAIR OF THE RABBIT DIAMETERS		4010.00	SR Technics Switzerland
21512					72-31-05		Package L	INSP-001	REMOVE HIGHMETAL		840.00	SR Technics Switzerland
21512					72-31-05		Package M	INSP-001	DISK BLEND RETAINER HOOK		840.00	SR Technics Switzerland
21512					72-31-05		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	905.00	SR Technics Switzerland
21512					72-31-05		Package SB00	SB 72-0122	ULTRASONIC / EDDY CURRENT INSPECTION		905.00	SR Technics Switzerland
21514	338-010-601-0	EASA;FAA;CAAC;ANAC	32	28	72-22-01	NO.1 AND NO.2 BEARING SUPPORT - FAN SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		635.00	SR Technics Switzerland
21514					72-22-01		Package B	INSP-001	RECRIMP SELF LOCKING NUT		605.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
21514					72-22-01		Package B	INSP-001	TOUCH-UP PAINT		605.00	SR Technics Switzerland
21514					72-22-01		Package B	INSP-001	REPAIR THREADS NO.2 BRG		605.00	SR Technics Switzerland
21514					72-22-01		Package C		REMOVE PAINT		3165.00	SR Technics Switzerland
21514					72-22-01		Package C	001	REPLACEMENT OF THE ALUMINIUM PAINT		3165.00	SR Technics Switzerland
21514					72-22-01		Package D	002	REPLACEMENT OF CRIMPED SELF-LOCKING NUTS		595.00	SR Technics Switzerland
21514					72-22-01		Package SB00	AD 2002-13-03	MAGNETIC PARTICLE INSPECTION (MPI).	IN CONJUNCTION WITH PACKAGE A	685.00	SR Technics Switzerland
22647	1348M79P08	EASA;FAA;CAAC;ANAC;CAA I	28	21	73-21-18	FUEL - HYDROMECHANICAL CONTROL	Package B	TEST	PRE TEST		4265.00	SR Technics Switzerland
22647	8061-526	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-18		Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	4265.00	SR Technics Switzerland
22647					73-21-18		Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST EXCLUDED PIECE PART REPAIRS		4980.00	SR Technics Switzerland
22647					73-21-18		Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXAMPLE: SERVO SLEEVE, TORQUE		9655.00	SR Technics Switzerland
22647					73-21-18		Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXAMPLE: PILOT VALVE BODY, PRES		13630.00	SR Technics Switzerland
22647					73-21-18		Package G		OVERHAUL		17725.00	SR Technics Switzerland
22647					73-21-18		Package SB00	83390-73-006	WIRE INSULATION SAFEGUARD IMPROVEMENTS	IN CONJUNCTION WITH PACKAGE LI	510.00	SR Technics Switzerland
22647					73-21-18		Package SB00	83390-73-008	IMPROVED OVERSPEED GOVERNOR SPEEDER SPRING ASSEMBLY, I	IN CONJUNCTION WITH PACKAGE LI	510.00	SR Technics Switzerland
22647					73-21-18		Package SB00	83390-73-009	INSPECTION OF PRESSURIZING VALVE PORT, 8061-511(1348M79P06), I	IN CONJUNCTION WITH PACKAGE H	510.00	SR Technics Switzerland
22647					73-21-18		Package SB01	73-104	REPLACEMENT OF EXISTING PART. REPLACING VIN 1680-684 RESOL' IN CONJUNCTION WITH PACKAGE M		510.00	SR Technics Switzerland
22647					73-21-18		Package SB01	73-EO-527943	HMU - PREVENTIVE BEARING REPLACEMENT	IN CONJUNCTION WITH PACKAGE M	510.00	SR Technics Switzerland
22647					73-21-18		Package SB01	83390-73-003	IMPROVEMENTS TO THE TORQUE MOTOR AND RESOLVER, 8061-512 IN CONJUNCTION WITH PACKAGE M		510.00	SR Technics Switzerland
22647					73-21-18		Package SB01	83390-73-005	INCORPORATION OF ANTI-ROTATION PUMP UNLOADING DESIGN, 80K IN CONJUNCTION WITH PACKAGE M		510.00	SR Technics Switzerland
22647					73-21-18		Package SB01	83390-73-012	IMPROVED TORQUE MOTOR (CARBIDE TIP ASSEMBLY)	IN CONJUNCTION WITH PACKAGE M	510.00	SR Technics Switzerland
22647					73-21-18		Package SB01	83390-73-014	IMPROVED PRESSURIZING VALVE OVERBOARD DRAIN SEAL	IN CONJUNCTION WITH PACKAGE M	510.00	SR Technics Switzerland
22647					73-21-18		Package SB02	73-069	DELTA P DRIVE PIN REPLACEMENT	IN CONJUNCTION WITH PACKAGE H	510.00	SR Technics Switzerland
22647					73-21-18		Package SB02	73-102	REPLACEMENT OF MIS-MACHINED PRESSURIZING VALVE SLEEVES	IN CONJUNCTION WITH PACKAGE H	510.00	SR Technics Switzerland
22647					73-21-18		Package SB02	73-112	REPLACEMENT OF OSG DRIVE PIN RETAINERS, REPLACING 3535-196 IN CONJUNCTION WITH PACKAGE H		510.00	SR Technics Switzerland
22647					73-21-18		Package SB02	73-127	INSPECTION FOR MISMACHINED VBV PORT, 8061-511(1348M79P06), 8K IN CONJUNCTION WITH PACKAGE H		510.00	SR Technics Switzerland
22647					73-21-18		Package SB02	83390-73-001	REWORK OF VALVE ASSEMBLIES TO ELIMINATE POTENTIAL TRAPPE IN CONJUNCTION WITH PACKAGE H		510.00	SR Technics Switzerland
22647					73-21-18		Package SB02	83390-73-004	USE OF FLUOROCARBON VITON PREFORMED PACKINGS IN HMU, MII IN CONJUNCTION WITH PACKAGE H		510.00	SR Technics Switzerland
22647					73-21-18		Package SB02	83390-73-010	INTRODUCTION OF IMPROVED HMU PRESSURIZING VALVE, 8061-512 IN CONJUNCTION WITH PACKAGE H		510.00	SR Technics Switzerland
22647					73-21-18		Package SB02	83390-73-011	USE OF FLUOROCARBON VITON PREFORMED PACKINGS IN HMU, GL IN CONJUNCTION WITH PACKAGE H		510.00	SR Technics Switzerland
22647					73-21-18		Package SB03	EASA-2017-0065	HYDRO-MECHANICAL UNITS - OPERATIONAL LIMITATIONS		510.00	SR Technics Switzerland
22647					73-21-18		Package SB04	FAA 2013-14-06	CORROSION OF THE DELTA-P VALVE		1520.00	SR Technics Switzerland
22647					73-21-18		Package SB05	73-0182	USE OF CIS FUEL IN CFM56-5A ENGINES		510.00	SR Technics Switzerland
22647					73-21-18		Package SB06	72-0122	USE OF CIS FUEL IN CFM56-5B ENGINES		510.00	SR Technics Switzerland
24630	336-026-101-0	EASA;FAA;CAAC;ANAC	21	28	72-53-09	STAGE 1 LPT NOZZLE - BORESCOPE PLUG	Package A	CLN/INSP	CLEANING AND INSPECTION		205.00	SR Technics Switzerland
24630					72-53-09		Package B	INSP-001	BLENDED THREAD HIGH METAL		440.00	SR Technics Switzerland
29444			17	28	72-63-15	ACCESSORY GEARBOX - STARTER ADAPTER	Package A	CLN/INSP	CLEANING AND INSPECTION		395.00	SR Technics Switzerland
44969	9531M11G02	EASA;FAA;CAAC;ANAC	23	28	72-42-01	COMBUSTION CHAMBER (SAC) - INNER COWLS	Package A	CLN/INSP	CLEANING AND INSPECTION		960.00	SR Technics Switzerland
44969					72-42-01		Package C	002	WELD REPAIR AND RESIZING OF THE INNER COWL		1550.00	SR Technics Switzerland
61388	1348M79P09	EASA;FAA;ANAC;CAA MALAY	44	21	73-21-78	HYDROMECHANICAL FUEL CONTROL	Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	3635.00	SR Technics Switzerland
61388	1348M79P10	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-78		Package B	TEST	PRE TEST		3635.00	SR Technics Switzerland
61388	1348M79P11	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-78		Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS.		5475.00	SR Technics Switzerland
61388	1348M79P12	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-78		Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS.		8005.00	SR Technics Switzerland
61388	1348M79P13	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-78		Package G		OVERHAUL		10935.00	SR Technics Switzerland
61388	1348M79P14	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-78		Package SB01	73-0122	HMU - CIS FUEL MAINTENANCE REQUIREMENT	IN CONJUNCTION WITH MEDIUM	700.00	SR Technics Switzerland
61388	8061-531	EASA;FAA;ANAC;CAA MALAYSIA;DGCA CIVIL A1			73-21-78		Package SB02	83628-73-003	IMPROVEMENTS TO THE RESOLVER	IN CONJUNCTION WITH MEDIUM	700.00	SR Technics Switzerland
61388	8061-532	EASA;FAA;ANAC;CAA MALAYSIA;DGCA CIVIL A1			73-21-78		Package SB03	83628-73-009	WIRE INSULATION SAFEGUARD IMPROVEMENTS	IN CONJUNCTION WITH MEDIUM	700.00	SR Technics Switzerland
61388	8061-533	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-78		Package SB05	73-EO-527943	HMU - PREVENTIVE BEARING REPLACEMENT	IN CONJUNCTION WITH MEDIUM	2070.00	SR Technics Switzerland
61388	8061-534	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-78		Package SB07	83628-73-016_01	IMPROVED PRESSURIZING VALVE OVERBOARD DRAIN SEAL	IN CONJUNCTION WITH MEDIUM	2070.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
61388	8061-535	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-78		Package SB08	83628-73-021	IMPROVED SHUTOFF SWITCH MOUNTING	IN CONJUNCTION WITH MEDIUM	2070.00	SR Technics Switzerland
61388	8061-536	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-21-78		Package SB12	73-0122	USE OF CIS FUELS		6305.00	SR Technics Switzerland
61388					73-21-78		Package SB14	EASA-2017-0065	OPERATIONAL LIMITATIONS		6305.00	SR Technics Switzerland
61388					73-21-78		Package SB15	FAA-2013-14-06	CORROSION OF THE DELTA-P VALVE		6305.00	SR Technics Switzerland
61388					73-21-78		Package SB18	8061-5 / 73-001	INTRODUCTION OF HYDROMECHANICAL UNIT VIN 8061-532 (P/N 1348	IN CONJUNCTION WITH HEAVY/ OV	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-001	REWORK OF VALVE ASSEMBLIES TO ELIMINATE POTENTIAL TRAPPE	IN CONJUNCTION WITH HEAVY/ OV	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-002	REPLACEMENT OF VESPEL BALL PIN 1419-240	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-003	IMPROVEMENTS TO THE RESOLVER	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-004	REPLACEMENT OF FMV, VSV, VBV, AND TCC VALVE CAPS TO ELIMIN.	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-005	USE OF FLUOROCARBON (VITON) PREFORMED PACKINGS IN HYDRON	IN CONJUNCTION WITH HEAVY/ OV	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-006	INCORPORATION OF ANTI-ROTATION PUMP UNLOADING DESIGN	IN CONJUNCTION WITH LIGHT	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-010	IMPROVED PRESSURIZING AND DELTA P VALVES	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-011	IMPROVED OVERSPEED GOVERNOR SPEEDER SPRING ASSEMBLY	IN CONJUNCTION WITH LIGHT	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-012	REWORK OF HMU VIN 8061-534 (P/N 1348M79P12) TO HMU VIN 8061-5	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-013	REWORK OF HMU VIN 8061-533 (P/N 1348M79P11) TO HMU VIN 8061-5	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-014	IMPROVED FOUR-PORT PRESSURIZING AND DELTA P VALVES	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-015	USE OF FLUOROCARBON (VITON GLT-600S) PREFORMED PACKINGS	IN CONJUNCTION WITH HEAVY/ OV	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-016	IMPROVED PRESSURIZING VALVE OVERBOARD DRAIN SEAL	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-017	IMPROVED TORQUE MOTOR (CARBIDE TIP ASSEMBLY)	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB18	83628-73-019	REPLACEMENT OF VSV/VBV PILOT VALVES ON SUSPECT LIST FOR P	IN CONJUNCTION WITH MEDIUM	510.00	SR Technics Switzerland
61388					73-21-78		Package SB19	73-0182	HMU - CIS FUEL MAINTENANCE REQUIREMENT	IN CONJUNCTION WITH MEDIUM	6305.00	SR Technics Switzerland
62366	301-785-501-0	EASA;FAA;ANAC;CAA UK	11	21	73-11-13	FUEL PUMP	Package A	INSP	FLUORECENT PENETRANT INSPECTION		415.00	SR Technics Switzerland
62366	301-785-502-0	EASA;FAA;ANAC;CAA UK			73-11-13		Package B	TEST	PRE TEST		2220.00	SR Technics Switzerland
62366	301-785-503-0	EASA;FAA;ANAC;CAA UK			73-11-13		Package B	TEST	BENCH TEST		2220.00	SR Technics Switzerland
62366	301-785-504-0	EASA;FAA;CAA UK			73-11-13		Package E		REPAIR		5145.00	SR Technics Switzerland
62366	301-785-505-0	EASA;FAA;CAA UK			73-11-13		Package G		OVERHAUL		9525.00	SR Technics Switzerland
62366	714900-1	EASA;FAA;ANAC;CAA UK			73-11-13		Package SB00	IA 219071.01	IMPROVED FILTER COVER, D-BOLT & LOCK NUT		470.00	SR Technics Switzerland
62366	714900-2	EASA;FAA;ANAC			73-11-13		Package SB01	714900-73-108	INTRODUCTION OF NEW FUEL PUMP WITH NEW FILTER COVER ATTACHMENT		470.00	SR Technics Switzerland
62366	714900-3	EASA;FAA;CAAC;ANAC;CAA UK			73-11-13		Package SB02	714900-73-114	INTRODUCTION OF NEW PUMP GEARS		4665.00	SR Technics Switzerland
62366	714900-4	EASA;FAA;CAAC;ANAC;CAA UK			73-11-13		Package SB02	714900-73-115	INTRODUCTION OF NEW PUMP GEARS		4665.00	SR Technics Switzerland
62366	714900-5	EASA;FAA;CAAC;ANAC;CAA UK			73-11-13		Package SB02	714900-73-116	INTRODUCTION OF NEW PUMP GEARS		4665.00	SR Technics Switzerland
62366					73-11-13		Package SB04	73-0111	WIRE INSULAT. SAFEGUARD IMPROVEMENTS		470.00	SR Technics Switzerland
62366					73-11-13		Package SB06	714900-73-112	INTRODUCTION OF NEW FUEL FILTER		4665.00	SR Technics Switzerland
62366					73-11-13		Package SB07	828300-73-110	MFP - NEW RETAINING RING		4665.00	SR Technics Switzerland
62366					73-11-13		Package SB09	714900-73-101	CONVERSION FROM BRONZE BEARINGS TO ALUMINUMBRONZE BEARINGS		4150.00	SR Technics Switzerland
62366					73-11-13		Package SB10	714900-73-104	INTRODUCTION OF NEW BEARING SEAL		4150.00	SR Technics Switzerland
62366					73-11-13		Package SB11	714900-73-113	INTRODUCTION OF NEW FUEL FILTER		4150.00	SR Technics Switzerland
62366					73-11-13		Package SB12	714900-73-111	FUEL AND CONTROL INTR.OF IMPR.SHAFT SEAL		470.00	SR Technics Switzerland
62366					73-11-13		Package SB13	AD 2006-26-01	REPLACING THE FUEL FILTERS ON ENGINE		470.00	SR Technics Switzerland
72531	9523M11G03	EASA;FAA;CAAC;ANAC	10	28	72-31-09	CFM56 COMPRESSOR ROTOR BLADE RETAINERS	Package A	CLN/INSP	CLEANING AND INSPECTION		385.00	SR Technics Switzerland
72531	9523M12G01	EASA;FAA;CAAC;ANAC			72-31-09		Package B	INSP-001	BLENDING		310.00	SR Technics Switzerland
73189	338-051-401-0	EASA;FAA;CAAC;ANAC	38	21	72-23-21	FAN FRAME ASSEMBLY - TUBE JUNCTION BOX PLATE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		520.00	SR Technics Switzerland
73189	338-051-410-0	EASA;FAA;CAAC;ANAC			72-23-21		Package B	001	REPLACE THE DEFECTIVE SELF-LOCKING INSERT ON THE JUNCTION PLATE ASSEMBLY		895.00	SR Technics Switzerland
73189	338-051-411-0	EASA;FAA;CAAC;ANAC			72-23-21		Package E	004	REPLACEMENT OF THE RIVETED NUTS ON THE JUNCTION PLATE ASSEMBLY		510.00	SR Technics Switzerland
73189					72-23-21		Package U	020	REPLACEMENT OF THE DRY FILM LUBRICANT COATING ON THE JUNCTION PLATE		2895.00	SR Technics Switzerland
73189					72-23-21		Package X	023	REPLACEMENT OF BONDED SILICONE GASKET ON THE JUNCTION PLATE		2645.00	SR Technics Switzerland
73190	338-020-703-0	EASA;FAA;CAAC;ANAC	49	21	72-23-21	FAN FRAME ASSEMBLY - TUBE JUNCTION BOX ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		520.00	SR Technics Switzerland
73190	338-020-704-0	EASA;FAA;CAAC;ANAC			72-23-21		Package C	002	REPLACEMENT OF CRIMPED SELF-LOCKING INSERT ON THE JUNCTION BOX		740.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
73190	338-020-705-0	EASA;FAA;CAAC;ANAC			72-23-21		Package G	006	REPLACEMENT OF THE BONDED SILICONE ELASTOMER GASKETS ON THE TUBE BUNDLE JUNCTION BOX		585.00	SR Technics Switzerland
73190	338-020-706-0	EASA;FAA;CAAC;ANAC			72-23-21		Package N	013	REPLACEMENT OF LATERAL BRACKET PLATE ON THE JUNCTION BOX		1495.00	SR Technics Switzerland
73190	338-020-707-0	EASA;FAA;CAAC;ANAC			72-23-21		Package O	014	REPAIR OF CRACKS ON BOX		1500.00	SR Technics Switzerland
73190	338-020-708-0	EASA;FAA;CAAC;ANAC			72-23-21		Package P	15-81030	REPLACEMENT ELASTOMER G		685.00	SR Technics Switzerland
73190					72-23-21		Package Q	15-81185	REPLACEMENT OF THE DEFECTIVE RIVETED NUTS		685.00	SR Technics Switzerland
73190					72-23-21		Package SB00	72-0845	REPLACEMENT OF STIFFENER		365.00	SR Technics Switzerland
73191	338-020-603-0	EASA;FAA;CAAC;ANAC	30	21	72-23-21	FAN FRAME ASSEMBLY - TUBE JUNCTION COVER ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		520.00	SR Technics Switzerland
73191	338-020-604-0	EASA;FAA;CAAC;ANAC			72-23-21		Package AN	015	REPAIR OF CRACKS ON COVER		690.00	SR Technics Switzerland
125452	215788	EASA;FAA;ANAC	20	21	73-11-14	FUEL PUMP - RING SEAL ROTATING	Package B	002	LAP ROTATING SEAL RING		700.00	SR Technics Switzerland
135024	238-0230-15	EASA;FAA;CAAC;ANAC	25	21	71-22-07	AFT ENGINE MOUNT - ASSY	Package C	CLN/INSP	PREINSPECTION OF AFT ENGINE MOUNT ASSEMBLY	IN CONJUNCTION WITH PACKAGE LI	2500.00	SR Technics Switzerland
135024	238M0230-15	EASA;FAA;CAAC;ANAC			71-22-07		Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIEC EXAMPLE: SHEAR PIN REPLACEMENT		1030.00	SR Technics Switzerland
135024	642-2300-11	EASA;FAA;CAAC;ANAC;CAA UK			71-22-07		Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIEC EXAMPLE: ONE LINK REPLACEMENT		1470.00	SR Technics Switzerland
135024	642-2300-3	EASA;FAA;CAAC;ANAC			71-22-07		Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY. EXCLUDED PIEC EXAMPLE: BEAM REPLACEMENT		2665.00	SR Technics Switzerland
135024					71-22-07		Package G	OVERHAUL	OVERHAUL	DISASSEMBLY, CLEANING, INSPECT	2950.00	SR Technics Switzerland
135024					71-22-07		Package SB00	RA32171-11	REPLACEMENT OF ENGINE MOUNT BEARINGS	IN CONJUNCTION WITH PACKAGE H	980.00	SR Technics Switzerland
135024					71-22-07		Package SB01	A320-RSA-CFM56-	AFT ENGINE MOUNT LINK NUT TORQUE CHECK	IN CONJUNCTION WITH PACKAGE LI	1170.00	SR Technics Switzerland
135024					71-22-07		Package SB02	216639	AFT MOUNT LINK, INSTALL NEW RET PLATE BOLTS	IN CONJUNCTION WITH PACKAGE LI	685.00	SR Technics Switzerland
135024					71-22-07		Package SB03	RA32071-115	AFT ENGINE MOUNT NUTS LOOSENING	IN CONJUNCTION WITH PACKAGE LI	1170.00	SR Technics Switzerland
135024					71-22-07		Package SB05	RA32071-146	INSPECTION OF AFT ENGINE MOUNT RETAINER	N CONJUNCTION WITH PACKAGE LI	1030.00	SR Technics Switzerland
135024					71-22-07		Package SB06	RA32071-160	REPETITIVE INSPECTION OF AFT ENGINE MOUNT INNER RETAINER	N CONJUNCTION WITH PACKAGE LI	1080.00	SR Technics Switzerland
135024					71-22-07		Package SB07	RA32071-164	INTRODUCTION OF AN IMPROVED AFT ENGINE MOUNT RETAINER AS N CONJUNCTION WITH PACKAGE LI		760.00	SR Technics Switzerland
135024					71-22-07		Package SB08	RA32071-165	INSPECTION OF AFT ENGINE MOUNT INNER RETAINER	N CONJUNCTION WITH PACKAGE LI	1030.00	SR Technics Switzerland
135024					71-22-07		Package SB09	RA32071-160	REPETITIVE INSPECTION OF AFT ENGINE MOUNT INNER RETAINER	N CONJUNCTION WITH PACKAGE LI	510.00	SR Technics Switzerland
135024					71-22-07		Package SB10	RA32071-164	INTRODUCTION OF AN IMPROVED AFT ENGINE MOUNT RETAINER AS N CONJUNCTION WITH PACKAGE LI		575.00	SR Technics Switzerland
135025	238-0401-501	EASA;FAA;CAAC;ANAC	28	35	78-11-05	EXHAUST - NOZZLE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		4145.00	SR Technics Switzerland
135025	642-4001-501	EASA;FAA;CAAC;ANAC			78-11-05		Package B	001	DISASSEMBLY/ASSEMBLY OF THE NOZZLE		9065.00	SR Technics Switzerland
135025	642-4612-501	EASA;FAA;CAAC;ANAC			78-11-05		Package C	002	REPLACEMENT OF DAMAGED PYLON SEAL ASSEMBLY	ASSEMBLED CONDITION	2725.00	SR Technics Switzerland
135025					78-11-05		Package D	003	NOZZLE SKIN REPAIR		8940.00	SR Technics Switzerland
135025					78-11-05		Package K	010	PATCH REPAIR		9420.00	SR Technics Switzerland
135025					78-11-05		Package L	011	EXHAUST NOZZLE WEAR PROTECTION	ASSEMBLED CONDITION	1500.00	SR Technics Switzerland
135025					78-11-05		Package M	012	6 O'CLOCK EXTERNAL PATCH	ASSEMBLED CONDITION	3700.00	SR Technics Switzerland
135131	1324M94P03	EASA;FAA;CAAC;ANAC	17	21	73-21-77	FUEL - HPTCC THERMOCOUPLE	Package B	TEST	BENCH TEST	READJUSTMENT AND TESTING	910.00	SR Technics Switzerland
135131	8TC19AAH1	EASA;FAA;CAAC;ANAC			73-21-77		Package C	TEST	PRE TEST AND TROUBLE SHOOTING	IN CONJUNCTION WITH PACKAGE R	155.00	SR Technics Switzerland
135147	642-2000-13	EASA;FAA;CAAC;ANAC;CAA I	26	21	71-21-08	FWD ENGINE MOUNT - ASSY	Package A	CLN/INSP	PREINSPECTION OF FWD ENGINE MOUNT ASSEMBLY	IN CONJUNCTION WITH PACKAGE LI	2725.00	SR Technics Switzerland
135147	642-2000-25	EASA;FAA;CAAC;ANAC;CAA UK			71-21-08		Package D	LIGHT	EXAMPLE: SHEAR PIN REPLACEMENT		920.00	SR Technics Switzerland
135147	642-2000-9	EASA;FAA;CAAC;ANAC			71-21-08		Package E	MEDIUM	EXAMPLE: CROSSBEAM ASSY REPL		1955.00	SR Technics Switzerland
135147	642M2000-501	EASA;FAA;CAAC;ANAC;CAA UK			71-21-08		Package F	HEAVY	EXAMPLE: BEAM ASSY REPLACEMENT		2990.00	SR Technics Switzerland
135147	642M2000-503	EASA;FAA;CAAC;ANAC;CAA UK			71-21-08		Package G	OVERHAUL	DISASSEMBLY, CLEANING, INSPECT		4150.00	SR Technics Switzerland
135147					71-21-08		Package SB00		RA32071-159/EASA AD 2017-0132		335.00	SR Technics Switzerland
135174	QEC BOX A319/A320/A32	EASA;FAA;ANAC	3	21	71-2X-XX	CFM56-5B QEC BOX MISCELLANEOUS PARTS	Package A	CLN/INSP	CLEANING & INSPECTION		795.00	SR Technics Switzerland
135174					71-2X-XX		Package B		OVERHAUL		1010.00	SR Technics Switzerland
138950	1559M27G01	EASA;FAA;CAAC;ANAC	11	28	72-32-05	CFM-56 SEAL-STATIONARY ASSY STG 4-5	Package A		BASIC REPAIR	STG 4/5	110.00	SRTAS
138950	1559M27G02	EASA;FAA;CAAC;ANAC			72-32-05		Package A	CLN/INSP	CLEANING 001 AND INSPECTION 001		110.00	SRTAS
138950	1559M27G06	EASA;FAA;CAAC;ANAC			72-32-05		Package B		FULL REPAIR	STG 4/5	430.00	SRTAS
138950					72-32-05		Package B	2	HONEYCOMB REPLACEMENT		430.00	SRTAS
138952	1559M27G03	EASA;FAA;CAAC;ANAC	11	28	72-33-03	CFM56 COMPR REAR STAT SEAL STG.6-8	Package A		BASIC REPAIR	STG 6	145.00	SRTAS
138952	1559M27G04	EASA;FAA;CAAC;ANAC			72-33-03		Package A	CLN/INSP	CLEANING 001 AND INSPECTION 001		145.00	SRTAS
138952					72-33-03		Package B		FULL REPAIR	STG 6	380.00	SRTAS

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
138952					72-33-03		Package B	1	HONEYCOMB REPLACEMENT		380.00	SRTAS
138952					72-33-03		Package D		FULL REPAIR	STG 7	380.00	SRTAS
138952					72-33-03		Package D	1	HONEYCOMB REPLACEMENT		380.00	SRTAS
138952					72-33-03		Package F		FULL REPAIR	STG 8	380.00	SRTAS
138952					72-33-03		Package F	1	HONEYCOMB REPLACEMENT		380.00	SRTAS
138955	1275M27P04	EASA;FAA;CAAC;ANAC	17	28	72-42-02	COMBUSTION CHAMBER - PRIMARY SWIRL NOZZLE	Package A	CLN/INSP	CLEANING & INSPECTION		60.00	SR Technics Switzerland
138955					72-42-02		Package C	02	PRIMARY SWIRL NOZZLE REPAIR		185.00	SR Technics Switzerland
138955					72-42-02		Package D	03	WELD ANTI-ROTATION TANG		130.00	SR Technics Switzerland
138977	9972M46G05	EASA;FAA;CAAC;ANAC	24	28	72-61-05	INLET GEARBOX & NO.3 BEARING - BEARING NO.3 LOCKING N	Package A	CLN/INSP	CLEANING AND INSPECTION		1050.00	SR Technics Switzerland
138977					72-61-05		Package C	002	REPAIR OF DAMAGED WRENCH SLOTS		1100.00	SR Technics Switzerland
138977					72-61-05		Package D	003	REPLACEMENT OF FIBER WASHER		1120.00	SR Technics Switzerland
138977					72-61-05		Package E	004	REPAIR 004 - REPAIR OF 4.6875-12 OR 5.300-16 THREADS		895.00	SR Technics Switzerland
138977					72-61-05		Package F	005	REMOVAL AND APPLICATION OF DRY FILM LUBRICANT		795.00	SR Technics Switzerland
138977					72-61-05		Package G	006	REPAIR OF GALLING ON DIA B		1845.00	SR Technics Switzerland
138977					72-61-05		Package H	007	MACHINING REPAIR OF DIAMETER C		1420.00	SR Technics Switzerland
139018	305-145-401-0	EASA;FAA;CAAC;ANAC	18	28	72-63-11	ACCESSORY GEARBOX - HANDCRANKING DRIVE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		370.00	SR Technics Switzerland
139054	9992M86G07	EASA;FAA;CAAC;ANAC	29	28	72-32-20	COMPRESSOR FRONT STATOR - PLUG ASSY-BORESCOPE	Package A	CLN/INSP	CLEANING AND INSPECTION		380.00	SR Technics Switzerland
139054	9992M86G08	EASA;FAA;CAAC;ANAC			72-32-20		Package B	001	REPLACEMENT OF DAMAGED PARTS ON THE STAGE 6-8 BORESCOPE PLUG ASSEMBLIES		570.00	SR Technics Switzerland
139334	1319M17P01	EASA;FAA;CAAC;ANAC	37	28	72-52-10	HIGH PRESSURE TURBINE ROTOR - REAR ROTATING SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		630.00	SR Technics Switzerland
139334	1319M17P02	EASA;FAA;CAAC;ANAC			72-52-10		Package A	INSP-001	ROTATION SEAL SERRATIONS DEFFECT REMOVAL		630.00	SR Technics Switzerland
139334					72-52-10		Package C	001	REPLACEMENT OF SEAL TEETH COATING		4370.00	SR Technics Switzerland
139334					72-52-10		Package F	004	REPAIR OF ILLEGIBLE PART MARKINGS		350.00	SR Technics Switzerland
139334					72-52-10		Package SB00	72-0171	CONVERT FROM CFM56-5B/2 TO CFM56-5B/2P	ONLY FPI LINE B DIAMETER E	460.00	SR Technics Switzerland
139335	1360M70G01	EASA;FAA;CAAC;ANAC	24	28	72-61-01	INLET GEARBOX & NO.3 BEARING - HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		560.00	SR Technics Switzerland
139335	1360M70G02	EASA;FAA;ANAC			72-61-01		Package B	001	REPLACEMENT OF THE OIL NOZZLES AND PLUGS		1280.00	SR Technics Switzerland
139335					72-61-01		Package C	002	REPLACEMENT OF DAMAGED STUDS		980.00	SR Technics Switzerland
139335					72-61-01		Package E	004	DIMENSIONAL RESTORATION OF SURFACE A AND DIAMETER C FOR SURFACE A		1660.00	SR Technics Switzerland
139335					72-61-01		Package F	004	DIMENSIONAL RESTORATION OF SURFACE A AND DIAMETER C FOR DIAMETER C		3495.00	SR Technics Switzerland
139335					72-61-01		Package H	007	REPAIR OF THE LOCATING HOLE AL		3255.00	SR Technics Switzerland
139335					72-61-01		Package SB01	SB 72-1097	IGB BOLTED JOINT IMPROVEMENT AND REWORK		985.00	SR Technics Switzerland
139336	1361M13P01	EASA;FAA;CAAC;ANAC	27	28	72-61-04	INLET GEARBOX & NO.3 BEARING - ROTATING SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		890.00	SR Technics Switzerland
139336					72-61-04		Package A	INSP-001	HAND LAP SEAL SURFACE D		890.00	SR Technics Switzerland
139336					72-61-04		Package B	001	REMOVAL AND APPLICATION OF DRY FILM LUBRICANT		1275.00	SR Technics Switzerland
139339	1475M30G03	EASA;FAA;CAAC;ANAC	42	28	72-32-06	COMPRESSOR FRONT STATOR - SHROUD, INLET GUIDE VANE	Package A	CLN/INSP	CLEANING AND INSPECTION		840.00	SR Technics Switzerland
139339					72-32-06		Package B	001	REPLACEMENT OF THE ABRADABLE SEAL ON THE HPC FRONT STATOR IGV SHROUD		3635.00	SR Technics Switzerland
139339					72-32-06		Package C	002	TRUNNION HOLE WEAR REPAIR	SINGLE	3255.00	SR Technics Switzerland
139339					72-32-06		Package D	INSP-001	REMOVE HIGH METAL		190.00	SR Technics Switzerland
139339					72-32-06		Package E	002	2ND TRUNNION HOLE WEAR REPAIR		2965.00	SR Technics Switzerland
139339					72-32-06		Package G	002	TRUNNION HOLE WEAR REPAIR	ALL	6180.00	SR Technics Switzerland
139339					72-32-06		Package SB00	72-0107	COMPRESSOR STATOR IGV SHROUD - REIDENTIFICATION		465.00	SR Technics Switzerland
139341	1498M40P03	EASA;FAA;CAAC;ANAC	39	28	72-52-04	HIGH PRESSURE TURBINE ROTOR - FRONT SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1485.00	SR Technics Switzerland
139341	1498M40P05	EASA;FAA;CAAC;ANAC			72-52-04		Package A	INSP	MEASUREMENT SHAFT CONCENTRICITY DIA B AND C	TECHNICAL INSTRUCTION	1485.00	SR Technics Switzerland
139341	1498M40P06	EASA;FAA;CAAC;ANAC			72-52-04		Package B	INSP-001	REMOVE HIGH METAL		455.00	SR Technics Switzerland
139341	1873M73P01	EASA;FAA;CAAC;ANAC			72-52-04		Package D	002	THERMAL SPRAY RABBET REPAIR		4315.00	SR Technics Switzerland
139341	2048M21P03	EASA;FAA;CAAC;ANAC			72-52-04		Package E	003	THERMAL SPRAY RABBET REPAIR		3210.00	SR Technics Switzerland
139341					72-52-04		Package F	005	MACHINING REPAIR OF RIB CORNER FRETTING		1155.00	SR Technics Switzerland
139341					72-52-04		Package SB00	72-0891	REPLACE FWD DAMPER SLEEVE		1200.00	SR Technics Switzerland
139342	1498M43P04	EASA;FAA;CAAC;ANAC	59	28	72-52-02	HIGH PRESSURE TURBINE ROTOR - DISK	Package A	CLN/INSP	CLEANING AND INSPECTION		4405.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139342	1498M43P05	EASA;FAA;CAAC;ANAC			72-52-02		Package B	INSP-001	BLENDING OF BORE EDGE RADIUS		3335.00	SR Technics Switzerland
139342	1498M43P06	EASA;FAA;CAAC;ANAC			72-52-02		Package B	INSP-001	BLENDING OF OD FWD AND AFT FACES		3335.00	SR Technics Switzerland
139342	1498M43P07	EASA;FAA;CAAC;ANAC			72-52-02		Package B	INSP-001	BLENDING OF WEB AND HUB FACES		3335.00	SR Technics Switzerland
139342	2410M49P01	EASA;FAA;CAAC;ANAC			72-52-02		Package B	INSP-001	REMOVAL OF HIGH METAL		3335.00	SR Technics Switzerland
139342	2410M49P02	EASA;FAA;CAAC;ANAC			72-52-02		Package D	1	REPLACEMENT OF THE DISK CLINCH NUTS		3370.00	SR Technics Switzerland
139342					72-52-02		Package F	5	THERMAL SPRAY REPAIR OF THE FORWARD FLANGE RABBET		3355.00	SR Technics Switzerland
139342					72-52-02		Package G	INSP-002	BLENDING WEAR BLADE RETAINER		1045.00	SR Technics Switzerland
139342					72-52-02		Package G	INSP-002	REMOVAL OF HIGH METAL		1045.00	SR Technics Switzerland
139342					72-52-02		Package I	8	SHOTPEENING REPAIR OF SURFACE		895.00	SR Technics Switzerland
139342					72-52-02		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) AND DISK BORE EDDY CURRENT INSPECTION (ECI)		4010.00	SR Technics Switzerland
139342					72-52-02		Package SB01	72-0223	HPT ROTOR DISK REWORK FROM 1498M43P04 TO 1498M43P05		985.00	SR Technics Switzerland
139342					72-52-02		Package SB02	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CF AND CFM56-5B6/2 TO CFM56-5B6/2P		920.00	SR Technics Switzerland
139342					72-52-02		Package SB03	72-1072	REPLACEMENT OF SUSPECT HPT ROTOR DISK	PN 1498M43P05	495.00	SR Technics Switzerland
139349	1523M35P01	EASA;FAA;CAAC;ANAC	34	28	72-31-08	COMPRESSOR ROTOR - REAR ROTATING AIR SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		1465.00	SR Technics Switzerland
139349	2116M25P01	EASA;FAA;CAAC;ANAC			72-31-08		Package B	INSP-001	REMOVAL OF HIGH METAL BY BLENDING		1180.00	SR Technics Switzerland
139349					72-31-08		Package C	001	REPAIR OF THE SEAL TEETH COATING		4165.00	SR Technics Switzerland
139349					72-31-08		Package D	003	REPAIR THE FORWARD AND AFT RABBET	DIAMETER B+C	3940.00	SR Technics Switzerland
139349					72-31-08		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	670.00	SR Technics Switzerland
139350	1523M37P01	EASA;FAA;CAAC;ANAC	39	28	72-41-05	COMBUSTION CASE - HPT NOZZLE SUPPORT BOLT SHIELD	Package A	CLN/INSP	CLEANING AND INSPECTION		820.00	SR Technics Switzerland
139350	1523M37P02	EASA;FAA;CAAC;ANAC			72-41-05		Package B	001	WELD REPAIR OF BOLT HOLE EROSION		2060.00	SR Technics Switzerland
139350					72-41-05		Package SB01	72-0575	REWORK OF THE BOLT SHIELD OUTSIDE DIAMETER		900.00	SR Technics Switzerland
139353	1523M43P01	EASA;FAA;CAAC;ANAC	30	28	72-51-11	HIGH PRESSURE TURBINE NOZZLE - SUPPORT NUT SHIELD	Package A	CLN/INSP	CLEANING AND INSPECTION		550.00	SR Technics Switzerland
139353	2071M15P01	EASA;FAA;CAAC;ANAC			72-51-11		Package B	001	WELD REPAIR OF BOLT HOLE EROSION		4185.00	SR Technics Switzerland
139353					72-51-11		Package SB00	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CF AND CFM56-5B6/2 TO CFM56-5B6/2P		245.00	SR Technics Switzerland
139354	1523M59G01	EASA;FAA;CAAC;ANAC	26	28	72-53-04	HPT SHROUD - SUPPORT HANGER	Package A	INSP-001	INSPECTION/CHECK		240.00	SRTAS
139354	1523M59G05	EASA;FAA;CAAC;ANAC			72-53-04		Package B		FULL REPAIR (Pre SB 72-0909/0962)		1940.00	SRTAS
139354	1808M61G01	EASA;FAA;CAAC;ANAC			72-53-04		Package B	008	STRAIGHT PIN REPLACEMENT		1940.00	SRTAS
139354	1808M61G02	EASA;FAA;CAAC;ANAC			72-53-04		Package B	009	PIN HOLE AND AXIAL CRACKS ON FORWARD INNER RAIL WELD REPAIR		1940.00	SRTAS
139354	1808M61G04	EASA;FAA;CAAC;ANAC			72-53-04		Package B	013	SEAL SLOT BREAKOUT WELD REPAIR		1940.00	SRTAS
139354	1808M61G05	EASA;FAA;CAAC;ANAC			72-53-04		Package B	014	REPAIR USING RBD	alternative to Repairs 002, 003, 005, 007	1940.00	SRTAS
139354	1808M61G06	EASA;FAA;CAAC;ANAC			72-53-04		Package B	015	AFT RAIL WELD REPAIR		1940.00	SRTAS
139354	1808M61G07	EASA;FAA;CAAC;ANAC			72-53-04		Package B	016	FORM REPAIR (CHECK SHAPE & TRUE UP)		1940.00	SRTAS
139354	1808M61G08	EASA;FAA;CAAC;ANAC			72-53-04		Package B	018	AFT RAIL WELD REPAIR		1940.00	SRTAS
139354	1808M61G09	EASA;FAA;CAAC;ANAC			72-53-04		Package B	INSP-001	INSPECTION/CHECK		1940.00	SRTAS
139354	1808M61G10	EASA;FAA;CAAC;ANAC			72-53-04		Package C		FULL REPAIR (Post SB 72-0909/0962)		2560.00	SRTAS
139354	1808M61G11	EASA;FAA;CAAC;ANAC			72-53-04		Package C	008	STRAIGHT PIN REPLACEMENT		2560.00	SRTAS
139354	1808M61G12	EASA;FAA;CAAC;ANAC			72-53-04		Package C	009	PIN HOLE AND AXIAL CRACKS ON FORWARD INNER RAIL WELD REPAIR		2560.00	SRTAS
139354	1893M42G01	EASA;FAA;CAAC;ANAC			72-53-04		Package C	013	SEAL SLOT BREAKOUT WELD REPAIR		2560.00	SRTAS
139354	1893M42G02	EASA;FAA;CAAC;ANAC			72-53-04		Package C	014	REPAIR UNDER CDR USING RBD	alternative to Repairs 002, 005, 007, 011	2560.00	SRTAS
139354	1893M42G03	EASA;FAA;CAAC;ANAC			72-53-04		Package C	015	AFT RAIL WELD REPAIR		2560.00	SRTAS
139354	1893M42G04	EASA;FAA;CAAC;ANAC			72-53-04		Package C	016	FORM REPAIR (CHECK SHAPE & TRUE UP)		2560.00	SRTAS
139354	1957M74G01	EASA;FAA;CAAC;ANAC			72-53-04		Package C	018	AFT RAIL WELD REPAIR		2560.00	SRTAS
139354	1957M74G02	EASA;FAA;CAAC;ANAC			72-53-04		Package D		ADDITIONAL WORKSCOPE		515.00	SRTAS
139354	1957M86G01	EASA;FAA;CAAC;ANAC			72-53-04		Package D	017	BRAZE REPAIR FOR WEAR ON HANGER RAILS		515.00	SRTAS
139354					72-53-04		Package E		ADDITIONAL WORKSCOPE	(WITH FULL REPAIR WORKSCOPE)	760.00	SRTAS
139354					72-53-04		Package E	72-0194	ENLARGE COOLING HOLES, INCREASE FORWARD LIP HEIGHT AND A 5B		760.00	SRTAS
139354					72-53-04		Package E	72-0217	ENLARGE COOLING HOLES, INCREASE FORWARD LIP HEIGHT AND A 5B		760.00	SRTAS
139354					72-53-04		Package F		ADDITIONAL WORKSCOPE	(WITH ANY OF THE PACKAGED WOF	870.00	SRTAS

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139354					72-53-04		Package F	72-0909	REWORK TO ADD AIR FILTER	5B	870.00	SRTAS
139354					72-53-04		Package H		ADDITIONAL WORKSCOPE		1265.00	SRTAS
139354					72-53-04		Package H	020	AIRFILTER REMOVAL AND REPLACEMENT	1893M42G03 / 1893M42G04 / 1808M6	1265.00	SRTAS
139354					72-53-04		Package I		ADDITIONAL WORKSCOPE		1015.00	SRTAS
139354					72-53-04		Package I	021	WELD OF THE PIN HOLE AND AXIAL AND RADIAL CRACK		1015.00	SRTAS
139381	301-475-207-6	EASA;FAA;CAAC;ANAC	35	28	72-22-14	NO.1 AND NO.2 BEARING SUPPORT - NO. 1 BEARING OIL BAFF	Package A	CLN/INSP	CLEANING AND INSPECTION		595.00	SR Technics Switzerland
139381					72-22-14		Package B	002	RESTORATION OF THE SHIMMING FUNCTION		4425.00	SR Technics Switzerland
139381					72-22-14		Package C	ASSEMBLY-001	BAFFLE THICKNESS GRINDING		845.00	SR Technics Switzerland
139382	301-539-211-0	EASA;FAA;CAAC;ANAC	34	28	72-22-03	NO.1 AND NO.2 BEARING SUPPORT - NO. 2 BEARING SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		870.00	SR Technics Switzerland
139382					72-22-03		Package B	001	REPLACE OF THE SWAGED SELF-LOCKING INSERTS		595.00	SR Technics Switzerland
139388	305-135-904-0	EASA;FAA;CAAC;ANAC	41	28	72-63-01	ACCESSORY GEARBOX - HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		1355.00	SR Technics Switzerland
139388	305-135-905-0	EASA;FAA;CAAC;ANAC			72-63-01		Package C	002	REPLACEMENT OF THE KEY-LOCKED STUDS		1085.00	SR Technics Switzerland
139388	340-046-602-0	EASA;FAA;CAAC;ANAC			72-63-01		Package D	003	REPLACEMENT OF THE KEY-LOCKED SELF-LOCKING INSERTS		945.00	SR Technics Switzerland
139388	340-046-603-0	EASA;FAA;CAAC;ANAC			72-63-01		Package F	006	REPLACEMENT OF THE RING-LOCKED INSERTS		930.00	SR Technics Switzerland
139388	340-046-604-0	EASA;FAA;CAAC;ANAC			72-63-01		Package G	005	BUSHING HANDCRANKING LINE DI		3135.00	SR Technics Switzerland
139388	340-046-605-0	EASA;FAA;CAAC;ANAC			72-63-01		Package H	007	REPLACEMENT OF THE AXIAL OIL NOZZLES		1590.00	SR Technics Switzerland
139388					72-63-01		Package I	008	SPOT TOUCH-UP OF THE NON-MACHINED SURFACES BY OXIDE FILM COATING		500.00	SR Technics Switzerland
139388					72-63-01		Package N	013	MACHINING OF BEARING SEATING SURFACES		9915.00	SR Technics Switzerland
139388					72-63-01		Package O	014	BLEND REPAIR OF MOUNT CLEVIS		560.00	SR Technics Switzerland
139388					72-63-01		Package P	015	BLENDING HAND CRANKING LOCATION		365.00	SR Technics Switzerland
139389	305-136-503-0	EASA;FAA;CAAC;ANAC	31	28	72-62-01	TRANSFER GEARBOX - HOUSING	Package A	CLN/INSP	CLEANING AND INSPECTION		1115.00	SR Technics Switzerland
139389	335-300-403-0	EASA;FAA;CAAC;ANAC			72-62-01		Package AB	007	REPAIR OF DIAMETERS D ON THE TGB HOUSING BY PLASMA SPRAYING		2140.00	SR Technics Switzerland
139389	338-089-601-0	EASA;FAA;CAAC;ANAC;CAA UK			72-62-01		Package B	001	REPLACEMENT OF THE SELF-LOCKING INSERTS		810.00	SR Technics Switzerland
139389	340-050-704-0	EASA;FAA;CAAC;ANAC			72-62-01		Package C	002	REPLACEMENT OF THE KEY-LOCKED STUDS		910.00	SR Technics Switzerland
139389	340-050-705-0	EASA;FAA;CAAC;ANAC			72-62-01		Package D	003	REPLACEMENT OF THE HEADLESS SHOULDER PINS		910.00	SR Technics Switzerland
139389					72-62-01		Package E	004	REPLACEMENT OF THE RING-LOCKED INSERTS		910.00	SR Technics Switzerland
139389					72-62-01		Package F	005	SPOT TOUCHUP OF THE NON-MACHINED SURFACES BY OXIDE FILM COATING		910.00	SR Technics Switzerland
139389					72-62-01		Package H	007	REPAIR OF DIAMETERS A ON THE TGB HOUSING BY PLASMA SPRAYING		2140.00	SR Technics Switzerland
139389					72-62-01		Package I	008	REPAIR OF SURFACES R ON THE TGB HOUSING BY PLASMA SPRAYING		2365.00	SR Technics Switzerland
139389					72-62-01		Package K	010	ID PLATE NAILS		840.00	SR Technics Switzerland
139389					72-62-01		Package L	011	REPAIR OF MACHINED SURFACES BY PLASMA SPRAYING		1195.00	SR Technics Switzerland
139389					72-62-01		Package N	013	BUSHING DIAMETER M OF TGB HOUSING		1745.00	SR Technics Switzerland
139389					72-62-01		Package R	007	REPAIR OF DIAMETERS C ON THE TGB HOUSING BY PLASMA SPRAYING		2140.00	SR Technics Switzerland
139389					72-62-01		Package S	008	REPAIR OF SURFACES S ON THE TGB HOUSING BY PLASMA SPRAYING		2365.00	SR Technics Switzerland
139389					72-62-01		Package SB00	72-0924	MARKING OF TGB ASSEMBLIES ON A SPECIFIC POPULATION OF ENGINES		290.00	SR Technics Switzerland
139400	305-138-602-0	EASA;FAA;CAAC;ANAC	19	28	72-63-17	ACCESSORY GEARBOX - HORIZONTAL DRIVE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1235.00	SR Technics Switzerland
139422	305-148-801-0	EASA;FAA;CAAC;ANAC	23	28	72-62-04	TRANSFER GEARBOX - HOUSING ASSY-HORIZONTAL BEVEL	Package A	CLN/INSP	CLEANING AND INSPECTION		290.00	SR Technics Switzerland
139422	335-305-000-0	EASA;FAA;CAAC;ANAC			72-62-04		Package B	001	REPLACEMENT OF KEY-LOCKED INSERTS		1570.00	SR Technics Switzerland
139422					72-62-04		Package C	002	REPLACEMENT OF JACKSCREW INSERTS		635.00	SR Technics Switzerland
139422					72-62-04		Package D	003	SPOT TOUCHUP OF NON-MACHINED SURFACES BY OXIDE FILM COATING		670.00	SR Technics Switzerland
139422					72-62-04		Package E	004	REPLACEMENT OF FLANGED BUSHINGS		725.00	SR Technics Switzerland
139422					72-62-04		Package F	005	REPLACEMENT OF FLANGED CENTERING BUSHINGS		640.00	SR Technics Switzerland
139422					72-62-04		Package H	007	MACHINING FLANGE		810.00	SR Technics Switzerland
139429	305-396-303-0	EASA;FAA;CAAC;ANAC	34	28	72-22-05	NO.1 AND NO.2 BEARING SUPPORT - FAN SHAFT ROTOR AIR/C	Package A	CLN/INSP	CLEANING AND INSPECTION		380.00	SR Technics Switzerland
139429	305-396-306-0	EASA;FAA;CAAC;ANAC			72-22-05		Package B	001	RECONDITIONING THE RABBIT DIAMETER WITH THE FAN SHAFT BY THERMAL SPRAYING		2725.00	SR Technics Switzerland
139430	305-408-301-0	EASA;FAA;CAAC;ANAC	45	21	72-55-10	LOW PRESSURE TURBINE SHAFT - CENTER VENT TUBE REAR	Package A	CLN/INSP	CLEANING AND INSPECTION		740.00	SR Technics Switzerland
139430	338-180-101-0	EASA;FAA;CAAC;ANAC			72-55-10		Package A	INSP-001	REMOVAL OF HIGH METAL/DAMAGED THREADST		740.00	SR Technics Switzerland
139430	338-180-401-0	EASA;FAA;CAAC;ANAC			72-55-10		Package B	001	REPLACEMENT OF ONE OR SEVERAL LOCATING PIN		980.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139430	340-170-401-0	EASA;FAA;CAAC;ANAC			72-55-10		Package C	002	REPAIR OF THE SLOTS BY WELD BUILDUP		3115.00	SR Technics Switzerland
139430	340-170-402-0	EASA;FAA;CAAC;ANAC			72-55-10		Package D	004	REPAIR OF THE INDEX HOLES BY WELD BUILD-UP		4695.00	SR Technics Switzerland
139430					72-55-10		Package I	008	RESHAPING SEAL TEETH		1080.00	SR Technics Switzerland
139431	335-070-301-6	EASA;FAA;CAAC;ANAC	21	28	72-00-03	ENGINE MODULES/ASSEMBLIES - LPT MAJOR MODULE - ADJU	Package B	ASSEMBLY-001	GRIND-ADJUST SLEEVE	FOR SHOP VISITS ONLY	1175.00	SR Technics Switzerland
139432	336-001-804-0	EASA;FAA;CAAC;ANAC;CAA I	51	28	72-54-03	LOW PRESSURE TURBINE - DISKS, STG 1-4	Package A	CLN/INSP	CLEANING AND INSPECTION		1180.00	SR Technics Switzerland
139432	336-001-909-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package B	INSP 001	BLENDING SURFACE		3190.00	SR Technics Switzerland
139432	336-002-006-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package C	INSP	INSPECTION OF THE DISKS (AFTER OVERTEMPERATURE AND/OR OV HARDNESS AND GROWTH CHECK		660.00	SR Technics Switzerland
139432	336-002-105-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-03		Package D	INSP 001	REMOVE HIGHMETAL ON WEB		1695.00	SR Technics Switzerland
139432	337-001-404-0	EASA;FAA;CAAC;ANAC			72-54-03		Package F	001	REPAIR OF STAGE 1 LPT DISKS FORWARD FLANGE BY MACHINIG		4100.00	SR Technics Switzerland
139432	337-001-605-0	EASA;FAA;CAAC;ANAC			72-54-03		Package G	001	REPAIR OF STAGE 2 LPT DISKS FORWARD FLANGE BY MACHINIG		5345.00	SR Technics Switzerland
139432	337-001-705-0	EASA;FAA;CAAC;ANAC			72-54-03		Package J	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 1	1955.00	SR Technics Switzerland
139432	337-001-802-0	EASA;FAA;CAAC;ANAC			72-54-03		Package K	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 2	1955.00	SR Technics Switzerland
139432	340-301-001-0	EASA;FAA;CAAC;ANAC			72-54-03		Package L	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 3	1955.00	SR Technics Switzerland
139432	340-301-101-0	EASA;FAA;CAAC;ANAC			72-54-03		Package M	003	BLENDING OF THE HUB ON THE LOW PRESSURE TURBINE	STAGE 4	1955.00	SR Technics Switzerland
139432	340-301-201-0	EASA;FAA;CAAC;ANAC			72-54-03		Package O	005	MACHINING OF MARKS ON FLANGES STG.1		8420.00	SR Technics Switzerland
139432	340-301-301-0	EASA;FAA;CAAC;ANAC			72-54-03		Package P	005	MACHINING OF MARKS ON FLANGES STG.2		8420.00	SR Technics Switzerland
139432					72-54-03		Package Q	005	MACHINING OF MARKS ON FLANGES STG.3		8420.00	SR Technics Switzerland
139432					72-54-03		Package R	005	MACHINING OF MARKS ON FLANGES STG.4		8420.00	SR Technics Switzerland
139432					72-54-03		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG1	IN CONJUNCTION WITH PACKAGE A	475.00	SR Technics Switzerland
139432					72-54-03		Package SB01	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG2	IN CONJUNCTION WITH PACKAGE A	475.00	SR Technics Switzerland
139432					72-54-03		Package SB02	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG3	IN CONJUNCTION WITH PACKAGE A	475.00	SR Technics Switzerland
139432					72-54-03		Package SB03	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI) STG4	IN CONJUNCTION WITH PACKAGE A	475.00	SR Technics Switzerland
139432					72-54-03		Package SB04	72-EO-521902	WORKSCOPE LPT OVERTEMP ANALYSE		135.00	SR Technics Switzerland
139432					72-54-03		Package SB05	72-0171	CONVERSION CFM56 ENG MODEL 5B1/2 TO 5B1/2P, 5B2/2 TO 5B2/2P, 5B4/2 TO 5B4/2P AND 5B6/2 TO 5B6/2P		350.00	SR Technics Switzerland
139432					72-54-03		Package T	006	RECONDITIONING BY PLASMA SPRAYING OF THE LPT ROTATING AIR STAGE 3		8420.00	SR Technics Switzerland
139443	336-013-101-0	EASA;FAA;CAAC;ANAC	24	28	72-54-17	LOW PRESSURE TURBINE - SEAL-ROTATING OIL FORWARD	Package A	CLN/INSP	CLEANING AND INSPECTION		880.00	SR Technics Switzerland
139443					72-54-17		Package B	001	REPAIR OF THE ALUMINUM-SILICIUM-POLYESTER ABRADABLE COATING		2665.00	SR Technics Switzerland
139443					72-54-17		Package C	002	LOCATING DIAMETER		2675.00	SR Technics Switzerland
139488	2423M30G01	EASA;FAA;CAAC;ANAC	32	28	72-23-30	FAN FRAME ASSEMBLY - DOWNSTREAM FAN CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		5195.00	SR Technics Switzerland
139488	2752M00G01	EASA;FAA;CAAC;ANAC			72-23-30		Package B	001	REPLACE THE HI-LITE BOLTS AND NUTS ON THE DOWNSTREAM FAN CASE ASSEMBLY		730.00	SR Technics Switzerland
139488	2752M00G02	EASA;FAA;CAAC;ANAC			72-23-30		Package C	002	REPLACEMENT OF THE SWAGED SELF-LOCKING INSERTS		870.00	SR Technics Switzerland
139488	2752M00G03	EASA;FAA;ANAC			72-23-30		Package E	004	SPOT TOUCH-UP OR FULL REPAIR OF THE SULFURIC ANODIZING		685.00	SR Technics Switzerland
139488	2752M00G04	EASA;FAA;ANAC			72-23-30		Package I	008	REPLACEMENT OF THE RIVETED SELF-LOCKING NUTS		1070.00	SR Technics Switzerland
139488	2752M00G05	EASA;FAA;CAAC;ANAC			72-23-30		Package K	010	BLEND REPAIR FOR CORROSION, NICKS, AND SCRATCHES		745.00	SR Technics Switzerland
139488	2752M00G06	EASA;FAA;ANAC			72-23-30		Package L	011	CORROSION REPAIR OF THE AFT FLANGE BOLT HOLES		5115.00	SR Technics Switzerland
139488	2752M00G07	EASA;FAA;ANAC			72-23-30		Package M	012	CORROSION REPAIR OF THE FORWARD FLANGE BOLT HOLES		3240.00	SR Technics Switzerland
139488	2752M00G08	EASA;FAA;CAAC;ANAC			72-23-30		Package N	013	CORROSION REPAIR ON B4 OUTER SURFACE OF FLANGES		9145.00	SR Technics Switzerland
139488	2752M00G09	EASA;FAA;ANAC			72-23-30		Package O	014	BOLTHOLES REAM/BUSHING REPAIR		4710.00	SR Technics Switzerland
139488	338-075-617-0	EASA;FAA;CAAC;ANAC			72-23-30		Package P	015	BLEND REPAIR OF THE OUTER DIA./FACES OF MID FLANGE	B5	1325.00	SR Technics Switzerland
139488	338-075-620-0	EASA;FAA;CAAC;ANAC			72-23-30		Package Q	047	MODULE LEVEL BLENDING		3420.00	SR Technics Switzerland
139488	338-075-621-0	EASA;FAA;CAAC;ANAC			72-23-30		Package R	016	BLEND REPAIR OF THE OUTER DIA./FACES OF MID FLANGE	B4	1470.00	SR Technics Switzerland
139488	338-075-622-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-30		Package S	048	MODULE LEVEL BOLTHOLE REPAIR		2675.00	SR Technics Switzerland
139488	338-075-625-0	EASA;FAA;CAAC;ANAC			72-23-30		Package SB00	72-0629	REWORK OF THE DOWNSTREAM FAN CASE HOLES 95 AND 96 OF THE FLANGE B4		490.00	SR Technics Switzerland
139488	338-075-626-0	EASA;FAA;CAAC;ANAC			72-23-30		Package SB01	72-1063	INSTALL REINFORCEMENT RING ON FLANGE B5		3550.00	SR Technics Switzerland
139488	338-075-627-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-30		Package T	051	B4/B6 FLANGE INNER SURFACE BLEND	72-00-23	1170.00	SR Technics Switzerland
139488	338-075-628-0	EASA;FAA;CAAC;ANAC			72-23-30		Package U	020	BUSHING REPAIR OF THE ELONGATED BOLTHOLES ON THE B5 FLANGE		2650.00	SR Technics Switzerland
139505	338-086-601-0	EASA;FAA;CAAC;ANAC	18	28	72-56-10	LOW PRESSURE TURBINE REAR FRAME - AIR HEATER COVER	Package A	CLN/INSP	CLEANING AND INSPECTION		890.00	SR Technics Switzerland
139505					72-56-10		Package B	001	REPLACE THE DEFECTIVE CRIMPED SELF-LOCKING NUTS ON THE AIR HEATER COVER		1115.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139515	9542M67P01	EASA;FAA;CAAC;ANAC	19	28	72-61-02	INLET GEARBOX & NO.3 BEARING - GEAR-BEVEL HORIZOTAL	Package A	CLN/INSP	CLEANING AND INSPECTION		1130.00	SR Technics Switzerland
139515					72-61-02		Package B	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA E	3040.00	SR Technics Switzerland
139515					72-61-02		Package C	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA F	3040.00	SR Technics Switzerland
139515					72-61-02		Package D	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA G	3040.00	SR Technics Switzerland
139515					72-61-02		Package E	001	REPAIR OF BEARING JOURNAL AND PILOT DIAMETERS	DIA J	3040.00	SR Technics Switzerland
139515					72-61-02		Package F	002	REPAIR OF THE LOCKING PIN HOLES	DIA H	1085.00	SR Technics Switzerland
139517	9972M31G03	EASA;FAA;CAAC;ANAC	26	28	72-61-03	INLET GEARBOX & NO.3 BEARING - RADIAL BEVEL GEAR	Package A	CLN/INSP	CLEANING AND INSPECTION		830.00	SR Technics Switzerland
139517					72-61-03		Package B	001	REPLACEMENT OF OIL SEAL		1305.00	SR Technics Switzerland
139520	9972M49G02	EASA;FAA;CAAC;ANAC	26	28	72-61-07	INLET GEARBOX & NO.3 BEARING - PULLER RING	Package A	CLN/INSP	CLEANING AND INSPECTION		1060.00	SR Technics Switzerland
139520					72-61-07		Package B	001	REPLACEMENT OF FIBER WASHER		1120.00	SR Technics Switzerland
139530	238-0210-505	EASA;FAA;CAAC;ANAC	28	21	71-21-08	FWD ENGINE MOUNT - LINK ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		1445.00	SR Technics Switzerland
139530	238-0210-507	EASA;FAA;CAAC;ANAC			71-21-08		Package D	003	REPLACE BEARING IN FORWARD ENGINE MOUNT LINK ASSEMBLY		1470.00	SR Technics Switzerland
139530	238-0210-509	EASA;FAA;CAAC;ANAC			71-21-08		Package E	004	BLEND REPAIR FOR MINOR DAMAGE - FORWARD MOUNT THRUST LINKS		805.00	SR Technics Switzerland
139530					71-21-08		Package F	005	PART NUMBER AND SERIAL NUMBER REPAIR		160.00	SR Technics Switzerland
139531	642-2002-503	EASA;FAA;CAAC;ANAC	30	21	71-21-08	FWD ENGINE MOUNT - CROSSBEAM ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		1210.00	SR Technics Switzerland
139531					71-21-08		Package O	014	BLEND REPAIR FOR MINOR DAMAGE-FORWARD ENGINE MOUNT CROSSBEAM		805.00	SR Technics Switzerland
139531					71-21-08		Package Q	016	REPLACE BUSHINGS IN FORWARD ENGINE MOUNT	CENTER BUSHING	2000.00	SR Technics Switzerland
139531					71-21-08		Package Q	016	REPLACE BUSHINGS IN FORWARD ENGINE MOUNT	LEFT LUG BUSHING	2000.00	SR Technics Switzerland
139531					71-21-08		Package Q	016	REPLACE BUSHINGS IN FORWARD ENGINE MOUNT	RIGHT LUG BUSHING	2000.00	SR Technics Switzerland
139531					71-21-08		Package R	017	FORWARD ENGINE MOUNT CROSSBEAM INNER CENTER SURFACE WEAR DAMAGE REPAIR		2265.00	SR Technics Switzerland
139532	642-2006-501	EASA;FAA;CAAC;ANAC	35	21	71-21-08	FWD ENGINE MOUNT - BEAM ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		1250.00	SR Technics Switzerland
139532	642-2006-503	EASA;FAA;CAAC;ANAC			71-21-08		Package B	ASSEMBLY-1	REPLACEMENT OF FASTENER SETS ON FWD BEAM		530.00	SR Technics Switzerland
139532	642M2000-1	EASA;FAA;CAAC;ANAC			71-21-08		Package F	005	PART NUMBER AND SERIAL NUMBER REPAIR		365.00	SR Technics Switzerland
139532					71-21-08		Package K	010	BLEND OF SNOOT DIAMETER - FORWARD ENGINE MOUNT BEAM		1140.00	SR Technics Switzerland
139532					71-21-08		Package L	011	REPLACE AFT BUSHING IN FORWARD MAIN BEAM		1835.00	SR Technics Switzerland
139532					71-21-08		Package N	013	BLEND OF SURFADE DAMAGE ON FORWARD ENGINE MOUNT BEAM		790.00	SR Technics Switzerland
139532					71-21-08		Package SB00	RA 32071-159	BEAM SNOOT INSP. AND REWORK		1345.00	SR Technics Switzerland
139535	238-0234-505	EASA;FAA;CAAC;ANAC	30	21	71-22-07	AFT ENGINE MOUNT - LINK ASSEMBLY	Package A	ASSEMBLY-1	REPLACEMENT OF LINK ASSEMBLY FASTENERS		1325.00	SR Technics Switzerland
139535	238-0234-507	EASA;FAA;CAAC;ANAC			71-22-07		Package A	CLN/INSP	CLEANING AND INSPECTION		1325.00	SR Technics Switzerland
139535	642-2302-501	EASA;FAA;CAAC;ANAC			71-22-07		Package C	002	REPLACE BEARING IN AFT ENGINE MOUNT LINK ASSEMBLY		1195.00	SR Technics Switzerland
139535	642-2302-503	EASA;FAA;CAAC;ANAC			71-22-07		Package D	003	REPLACE BUSHINGS IN LINK ASSEMBLY		685.00	SR Technics Switzerland
139535					71-22-07		Package F	005	BLEND REPAIR FOR MINOR DAMAGE - AFT MOUNT LINKS		390.00	SR Technics Switzerland
139535					71-22-07		Package G	006	PART NUMBER AND SERIAL NUMBER REPAIR		365.00	SR Technics Switzerland
139535					71-22-07		Package SB00	RA32171-11	REPLACEMENT OF ENGINE MOUNT BEARINGS	LINK ASSEMBLY	1285.00	SR Technics Switzerland
139536	238-0231-505	EASA;FAA;CAAC;ANAC	29	21	71-22-07	AFT ENGINE MOUNT - BEAM	Package A	ASSEMBLY-1	REPLACEMENT OF BEAM ASSEMBLY FASTENERS		1210.00	SR Technics Switzerland
139536	642-2301-501	EASA;FAA;CAAC;ANAC			71-22-07		Package A	CLN/INSP	CLEANING AND INSPECTION		1210.00	SR Technics Switzerland
139536					71-22-07		Package B	001	REPLACE 1 EA BEARINGS IN AFT ENGINE MOUNT BEAM		1875.00	SR Technics Switzerland
139536					71-22-07		Package C	001	REPLACE 2 EA BEARINGS IN AFT ENGINE MOUNT BEAM		3865.00	SR Technics Switzerland
139536					71-22-07		Package D	001	REPLACE 3 EA BEARINGS IN AFT ENGINE MOUNT BEAM		5195.00	SR Technics Switzerland
139536					71-22-07		Package E	004	BLEND REPAIR FOR MINOR DAMAGE - AFT BEAM		685.00	SR Technics Switzerland
139536					71-22-07		Package G	006	PART NUMBER AND SERIAL NUMBER REPAIR		350.00	SR Technics Switzerland
139536					71-22-07		Package SB00	RA32171-11	REPLACEMENT OF ENGINE MOUNT BEARINGS		1285.00	SR Technics Switzerland
139541	1588M89G02	EASA;FAA;CAAC;ANAC	52	28	72-31-06	COMPRESSOR ROTOR - SPOOL STG 4-9	Package A	CLN/INSP	CLEANING AND INSPECTION		2660.00	SR Technics Switzerland
139541	1588M89G03	EASA;FAA;CAAC;ANAC			72-31-06		Package B	INSP-001	BLEND BORES STG. 4-9		1585.00	SR Technics Switzerland
139541	2048M20G03	EASA;FAA;CAAC;ANAC			72-31-06		Package B	INSP-001	REMOVE HIGH METAL		1585.00	SR Technics Switzerland
139541	2048M20G04	EASA;FAA;CAAC;ANAC			72-31-06		Package C	INSP-001	BLEND PLATFORM RAIL OUTER DIA.		1640.00	SR Technics Switzerland
139541	2048M20G05	EASA;FAA;ANAC;TCCA			72-31-06		Package D	INSP-001	BLEND FWD SIDE PLATFORM STG 4		1275.00	SR Technics Switzerland
139541					72-31-06		Package E	001	REPAIR OF THE SEAL TEETH COATINGS		7520.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139541					72-31-06		Package F	002	REPAIR OF ILLEGIBLE PART MARKINGS		185.00	SR Technics Switzerland
139541					72-31-06		Package G	003	REPAIR OF THE FORWARD AND AFT RABBIT DIAMETERS		4115.00	SR Technics Switzerland
139541					72-31-06		Package H	004	BLEND REPAIR OF BLADE PLATFORM RAILS		1925.00	SR Technics Switzerland
139541					72-31-06		Package I	006	REPAIR OF THE FORWARD AND AFT RABBIT DIAMETERS		5475.00	SR Technics Switzerland
139541					72-31-06		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	1850.00	SR Technics Switzerland
139576	2423M70G01	EASA;FAA;CAAC;ANAC;CAA I	36	28	72-23-04	FAN FRAME ASSEMBLY - OUTLET GUIDE VANE INNER SHROU	Package A	CLN/INSP	CLEANING AND INSPECTION		890.00	SR Technics Switzerland
139576	338-007-203-0	EASA;FAA;CAAC;ANAC			72-23-04		Package B	001	TOUCH UP OR TOTAL REPAIR OF SULVURIC ANODIZING		870.00	SR Technics Switzerland
139576	338-007-205-0	EASA;FAA;CAAC;ANAC			72-23-04		Package C	002	REPLACEMENT OF THE RIVETED SELF-LOCKING NUTS		860.00	SR Technics Switzerland
139576	340-002-408-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-04		Package E	004	CENTRAL RIVET HOLES ON FWD DIAMETAR		675.00	SR Technics Switzerland
139576					72-23-04		Package P	015-94525	HOLES STRUT NR.5 AND NR.6 CASE A		1385.00	SR Technics Switzerland
139966	338-077-904-0	EASA;FAA;CAAC;ANAC	32	28	72-23-01	FAN FRAME ASSEMBLY - FAN FRAME	Package A	CLN/INSP	CLEANING AND INSPECTION		3700.00	SR Technics Switzerland
139966	338-077-905-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AG	032	REPLACEMENT OF CRIMPED SELF-LOCKING NUTS		840.00	SR Technics Switzerland
139966	338-077-907-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AH	043	REPLACE OF RIVETS/FAIRING ON THE STRUTS		2015.00	SR Technics Switzerland
139966	338-077-910-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AL	70-43-31	REMOVAL OF ATTACHED PARTS		375.00	SR Technics Switzerland
139966	338-077-911-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AM	70-41-14	REMOVAL OF BROKEN BOLTS		555.00	SR Technics Switzerland
139966	338-077-912-0	EASA;FAA;CAAC;ANAC			72-23-01		Package AN	046	BLEND GROUND HANDLING PORTS		375.00	SR Technics Switzerland
139966	338-077-913-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-01		Package C	002	REPLACE THE RING-LOCKED STUDS		1205.00	SR Technics Switzerland
139966	338-077-914-0	EASA;FAA;CAAC;ANAC			72-23-01		Package D	003	REPLACEMENT OF SWAGED SELF-LOCKING INSERTS		700.00	SR Technics Switzerland
139966					72-23-01		Package SB00	72-0285	REWORK OF FAN FRAME WELDMENT TO INSTALL THE COMPOSITE E ON ENGINE WITH NO RACC SYSTEM		980.00	SR Technics Switzerland
139966					72-23-01		Package SB01	72-0708	REWORK OF THE FAN FRAME FROM DAC TO SAC AND REIDENTIFICATION		685.00	SR Technics Switzerland
139966					72-23-01		Package SB02	72-0633	NEW PLATE WITH TECH INSERTION KITS INST.		1080.00	SR Technics Switzerland
139996	2406M74G01	EASA;FAA;CAAC;ANAC	62	28	72-21-05	FAN AND BOOSTER - SPINNER FRONT CONE	Package A	CLN/INSP	CLEANING AND INSPECTION		630.00	SR Technics Switzerland
139996	2406M74G02	EASA;FAA;CAAC;ANAC			72-21-05		Package AA	026	REPLACEMENT OF DEFECTIVE SWAGED SELF-LOCKING INSERTS ON THE SPINNER FRONT CONE ASSEM		895.00	SR Technics Switzerland
139996	337-005-118-0	EASA;FAA;CAAC;ANAC			72-21-05		Package AC	028	REPAIR BOLT HOLES BY BUSHING		2070.00	SR Technics Switzerland
139996	338-001-204-0	EASA;FAA;CAAC;ANAC			72-21-05		Package AF	031	REPAIR ATTACHMENT AREA		1350.00	SR Technics Switzerland
139996	338-085-202-0	EASA;FAA;CAAC;ANAC			72-21-05		Package AI	034	BLEND ON ATTACHMENT SURFACE		635.00	SR Technics Switzerland
139996	338-085-203-0	EASA;FAA;CAAC;ANAC			72-21-05		Package D	003	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS ON THE SPIN TECHNICAL INSTRUCTION		1260.00	SR Technics Switzerland
139996	338-085-204-0	EASA;FAA;CAAC;ANAC			72-21-05		Package E	004	REPLACEMENT OF THE BONDED INSERTS AND/OR BONDED WASHERS ON THE SPINNER FRONT CONE		1655.00	SR Technics Switzerland
139996					72-21-05		Package I	008	REPAIR OF THE MOLYBDENUM DISULFIDE COATING ON THE SPINNER FRONT CONE		1255.00	SR Technics Switzerland
139996					72-21-05		Package O	014	REMOVE SURFACE DEFECTS AND REPAIR SULPHURIC ANODIZING, ANTI-EROSION PAINT AND WHITE SPII		2385.00	SR Technics Switzerland
139996					72-21-05		Package Q	016	REPAIR OF THE LOCATING DIAMETER ON THE SPINNER FRONT CONE BY PLASMA SPRAYING		1380.00	SR Technics Switzerland
139996					72-21-05		Package W	022	REPAIR BOLT HOLES		1215.00	SR Technics Switzerland
140019	1795M66P01	EASA;FAA;CAAC;ANAC	35	28	72-52-06	HIGH PRESSURE TURBINE ROTOR - BLADE RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		1075.00	SR Technics Switzerland
140019	2002M15P01	EASA;FAA;CAAC;ANAC			72-52-06		Package B	INSP-001	REMOVE HIGHMETAL		1105.00	SR Technics Switzerland
140019	2410M51P01	EASA;FAA;CAAC;ANAC			72-52-06		Package B	INSP-001	STRAIGHT SEAL		1105.00	SR Technics Switzerland
140019					72-52-06		Package B	INSP-001	BLENDING OF SEAL		1105.00	SR Technics Switzerland
140019					72-52-06		Package C	001	REPAIR OF PART/SERIAL NUMBERS THAT CANNOT BE READ ON BLADE RETAINER.		365.00	SR Technics Switzerland
140019					72-52-06		Package D	003	THERMAL SPRAY REPAIR OF DIAMETER E		7635.00	SR Technics Switzerland
140077	215371	EASA;FAA;ANAC	21	21	73-11-14	FUEL PUMP - HOUSING, RELIEF VALVE	Package B	011	REWORK PISTON SEAT INNER DIAMETER		1120.00	SR Technics Switzerland
140078	215372	EASA;FAA;ANAC	21	21	73-11-14	FUEL PUMP - RELIEF VALVE PISTON	Package B	010	REWORK PISTON SEAT		285.00	SR Technics Switzerland
140104			19	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		555.00	SR Technics Switzerland
140131	1851M59P01	EASA;FAA;CAAC;ANAC	30	28	72-52-08	HIGH PRESSURE TURBINE ROTOR - NO. 4 BEARING RETAINER	Package A	CLN/INSP	CLEANING AND INSPECTION		640.00	SR Technics Switzerland
140131	9339M45P03	EASA;FAA;CAAC;ANAC			72-52-08		Package B	INSP-001	RECONDITION OF SILVER PLATE		4290.00	SR Technics Switzerland
140131					72-52-08		Package C	INSP-001	BLENDING NUT WRENCH SLOTS		865.00	SR Technics Switzerland
140150	338-007-103-0	EASA;FAA;CAAC;ANAC;CAA I	29	28	72-23-23	FAN FRAME ASSEMBLY - FAN SPLITTER FAIRING	Package A	CLN/INSP	CLEANING AND INSPECTION		1075.00	SR Technics Switzerland
140150	340-002-602-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-23		Package B	001	SPOT TOUCH-UP OR FULL REPAIR OF THE SULFURIC ANODIZING		1340.00	SR Technics Switzerland
140150					72-23-23		Package E	004	REPAIR OF ATTACHMENT HOLE BY WELDING		5695.00	SR Technics Switzerland
140150					72-23-23		Package F	005	REPAIR OF THE CONNECTING GROOVE		5410.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140150					72-23-23		Package G	006	REPAIR OF ATTACHMENT HOLE BY BUSHING		2995.00	SR Technics Switzerland
140290	338-061-004-0	EASA;FAA;CAAC;ANAC	23	28	72-54-12	LOW PRESSURE TURBINE - OUTER STATIONARY AIR SEAL ST	Package A		STG 1 - BASIC REPAIR		245.00	SRTAS
140290	338-061-005-0	EASA;FAA;CAAC;ANAC			72-54-12		Package A	CLN-001	CLEANING		245.00	SRTAS
140290	338-061-104-0	EASA;FAA;CAAC;ANAC			72-54-12		Package A	INSP-001	VISUAL / DIMENSIONAL		245.00	SRTAS
140290	338-082-401-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B		STG 1 - FULL REPAIR		1160.00	SRTAS
140290	338-112-603-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1160.00	SRTAS
140290	338-112-604-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	003	WELD REPAIR OF CRACKS		1160.00	SRTAS
140290	338-112-605-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	006	APPLICATION OF APVS COATING		1160.00	SRTAS
140290	338-112-606-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	007	REPAIR OF WEAR ON LOCATING DOWEL		1160.00	SRTAS
140290	338-112-607-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	CLN-001	CLEANING		1160.00	SRTAS
140290	338-112-650-0	EASA;FAA;CAAC;ANAC			72-54-12		Package B	INSP-001	VISUAL / DIMENSIONAL		1160.00	SRTAS
140290	338-112-651-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C		STG 1 - FULL REPAIR		1710.00	SRTAS
140290	338-112-704-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1710.00	SRTAS
140290	338-112-705-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	003	WELD REPAIR OF CRACKS		1710.00	SRTAS
140290	338-112-706-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	005	REMOVAL AND REPLACEMENT OF THRUST (MATERIAL NOT INCLUDE REPAIR 005 OR SB 72-0630)		1710.00	SRTAS
140290	338-112-707-0	EASA;FAA;CAAC			72-54-12		Package C	006	APPLICATION OF APVS COATING		1710.00	SRTAS
140290	338-112-708-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	72-0630	INSTALL THRUST TO PREVENT POSSIBLE DISENGAGEMENT	REPAIR 005 OR SB 72-0630	1710.00	SRTAS
140290	338-112-709-0	EASA;FAA;CAAC;ANAC			72-54-12		Package C	CLN-001	CLEANING		1710.00	SRTAS
140290	338-112-803-0	EASA;FAA;CAAC;ANAC			72-54-12		Package D		STG 1 - ADDITIONAL WORKSCOPE		175.00	SRTAS
140290	338-112-804-0	EASA;FAA;CAAC;ANAC			72-54-12		Package D	72-0342	CHAMFER HOOK TO PREVENT INTERFERENCE WITH CASE		175.00	SRTAS
140290	338-112-805-0	EASA;FAA;CAAC			72-54-12		Package E		STG 1 - ADDITIONAL WORKSCOPE		2445.00	SRTAS
140290	338-121-602-0	EASA;FAA;CAAC			72-54-12		Package E	72-0630	INSTALL THRUST TO PREVENT POSSIBLE DISENGAGEMENT	STAND ALONE	2445.00	SRTAS
140290					72-54-12		Package F		STG 1 - ADDITIONAL WORKSCOPE		130.00	SRTAS
140290					72-54-12		Package F	011	REPLACEMENT OF COVER STRIP		130.00	SRTAS
140290					72-54-12		Package G		STG-2 - BASIC REPAIR		245.00	SRTAS
140290					72-54-12		Package G	CLN-001	CLEANING		245.00	SRTAS
140290					72-54-12		Package G	INSP-001	VISUAL / DIMENSIONAL		245.00	SRTAS
140290					72-54-12		Package H		STG 2 - FULL REPAIR		1145.00	SRTAS
140290					72-54-12		Package H	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1145.00	SRTAS
140290					72-54-12		Package H	003	WELD REPAIR OF CRACKS		1145.00	SRTAS
140290					72-54-12		Package H	008	REPLACEMENT OF THE ANTI ROTATION LOCK		1145.00	SRTAS
140290					72-54-12		Package H	009	WELD BUILD UP OF ANTI ROTATION SLOT		1145.00	SRTAS
140290					72-54-12		Package H	INSP-001	VISUAL / DIMENSIONAL		1145.00	SRTAS
140290					72-54-12		Package I		STG 2 - ADDITIONAL WORKSCOPE		175.00	SRTAS
140290					72-54-12		Package I	72-0302	CHAMFER LOCK TO PREVENT INTERFERENCE WITH NGV		175.00	SRTAS
140290					72-54-12		Package J		STG 2 - ADDITIONAL WORKSCOPE		280.00	SRTAS
140290					72-54-12		Package J	72-0342	CHAMFER HOOK TO PREVENT INTERFERENCE WITH CASE		280.00	SRTAS
140290					72-54-12		Package K		STG-3 - BASIC REPAIR		245.00	SRTAS
140290					72-54-12		Package K	CLN-001	CLEANING		245.00	SRTAS
140290					72-54-12		Package K	INSP-001	VISUAL / DIMENSIONAL		245.00	SRTAS
140290					72-54-12		Package L		STG 3 - FULL REPAIR		1225.00	SRTAS
140290					72-54-12		Package L	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1225.00	SRTAS
140290					72-54-12		Package L	003	WELD REPAIR OF CRACKS		1225.00	SRTAS
140290					72-54-12		Package L	008	REPLACEMENT OF THE ANTI ROTATION LOCK		1225.00	SRTAS
140290					72-54-12		Package L	009	WELD BUILD-UP OF THE ANTI ROTATION LOCK		1225.00	SRTAS
140290					72-54-12		Package L	INSP-001	VISUAL / DIMENSIONAL		1225.00	SRTAS
140290					72-54-12		Package M		STG 3 - ADDITIONAL WORKSCOPE		280.00	SRTAS
140290					72-54-12		Package M	72-0342	CHAMFER HOOK TO PREVENT INTERFERENCE WITH CASE		280.00	SRTAS

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140290					72-54-12		Package N		STG 4 - FULL REPAIR		885.00	SRTAS
140290					72-54-12		Package N	001	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		885.00	SRTAS
140290					72-54-12		Package N	003	WELD REPAIR OF CRACKS		885.00	SRTAS
140290					72-54-12		Package N	004	REPLACE ANTI-ROTATION LOCK		885.00	SRTAS
140290					72-54-12		Package N	INSP-001	VISUAL / DIMENSIONAL		885.00	SRTAS
140290					72-54-12		Package O		STG 4 - ADDITIONAL WORKSCOPE		200.00	SRTAS
140290					72-54-12		Package O	002	REPLACEMENT OF RETAINING HOOK		200.00	SRTAS
140290					72-54-12		Package S		THRUST-MATERIAL IN ADDITION TO REPAIR CHARGE (REPAIR 005/SB 72-0630/0567)		425.00	SRTAS
141267	305-138-501-0	EASA;FAA;CAAC;ANAC	5	28	72-62-07	ADAPTER ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		305.00	SR Technics Switzerland
141267					72-62-07		Package B	001	REPLACE KEY LOCKED STUDS		395.00	SR Technics Switzerland
144730	338-077-501-0	EASA;FAA;CAAC;ANAC	34	28	72-54-05	LOW PRESSURE TURBINE - ROTOR SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1100.00	SR Technics Switzerland
144730	338-077-502-0	EASA;FAA;CAAC;ANAC;CAA UK			72-54-05		Package B	INSP-001	REMOVAL OF HIGH MEATL		700.00	SR Technics Switzerland
144730	340-301-702-0	EASA;FAA;CAAC;ANAC			72-54-05		Package H	007	REPAIR OF THE NEAR DIAMETER MATING THE LPT FORWARD ROTATING AIR SEAL BY PLASMA SPRAYING		3025.00	SR Technics Switzerland
144730					72-54-05		Package I	008	REPAIR OF THE DIAMETER LOCATING THE LPT FORWARD ROTATING DIA G		2985.00	SR Technics Switzerland
144730					72-54-05		Package SB00	AD 2002-13-03	FLUORESCENT PENETRANT INSPECTION (FPI)	IN CONJUNCTION WITH PACKAGE A	900.00	SR Technics Switzerland
144739	2406M75G01	EASA;FAA;CAAC;ANAC	44	28	72-21-05	FAN AND BOOSTER - SPINNER REAR CONE	Package A	CLN/INSP	CLEANING AND INSPECTION		750.00	SR Technics Switzerland
144739	338-001-304-0	EASA;FAA;CAAC;ANAC			72-21-05		Package AB	027	REPAIR OF SPINNER REAR CONE AFT FLANGE BOLT HOLES		1305.00	SR Technics Switzerland
144739	338-001-305-0	EASA;FAA;CAAC;ANAC			72-21-05		Package AE	030	REPAIR OF THE FRONT FLANGE OF THE REAR CONE BY BLENDING		1570.00	SR Technics Switzerland
144739	340-000-205-0	EASA;FAA;CAAC;ANAC;CAA UK			72-21-05		Package AG	032	REPAIR OF SPINNER REAR CONE AFT FLANGE BOLT HOLES		2600.00	SR Technics Switzerland
144739					72-21-05		Package B	001	REMOVAL OF SURFACE DEFECTS AND SPOT TOUCH-UP OF OXIDE FILM COATING		1305.00	SR Technics Switzerland
144739					72-21-05		Package C	002	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS ON THE REAR CONE		1300.00	SR Technics Switzerland
144739					72-21-05		Package D	INSP-001	BLEND CORROSION ON SURFACE D		555.00	SR Technics Switzerland
144739					72-21-05		Package R	017	REPAIR OF THE SPINNER REAR CONE DIAMETERS THAT LOCATES THE SPINNER FRONT CONE AND THE I		3635.00	SR Technics Switzerland
144739					72-21-05		Package T	019	REPLACEMENT OF THE BONDED SEAL ON THE SPINNER REAR CONE ASSEMBLY		1665.00	SR Technics Switzerland
144739					72-21-05		Package Z	025	REPAIR OF THE SPINNER REAR CONE SURFACES THAT MATES WITH THE FAN BLADES, THE FAN DISK AN		4445.00	SR Technics Switzerland
144759	338-010-502-0	EASA;FAA;CAAC;ANAC	34	28	72-22-02	NO.1 AND NO.2 BEARING SUPPORT - NO. 1 BEARING SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		870.00	SR Technics Switzerland
144759	340-033-005-0	EASA;FAA;CAAC;ANAC			72-22-02		Package B	001	REPLACEMENT OF THE CRIMPED SELF-LOCKING NUTS ON THE NO. 1 BEARING SUPPORT ASSEMBLY		635.00	SR Technics Switzerland
144759					72-22-02		Package L	011	FINAL CLEANING AND CONDITIONING		175.00	SR Technics Switzerland
144776	1968M59G01	EASA;FAA;CAAC;ANAC	34	28	72-42-01	COMBUSTION CHAMBER (SAC) - OUTER COWLS	Package A	CLN/INSP	CLEANING AND INSPECTION		820.00	SR Technics Switzerland
144776	9531M61G06	EASA;FAA;CAAC;ANAC			72-42-01		Package B	001	WELD REPAIR AND RESIZE OF THE HS188 OUTER COWL		1695.00	SR Technics Switzerland
144778	336-026-302-0	EASA;FAA;CAAC;ANAC	40	28	72-54-16	LOW PRESSURE TURBINE - FWD ROTATING AIR SEAL ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1000.00	SR Technics Switzerland
144778					72-54-16		Package B	001	REPLACEMENT OF THE ABRADABLE HONEYCOMB LINERS		4800.00	SR Technics Switzerland
144778					72-54-16		Package C	002	REPAIR OF THE ABRADABLE COATING	DIA H	2080.00	SR Technics Switzerland
144778					72-54-16		Package D	003	REPAIR OF THE OUTER DIAMETER MATING THE LPT ROTOR SUPPORT BY PLASMA SPRAYING		2080.00	SR Technics Switzerland
144778					72-54-16		Package E	004	REPAIR OF THE INNER DIAMETER MATING THE LPT ROTOR SUPPORT DIA B		2150.00	SR Technics Switzerland
144795	338-010-302-0	EASA;FAA;CAAC;ANAC	56	28	72-53-07	STAGE 1 LPT NOZZLE - INNER AIR SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		645.00	SR Technics Switzerland
144795	338-111-002-0	EASA;FAA;CAAC;ANAC			72-53-07		Package B	001	REPLACEMENT OF THE ABRADABLE HONEYCOMB LINER		5965.00	SR Technics Switzerland
144795	338-111-003-0	EASA;FAA;CAAC;ANAC			72-53-07		Package C	002	REPAIR OF THE PLASMA THERMAL COATING ON THE FACE THAT MATE EFF. M		2470.00	SR Technics Switzerland
144795	338-111-050-0	EASA;FAA;CAAC;ANAC			72-53-07		Package C	002	REPLACEMENT OF THE PLASMA THERMAL COATING ON THE FACE MATE EFF. N		2470.00	SR Technics Switzerland
144795	338-111-051-0	EASA;FAA;CAAC;ANAC			72-53-07		Package E	004	REPAIR OF THE COOLING AIR DUCT BORES		3785.00	SR Technics Switzerland
144795	340-311-001-0	EASA;FAA;CAAC;ANAC			72-53-07		Package G	006	REPAIR OF THE DIAMETER LOCATING THE STAGE 1 LPT NOZZLE STATIONARY AIR SEAL		3075.00	SR Technics Switzerland
144795					72-53-07		Package H	007	REPLACEMENT OR RESTORE OF THE KEYING PIN		1000.00	SR Technics Switzerland
144795					72-53-07		Package L	011	BLENDING OR BRAZING OF CRACKS BTW FRONT FLANGE AND REAR FLANGE		2150.00	SR Technics Switzerland
144795					72-53-07		Package SB00	72-0785	INTRODUCTION OF A NEW FRONT FLANGE WITH 6 VENTILATION HOLES AND REWORK OF THE OLD PART		805.00	SR Technics Switzerland
144800	338-085-402-0	EASA;FAA;CAAC;ANAC	26	28	72-54-13	LOW PRESSURE TURBINE - NOZZLE SEGMENTS STG 3 - 4	Package A		STG 3/4 - BASIC REPAIR		270.00	SRTAS
144800	338-085-403-0	EASA;FAA;CAAC;ANAC			72-54-13		Package A	INSP-001	VISUAL / DIMENSIONAL		270.00	SRTAS
144800	338-085-404-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AA		STG 3 - ADDITIONAL		1430.00	SRTAS
144800	338-085-405-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AA	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE PERFORMED AS PART OF FULL REPAIR		1430.00	SRTAS

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
144800	338-085-452-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AB		STG 3 - ADDITIONAL		3080.00	SRTAS
144800	338-085-502-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AB	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE	WHEN PERFORMED INDEPENDENTL	3080.00	SRTAS
144800	338-085-503-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AD		STG 3 - ADDITIONAL		1080.00	SRTAS
144800	338-085-504-0	EASA;FAA;CAAC;ANAC			72-54-13		Package AD	021	REPLACEMENT OF THE HONEYCOMB LINER	(HONEYCOMB.HONEYCOMB SUPPO	1080.00	SRTAS
144800	338-109-702-0	EASA;FAA;CAAC;ANAC			72-54-13		Package C		STG 3 - MINOR REPAIR		1580.00	SRTAS
144800	338-109-704-0	EASA;FAA;CAAC;ANAC			72-54-13		Package C	001	AIRFOIL BLEND REPAIR		1580.00	SRTAS
144800	338-109-705-0	EASA;FAA;CAAC;ANAC			72-54-13		Package C	009	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1580.00	SRTAS
144800	338-109-802-0	EASA;FAA;CAAC;ANAC			72-54-13		Package C	INSP-001	VISUAL / DIMENSIONAL		1580.00	SRTAS
144800	338-109-804-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E		STG 3 - FULL REPAIR		3265.00	SRTAS
144800	338-109-805-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	001	AIRFOIL BLEND REPAIR		3265.00	SRTAS
144800	338-110-102-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	003	REPAIR CRACKS BY DIFFUSION BRAZING		3265.00	SRTAS
144800	338-110-103-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	005	RECONDITIONING OF THE VAPOUR PHASE ALUMINISATION		3265.00	SRTAS
144800	338-110-202-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	009	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		3265.00	SRTAS
144800	338-110-203-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	015	RECONDITIONING BY DIFFUSION BRAZING OF THE MATING SURFACES WITH THE OSAS		3265.00	SRTAS
144800	338-161-604-0	EASA;FAA;CAAC;ANAC			72-54-13		Package E	INSP-001	VISUAL / DIMENSIONAL		3265.00	SRTAS
144800	338-161-605-0	EASA;FAA;CAAC;ANAC			72-54-13		Package F		STG 3 - ADDITIONAL WORKSCOPE		760.00	SRTAS
144800	338-161-607-0	EASA;FAA;CAAC;ANAC			72-54-13		Package F	012	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES		760.00	SRTAS
144800	338-161-608-0	EASA;FAA;CAAC;ANAC			72-54-13		Package G		STG 3 - ADDITIONAL WORKSCOPE		800.00	SRTAS
144800	338-161-704-0	EASA;FAA;CAAC;ANAC			72-54-13		Package G	72-0328	REWORK FOR OVERSPEED IMPROVEMENT	(WHEN PERFORMED INDEPENDENT	800.00	SRTAS
144800	338-161-705-0	EASA;FAA;CAAC;ANAC			72-54-13		Package H		STG 3 - ADDITIONAL WORKSCOPE		690.00	SRTAS
144800	338-161-707-0	EASA;FAA;CAAC;ANAC			72-54-13		Package H	72-0328	REWORK FOR OVERSPEED IMPROVEMENT	(PART OF MINOR OR FULL REPAIR)	690.00	SRTAS
144800	338-161-708-0	EASA;FAA;CAAC;ANAC			72-54-13		Package I		STG 4 - ADDITIONAL WORKSCOPE		1700.00	SRTAS
144800	340-303-301-0	EASA;FAA;CAAC;ANAC			72-54-13		Package I	021	REPLACE HONEYCOMB LINER		1700.00	SRTAS
144800	340-303-401-0	EASA;FAA;CAAC;ANAC			72-54-13		Package J		STG 4 - MINOR REPAIR		335.00	SRTAS
144800	340-303-501-0	EASA;FAA;CAAC;ANAC			72-54-13		Package J	001	AIRFOIL BLEND REPAIR		335.00	SRTAS
144800	340-303-601-0	EASA;FAA;CAAC;ANAC			72-54-13		Package J	INSP-001	VISUAL / DIMENSIONAL		335.00	SRTAS
144800					72-54-13		Package K		STG 4 - MEDIUM REPAIR		1580.00	SRTAS
144800					72-54-13		Package K	001	AIRFOIL BLEND REPAIR.		1580.00	SRTAS
144800					72-54-13		Package K	009	REPLACE HONEYCOMB LINER (HONEY COMB MATERIAL INCLUDED IN PRICE)		1580.00	SRTAS
144800					72-54-13		Package K	INSP-001	VISUAL / DIMENSIONAL		1580.00	SRTAS
144800					72-54-13		Package L		STG 4 - FULL REPAIR		3265.00	SRTAS
144800					72-54-13		Package L	001	AIRFOIL BLEND REPAIR		3265.00	SRTAS
144800					72-54-13		Package L	003	REPAIR CRACKS BY DIFFUSION BRAZING		3265.00	SRTAS
144800					72-54-13		Package L	009	REPLACE HONEYCOMB LINER (HONEY COMB MATERIAL INCLUDED IN PRICE)		3265.00	SRTAS
144800					72-54-13		Package L	015	RECONDITIONING BY DIFFUSION BRAZING OF THE MATING SURFACES WITH THE OSAS		3265.00	SRTAS
144800					72-54-13		Package L	INSP-001	VISUAL / DIMENSIONAL		3265.00	SRTAS
144800					72-54-13		Package M		STG 4 - ADDITIONAL WORKSCOPE		670.00	SRTAS
144800					72-54-13		Package M	012	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES		670.00	SRTAS
144800					72-54-13		Package X		STG 4 - ADDITIONAL		1430.00	SRTAS
144800					72-54-13		Package X	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE	AS PART OF FULL REPAIR	1430.00	SRTAS
144800					72-54-13		Package Y		STG 4 - ADDITIONAL		3080.00	SRTAS
144800					72-54-13		Package Y	023	SEAL SLOT RECONDITIONING BY RBD61 BRAZE	WHEN PERFORMED INDEPENDENTL	3080.00	SRTAS
600262	218921-1	EASA;FAA;ANAC	21	21	73-11-14	FUEL PUMP - PLATE BEARING ASSY	Package B	007	REWORK BEARING PLATE		1105.00	SR Technics Switzerland
603639	2423M40G01	EASA;FAA;CAAC;ANAC	40	35	72-23-02	FAN FRAME ASSEMBLY - FAN INLET / UPSTREAM FAN CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		2545.00	SR Technics Switzerland
603639	338-075-329-6	EASA;FAA;CAAC;ANAC			72-23-02		Package AN	050	WELD BUILD UP BOLTHOLES	72-00-23	17685.00	SR Technics Switzerland
603639	338-075-332-6	EASA;FAA;CAAC;ANAC			72-23-02		Package B	001	REPLACEMENT OF SWAGED SELF-LOCKING INSERTS		1050.00	SR Technics Switzerland
603639	338-075-335-6	EASA;FAA;CAAC;ANAC			72-23-02		Package D	003	REPLACEMENT OF HI-LOK BOLT RIVETS		1385.00	SR Technics Switzerland
603639	338-075-336-0	EASA;FAA;CAAC;ANAC;CAA UK			72-23-02		Package H	007	REPLACEMENT OF THE RIVETED AND BONDED BOSSES		1530.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
603639					72-23-02		Package I	008	REPLACEMENT OF THE RIVETED SELF LOCKING NUTS		1610.00	SR Technics Switzerland
603639					72-23-02		Package K	010	REPLACE THE DAMPERS ASSEMBLY ON THE UPSTREAM FAN CASE ASSEMBLY AGB MOUNT BRACKETS		1470.00	SR Technics Switzerland
603639					72-23-02		Package L	011	FULL OR PARTIAL REPLACEMENT OF THE ABRADABLE LINER		23125.00	SR Technics Switzerland
603639					72-23-02		Package M	012	LOCAL RECONDITIONING OF THE ABRADABLE SILICONE LINER (BLACK COLOR), FAN INLET CASLOR), FAN		7320.00	SR Technics Switzerland
603639					72-23-02		Package R	017	REPAIR OF ELONGATED BOLT HOLES AND/OR WEAR ON B1, B3 AND/OR B4 FLANGES BY TIG WELDING		3735.00	SR Technics Switzerland
603639					72-23-02		Package S	018	BLEND REPAIR FOR CORROSION NICKS AND SCRATCHES		1610.00	SR Technics Switzerland
603639					72-23-02		Package SB00	72-0213	INSPECTION OF THE FORWARD ACOUSTICAL PANELS ATTACHMENT		460.00	SR Technics Switzerland
603639					72-23-02		Package T	019	WELD BUILD UP BOLT HOLES		4150.00	SR Technics Switzerland
603639					72-23-02		Package U	038	PARTIAL REPLACEMENT OF ABRADABLE		3910.00	SR Technics Switzerland
603670	301-475-904-6	EASA;FAA;CAAC;ANAC	19	28	72-22-00	NO.1 AND NO.2 BEARING SUPPORT - ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		80.00	SR Technics Switzerland
603670	337-011-702-6	EASA;FAA;CAAC;ANAC			72-22-00		Package B	ASSEMBLY-001	SHIM WIDTH GRINDING		225.00	SR Technics Switzerland
604567	642W9810-505	EASA;FAA;CAAC;ANAC	22	21	71-50-03	ENGINE CONTROL UNIT (ECU) CHANNEL A HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	420.00	SR Technics Switzerland
604567					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1305.00	SR Technics Switzerland
604567					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	4015.00	SR Technics Switzerland
604567					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	7745.00	SR Technics Switzerland
604600	642W9811-505	EASA;FAA;CAAC;ANAC	22	21	71-50-03	ENGINE CONTROL UNIT (ECU) CHANNEL B AND MISCELLANEC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland
604600	642W9811-507	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1265.00	SR Technics Switzerland
604600					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	4150.00	SR Technics Switzerland
604600					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	8360.00	SR Technics Switzerland
604601	642W9812-505	EASA;FAA;CAAC;ANAC	21	21	71-50-03	ENGINE CONTROL UNIT (ECU) TO THRUST REVERSER JUNCTI	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland
604601					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1265.00	SR Technics Switzerland
604601					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3290.00	SR Technics Switzerland
604601					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	3995.00	SR Technics Switzerland
604602	642W9813-505	EASA;FAA;CAAC;ANAC	21	21	71-50-03	ENGINE CONTROL UNIT (ECU) TO THRUST REVERSER JUNCTI	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland
604602					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1265.00	SR Technics Switzerland
604602					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3290.00	SR Technics Switzerland
604602					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	3995.00	SR Technics Switzerland
604603	642W9814-503	EASA;FAA;CAAC;ANAC	21	21	71-50-03	INTEGRATED DRIVE GENERATOR (IDG) CONTROL AND ANTI-IC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland
604603	642W9874-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1265.00	SR Technics Switzerland
604603					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	5030.00	SR Technics Switzerland
604603					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	7545.00	SR Technics Switzerland
604604	642W9815-503	EASA;FAA;CAAC;ANAC	22	21	71-50-03	FAN CASE LEFT SIDE HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	420.00	SR Technics Switzerland
604604	642W9880-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1585.00	SR Technics Switzerland
604604	642W9880-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	5710.00	SR Technics Switzerland
604604	642W9880-505	EASA;FAA;CAAC;ANAC			71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	7540.00	SR Technics Switzerland
604605	642W9817-501	EASA;FAA;CAAC;ANAC	22	21	71-50-03	GENERATOR FEEDER HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland
604605					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	895.00	SR Technics Switzerland
604605					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	1890.00	SR Technics Switzerland
604605					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	3525.00	SR Technics Switzerland
604606	642W9818-503	EASA;FAA;CAAC;ANAC	21	21	71-50-03	VIBRATION SENSOR HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland
604606	642W9818-505	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1265.00	SR Technics Switzerland
604606					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	2535.00	SR Technics Switzerland
604606					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	2825.00	SR Technics Switzerland
604607	642W9819-503	EASA;FAA;CAAC;ANAC	21	21	71-50-03	FIRE DETECTOR - CHANNEL A (FAN) HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland
604607					71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1245.00	SR Technics Switzerland
604607					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	1710.00	SR Technics Switzerland
604607					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	3525.00	SR Technics Switzerland
604608	642W9820-503	EASA;FAA;CAAC;ANAC	21	21	71-50-03	FIRE DETECTOR - CHANNEL B (FAN) HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
604608	642W9883-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1245.00	SR Technics Switzerland
604608					71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	1710.00	SR Technics Switzerland
604608					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	3525.00	SR Technics Switzerland
604610	642W9945-505	EASA;FAA;CAAC;ANAC	14	21	71-50-03	WIRE HARNESSSES	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	345.00	SR Technics Switzerland
604610	642W9955-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1140.00	SR Technics Switzerland
604610	642W9955-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	1605.00	SR Technics Switzerland
604610					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	2385.00	SR Technics Switzerland
604611	642W9946-505	EASA;FAA;CAAC;ANAC	14	21	71-50-03	WIRING HARNESS	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	395.00	SR Technics Switzerland
604611	642W9956-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST.	NO CONNECTIONS ARE AFFECTED	1305.00	SR Technics Switzerland
604611	642W9956-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST.	LESS THAN OR EQUAL TO 50% OF T	1950.00	SR Technics Switzerland
604611					71-50-03		Package F	HEAVY	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST.	MORE THAN 50% OF CONNECTIONS	2465.00	SR Technics Switzerland
604612	642W9947-505	EASA;FAA;CAAC;ANAC	13	21	71-50-03	HARNES VIBRATION SENSOR (TRF)	Package B	TEST	PRE TEST	TESTING AND FAULT ISALATION	325.00	SR Technics Switzerland
604612	642W9957-501	EASA;FAA;CAAC;ANAC			71-50-03		Package C	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1140.00	SR Technics Switzerland
604612	642W9957-503	EASA;FAA;CAAC;ANAC			71-50-03		Package D	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	1605.00	SR Technics Switzerland
604612					71-50-03		Package E	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	2080.00	SR Technics Switzerland
604613	642W9948-505	EASA;FAA;CAAC;ANAC	9	21	71-50-03	ECS VALVE WIRING HARNESS (4207KS)	Package C	TEST	PRE TEST		335.00	SR Technics Switzerland
604613	642W9958-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D		LIGHT REPAIR		1110.00	SR Technics Switzerland
604613	642W9958-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E		MEDIUM REPAIR		3725.00	SR Technics Switzerland
604613					71-50-03		Package F		HEAVY REPAIR		5750.00	SR Technics Switzerland
604614	642W9985-501	EASA;FAA;CAAC;ANAC	21	21	71-50-03	INTERPHONE JACK WIRE HARNESS (INLET)	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland
604614	642W9995-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	770.00	SR Technics Switzerland
604614	642W9995-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	1460.00	SR Technics Switzerland
604614					71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	1765.00	SR Technics Switzerland
609271	320-402-301-0	EASA;FAA;CAAC;ANAC	21	21	73-22-97	ELECTRICAL HARNESS CJ11L DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609271	325-014-802-0	EASA;FAA;CAAC;ANAC			73-22-97		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609271					73-22-97		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3750.00	SR Technics Switzerland
609271					73-22-97		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5360.00	SR Technics Switzerland
609410	320-282-901-0	EASA;FAA;CAAC;ANAC	21	21	73-22-83	ELECTRICAL HARNESS CJ11L SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609410					73-22-83		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609410					73-22-83		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3750.00	SR Technics Switzerland
609410					73-22-83		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5360.00	SR Technics Switzerland
609411	320-402-401-0	EASA;FAA;CAAC;ANAC	21	21	73-22-98	ELECTRICAL HARNESS CJ12L DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609411	325-014-901-0	EASA;FAA;CAAC;ANAC			73-22-98		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609411					73-22-98		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	4015.00	SR Technics Switzerland
609411					73-22-98		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5430.00	SR Technics Switzerland
609412	320-290-201-0	EASA;FAA;CAAC;ANAC	21	21	73-22-85	ELECTRICAL HARNESS CJ12L SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609412					73-22-85		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609412					73-22-85		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	4015.00	SR Technics Switzerland
609412					73-22-85		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5430.00	SR Technics Switzerland
609413	320-364-201-0	EASA;FAA;CAAC;ANAC	23	21	73-22-74	ELECTRICAL HARNESS J9	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609413	320-364-202-0	EASA;FAA;CAAC;ANAC			73-22-74		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609413	320-364-203-0	EASA;FAA;CAAC;ANAC			73-22-74		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	4015.00	SR Technics Switzerland
609413					73-22-74		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5430.00	SR Technics Switzerland
609413					73-22-74		Package SB00	72-0205	NEW POSITION OF THE C94 CONNECTOR MASTER KEY	IN CONJUNCTION WITH PACKAGE LI	375.00	SR Technics Switzerland
609413					73-22-74		Package SB01	73-0250	INTRODUCTION OF NEW J9 AND J10 HARNESS AND REWORK OF OLI IN CONJUNCTION WITH PACKAGE M		375.00	SR Technics Switzerland
609414	320-366-601-0	EASA;FAA;CAAC;ANAC	21	21	73-22-96	ELECTRICAL HARNESS CJ12R DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609414					73-22-96		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609414					73-22-96		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3690.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
609414					73-22-96		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5170.00	SR Technics Switzerland
609415	320-290-301-0	EASA;FAA;CAAC;ANAC	23	21	73-22-86	ELECTRICAL HARNESS CJ12R SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609415	320-290-302-0	EASA;FAA;CAAC;ANAC			73-22-86		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609415					73-22-86		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3690.00	SR Technics Switzerland
609415					73-22-86		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5170.00	SR Technics Switzerland
609415					73-22-86		Package SB00	73-0228	INTRODUCTION OF NEW CJ12R ELECTRICAL HARNESS OR REWORK	IN CONJUNCTION WITH PACKAGE M	275.00	SR Technics Switzerland
609416	320-366-501-0	EASA;FAA;CAAC;ANAC	21	21	73-22-95	ELECTRICAL HARNESS CJ11R DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609416					73-22-95		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609416					73-22-95		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3880.00	SR Technics Switzerland
609416					73-22-95		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5025.00	SR Technics Switzerland
609417	320-290-101-0	EASA;FAA;CAAC;ANAC	23	21	73-22-84	ELECTRICAL HARNESS CJ11R SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609417	320-290-102-0	EASA;FAA;CAAC;ANAC			73-22-84		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609417					73-22-84		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3880.00	SR Technics Switzerland
609417					73-22-84		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5025.00	SR Technics Switzerland
609417					73-22-84		Package SB00	73-0228	INTRODUCTION OF NEW CJ11R AND CJ12R ELECTRICAL HARNESS O	IN CONJUNCTION WITH PACKAGE V	275.00	SR Technics Switzerland
609418	320-366-301-0	EASA;FAA;CAAC;ANAC	21	21	73-22-94	ELECTRICAL HARNESS J12	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609418					73-22-94		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609418					73-22-94		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	1880.00	SR Technics Switzerland
609418					73-22-94		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	3750.00	SR Technics Switzerland
609419	320-296-801-0	EASA;FAA;CAAC;ANAC	21	21	73-22-78	ELECTRICAL HARNESS J12 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609419					73-22-78		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609419					73-22-78		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	1880.00	SR Technics Switzerland
609419					73-22-78		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	3750.00	SR Technics Switzerland
609420	320-392-801-0	EASA;FAA;CAAC;ANAC	22	21	73-22-91	ELECTRICAL HARNESS J7 DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609420	320-401-501-0	EASA;FAA;CAAC;ANAC			73-22-91		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609420					73-22-91		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3750.00	SR Technics Switzerland
609420					73-22-91		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5170.00	SR Technics Switzerland
609420					73-22-91		Package SB00	72-0203	INTRODUCTION OF SHORTER 57 WIRING HARNESS TO PREVENT INT	IN CONJUNCTION WITH PACKAGE LI	275.00	SR Technics Switzerland
609421	320-364-001-0	EASA;FAA;CAAC;ANAC	22	21	73-22-72	ELECTRICAL HARNESS J7 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609421	320-392-601-0	EASA;FAA;CAAC;ANAC			73-22-72		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609421	320-392-602-0	EASA;FAA;CAAC;ANAC			73-22-72		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3750.00	SR Technics Switzerland
609421	320-401-401-0	EASA;FAA;CAAC;JCAB;ANAC			73-22-72		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5170.00	SR Technics Switzerland
609421					73-22-72		Package SB00	72-0203	INTRODUCTION OF SHORTER 57 WIRING HARNESS TO PREVENT INT	IN CONJUNCTION WITH PACKAGE LI	275.00	SR Technics Switzerland
609422	320-392-901-0	EASA;FAA;CAAC;ANAC	22	21	73-22-92	ELECTRICAL HARNESS J8 DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609422	320-392-902-0	EASA;FAA;CAAC;ANAC			73-22-92		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609422					73-22-92		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3900.00	SR Technics Switzerland
609422					73-22-92		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5625.00	SR Technics Switzerland
609422					73-22-92		Package SB00	72-0191	MODIFICATION OF J8 WIRING HARNESSES	IN CONJUNCTION WITH PACKAGE LI	275.00	SR Technics Switzerland
609423	320-392-701-0	EASA;FAA;CAAC;ANAC	23	21	73-22-73	ELECTRICAL HARNESS J8 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	510.00	SR Technics Switzerland
609423	320-392-702-0	EASA;FAA;CAAC;ANAC			73-22-73		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609423					73-22-73		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	4135.00	SR Technics Switzerland
609423					73-22-73		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	8400.00	SR Technics Switzerland
609423					73-22-73		Package SB00	72-0191	MODIFICATION OF J8 WIRING HARNESSES	IN CONJUNCTION WITH PACKAGE LI	275.00	SR Technics Switzerland
609424	320-364-501-0	EASA;FAA;CAAC;ANAC	25	21	73-22-79	ELECTRICAL HARNESS J13	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609424	320-366-401-0	EASA;FAA;CAAC;ANAC			73-22-79		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609424	320-366-402-0	EASA;FAA;CAAC;ANAC			73-22-79		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	5430.00	SR Technics Switzerland
609424	320-401-101-0	EASA;FAA;CAAC;JCAB;ANAC			73-22-79		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	8075.00	SR Technics Switzerland
609424					73-22-79		Package SB00	72-0191	MODIFICATION OF J8 AND J13 WIRING HARNESSES	IN CONJUNCTION WITH PACKAGE LI	275.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
609438	320-372-601-0	EASA;FAA;CAAC;ANAC	23	21	73-22-75	ELECTRICAL HARNESS J10 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609438	320-372-602-0	EASA;FAA;CAAC;ANAC			73-22-75		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609438					73-22-75		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	4015.00	SR Technics Switzerland
609438					73-22-75		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5555.00	SR Technics Switzerland
609438					73-22-75		Package SB00	73-0250	INTRODUCTION OF NEW J9 AND J10 HARNESS AND REWORK OF OLI IN CONJUNCTION WITH PACKAGE M		375.00	SR Technics Switzerland
609439	320-298-101-0	EASA;FAA;CAAC;ANAC	21	21	73-22-82	ELECTRICAL HARNESS DPM	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	375.00	SR Technics Switzerland
609439					73-22-82		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609439					73-22-82		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3820.00	SR Technics Switzerland
609439					73-22-82		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	4655.00	SR Technics Switzerland
609445	320-364-401-0	EASA;FAA;CAAC;ANAC	21	21	73-22-76	ELECTRICAL HARNESS J11 SAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	400.00	SR Technics Switzerland
609445					73-22-76		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1140.00	SR Technics Switzerland
609445					73-22-76		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3785.00	SR Technics Switzerland
609445					73-22-76		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5360.00	SR Technics Switzerland
609446	320-366-701-0	EASA;FAA;CAAC;ANAC	15	21	73-22-87	HARNESS WIRING CJ13	Package C	TEST	PRE TEST		375.00	SR Technics Switzerland
609446	320-401-201-0	EASA;FAA;CAAC;ANAC			73-22-87		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1280.00	SR Technics Switzerland
609446					73-22-87		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	5430.00	SR Technics Switzerland
609446					73-22-87		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	8075.00	SR Technics Switzerland
609447	320-366-201-0	EASA;FAA;CAAC;ANAC	21	21	73-22-93	ELECTRICAL HARNESS J11 DAC	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	390.00	SR Technics Switzerland
609447					73-22-93		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1140.00	SR Technics Switzerland
609447					73-22-93		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3785.00	SR Technics Switzerland
609447					73-22-93		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	5360.00	SR Technics Switzerland
610350	301-797-401-0	EASA;FAA;CAAC;ANAC;CAA I	25	21	73-11-14	FUEL PUMP	Package B	TEST	BENCH-TEST	READJUSTMENT AND TESTING	2150.00	SR Technics Switzerland
610350	301-797-402-0	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-11-14		Package C	TEST	PRE TEST AND TROUBLE SHOOTING	IN CONJUNCTION WITH PACKAGE LI	160.00	SR Technics Switzerland
610350	724400-1	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-11-14		Package D	LIGHT	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST EXAMPLE: RING SEAL ROTATING OR		4425.00	SR Technics Switzerland
610350	724400-2	EASA;FAA;CAAC;ANAC;CAA MALAYSIA;DGCA C			73-11-14		Package E	MEDIUM	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST EXAMPLE: PLATE BEARING ASSY RE		5145.00	SR Technics Switzerland
610350					73-11-14		Package F	HEAVY	DISASSEMBLY, CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST EXAMPLE: MAIN GEAR HOUSING REI		7025.00	SR Technics Switzerland
610350					73-11-14		Package G		OVERHAUL		8810.00	SR Technics Switzerland
610350					73-11-14		Package SB02	714900-73-112	INTRODUCTION OF A NEW FUEL FILTER	SB 73-0107 - IN CONJUNCTION WITH	245.00	SR Technics Switzerland
610350					73-11-14		Package SB03	73-0111	REPLACEMENT OF THE CURRENT DEFECTIVE SIXTH ATTACHMENT C EQUIPPED WITH D-HEAD BOLT / IN C		245.00	SR Technics Switzerland
610350					73-11-14		Package SB04	AD 2006-26-01	CHECK FUEL FILTER PART NUMBER	IN CONJUNCTION WITH PACK LIGHT	245.00	SR Technics Switzerland
610350					73-11-14		Package SB05	EO-526918	REMOVE SRU	IN CONJUNCTION WITH PACK LIGHT	245.00	SR Technics Switzerland
610350					73-11-14		Package SB06	828300-73-110	NEW FILTER BYPASS VALVE RETAINING RING	SB 73-0287	245.00	SR Technics Switzerland
610350					73-11-14		Package SB07	724400-73-200	INTRODUCTION OF ALTERNATIVE RELIEF VALVE FOR MFP 724400	SB 73-0300	245.00	SR Technics Switzerland
610972	056-000-217-0	EASA;FAA;CAAC;ANAC	4	21	72-56-01	CFM56 OIL SCAVENGE ELBOW	Package S	018	ADJUSTMENT NEW ELBOW		160.00	SR Technics Switzerland
610972					72-56-01		Package S	018	ADJUSTMENT OLD ELBOW		160.00	SR Technics Switzerland
610972					72-56-01		Package S	018	REPLACE ELBOW NUT		160.00	SR Technics Switzerland
613126	1523M69P01	EASA;FAA;CAAC;ANAC	24	28	72-53-02	HPT SHROUD - NOZZLE SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		450.00	SR Technics Switzerland
613126	1523M71G06	EASA;FAA;CAAC;ANAC;CAA UK			72-53-02		Package B	INSP-001	BLENDED THE MID HEAT SHIELD WORN AREA		375.00	SR Technics Switzerland
613126	1523M71G07	EASA;FAA;CAAC;ANAC;CAA UK			72-53-02		Package Z	25	BRAZE REPAIR OF THE FORWARD HEAT SHIELD		690.00	SR Technics Switzerland
613853	301-547-206-0	EASA;FAA;CAAC;ANAC	9	28	72-23-06	CFM56 SELF-ALIGNING PLAIN BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		545.00	SR Technics Switzerland
613853					72-23-06		Package B	001	REPLACE COURBHANE SEAL		685.00	SR Technics Switzerland
614086	337-089-901-0	EASA;FAA;CAAC;ANAC	20	28	72-56-04	LOW PRESSURE TURBINE REAR FRAME - STREAM FAIRING	Package A	CLN/INSP	CLEANING AND INSPECTION		760.00	SR Technics Switzerland
614086	340-165-503-0	EASA;FAA;CAAC;ANAC			72-56-04		Package B	001	REPLACEMENT OF ANCHOR NUTS		495.00	SR Technics Switzerland
618233	9972M48P01	EASA;FAA;CAAC;ANAC	4	28	72-61-06	CFM56-ALL NO.3 BEARING PULLER NUT	Package A	CLN/INSP	CLEANING & INSPECTION		185.00	SR Technics Switzerland
618234	9542M68P02	EASA;FAA;CAAC;ANAC	20	28	72-61-12	INLET GEARBOX & NO.3 BEARING - OUTER SPANNER NUT	Package A	CLN/INSP	CLEANING AND INSPECTION		1035.00	SR Technics Switzerland
618701	336-026-806-0	EASA;FAA;CAAC;ANAC	42	35	72-56-02	LOW PRESSURE TURBINE REAR FRAME - NO.5 BEARING SUPP	Package A	CLN/INSP	CLEANING AND INSPECTION		905.00	SR Technics Switzerland
618701	336-026-807-0	EASA;FAA;CAAC;ANAC			72-56-02		Package C	002	REPAIR OF THE ABRADABLE COATING		3240.00	SR Technics Switzerland
618701	340-165-901-0	EASA;FAA;CAAC;ANAC			72-56-02		Package G	006	RECONDITIONING OF RABBIT DIAMETER G		2865.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
618701	340-165-903-0	EASA;FAA;CAAC;ANAC			72-56-02		Package H	007	REPLACEMENT OR CRACKS REPAIR OF OIL SCAVENGE TUBE NIPPLE BY WELD BUILD-UP		4925.00	SR Technics Switzerland
618701	340-165-904-0	EASA;FAA;CAAC;ANAC			72-56-02		Package I	008	RECONDITIONING OF THE LOCATING DIAMETER OF THE RING BY PLASMA SPRAYING		3240.00	SR Technics Switzerland
618701					72-56-02		Package J	009	CRACKS REPAIR OF NO. 5 BEARING SUPPORT BY WELD BUILD-UP		5060.00	SR Technics Switzerland
618701					72-56-02		Package M	012	COOLING HOLE WELDING		3760.00	SR Technics Switzerland
618701					72-56-02		Package N	013	REPAIR OF SAFETY WIRE HOLES ON THE OIL SCAVENGE TUBE NIPPLE		1955.00	SR Technics Switzerland
618701					72-56-02		Package R	017	REPAIR OF THE LOCATING DIAMETER WITH THE TURBINE REAR FRAME BY PLASMA SPRAY COATING		3240.00	SR Technics Switzerland
618701					72-56-02		Package SB00	72-0292	INTRODUCTION OF NEW NO.5 BEARING SUPPORT		1180.00	SR Technics Switzerland
618701					72-56-02		Package SB02	72-0546	INTRODUCTION OF NEW N°5 BEARING SUPPORT NIPPLE DESIGN OR REWORK OF THE OLD ONE		4995.00	SR Technics Switzerland
618701					72-56-02		Package SB03	72-0521	INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD		1350.00	SR Technics Switzerland
618701					72-56-02		Package U	014	REPAIR OF TAPPED HOLE WITH LOCALLY MANUFACTURED THREADED INSERT		2540.00	SR Technics Switzerland
623552	337-111-302-0	EASA;FAA;CAAC;ANAC	20	28	72-55-13	LOW PRESSURE TURBINE SHAFT - BEARING NO.4 RING-RETA	Package A	CLN/INSP	CLEANING AND INSPECTION		375.00	SR Technics Switzerland
624055	305-037-204-0	EASA;FAA;CAAC;ANAC	6	21	72-23-24	CFM56 TUBE, GUIDE TO VIBRATION SENSOR	Package A	CLN/INSP	CLEANING AND INSPECTION		365.00	SR Technics Switzerland
625809	217621-1	EASA;FAA;ANAC	18	21	73-11-14	FUEL PUMP - FRONT COVER	Package A	INSP	INSPECTION		430.00	SR Technics Switzerland
625809					73-11-14		Package E	004	PUMP COVER ASSEMBLY REPAIR		385.00	SR Technics Switzerland
628689	772896	EASA;FAA;CAAC;ANAC	9	21	24-19-17	QUICK ATTACH-DETACH ADAPTER	Package A	CLN/INSP	CLEANING AND INSPECTION		725.00	SR Technics Switzerland
630864	1561M26G01	EASA;FAA;CAAC;ANAC	40	28	72-42-02	COMBUSTION CHAMBER (SAC) - DOME	Package A	CLN/INSP	CLEANING AND INSPECTION,		930.00	SR Technics Switzerland
630864	1561M26G03	EASA;FAA;CAAC;ANAC			72-42-02		Package B	005	REMOVAL OF THE THERMAL BARRIER COATING FROM THE COMBUSTION CHAMBER DOME		2290.00	SR Technics Switzerland
630864	1561M26G05	EASA;FAA;CAAC;ANAC			72-42-02		Package F	006	APPLICATION OF THERMAL BARRIER COATING ON COMBUSTION CHAMBER DOME		11125.00	SR Technics Switzerland
630864	1561M26G06	EASA;FAA;CAAC;ANAC			72-42-02		Package F	008	REPLACEMENT OF THE PRIMARY SWIRL NOZZLE RETAINER		11125.00	SR Technics Switzerland
630864	2255M24G06	EASA;FAA;CAAC;ANAC			72-42-02		Package F	009	PLUG WELDING AND DRILLING OF THE BOLTHOLES IN THE COMBUSTION CHAMBER DOME		11125.00	SR Technics Switzerland
630864	2255M24G07	EASA;FAA;CAAC;ANAC			72-42-02		Package F	013	SPECIAL SIZING TECHNIQUE, VENTURI DIAMETER SIZING AND WELD REPAIR		11125.00	SR Technics Switzerland
630864	2255M77G01	EASA;FAA;CAAC;ANAC			72-42-02		Package G	004	COMBUSTOR DOME DEFLECTOR PLATE REPLACEMENT		5725.00	SR Technics Switzerland
630864	2255M77G02	EASA;FAA;ANAC			72-42-02		Package K	010	REPLACEMENT OF THE SLEEVE AND DEFLECTOR		5650.00	SR Technics Switzerland
630864	2255M77G03	EASA;FAA;ANAC			72-42-02		Package M	012	SECONDARY SWIRL NOZZLE REPLACEMENT		6325.00	SR Technics Switzerland
630864	2813M78G01	EASA;FAA;CAAC;ANAC			72-42-02		Package O	014	THICK BELLMOUNT REPLACEMENT REPAIR		7740.00	SR Technics Switzerland
630864					72-42-02		Package Q	016	CC DOME-REPLACEMENT OF SECONDARY SWIRLER NOZZLE		4390.00	SR Technics Switzerland
630864					72-42-02		Package R	017	CC DOME-REPLACEMENT OF SLEEVE AN DEFLECTOR		2425.00	SR Technics Switzerland
630864					72-42-02		Package S	018	RETAINERLESS PRIMARY SWIRLER REPLACEMENT		3375.00	SR Technics Switzerland
630864					72-42-02		Package SB00	72-0507	SWIRLERS - THICK FLANGE		7740.00	SR Technics Switzerland
630864					72-42-02		Package SB00	72-0888	REWORK THE OLD COMBUSTION CHAMBER DOME TO THE NEW COMBUSTION CHAMBER DOME P/N 2255		7740.00	SR Technics Switzerland
630864					72-42-02		Package SB03	72-1083	INTRODUCTION OF REWORKED CC DOME WITH RETAINER SWIRL REPLACEMENT OF BELMOUTH FLAN		8285.00	SR Technics Switzerland
630864					72-42-02		Package SB04	72-1083	INTRODUCTION OF REWORKED CC DOME WITH RETAINER SWIRL REPLACEMENT OF SECONDARY NO.		8285.00	SR Technics Switzerland
631146	1317M57G02	EASA;FAA;CAAC;ANAC	45	28	72-42-03	COMBUSTION CHAMBER (SAC) - INNER LINER	Package A	CLN/INSP	CLEANING AND INSPECTION		505.00	SR Technics Switzerland
631146	1317M57G03	EASA;FAA;CAAC;ANAC			72-42-03		Package AN	OS 255084	AIRFLOW TEST OF LARGE DIA. MULTI HOLES ON INNER LINER		3240.00	SR Technics Switzerland
631146	1317M57G05	EASA;FAA;CAAC;ANAC			72-42-03		Package C	002	PULSE WELD REPAIR OF THE INNER LINER SEAL		4115.00	SR Technics Switzerland
631146	1968M64G01	EASA;FAA;CAAC;ANAC			72-42-03		Package I	008	WELDED PATCH REPAIR		3240.00	SR Technics Switzerland
631146	1968M64G02	EASA;FAA;CAAC;ANAC			72-42-03		Package K	001	WELD REPAIR AND RESIZING AND STRESS RELIEF OF THE INNER LINER		13915.00	SR Technics Switzerland
631146	1968M64G04	EASA;FAA;CAAC;ANAC			72-42-03		Package K	003	REMOVAL OF THE NUT PLATES IN THE LINER		13915.00	SR Technics Switzerland
631146	2256M23G02	EASA;FAA;CAAC;ANAC			72-42-03		Package K	004	INSTALLATION OF THE NUT PLATES IN THE INNER LINER		13915.00	SR Technics Switzerland
631146	2256M23G03	EASA;FAA;CAAC;ANAC			72-42-03		Package K	005	REMOVAL OF THE THERMAL BARRIER COATING FROM THE INNER LINER		13915.00	SR Technics Switzerland
631146	2256M23G04	EASA;FAA;CAAC;ANAC			72-42-03		Package K	006	APPLY THE THERMAL BARRIER COATING ON THE INNER LINER		13915.00	SR Technics Switzerland
631146	2257M42G01	EASA;FAA;CAAC;ANAC			72-42-03		Package K	007	COMBUSTION CHAMBER INNER LINER BOLT HOLE DRILLING REPAIR		13915.00	SR Technics Switzerland
631146	2257M42G02	EASA;FAA;CAAC;ANAC			72-42-03		Package K	009	BRAZED DOUBLER WELD REPAIR OF THE INNER LINER AFT SUPPORT RING		13915.00	SR Technics Switzerland
631146	2480M43G02	EASA;FAA;CAAC;ANAC			72-42-03		Package K	010	MINOR (LESS THAN SIX) BOLTHOLE REPAIR		13915.00	SR Technics Switzerland
631146					72-42-03		Package K	016	REPAIR OF THE INNER LINER IMPROVED GEOMETRY AND MATERIAL BY REPLACING MISSING LEGS		13915.00	SR Technics Switzerland
631146					72-42-03		Package K	017	WELDING AND RESIZING REPAIR FOR THE INNER LINER WITH IMPROVED GEOMETRY AND MATERIAL AFT		13915.00	SR Technics Switzerland
631146					72-42-03		Package M	012	(THICK) THERMAL BARRIER COATING REPLACEMENT		1350.00	SR Technics Switzerland
631146					72-42-03		Package N	013	INNER LINER AFT FLANGE REPLACEMENT		8825.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
631146					72-42-03		Package P	015	APPLICATION OF TBC ON INNER LINER WITH LARGE DIA MULTI HOLE additional TAT +9, in cork		4385.00	SR Technics Switzerland
631146					72-42-03		Package SB00	72-0336	INNER AND OUTER LINER THICKER TBC FIELD REWORK		2505.00	SR Technics Switzerland
631146					72-42-03		Package SB03	72-0584	INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS	IN CONJUNCTION WITH PACKAGE K	545.00	SR Technics Switzerland
631146					72-42-03		Package SB05	72-0692	REWORK OF THE INNER COMBUSTION CHAMBER LINER		10120.00	SR Technics Switzerland
631146					72-42-03		Package SB06	72-0812	REWORK OF PRE_TECH INSERTION COMBUSTION CHAMBER INNER LINER WITH THIN TBC		2070.00	SR Technics Switzerland
631146					72-42-03		Package SB07	72-0844	REWORK OF TECH INSERTION INNER LINER INTO MULTI-HOLE COOLING PATCH WITH THIN TBC CONFIGL		4385.00	SR Technics Switzerland
631146					72-42-03		Package T	019	REPAIR OF THE BRAZE JOINT OF THE COMBUSTION CHAMBER INNER LINER AFT FLANGE DOUBLER		2070.00	SR Technics Switzerland
631146					72-42-03		Package U	020	PLUG-WELD INNER LINER HOLE		7480.00	SR Technics Switzerland
631146					72-42-03		Package U	020	WELD AND RESIZE REPAIR OF THE INNER NON-MULTIHOLE AREAS		7480.00	SR Technics Switzerland
631146					72-42-03		Package V	021	APPLICATION OF THIN THERMAL BARRIER COATING ON INNER LINERS WITH LARGE DIAMETER MULTI-HO		4385.00	SR Technics Switzerland
631146					72-42-03		Package W	022	CRACK WELDRESIZE	additional TAT +9, in cork	9095.00	SR Technics Switzerland
631393	1498M58P01	EASA;FAA;CAAC;ANAC	20	28	72-41-03	COMBUSTION CASE - HPT INNER STATIONARY SEAL	Package A	CLN/INSP	CLEANING & INSPECTION		60.00	SR Technics Switzerland
631393	1498M58P04	EASA;FAA;CAAC;ANAC			72-41-03		Package C	002	REPLACEMENT OF THE SEAL CLINCH NUTS		130.00	SR Technics Switzerland
634072	338-065-603-0	EASA;FAA;CAAC;ANAC	51	35	72-54-07	LOW PRESSURE TURBINE - CASE	Package A	CLN/INSP	CLEANING AND INSPECTION		1685.00	SR Technics Switzerland
634072	338-117-404-0	EASA;FAA;CAAC;ANAC			72-54-07		Package B	001	REPLACEMENT OF RIVETED PARTS AND RIVETS		2220.00	SR Technics Switzerland
634072	338-117-406-0	EASA;FAA;CAAC;ANAC			72-54-07		Package C	002	REPAIR OF THE OUTER DIAMETER LOCATING THE HPT SHROUD SUF DIAMETER "A"		4530.00	SR Technics Switzerland
634072	338-117-407-0	EASA;FAA;CAAC;ANAC			72-54-07		Package C	002	REPAIR OF THE OUTER DIAMETER LOCATING THE HPT SHROUD SUF DIAMETER "G"		4530.00	SR Technics Switzerland
634072	338-117-450-0	EASA;FAA;CAAC;ANAC			72-54-07		Package D	003	REPLACEMENT OF THE BORESCOPE BOSSES		1660.00	SR Technics Switzerland
634072	338-117-451-0	EASA;FAA;CAAC;ANAC			72-54-07		Package H	007	REPAIR OF THE OUTER DIAMETER LOCATING THE LPT FRAME		6165.00	SR Technics Switzerland
634072	338-117-452-0	EASA;FAA;CAAC;ANAC			72-54-07		Package J	009	REPAIR OF THE SURFACE WHICH MATES WITH LPT FRAME (BARE)		6165.00	SR Technics Switzerland
634072	338-117-453-0	EASA;FAA;CAAC;ANAC			72-54-07		Package J	009	REPAIR OF THE SURFACE WHICH MATES WITH LPT FRAME (PLASMA)		6165.00	SR Technics Switzerland
634072	338-117-454-0	EASA;FAA;CAAC;ANAC			72-54-07		Package O	014	REPAIR OF INNER DIAMETERS OF NOZZLES SUPPORT RING BY PLAS RAIL 1 TO 6		6605.00	SR Technics Switzerland
634072	338-117-455-0	EASA;FAA;CAAC;ANAC			72-54-07		Package O	014	REPAIR OF INNER DIAMETERS OF NOZZLES SUPPORT RING BY PLAS RAIL 1 TO 6		6605.00	SR Technics Switzerland
634072	340-305-003-0	EASA;FAA;CAAC;ANAC			72-54-07		Package P	15-94761	BLENDING OF CRACKS ON RAIL 6 ANTI-ROTATION SLOTS		450.00	SR Technics Switzerland
634072					72-54-07		Package Q	016	WELD BUILD UP OF CRAKS ON RAILS 1,3,5 AND 7 NOZZLE SUPPORT RAIL 1/3/5		16575.00	SR Technics Switzerland
634072					72-54-07		Package R	017	REPLACEMENT OF ANTI ROTATION PINS	RD 15-93532	1790.00	SR Technics Switzerland
634072					72-54-07		Package S	018	REPAIR OF PAR RAILS NOZZLES SUPPORT RING BY WELD BUILD UP RAILS 2/4/6/8		21945.00	SR Technics Switzerland
634072					72-54-07		Package SB00	72-0589	REIDENTIFICATION OF LPT CASE IN FIELD		245.00	SR Technics Switzerland
634072					72-54-07		Package SB01	72-0706	REWORK OF THE LPT CASE RAIL "O" SUPPORT RING AND REIDENTIFICATION OF THE LPT CASE		5300.00	SR Technics Switzerland
634072					72-54-07		Package SB02	EASA-2014-0130	CHECK LIFE LIMITS		495.00	SR Technics Switzerland
634072					72-54-07		Package SB03	72-0933	INTRODUCTION OF NEW PLATE		495.00	SR Technics Switzerland
634072					72-54-07		Package T	019	REPAIR OF ODD RAILS NOZZLES SUPPORT RING BY WELD BUILD UP RAIL 1/3/5/7		14645.00	SR Technics Switzerland
634072					72-54-07		Package V	021	REPAIR OF WEAR MARKS ON RAIL 0 SUPPORT RING BY PLASMA SPRAYING		6605.00	SR Technics Switzerland
634151	1523M29G04	EASA;FAA;CAAC;ANAC	50	28	72-53-02	HPT SHROUD - NOZZLE SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1225.00	SR Technics Switzerland
634151	1784M36G01	EASA;FAA;CAAC;ANAC			72-53-02		Package AC	015	AFT FLANGE HEADLESS STRAIGHT PIN REPLACEMENT		905.00	SR Technics Switzerland
634151	1784M36G02	EASA;FAA;CAAC;ANAC			72-53-02		Package AM	017	HANGER ANTI-ROTATION PIN REPLACEMENT		605.00	SR Technics Switzerland
634151	2002M69G02	EASA;FAA;CAAC;ANAC			72-53-02		Package AN	022	THERMAL SPRAY REPAIR OF THE SHROUD HANGER RAIL INNER DIA/ DIM. L / DIM. K		8080.00	SR Technics Switzerland
634151	2002M69G03	EASA;FAA;CAAC;ANAC			72-53-02		Package B	INSP-001	BLEND TO REMOVE HIGH METAL		2140.00	SR Technics Switzerland
634151	2002M69G05	EASA;FAA;CAAC;ANAC			72-53-02		Package B	INSP-001	BLENDING WEAR INSIDE DIA.		2140.00	SR Technics Switzerland
634151	2002M90G01	EASA;FAA;CAAC;ANAC			72-53-02		Package B	INSP-001	TACK-WELD BOSS		2140.00	SR Technics Switzerland
634151	2063M40G01	EASA;FAA;CAAC;ANAC			72-53-02		Package B	INSP-001	TACK-WELD BUSHING		2140.00	SR Technics Switzerland
634151					72-53-02		Package C	004	FORWARD FLANGE WEAR REPAIR		4530.00	SR Technics Switzerland
634151					72-53-02		Package E	018	REPAIR FOR LOCAL WEAR ON THE VANE MOUNT AFT FACE		3410.00	SR Technics Switzerland
634151					72-53-02		Package G	012	(EFFECT N) REPLACEMENT OF SUPPORT BUSHINGS		2805.00	SR Technics Switzerland
634151					72-53-02		Package H	013	(EFFECT N) REPLACEMENT OF THE BORESCOPE BOSS		475.00	SR Technics Switzerland
634151					72-53-02		Package M	023	FORWARD RAIL EROSION REPAIR		435.00	SR Technics Switzerland
634151					72-53-02		Package O	014	SELF RETAINING SLABBED HEAD BOLT REPLACEMENT		615.00	SR Technics Switzerland
634151					72-53-02		Package SB01	72-0270	HPT NOZZLE SHROUD SUPPORT REWORK FROM 2002M69G02 TO 1784M36G01		4695.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
634151					72-53-02		Package SB02	72-0143	MODIFY HPT/LPTN SUPPORT		4695.00	SR Technics Switzerland
634151					72-53-02		Package SB03	72-0878	REWORK FWD FLANGE SHROUD NOZZLE SUPPORT		4695.00	SR Technics Switzerland
634151					72-53-02		Package T	019	FORWARD FLANGE DIMENSIONAL REPAIR		6255.00	SR Technics Switzerland
634151					72-53-02		Package V	021	PLASMA SPRAY REPAIR OF SURFACE AM		2635.00	SR Technics Switzerland
634151					72-53-02		Package W	021	PLASMA SPRAY REPAIR OF DIAMETER FM		2635.00	SR Technics Switzerland
634151					72-53-02		Package X	022	REPAIR SHROUD ID DIM.M		8035.00	SR Technics Switzerland
635241	301-547-905-0	EASA;FAA;CAAC;ANAC;CAA I	24	28	72-55-07	LOW PRESSURE TURBINE SHAFT - RETAINER NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION		390.00	SR Technics Switzerland
635241	64ECR101	EASA;FAA;CAAC;ANAC			72-55-07		Package N	001	REPAIR OF THE MATING FACES	ITEM 1	540.00	SR Technics Switzerland
635241	650-784-016-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-07		Package O	001	REPAIR OF THE MATING FACES	ITEM 2	540.00	SR Technics Switzerland
635241	650-784-037-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-07		Package P	001	REPAIR OF THE MATING FACES	ITEM 3	540.00	SR Technics Switzerland
635241	650-784-038-0	EASA;FAA;CAAC;ANAC;CAA UK			72-55-07		Package Q	001	REPAIR OF THE MATING FACES	ITEM 4	540.00	SR Technics Switzerland
635241	650-784-075-0	EASA;FAA;CAAC;ANAC			72-55-07		Package U	002	REPAIR OF THE SILVER PLATING	ITEM 1-3	1435.00	SR Technics Switzerland
635241					72-55-07		Package X	002	REPAIR OF THE SILVER PLATING	ITEM 4	1435.00	SR Technics Switzerland
635521	9324M22G01	EASA;FAA;CAAC;ANAC	16	28	72-00-53	ENGINE MODULES/ASSEMBLIES - HPT SHROUD & STAGE 1 LP	Package A	CLN/INSP	CLEANING AND INSPECTION		485.00	SR Technics Switzerland
635521	9324M62G01	EASA;FAA;CAAC;ANAC			72-00-53		Package B	INSP-001	REMOVE PAD LOCAL SCAPS		865.00	SR Technics Switzerland
637097	1887M18G01	EASA;FAA;CAAC;ANAC	26	28	72-00-31	ENGINE MODULES/ASSEMBLIES - COMPRESSOR ROTOR ASST	Package A	CLN/INSP	CLEANING AND INSPECTION		3355.00	SR Technics Switzerland
637097	1887M18G03	EASA;FAA;CAAC;ANAC			72-00-31		Package B	001	BLENDING BLADES STG 1		870.00	SR Technics Switzerland
637097	1887M18G04	EASA;FAA;CAAC;ANAC			72-00-31		Package C	002	BLENDING BLADES STG 2-3		870.00	SR Technics Switzerland
637097	9324M78G01	EASA;FAA;CAAC;ANAC			72-00-31		Package D	003	BLENDING BLADES STG 4-9		870.00	SR Technics Switzerland
637097					72-00-31		Package G	006	LUBRICANT DOVETAIL	72-31-04	870.00	SR Technics Switzerland
637097					72-00-31		Package H		BLADE LOCK REPLACEMENT	72-31-00	970.00	SR Technics Switzerland
637097					72-00-31		Package N	INSP-001	BLEND STG.2 RETAINER HOOK		530.00	SR Technics Switzerland
637097					72-00-31		Package O	INSP-001	BLEND STG.4 DOVETAIL FWD		530.00	SR Technics Switzerland
637097					72-00-31		Package P	INSP-001	BLEND STG.1-2 SEAL TEETH		530.00	SR Technics Switzerland
637097					72-00-31		Package Q	INSP-001	BLEND STG.4-9 SEAL TEETH		530.00	SR Technics Switzerland
637097					72-00-31		Package R	INSP-001	LUBRICANT THREAD	72-31-07	530.00	SR Technics Switzerland
637097					72-00-31		Package S	INSP-001	BLEND LOCKING LUG SLOT	72-00-31	530.00	SR Technics Switzerland
642808	9968M26P02	EASA;FAA;CAAC;ANAC	17	28	72-42-04	COMBUSTION CHAMBER - IGNITER FERRULE	Package A	CLN/INSP	CLEANING AND INSPECTION		105.00	SR Technics Switzerland
642808					72-42-04		Package W	022	IGNITER FERRULE BORE WELD REPAIR		420.00	SR Technics Switzerland
643129			31	28	72-55-06	LOW PRESSURE TURBINE SHAFT - CENTER VENT TUBE	Package A	CLN/INSP	CLEANING AND INSPECTION	PN337-111-603-0 FOR SHOP VISIT ON	510.00	SR Technics Switzerland
643129					72-55-06		Package AN	SPM 70-41-11	REMOVE HIGH METAL		195.00	SR Technics Switzerland
643129					72-55-06		Package B	001	REPAIR OF THE FRONT AND/OR MID JOURNALS		2060.00	SR Technics Switzerland
643129					72-55-06		Package C	002	REPAIR OF THE AFT JOURNAL		2590.00	SR Technics Switzerland
643129					72-55-06		Package D	003	CENTRAL SECTION REPLACEMENT		3600.00	SR Technics Switzerland
643129					72-55-06		Package E	004	REPLACEMENT OF ONE OR TWO MID JOURNAL SECTIONS		3875.00	SR Technics Switzerland
643129					72-55-06		Package F	005	REPLACEMENT OF THE FORWARD SECTION		2720.00	SR Technics Switzerland
643129					72-55-06		Package H	007	REPAIR OF THE INDEX HOLES BY WELD BUILD-UP		4105.00	SR Technics Switzerland
643129					72-55-06		Package I	008	REPAIR OF THE ANTI-ROTATION TANG BY WELD BUILD-UP		3835.00	SR Technics Switzerland
643129					72-55-06		Package J	009	LAST CLEANING AND CONDITIONING OF THE CENTER VENT TUBE		435.00	SR Technics Switzerland
643129					72-55-06		Package K	010	WELD BUILD UP OF THE REAR SLOT FACES		1885.00	SR Technics Switzerland
643129					72-55-06		Package L	011	REPAIR OF CRACK IN THE CENTRAL SECTION BY WELD BUILD-UP		2340.00	SR Technics Switzerland
643129					72-55-06		Package O	014	REPAIR OF ILLEGIBLE PART MARKINGS		120.00	SR Technics Switzerland
643129					72-55-06		Package SB00	72-0753	INTRODUCTION OF A NEW CENTER VENT TUBE WITH NEW DAMPER SEAL AND REWORK OF THE OLD CV		1755.00	SR Technics Switzerland
647987	1522M10G01	EASA;FAA;CAAC;ANAC	21	28	72-53-05	HPT SHROUD - AIR IMPINGEMENT MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION		930.00	SR Technics Switzerland
647987	1668M93G01	EASA;FAA;CAAC;ANAC			72-53-05		Package B	001	WELD REPAIR OF AXIAL CRACKS NEXT TO THE AIR IMPINGEMENT MANIFOLD NUT		760.00	SR Technics Switzerland
647987	1668M93G02	EASA;FAA;CAAC;ANAC;CAA UK			72-53-05		Package C	002	PLASMA SPRAY REPAIR OF FLANGE SEALING SURFACES	DETAIL B	2890.00	SR Technics Switzerland
647987	1668M93G03	EASA;FAA;CAAC;ANAC			72-53-05		Package C	002	PLASMA SPRAY REPAIR OF FLANGE SEALING SURFACES	DETAIL C	2890.00	SR Technics Switzerland
647987	2071M29G01	EASA;FAA;CAAC;ANAC			72-53-05		Package F	005	SPLASH PLATE AND SPLASH PLATE SUPPORT WELD REPAIR		760.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
647987	2071M29G02	EASA;FAA;CAAC;ANAC			72-53-05		Package G	006	SPLASH PLATE AND SPLASH PLATE SUPPORT WELD REPAIR		760.00	SR Technics Switzerland
647987	2071M29G03	EASA;FAA;CAAC;ANAC			72-53-05		Package I	008	BRAZE JOINT REPAIR		2915.00	SR Technics Switzerland
647987					72-53-05		Package J	009	BRAZE JOINT REPAIR		865.00	SR Technics Switzerland
647987					72-53-05		Package M	012	FORWARD TABS PLASMA SPRAY REPAIR		1530.00	SR Technics Switzerland
647987					72-53-05		Package N	013	BOLT LUG BRAZE JOINT REPAIR		2055.00	SR Technics Switzerland
647987					72-53-05		Package N	014	BOLT LUG BRAZE JOINT REPAIR		2055.00	SR Technics Switzerland
647987					72-53-05		Package P	015	WELD REPAIR OF THE AFT OUTER TUBE SUPPORT		1275.00	SR Technics Switzerland
647987					72-53-05		Package Q	016	WELD REPAIR OF THE AFT OUTER TUBE SUPPORT		2080.00	SR Technics Switzerland
647987					72-53-05		Package SB01	72-0421	HIGH PRESSURE TURBINE NOZZLE (72-51-00) - INTRODUCTION OF FIELD REWORK FOR HPT AIR MANIFOL		3710.00	SR Technics Switzerland
648442	338-062-201-0	EASA;FAA;CAAC;ANAC	4	21	72-22-08	CFM56 TUBE	Package A	CLN/INSP	CLEANING & INSPECTION		305.00	SR Technics Switzerland
648442					72-22-08		Package A	CLN/INSP	PRESSURE TEST		305.00	SR Technics Switzerland
648442					72-22-08		Package B	01	BLENDING		250.00	SR Technics Switzerland
648443	338-062-001-0	EASA;FAA;CAAC;ANAC	6	21	72-22-08	CFM56 TUBE	Package A	CLN/INSP	CLEANING & INSPECTION		305.00	SR Technics Switzerland
648443	338-062-003-0	EASA;FAA;CAAC;ANAC			72-22-08		Package A	CLN/INSP	PRESSURE TEST		305.00	SR Technics Switzerland
648443	338-062-701-0	EASA;FAA;CAAC;ANAC			72-22-08		Package B	001	BLENDING		310.00	SR Technics Switzerland
648501	335-070-401-0	EASA;FAA;CAAC;ANAC	13	28	72-56-12	LOW PRESSURE TURBINE REAR FRAME - REAR INSULATION E	Package A	CLN/INSP	CLEANING AND INSPECTION		245.00	SR Technics Switzerland
648693	336-031-802-0	EASA;FAA;CAAC;ANAC	12	28	72-56-09	LOW PRESSURE TURBINE REAR FRAME - RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		315.00	SR Technics Switzerland
648704	338-072-151-0	EASA;FAA;CAAC;ANAC	13	28	72-55-20	LOW PRESSURE TURBINE SHAFT - PIN-SHOULDER	Package A	CLN/INSP	CLEANING AND INSPECTION		115.00	SR Technics Switzerland
648717	1864M97P01	EASA;FAA;CAAC;ANAC	13	28	72-52-11	COMPRESSOR FRONT STATOR - RETAINING RING	Package A	CLN/INSP	CLEANING AND INSPECTION		220.00	SR Technics Switzerland
648726	1663M70P02	EASA;FAA;CAAC;ANAC	13	28	72-31-14	COMPRESSOR ROTOR - COMPRESSOR SHAFT RETAINING RIN	Package A	CLN/INSP	CLEANING AND INSPECTION		205.00	SR Technics Switzerland
648728	1499M47P02	EASA;FAA;CAAC;ANAC	5	28	72-31-15	COMPRESSOR ROTOR DAMPER RING, STAGE 1-2 SPOOL	Package A	CLN/INSP	CLEANING & INSPECTION		110.00	SR Technics Switzerland
654796	9321M97P02	EASA;FAA;CAAC;ANAC	5	28	72-33-20	CFM56 STOP. STATOR SECTOR	Package A	CLN/INSP	CLEANING & INSPECTION		100.00	SR Technics Switzerland
654828	9971M82P02	EASA;FAA;CAAC;ANAC	5	28	72-52-09	CFM56 RING-RETAINING	Package A	CLN/INSP	CLEANING AND INSPECTION		385.00	SR Technics Switzerland
654909	337-112-801-0	EASA;FAA;CAAC;ANAC	13	21	72-54-14	LOW PRESSURE TURBINE - SUPPORT BRACKET	Package A	CLN/INSP	CLEANING AND INSPECTION		315.00	SR Technics Switzerland
654909					72-54-14		Package AE	ASSEMBLY	MOUNT BRACKET REPLACE BUSHING		890.00	SR Technics Switzerland
654954	305-140-104-0	EASA;FAA;CAAC;ANAC	6	28	72-63-20	CFM56 AGB HORIZONTAL DRIVE SHAFT HOUSING CFM56	Package A	CLN/INSP	CLEANING AND INSPECTION		460.00	SR Technics Switzerland
655153	1358M93P01	EASA;FAA;CAAC;ANAC	4	28	72-52-09	CFM56 HPT SEAL-BLADE	Package A	CLN/INSP	CLEANING & INSPECTION		40.00	SR Technics Switzerland
655176	301-298-208-0	EASA;FAA;CAAC;ANAC	13	28	72-22-06	NO.1 AND NO.2 BEARING SUPPORT - REAR ROTATING AIR/OIL	Package A	CLN/INSP	CLEANING AND INSPECTION		820.00	SR Technics Switzerland
655176	301-298-211-0	EASA;FAA;CAAC;ANAC;CAA UK			72-22-06		Package B	001	RECONDITIONING OF SILVER PLATING ON THE FORWARD MATING FACE AND/OR THREADS		465.00	SR Technics Switzerland
655179	301-298-006-0	EASA;FAA;CAAC;ANAC	16	28	72-22-13	NO.1 & NO.2 BEARING SUPPORT - RETAINING NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION		750.00	SR Technics Switzerland
655179					72-22-13		Package B	001	REPLACEMENT OF SILVER PLATING ON NO. 1 BEARING INNER RACE RETAINING NUT		1205.00	SR Technics Switzerland
655179					72-22-13		Package C	002	REPAIR OF THE SILVER PLATE MATING FACES OF THE RETAINING NUTS		760.00	SR Technics Switzerland
656214	301-436-804-0	EASA;FAA;CAAC;ANAC	15	28	72-22-13	NO.1 & NO.2 BEARING SUPPORT - RETAINING NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION		770.00	SR Technics Switzerland
656214	337-011-902-0	EASA;FAA;CAAC;ANAC			72-22-13		Package D	003	EQUALIZE THE RETAINING NUT SURFACE B		555.00	SR Technics Switzerland
656381	305-145-502-0	EASA;FAA;CAAC;ANAC	3	21	72-63-12	ACCESSORY GEARBOX HANDCRANKING NUT	Package A	CLN/INSP	CLEANING & INSPECTION		60.00	SR Technics Switzerland
656382	305-151-403-0	EASA;FAA;CAAC;ANAC	4	28	72-63-13	ACCESSORY GEARBOX V-CLAMP	Package A	CLN/INSP	CLEANING & INSPECTION		125.00	SR Technics Switzerland
663314	PBF1340-3-3	EASA;FAA;CAAC;ANAC	6	21	71-21-08	CFM56-5B FWD ENGINE MOUNT BOLT	Package A	CLN/INSP	CLEANING & INSPECTION		365.00	SR Technics Switzerland
663315			6	21	71-22-07	CFM56-5B AFT ENGINE MOUNT BOLT	Package A	CLN/INSP	CLEANING & INSPECTION		365.00	SR Technics Switzerland
664390	338-003-504-0	EASA;FAA;CAAC;ANAC	14	28	72-21-09	CFM56-5B STG.5 STEEL BOOSTER VANE ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION		790.00	SR Technics Switzerland
664390	338-003-505-0	EASA;FAA;CAAC;ANAC			72-21-09		Package B	1	BLEND REPAIR OF THE VANE AIRFOIL		555.00	SR Technics Switzerland
664390	338-003-509-0	EASA;FAA;CAAC;ANAC			72-21-09		Package C	2	REPL. OF THE SILICONE ABRADABLE COATING CHARGED WITH HOLLOW GLASS BEADS ON THE INNER S		3475.00	SR Technics Switzerland
664390					72-21-09		Package D	3	REPL. OUTER SHROUD STG 5		5065.00	SR Technics Switzerland
664390					72-21-09		Package E	4	REPLACEMENT OF THE SELF-LOCKING CRIMPED NUTS AND/OR THE RIVETED SELF-LOCKING NUTS		895.00	SR Technics Switzerland
664390					72-21-09		Package K	INSP-001	REMOVE HIGHMETAL ON AIRFOIL		920.00	SR Technics Switzerland
664390					72-21-09		Package L	40	APPLY PAINTING STAGE 5		5175.00	SR Technics Switzerland
664390					72-21-09		Package SB01	72-0418	REPLACEMENT OR REWORK OF THE STAGE 5 BOOSTER VANE ASSEMBLY		4530.00	SR Technics Switzerland
664390					72-21-09		Package SB02	72-0506	IMPROVEMENT OF THE FAN AND BOOSTER STG 5 VANE ASSY TO PREVENT CORROSION		7975.00	SR Technics Switzerland
672589	338-003-104-0	EASA;FAA;CAAC;ANAC	13	28	72-21-09	CFM56-5B BOOSTER VANE ASSY TITANIUM STG. 1-5	Package A	CLN/INSP	CLEANING AND INSPECTION		850.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672589	338-003-106-0	EASA;FAA;CAAC;ANAC			72-21-09		Package AK	061	SPOTFACING OF CORROSION		2410.00	SR Technics Switzerland
672589	338-003-203-0	EASA;FAA;CAAC;ANAC			72-21-09		Package AL	037	SPOT TOUCH UP BOOSTER VANE		1610.00	SR Technics Switzerland
672589	338-003-204-0	EASA;FAA;CAAC;ANAC			72-21-09		Package AL	060	BLEND REPAIR OF CORROSION		1610.00	SR Technics Switzerland
672589	338-003-205-0	EASA;FAA;CAAC;ANAC			72-21-09		Package AN	039	REPLACE VANES / NUTS / SHROUDS		6250.00	SR Technics Switzerland
672589	338-003-305-0	EASA;FAA;CAAC;ANAC			72-21-09		Package B	INSP-001	REMOVE HIGHMETAL ON AIRFOL		1305.00	SR Technics Switzerland
672589	338-003-306-0	EASA;FAA;CAAC;ANAC			72-21-09		Package C	002	REPLACEMENT INNER SHROUD		3735.00	SR Technics Switzerland
672589	338-003-315-0	EASA;FAA;ANAC			72-21-09		Package D	001	BLEND VANE AIRFOIL		5985.00	SR Technics Switzerland
672589	338-003-316-0	EASA;FAA;CAAC;ANAC			72-21-09		Package D	003	REPLACE OUTER SHROUD ABRADABLE COATING		5985.00	SR Technics Switzerland
672589	338-003-403-0	EASA;FAA;CAAC;ANAC			72-21-09		Package E	004	REPLACE LOCKING NUTS STG.5		945.00	SR Technics Switzerland
672589	338-003-404-0	EASA;FAA;CAAC;ANAC			72-21-09		Package G	006	FRONT INNER DIAMETER F / STG.1		3000.00	SR Technics Switzerland
672589	338-003-414-0	EASA;FAA;ANAC			72-21-09		Package H	007	FRONT OUTER DIMENSION O / STG.1		3000.00	SR Technics Switzerland
672589	338-003-502-0	EASA;FAA;CAAC;ANAC			72-21-09		Package SB00	72-0218	REWORK OF FAN AND BOOSTER STG1 VANE ASSY		5065.00	SR Technics Switzerland
672589	338-003-503-0	EASA;FAA;CAAC;ANAC			72-21-09		Package SB01	72-0418	REPL. OR REWORK OF THE STG. 5 BOOSTER VANE ASSY		5065.00	SR Technics Switzerland
672589	338-003-506-0	EASA;FAA;CAAC;ANAC			72-21-09		Package SB02	72-1031	REWORK AND REIDENTIFICATION OF VANE ASSY STG. 2-4		5985.00	SR Technics Switzerland
672589					72-21-09		Package SB03	72-0917	INNER SHROUD REWORK AND REIDENTIFICATION OF VANE ASSY STG. 2		5065.00	SR Technics Switzerland
672589					72-21-09		Package SB04	72-1065	REWORK AND REIDENTIFICATION OF VANE ASSY STG. 2-4		2610.00	SR Technics Switzerland
672596	1386M56P02	EASA;FAA;CAAC;ANAC	10	28	72-31-07	CFM56 COMPRESSOR ROTOR SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		965.00	SR Technics Switzerland
672596	1386M56P03	EASA;FAA;CAAC;ANAC			72-31-07		Package B	INSP-001	APPLY DRY FILM LUBRICANT		1610.00	SR Technics Switzerland
672596	1590M28G01	EASA;FAA;CAAC;ANAC			72-31-07		Package B	INSP-001	BLENDING REPAIR		1610.00	SR Technics Switzerland
672596	1590M28G02	EASA;FAA;CAAC;ANAC			72-31-07		Package E	004	REPAIR ROTOR LOCK SLOT		3335.00	SR Technics Switzerland
672596	1590M28G04	EASA;FAA;CAAC;ANAC			72-31-07		Package F	005	REPAIR ROTOR SHAFT		6130.00	SR Technics Switzerland
672596	1590M28G05	EASA;FAA;CAAC;ANAC			72-31-07		Package G	006	ROTOR SHAFT DAMAGED THREADS		1745.00	SR Technics Switzerland
672596					72-31-07		Package SB00	AD 2002-13-03	ENHANCED LLP INSP	AD 2002-13-03_007	810.00	SR Technics Switzerland
672783	1871M49G03	EASA;FAA;CAAC;ANAC	6	28	72-09-04	CFM56 ENGINE HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		175.00	SR Technics Switzerland
672783	1895M34G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	01	REPLACE TAB (FOR 321 STEEL)		75.00	SR Technics Switzerland
672783	1895M35G01	EASA;FAA;CAAC;ANAC			72-09-04		Package C	INSP/CHK	REPLACE INSERT	SPM 70-42-XY	195.00	SR Technics Switzerland
672783	2174M29G01	EASA;FAA;ANAC			72-09-04		Package L	11	REPLACE KEY LOCKED INSERT		100.00	SR Technics Switzerland
672783	2175M14G01	EASA;FAA;CAAC;ANAC			72-09-04		Package M	51	BRACKET PIN REPLACE		155.00	SR Technics Switzerland
672783					72-09-04		Package N	REPAIR	SPM SHOCK-MOUNT REPLACE ELASTOMER		85.00	SR Technics Switzerland
672792	338-040-751-0	EASA;FAA;CAAC;ANAC	6	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING AND INSPECTION		395.00	SR Technics Switzerland
672792					72-09-03		Package B	REPAIR	REPAIR AND PRESSURE TEST		1080.00	SR Technics Switzerland
672828	338-031-631-0	EASA;FAA;CAAC;ANAC	12	35	72-56-01	CFM56-5B TURBINE REAR FRAME MODUL 56	Package A	CLN/INSP	CLEANING AND INSPECTION		2770.00	SR Technics Switzerland
672828	338-031-642-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AA	18	FULL OR PARTIAL REPLACEMENT OF THE OIL SCAVENGE TUBE ASSEMBLY		2600.00	SR Technics Switzerland
672828	338-031-643-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AB	26	CLEVIS MOUNT BORES - BUSHING		3895.00	SR Technics Switzerland
672828	338-061-623-0	EASA;FAA;ANAC			72-56-01		Package AC	15-9464	RECONDITIONING OF THE CLEVIS MOUNT FIXATION AREA		1710.00	SR Technics Switzerland
672828	338-061-625-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AD	29	REPLACEMENT OF INSULATION ASSEMBLY OF THE INNER HUB		1315.00	SR Technics Switzerland
672828	338-061-626-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AE	25	REPLACEMENT OF NEW BUSHINGS		3340.00	SR Technics Switzerland
672828	338-061-627-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AI	34	REPLACEMENT OF SUMP FLOODING TUBE		1305.00	SR Technics Switzerland
672828	338-102-904-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AJ	51	RADIUS DIA K POLISHING		640.00	SR Technics Switzerland
672828	338-102-907-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AM	38	REPAIR OF THE BRACKET CENTERING DIAMETER OF THE OIL SCAVENGE TUBE ASSEMBLY BY WELD BUII		4535.00	SR Technics Switzerland
672828	338-102-908-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AN	47	WELD BUILD-UP CLEVIS MOUNT AREA		2160.00	SR Technics Switzerland
672828	338-102-909-0	EASA;FAA;CAAC;ANAC			72-56-01		Package B	1	REPLACEMENT OF THE DEFECTIVE STUDS ON THE AFT FACE OF THE INNER HUB		2865.00	SR Technics Switzerland
672828	338-102-910-0	EASA;FAA;CAAC;ANAC			72-56-01		Package B	INSP-001	REMOVE HIGH METAL		2865.00	SR Technics Switzerland
672828	338-102-912-0	EASA;FAA;CAAC;ANAC			72-56-01		Package B	INSP-001	REWELD STOP WELD ON STUDS		2865.00	SR Technics Switzerland
672828	338-171-703-0	EASA;FAA;CAAC;ANAC			72-56-01		Package C	2	REPLACEMENT OF THE DEFECTIVE CRIMPED SELF-LOCKING NUTS		1225.00	SR Technics Switzerland
672828	338-171-704-0	EASA;FAA;CAAC;ANAC			72-56-01		Package D	3	REPLACEMENT OF THE DEFECTIVE SELF-LOCKING INSERTS		1440.00	SR Technics Switzerland
672828	338-171-705-0	EASA;FAA;CAAC;ANAC			72-56-01		Package E	4	REPLACEMENT OF DEFECTIVE FASTENERS AND/ OR DEFECTIVE ASSOCIATED PARTS		1440.00	SR Technics Switzerland
672828	338-171-706-0	EASA;FAA;CAAC;ANAC			72-56-01		Package F	5	REPLACE THE DEFECTIVE BUSHINGS IN THE HANDLING BRACKETS ON THE TURBINE FRAME		1170.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672828	338-171-707-0	EASA;FAA;CAAC;ANAC			72-56-01		Package H	7	REPAIR OF THE DIAMETER MATING WITH THE LPT CASE		4530.00	SR Technics Switzerland
672828	338-171-751-0	EASA;FAA;CAAC;ANAC			72-56-01		Package I	8	REPAIR OF THE REAR FLANGE MATING FACE		4005.00	SR Technics Switzerland
672828	338-171-752-0	EASA;FAA;CAAC;ANAC			72-56-01		Package J	9	REPLACEMENT OF THE END FITTINGS ON THE OIL SUPPLY AND SCAVENGE TUBES		655.00	SR Technics Switzerland
672828	338-173-801-0	EASA;FAA;CAAC;ANAC			72-56-01		Package L	19	REPLACEMENT OF THE TUBE BOSS CONNECTION NIPPLE		1620.00	SR Technics Switzerland
672828					72-56-01		Package M	46	REPAIR OF CRACKS IN WELD BEAD OF THE INSULATION BLANKET		1730.00	SR Technics Switzerland
672828					72-56-01		Package N	22	REPLACEMENT OF THE DEFECTIVE STUDS ON THE FORWARD FACE OF THE INNER HUB		2930.00	SR Technics Switzerland
672828					72-56-01		Package P	15	REPAIR OF THE DIAMETER MATING WITH THE EXHAUST NOZZLE		3810.00	SR Technics Switzerland
672828					72-56-01		Package Q	20	WELD REPAIR OF CRACKS FOR WELDED ASSEMBLY FRAME		5575.00	SR Technics Switzerland
672828					72-56-01		Package R	14	REPLACEMENT OF THE FIXATION ASSEMBLY OF THE OIL SUPPLY TUBE ASSEMBLY		1955.00	SR Technics Switzerland
672828					72-56-01		Package S	21	WELD REPAIR OF CRACKS		7125.00	SR Technics Switzerland
672828					72-56-01		Package SB01	72-0499	REWORK AND REIDENTIFICATION OF THE OLD LPT FRAME TO PERM THE OIL SUPPLY TUBE ON WING OR		1745.00	SR Technics Switzerland
672828					72-56-01		Package SB02	EASA-2021-0062	LPT REAR FRAMES - INSPECTION/REPLACEMENT		930.00	SR Technics Switzerland
672828					72-56-01		Package SB03	72-0716	INSPECTION OF TANGENTIAL STRUTS TURBINE REAR ON SAC ENGINE		890.00	SR Technics Switzerland
672828					72-56-01		Package SB04	79-0020	INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES		1015.00	SR Technics Switzerland
672828					72-56-01		Package SB05	72-0331	INTRODUCTION OF NEW COMPOSITE OGV		1470.00	SR Technics Switzerland
672828					72-56-01		Package SB06	72-0403	LPT FRAME - REPL. OF OIL SUPPLY TUBE		1265.00	SR Technics Switzerland
672828					72-56-01		Package SB07	72-0570	INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENAGE TUBE		1470.00	SR Technics Switzerland
672828					72-56-01		Package SB10	EASA 2007-0221	TIME LIMIT AND LIFE REDUCTION		1470.00	SR Technics Switzerland
672828					72-56-01		Package SB10	EASA-2014-0130	TIME LIMIT AND MANDATORY INSPECTION		1470.00	SR Technics Switzerland
672828					72-56-01		Package SB10	FAA 2009-0110	TIME LIMIT AND MANDATORY INSPECTION		1470.00	SR Technics Switzerland
672828					72-56-01		Package SB13	72-0118	INSPECTION OF TANGENTIAL STRUTS TURBINE REAR FRAME ON DAC ENGINES		1470.00	SR Technics Switzerland
672828					72-56-01		Package SB14	72-0850	INSPECTION OF TURBINE REAR FRAME		845.00	SR Technics Switzerland
672828					72-56-01		Package SB17	72-0734	INSPECTION OF TANGENTIAL STRUTS TURBINE REAR FRAME ON DAC ENGINES		845.00	SR Technics Switzerland
672828					72-56-01		Package SB18	AD 2016-02-04	PREVENT FAILURE OF THE TRF ON THE LPT FRAME		1445.00	SR Technics Switzerland
672828					72-56-01		Package SB19	72-0620	INSPECTION OF TURBINE REAR FRAME ON SAC ENGINES		735.00	SR Technics Switzerland
672828					72-56-01		Package SB20	FAA 2009-18-01	THRESHOLDS INSPECTION FOR LPT REAR FRAMES		715.00	SR Technics Switzerland
672828					72-56-01		Package U	31	RECONDITIONING OF THE DIAMETER OIL SCAVENGE TUBE		5965.00	SR Technics Switzerland
672828					72-56-01		Package V	16	REPAIR OF THE DIAMETER MATING WITH THE OIL SUMP ASSEMBLY		4260.00	SR Technics Switzerland
672828					72-56-01		Package W	43	REPAIR OF CLEVIS MOUNT AREA		1745.00	SR Technics Switzerland
672828					72-56-01		Package X	23	INSTALLATION OF BUSHING IN STUD HOLES		1305.00	SR Technics Switzerland
672828					72-56-01		Package Y	15-93481	REPLACEMENT OF INSULATION		1280.00	SR Technics Switzerland
672828					72-56-01		Package Z	17	FULL OR PART REPLACEMENT OF THE OIL SUPPLY TUBE ASSEMBLY		1955.00	SR Technics Switzerland
673774	338-069-701-0	EASA;FAA;CAAC;ANAC	7	28	72-55-06	CFM56-5B LP TURBINE CENTER VENT TUBE	Package A	CLN/INSP	CLEANING & INSPECTION		510.00	SR Technics Switzerland
673774	338-180-301-0	EASA;FAA;CAAC;ANAC			72-55-06		Package AN		REMOVE HIGH METAL	SPM 70-41-11	125.00	SR Technics Switzerland
673774	338-180-302-0	EASA;FAA;CAAC;ANAC			72-55-06		Package B	01	REPAIR OF THE FRONT AND/OR MID JOURNALS		2060.00	SR Technics Switzerland
673774	338-180-303-0	EASA;FAA;CAAC;ANAC			72-55-06		Package C	02	REPAIR OF THE AFT JOURNAL		2590.00	SR Technics Switzerland
673774	338-180-304-0	EASA;FAA;CAAC;ANAC			72-55-06		Package D	03	CENTRAL SECTION REPLACEMENT		3600.00	SR Technics Switzerland
673774					72-55-06		Package E	04	REPLACEMENT OF ONE OR TWO MID JOURNAL SECTIONS		3875.00	SR Technics Switzerland
673774					72-55-06		Package F	05	REPLACEMENT OF THE FORWARD SECTION		2720.00	SR Technics Switzerland
673774					72-55-06		Package H	07	REPAIR OF THE INDEX HOLES BY WELD BUILD-UP		4105.00	SR Technics Switzerland
673774					72-55-06		Package I	08	REPAIR OF THE ANTI-ROTATION TANG BY WELD BUILD-UP		2155.00	SR Technics Switzerland
673774					72-55-06		Package J	09	LAST CLEANING AND CONDITIONING OF THE CENTER VENT TUBE		435.00	SR Technics Switzerland
673774					72-55-06		Package K	10	WELD BUILD UP OF THE REAR SLOTS FACES		1885.00	SR Technics Switzerland
673774					72-55-06		Package L	11	REPAIR OF CRACK IN THE CENTRAL SECTION BY WELD BUILD-UP		2340.00	SR Technics Switzerland
673774					72-55-06		Package O	14	REPAIR OF ILLEGIBLE PART MARKINGS		120.00	SR Technics Switzerland
673774					72-55-06		Package SB00	72-0753	INTRODUCTION OF A NEW CENTER VENT TUBE WITH NEW DAMPER SEAL AND REWORK OF THE OLD CV		1755.00	SR Technics Switzerland
453	338-111-303-0	EASA;FAA;CAAC;ANAC	37	28	72-53-08	STAGE 1 LPT NOZZLE - REAR FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		1100.00	SR Technics Switzerland
453	338-111-304-0	EASA;FAA;CAAC;ANAC			72-53-08		Package B	002	REPAIR OF THE PLASMA THERMAL COATING ON THE FACE MATING WITH THE STAGE 1 LPT NOZZLE SEG		2675.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
453	338-111-305-0	EASA;FAA;CAAC;ANAC			72-53-08		Package D	004	REPAIR OF THE MATING FACE BY PLASMA SPRAYING		2810.00	SR Technics Switzerland
1518	1559M16G01	EASA;FAA;CAAC;ANAC	42	28	72-33-02	COMPRESSOR REAR STATOR - VANE SECTORS	Package A		BASIC REPAIR STAGE 6/7/8		230.00	SRTAS
1518	1559M16G02	EASA;FAA;CAAC;ANAC			72-33-02		Package A	CLN 001	CLEANING		230.00	SRTAS
1518	1559M16G03	EASA;FAA;CAAC;ANAC			72-33-02		Package A	INSP 001	VISUAL/DIMENSIONAL INSPECTION		230.00	SRTAS
1518	1559M16G04	EASA;FAA;CAAC;ANAC			72-33-02		Package B		FULL REPAIR STAGE 6/7/8		525.00	SRTAS
1518	1559M17G01	EASA;FAA;CAAC;ANAC			72-33-02		Package B	001	REPLACEMENT OF THE OUTER PLATFORM WEAR COATING		525.00	SRTAS
1518	1559M17G02	EASA;FAA;CAAC;ANAC			72-33-02		Package B	002	AIRFOIL LEADING AND TRAILING EDGES BLEND REPAIR		525.00	SRTAS
1518	1559M17G03	EASA;FAA;CAAC;ANAC			72-33-02		Package G		ADDITIONAL WORK SCOPE STAGE 6		125.00	SRTAS
1518	1559M17G04	EASA;FAA;CAAC;ANAC			72-33-02		Package G	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	125.00	SRTAS
1518	1559M18G01	EASA;FAA;CAAC;ANAC			72-33-02		Package H		ADDITIONAL WORK SCOPE STAGE 6		955.00	SRTAS
1518	1559M18G02	EASA;FAA;CAAC;ANAC			72-33-02		Package H	008	INNER PLATFORM J-HOOK		955.00	SRTAS
1518	1559M18G03	EASA;FAA;CAAC;ANAC			72-33-02		Package N		ADDITIONAL WORK SCOPE STAGE 7		125.00	SRTAS
1518	1559M18G04	EASA;FAA;CAAC;ANAC			72-33-02		Package N	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	125.00	SRTAS
1518	P206G05	EASA;FAA;CAAC;ANAC			72-33-02		Package O		ADDITIONAL WORK SCOPE STAGE 7		955.00	SRTAS
1518	P206G06	EASA;FAA;CAAC;ANAC			72-33-02		Package O	008	INNER PLATFORM J-HOOK		955.00	SRTAS
1518	P206G07	EASA;FAA;CAAC;ANAC			72-33-02		Package U		ADDITIONAL WORK SCOPE STAGE 8		125.00	SRTAS
1518	P206G08	EASA;FAA;CAAC;ANAC			72-33-02		Package U	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	125.00	SRTAS
1518	P207G01	EASA;FAA;CAAC;ANAC			72-33-02		Package V		ADDITIONAL WORK SCOPE STAGE 8		955.00	SRTAS
1518	P207G02	EASA;FAA;CAAC;ANAC			72-33-02		Package V	008	INNER PLATFORM J-HOOK		955.00	SRTAS
1518	P207G03	EASA;FAA;CAAC;ANAC										
1518	P207G04	EASA;FAA;CAAC;ANAC										
1518	P207G05	EASA;FAA;CAAC;ANAC										
1518	P207G06	EASA;FAA;CAAC;ANAC										
1518	P207G07	EASA;FAA;CAAC;ANAC										
1518	P207G08	EASA;FAA;CAAC;ANAC										
1518	P208G01	EASA;FAA;CAAC;ANAC										
1518	P208G02	EASA;FAA;CAAC;ANAC										
1518	P208G03	EASA;FAA;CAAC;ANAC										
1518	P208G04	EASA;FAA;CAAC;ANAC										
1518	P208G05	EASA;FAA;CAAC;ANAC										
1518	P208G06	EASA;FAA;CAAC;ANAC										
1518	P246G01	EASA;FAA;CAAC;ANAC										
1518	P246G02	EASA;FAA;CAAC;ANAC										
1518	P246G03	EASA;FAA;CAAC;ANAC										
1518	P246G04	EASA;FAA;CAAC;ANAC										
1518	P246G09	EASA;FAA;CAAC;ANAC										
1518	P247G01	EASA;FAA;CAAC;ANAC										
1518	P247G02	EASA;FAA;CAAC;ANAC										
1518	P247G03	EASA;FAA;CAAC;ANAC										
1518	P247G04	EASA;FAA;CAAC;ANAC										
1518	P247G09	EASA;FAA;CAAC;ANAC										
1518	P248G01	EASA;FAA;CAAC;ANAC										
1518	P248G02	EASA;FAA;CAAC;ANAC										
1518	P248G03	EASA;FAA;CAAC;ANAC										
1518	P248G04	EASA;FAA;CAAC;ANAC										
1518	P256G01	EASA;FAA;CAAC;ANAC										
1518	P256G02	EASA;FAA;CAAC;ANAC										
1518	P256G03	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
1518	P256G04	EASA;FAA;CAAC;ANAC										
1518	P256G05	EASA;FAA;CAAC;ANAC										
1518	P256G06	EASA;FAA;CAAC;ANAC										
1518	P256G07	EASA;FAA;CAAC;ANAC										
1518	P256G08	EASA;FAA;CAAC;ANAC										
1518	P257G01	EASA;FAA;CAAC;ANAC										
1518	P257G02	EASA;FAA;CAAC;ANAC										
1518	P257G03	EASA;FAA;CAAC;ANAC										
1518	P257G04	EASA;FAA;CAAC;ANAC										
1518	P258G01	EASA;FAA;CAAC;ANAC										
1518	P258G02	EASA;FAA;CAAC;ANAC										
1518	P258G03	EASA;FAA;CAAC;ANAC										
1548	1476M51P01	EASA;FAA;CAAC;ANAC;CAA I	32	28	72-32-13	COMPRESSOR FRONT STATOR - VSV ACTUATION HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION	PRICE PER STAGE	265.00	SR Technics Switzerland
1548	1476M80P01	EASA;FAA;CAAC;ANAC			72-32-13		Package B	002	REPAIR FOR THE STAGE 1, STAGE 2 AND STAGE 3 BELLCRANK BORE	PRICE PER STAGE	1080.00	SR Technics Switzerland
1548	1559M35G01	EASA;FAA;CAAC;ANAC										
1548	1559M91P01	EASA;FAA;CAAC;ANAC										
1548	9511M24P04	EASA;FAA;CAAC;ANAC										
1548	9511M24P07	EASA;FAA;CAAC;ANAC										
1548	9511M26P02	EASA;FAA;CAAC;ANAC										
1820	1523M42G02	EASA;FAA;CAAC;ANAC	34	28	72-51-05	HIGH PRESSURE TURBINE NOZZLE - OUTER STATIONARY SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		870.00	SR Technics Switzerland
1820	1523M42G04	EASA;FAA;CAAC;ANAC			72-51-05		Package A	INSP-001	T1 315027 CRACKS IN SCALLOPS		870.00	SR Technics Switzerland
1820	1784M84G01	EASA;FAA;CAAC;ANAC			72-51-05		Package C	002	T400 WEARCOAT REPLACEMENT		2225.00	SR Technics Switzerland
1820	1784M84G02	EASA;FAA;CAAC;ANAC			72-51-05		Package D	003	HONEYCOMB REPLACEMENT		8075.00	SR Technics Switzerland
1820	1784M84G05	EASA;FAA;CAAC;ANAC			72-51-05		Package E	005	DIAMETER B DIMENSIONAL RESTORATION		2645.00	SR Technics Switzerland
1820	1808M58G01	EASA;FAA;CAAC;ANAC			72-51-05		Package G	006	DIAMETER F MACHINING REPAIR		910.00	SR Technics Switzerland
1820	1808M58G03	EASA;FAA;CAAC;ANAC			72-51-05		Package SB00	72-0231	INTRODUCTION OF NEW STATIONARY HPT OUTER SEAL		1185.00	SR Technics Switzerland
1820	1808M58G05	EASA;FAA;CAAC;ANAC										
1820	1808M58G07	EASA;FAA;CAAC;ANAC										
1820	1808M58G08	EASA;FAA;CAAC;ANAC										
1820	2091M57G01	EASA;FAA;CAAC;ANAC										
1820	2091M57G02	EASA;FAA;CAAC;ANAC										
1820	2091M57G03	EASA;FAA;CAAC;ANAC										
2009	1498M45P03	EASA;FAA;CAAC;ANAC	50	28	72-52-05	HIGH PRESSURE TURBINE ROTOR - REAR SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		1485.00	SR Technics Switzerland
2009	1498M45P04	EASA;FAA;CAAC;ANAC;TCCA			72-52-05		Package B	INSP-001	REMOVE HIGH METAL		300.00	SR Technics Switzerland
2009	1498M45P05	EASA;FAA;CAAC;ANAC			72-52-05		Package B	INSP-001	BLENDING AIRSEAL		300.00	SR Technics Switzerland
2009	1498M45P06	EASA;FAA;CAAC;ANAC			72-52-05		Package C	001	REPLACEMENT OF SEAL TEETH WEAR COATING		6035.00	SR Technics Switzerland
2009	1498M45P07	EASA;FAA;CAAC;ANAC			72-52-05		Package F	005	THERMAL SPRAY REPAIR OF THE BEARING JOURNAL		7520.00	SR Technics Switzerland
2009	1498M45P08	EASA;FAA;CAAC;ANAC			72-52-05		Package G	006	HPT AFT SHAFT THERMAL SPRAY REPAIR OF AREA M		7365.00	SR Technics Switzerland
2009	1864M90P04	EASA;FAA;CAAC;ANAC			72-52-05		Package H	007	BUSHING REPLACEMENT		1575.00	SR Technics Switzerland
2009	1864M90P05	EASA;FAA;CAAC;ANAC			72-52-05		Package M	012	BLEND ANTI-ROTATION SLOTS		665.00	SR Technics Switzerland
2009	1864M90P06	EASA;FAA;CAAC;ANAC			72-52-05		Package SB00	72-0224	HPT REAR SHAFT AND BUSHING REWORK		2400.00	SR Technics Switzerland
2009	1864M90P07	EASA;FAA;CAAC;ANAC										
2009	1873M62G02	EASA;FAA;CAAC;ANAC										
2009	1873M62G03	EASA;FAA;CAAC;ANAC										
2009	1873M62G04	EASA;FAA;CAAC;ANAC										
2009	1873M62G05	EASA;FAA;CAAC;ANAC										
2082	1493M73G04	EASA;FAA;CAAC;ANAC	28	28	72-42-00	COMBUSTION CHAMBER (SAC)	Package A	CLN/INSP	CLEANING AND INSPECTION		4390.00	SR Technics Switzerland
2082	1493M73G06	EASA;FAA;CAAC;ANAC			72-42-00		Package F		DISASSEMBLY AND ASSEMBLY	EXCLUDED PIECE PART REPAIRS	3635.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
2082	1493M73G08	EASA;FAA;CAAC;ANAC			72-42-00		Package SB00	72-0327	INTRODUCTION OF NEW OUTER COWL WITH INCREASED DURABIL	IN CONJUNCTION WITH PACKAGE F	265.00	SR Technics Switzerland
2082	1968M41G01	EASA;FAA;CAAC;ANAC			72-42-00		Package SB01	72-0765	NEW OUTER LINER FOR HARSH ENVIRONMENT OPERATORS	IN CONJUNCTION WITH PACKAGE F	265.00	SR Technics Switzerland
2082	1968M41G02	EASA;FAA;CAAC;ANAC			72-42-00		Package SB02	72-0273	COMBUSTION DOME SWIRLER SUPPORT ELIMINATION	IN CONJUNCTION WITH PACKAGE F	265.00	SR Technics Switzerland
2082	1968M41G03	EASA;FAA;CAAC;ANAC			72-42-00		Package SB05	72-0586	ON WING INSPECTION AND SHOP LEVEL ACTION FOR INNER AND OL	IN CONJUNCTION WITH PACKAGE F	265.00	SR Technics Switzerland
2082	1968M41G04	EASA;FAA;CAAC;ANAC			72-42-00		Package SB08	72-0237	COMBUSTION CHAMBER INNER COWL BOLT INSPECTION	IN CONJUNCTION WITH PACKAGE F	915.00	SR Technics Switzerland
2082	1968M46G08	EASA;FAA;CAAC;ANAC			72-42-00		Package SB09	72-0782	NEW COMBUSTION CHAMBER ASSEMBLY FOR HARSH ENVIRONMEN	IN CONJUNCTION WITH PACKAGE F	265.00	SR Technics Switzerland
2082	1968M46G10	EASA;FAA;CAAC;ANAC			72-42-00		Package SB10	72-0852	INTRODUCTION OF NEW COMBUSTION CHAMBER ASSEMBLY	IN CONJUNCTION WITH PACKAGE F	265.00	SR Technics Switzerland
2082	1968M65G01	EASA;FAA;CAAC;ANAC										
2082	1968M65G03	EASA;FAA;CAAC;ANAC										
2082	1968M68G04	EASA;FAA;CAAC;ANAC										
2082	1968M68G06	EASA;FAA;CAAC;ANAC										
2082	1968M68G07	EASA;FAA;CAAC;ANAC										
2082	1968M68G08	EASA;FAA;CAAC;ANAC										
2082	1968M68G16	EASA;FAA;CAAC;ANAC										
2082	1968M68G17	EASA;FAA;CAAC;ANAC										
2082	1968M68G19	EASA;FAA;CAAC;ANAC										
2082	1968M68G20	EASA;FAA;CAAC;ANAC										
2082	1968M68G22	EASA;FAA;CAAC;ANAC										
2082	1968M68G41	EASA;FAA;CAAC;ANAC										
2082	2256M26G03	EASA;FAA;CAAC;ANAC										
2082	2256M26G04	EASA;FAA;CAAC;ANAC										
2082	2480M46G01	EASA;FAA;CAAC;CAAC;ANAC										
2187	305-136-803-0	EASA;FAA;CAAC;ANAC;CAA I	21	28	72-62-06	TRANSFER GEARBOX - HORIZONTAL DRIVE SHAFTS	Package A	CLN/INSP	CLEANING AND INSPECTION		1155.00	SR Technics Switzerland
2187	305-136-804-0	EASA;ANAC;CAA UK			72-62-06		Package SB00	72-1078	RE-IDENT OF RADIAL DRIVE SHAFT IN FIELD		285.00	SR Technics Switzerland
2187	305-136-805-0	EASA;FAA;CAAC;ANAC;CAA UK			72-62-06		Package SB01	72-1109	REMOVAL FROM SERVICE OF SUSPECTED RADIAL DRIVE SHAFT		175.00	SR Technics Switzerland
2187	340-050-101-0	EASA;FAA;CAAC;ANAC										
2187	340-050-102-0	EASA;FAA;CAAC;ANAC										
2187	340-050-103-0	EASA;FAA;CAAC;ANAC										
2187	340-051-101-0	EASA;FAA;CAAC;ANAC										
2716	238-0851-509	EASA;FAA;CAAC;ANAC	8	21	26-10-00	CFM56-5B FIRE DETECTOR INSTALLATION	Package B		TEST		1245.00	SR Technics Switzerland
2716	642-5855-501	EASA;FAA;CAAC;ANAC										
2716	642-5855-503	EASA;FAA;CAAC;ANAC										
3016	9324M67G01	EASA;FAA;ANAC	22	28	72-33-00	COMPRESSOR REAR STATOR - ASSEMBLY	Package B	ASSEMBLY	HONEY COMB GRINDING	PN9324M67G01 9324M77G01 FOR SH	1890.00	SR Technics Switzerland
3249	108280-199	EASA;FAA;CAAC;ANAC	36	21	71-00-17	TUBES, DUCTS AND HOSES	Package A	CLN/INSP	CLEANING AND INSPECTION		465.00	SR Technics Switzerland
3249	108280-211	EASA;FAA;CAAC;ANAC			71-00-17		Package A	TEST	PRESSURE TEST		465.00	SR Technics Switzerland
3249	108280-53	EASA;FAA;CAAC;ANAC			71-00-17		Package B	1	BLEND REPAIR OF EXTERNAL TUBING, FIRE DETECTOR SUPPORT RAILS		370.00	SR Technics Switzerland
3249	110551-503	EASA;FAA;CAAC;ANAC			71-00-17		Package C	2	EXPASION REPAIR OF SMOOTH DENTS		365.00	SR Technics Switzerland
3249	110560-17	EASA;FAA;ANAC			71-00-17		Package D	3	WELD REPAIR CRACKS		370.00	SR Technics Switzerland
3249	112441-507	EASA;FAA;CAAC;ANAC			71-00-17		Package E	4	DOUBLE REPAIR AND SECTION REPLACEMENT		405.00	SR Technics Switzerland
3249	116854-507	EASA;FAA;CAAC;ANAC			71-00-17		Package J	9	WELD REPAIR FOR ANTI-ICE DUCT SHROUD ADAPTER CRACKS		475.00	SR Technics Switzerland
3249	14495-505	EASA;FAA;CAAC;ANAC			71-00-17		Package K	10	ANTI-ICE DUCT AIRGAB INSULATION REPAIR		505.00	SR Technics Switzerland
3249	14495-507	EASA;FAA;CAAC;ANAC			71-00-17		Package L	11	REPLACEMENT OF AERODYNAMIC SEALANT		275.00	SR Technics Switzerland
3249	17451-519	EASA;FAA;CAAC;ANAC			71-00-17		Package M	12	DRAIN MANIFOLD AND DRAIN ASSEMBLY RESERVOIR THREADED FIT DRAIN RESERVOIR - REPLACE ELBO		725.00	SR Technics Switzerland
3249	17451-525	EASA;FAA;CAAC;ANAC			71-00-17		Package M	12	DRAIN MANIFOLD AND DRAIN ASSEMBLY RESERVOIR THREADED FIT DRAIN MANIFOLD - REPLACE UNION		725.00	SR Technics Switzerland
3249	17452-503	EASA;FAA;CAAC;ANAC			71-00-17		Package M	12	DRAIN MANIFOLD AND DRAIN ASSEMBLY RESERVOIR THREADED FIT DRAIN MANIFOLD - REPLACE ELBOV		725.00	SR Technics Switzerland
3249	238-0502-503	EASA;FAA;CAAC;ANAC			71-00-17		Package M	12	DRAIN MANIFOLD AND DRAIN ASSEMBLY RESERVOIR THREADED FIT DRAIN RESERVOIR - REPLACE UNIO		725.00	SR Technics Switzerland
3249	238-0602-503	EASA;FAA;CAAC;ANAC			71-00-17		Package Q	16	HIGH EMISSIVITY COATING REPAIR		635.00	SR Technics Switzerland
3249	238-0612-503	EASA;FAA;CAAC;ANAC			71-00-17		Package S	18	REMOVE DAMAGED BRACKET		995.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3249	238-0701-523	EASA;FAA;CAAC;ANAC			71-00-17		Package S	18	WELD BUILD-UP BRACKET		995.00	SR Technics Switzerland
3249	238-0701-525	EASA;FAA;CAAC;ANAC			71-00-17		Package SB00	RA32036-10	PNEUMATIC - UPPER 9TH STAGE HIGH PRESSURE DUCT SUPPORT LINK REMOVAL		420.00	SR Technics Switzerland
3249	238-0701-527	EASA;FAA;CAAC;ANAC			71-00-17		Package SB01	RA32036-13	INSPECTION OF THE UPPER 9TH STAGE HP DUCT AND SUPPORT LINKS		495.00	SR Technics Switzerland
3249	238-0701-529	EASA;FAA;CAAC;ANAC			71-00-17		Package SB02	RA32036-11	INSPECTION AND MODIFICATION OF PLYON INTERFACE DUCT		575.00	SR Technics Switzerland
3249	238-0801-512	EASA;FAA;CAAC;ANAC			71-00-17		Package SB03	RA32030-4	ANTI-ICE DUCT INSULATION PAN-DOWN MODIFICATION		335.00	SR Technics Switzerland
3249	238-0801-513	EASA;FAA;CAAC;ANAC										
3249	238-0801-535	EASA;FAA;CAAC;ANAC										
3249	238-0801-539	EASA;FAA;CAAC;ANAC										
3249	238-0801-541	EASA;FAA;CAAC;ANAC										
3249	238-0801-543	EASA;FAA;CAAC;ANAC										
3249	238-0801-545	EASA;FAA;CAAC;ANAC										
3249	238-0801-547	EASA;FAA;CAAC;ANAC										
3249	238-0801-549	EASA;FAA;CAAC;ANAC										
3249	238-0801-551	EASA;FAA;CAAC;ANAC										
3249	238-0801-557	EASA;FAA;CAAC;ANAC										
3249	238-0801-561	EASA;FAA;CAAC;ANAC										
3249	238D0551-509	EASA;FAA;CAAC;ANAC										
3249	238D0551-517	EASA;FAA;CAAC;ANAC										
3249	238D0551-519	EASA;FAA;CAAC;ANAC										
3249	238D0561-503	EASA;FAA;CAAC;ANAC										
3249	238D0611-505	EASA;FAA;CAAC;ANAC										
3249	238D0611-507	EASA;FAA;CAAC;ANAC										
3249	238D0611-509	EASA;FAA;ANAC										
3249	642-5503-501	EASA;FAA;CAAC;ANAC										
3249	642-5508-503	EASA;FAA;CAAC;ANAC										
3249	642-5508-505	EASA;FAA;CAAC;ANAC										
3249	642-5510-501	EASA;FAA;CAAC;ANAC										
3249	642-5511-503	EASA;FAA;CAAC;ANAC										
3249	642-5515-507	EASA;FAA;CAAC;ANAC										
3249	642-5520-507	EASA;FAA;CAAC;ANAC										
3249	642-5612-501	EASA;FAA;CAAC;ANAC										
3249	642-5612-503	EASA;FAA;CAAC;ANAC										
3249	642-5658-501	EASA;FAA;CAAC;ANAC										
3249	642-5658-503	EASA;FAA;CAAC;ANAC										
3249	642-5754-501	EASA;FAA;CAAC;ANAC										
3249	642-5754-503	EASA;FAA;CAAC;ANAC										
3249	642-5754-505	EASA;FAA;CAAC;ANAC										
3249	642-5754-507	EASA;FAA;CAAC;ANAC										
3249	642-5801-507	EASA;FAA;CAAC;ANAC										
3249	642-5801-509	EASA;FAA;CAAC;ANAC										
3249	642-5801-511	EASA;FAA;CAAC;ANAC										
3249	642-5801-515	EASA;FAA;CAAC;ANAC										
3249	642-5801-517	EASA;FAA;CAAC;ANAC										
3249	642-5801-519	EASA;FAA;CAAC;ANAC										
3249	642-5801-521	EASA;FAA;CAAC;ANAC										
3249	642-5926-501	EASA;FAA;CAAC;ANAC										
3249	642-5926-503	EASA;FAA;CAAC;ANAC										
3249	642-5926-504	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3249	642D5752-501	EASA;FAA;CAAC;ANAC										
3249	9909873-103	EASA;FAA;CAAC;ANAC										
3249	9909874-107	EASA;FAA;CAAC;ANAC										
3249	9909874-207	EASA;FAA;CAAC;ANAC										
3249	9909875-103	EASA;FAA;CAAC;ANAC										
3249	AE705925-31	EASA;FAA;CAAC;ANAC										
3249	AE705926-19	EASA;FAA;CAAC;ANAC										
3249	AE705926-23	EASA;FAA;CAAC;ANAC										
3249	AE705926-25	EASA;FAA;CAAC;ANAC										
3249	AE706058-65	EASA;FAA;CAAC;ANAC										
3249	AE706058-8	EASA;FAA;CAAC;ANAC										
3249	AE707418-1	EASA;FAA;CAAC;ANAC										
3249	AE707419-1	EASA;FAA;CAAC;ANAC										
3249	AE707419-3	EASA;FAA;CAAC;ANAC										
3249	AE707422-1	EASA;FAA;CAAC;ANAC										
3249	AE707422-2	EASA;FAA;CAAC;ANAC										
3249	AE707422-3	EASA;FAA;CAAC;ANAC										
3249	AE708821-1	EASA;FAA;CAAC;ANAC										
3249	AE708821-2	EASA;FAA;CAAC;ANAC										
3249	AE709459-3	EASA;FAA;CAAC;ANAC										
3249	AE709461-1	EASA;FAA;CAAC;ANAC										
3249	AE710155-1	EASA;FAA;CAAC;ANAC										
3249	S700H0391-199	EASA;FAA;CAAC;ANAC										
3249	S700H0391-211	EASA;FAA;CAAC;ANAC										
3249	S700H0391-53	EASA;FAA;CAAC;ANAC										
3249	S700H0981-17	EASA;FAA;CAAC;ANAC										
3461	301-480-220-0	EASA;FAA;CAAC;ANAC	20	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		1400.00	SR Technics Switzerland
3461	301-480-221-0	EASA;FAA;CAAC;ANAC										
3461	301-480-225-0	EASA;FAA;CAAC;ANAC										
3461	301-480-320-0	EASA;FAA;CAAC;ANAC										
3461	301-480-326-0	EASA;FAA;CAAC;ANAC										
3461	301-480-720-0	EASA;FAA;CAAC;ANAC										
3461	301-480-724-0	EASA;FAA;CAAC;ANAC										
3461	301-480-726-0	EASA;FAA;CAAC;ANAC										
3461	301-480-920-0	EASA;FAA;CAAC;ANAC										
3461	301-480-923-0	EASA;FAA;CAAC;ANAC										
3461	301-480-926-0	EASA;FAA;CAAC;ANAC										
3461	301-481-220-0	EASA;FAA;CAAC;ANAC										
3461	301-481-223-0	EASA;FAA;CAAC;ANAC										
3461	301-481-225-0	EASA;FAA;CAAC;ANAC										
3461	305-100-410-0	EASA;FAA;CAAC;ANAC										
3461	305-100-415-0	EASA;FAA;CAAC;ANAC										
3461	305-115-100-0	EASA;FAA;CAAC;ANAC										
3461	305-115-104-0	EASA;FAA;CAAC;ANAC										
3461	305-115-200-0	EASA;FAA;CAAC;ANAC										
3461	305-115-201-0	EASA;FAA;CAAC;ANAC										
3461	305-115-205-0	ANAC										
3461	305-115-306-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3461	305-132-701-0	EASA;FAA;CAAC;ANAC										
3461	305-132-702-0	EASA;FAA;CAAC;ANAC										
3461	305-148-201-0	EASA;FAA;CAAC;ANAC										
3461	305-148-202-0	EASA;FAA;CAAC;ANAC										
3461	335-304-101-0	EASA;FAA;CAAC;ANAC										
3461	335-304-102-0	EASA;FAA;CAAC;ANAC										
3461	335-304-103-0	EASA;FAA;CAAC;ANAC										
3461	335-304-201-0	EASA;FAA;CAAC;ANAC										
3461	335-304-202-0	EASA;FAA;CAAC;ANAC										
3461	335-304-203-0	EASA;FAA;CAAC;ANAC										
3461	335-304-401-0	EASA;FAA;CAAC;ANAC										
3461	335-304-402-0	EASA;FAA;CAAC;ANAC										
3461	335-304-501-0	EASA;FAA;CAAC;ANAC										
3461	335-304-503-0	EASA;FAA;CAAC;ANAC										
3461	335-304-601-0	EASA;FAA;CAAC;ANAC										
3461	335-304-602-0	EASA;FAA;CAAC;ANAC										
3461	335-304-603-0	EASA;FAA;CAAC;ANAC										
3461	335-304-901-0	EASA;FAA;CAAC;ANAC										
3461	335-304-902-0	EASA;FAA;CAAC;ANAC										
3461	335-304-903-0	EASA;FAA;CAAC;ANAC										
3461	340-050-401-0	EASA;FAA;CAAC;ANAC										
3461	340-050-402-0	EASA;FAA;CAAC;ANAC										
3461	340-050-404-0	EASA;FAA;ANAC										
3461	340-050-901-0	EASA;FAA;CAAC;ANAC										
3461	340-050-902-0	EASA;FAA;CAAC;ANAC										
3461	340-051-001-0	EASA;FAA;CAAC;ANAC										
3461	340-051-002-0	EASA;FAA;CAAC;ANAC										
3461	340-052-502-0	EASA;FAA;CAAC;ANAC										
3461	340-052-503-0	EASA;FAA;CAAC;ANAC										
3461	340-052-602-0	EASA;FAA;CAAC;ANAC										
3461	340-052-603-0	EASA;FAA;CAAC;ANAC										
3461	340-054-502-0	EASA;FAA;CAAC;ANAC										
3461	340-054-503-0	EASA;FAA;CAAC;ANAC										
3461	340-055-801-0	EASA;FAA;CAAC;ANAC										
3461	340-055-901-0	EASA;FAA;CAAC;ANAC										
3461	340-056-001-0	EASA;FAA;CAAC;ANAC										
3461	340-056-101-0	EASA;FAA;CAAC;ANAC										
3461	340-056-102-0	EASA;FAA;ANAC;CAA UK										
3461	340-056-202-0	EASA;FAA;CAAC;ANAC										
3461	340-056-302-0	EASA;FAA;CAAC;ANAC										
3461	340-056-401-0	EASA;FAA;CAAC;ANAC										
3461	340-154-101-0	EASA;FAA;CAAC;ANAC										
3461	340-154-201-0	EASA;FAA;CAAC;ANAC										
3461	340-155-101-0	EASA;FAA;CAAC;ANAC										
3461	9541M89P01	EASA;FAA;CAAC;ANAC										
3461	9725M84P08	EASA;FAA;CAAC;ANAC										
3461	9725M84P09	EASA;FAA;CAAC;ANAC										
3461	9972M33P06	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
3461	9972M33P07	EASA;FAA;CAAC;ANAC										
3461	9972M33P08	EASA;FAA;CAAC;ANAC										
3461	9972M34P08	EASA;FAA;CAAC;ANAC										
3461	9972M34P09	EASA;FAA;CAAC;ANAC										
3461	9972M34P10	EASA;FAA;CAAC;ANAC										
3941	J816P050A	EASA;FAA;CAAC;ANAC	6	28	72-21-11	CFM56 BOLT-SHEAR DBL HEX HD FAN AND BOOS	Package A	CLN/INSP	CLEANING AND INSPECTION		40.00	SR Technics Switzerland
3941	J816P060A	EASA;FAA;CAAC;ANAC										
7611	390-610-001-0	EASA;FAA;CAAC;ANAC	7	21	73-21-94	CFM56-5B IDENTIFICATION PLUG (PUSH - PULL)	Package A	TEST	TESTING AND TROUBLESHOOTING		360.00	SR Technics Switzerland
7611	390-610-501-0	EASA;FAA;CAAC;ANAC			73-21-94		Package B		REPAIR		810.00	SR Technics Switzerland
7611	390-611-001-0	EASA;FAA;CAAC;ANAC			73-21-94		Package C		OVERHAUL		1225.00	SR Technics Switzerland
7611	390-611-101-0	EASA;FAA;CAAC;ANAC			73-21-94		Package SB00	SB 72-0340	INTRODUCTION OF NEW RECONFIGURABLE HYBRID TECHNOLOGY IDENTIFICATION CONNECTORS		325.00	SR Technics Switzerland
7611	390-611-201-0	EASA;FAA;CAAC;ANAC			73-21-94		Package SB01	SB 73-0218	INTRODUCTION OF NEW CODING FOR TECH INSERTION ENGINE MODELS		325.00	SR Technics Switzerland
7611	390-611-301-0	EASA;FAA;CAAC;ANAC;CAA UK			73-21-94		Package SB02	SB 73-0219	INTRODUCTION OF NEW COING FOR TECH INSERTION ENGINE MODELS		325.00	SR Technics Switzerland
7611	390-611-401-0	EASA;FAA;CAAC;ANAC										
7611	390-611-501-0	EASA;FAA;CAAC;ANAC										
7611	390-611-601-0	EASA;FAA;CAAC;ANAC										
7611	390-611-801-0	EASA;FAA;CAAC;ANAC										
8459	238-0802-503	EASA;FAA;CAAC;ANAC	15	21	71-70-00	DRAIN MODULE MANIFOLD	Package B	LIGHT	DISASSEMBLY,CLEANING, INSPECTION, ASSEMBLY AND FINAL TEST. EXCLUDED PIECE PART REPAIRS.		630.00	SR Technics Switzerland
8459	238-0804-503	EASA;FAA;CAAC;ANAC			71-70-00		Package M	012	REPAIR		1910.00	SR Technics Switzerland
8459	238-0811-501	EASA;FAA;CAAC;ANAC										
11542	301-792-202-0	EASA;FAA;CAAC;ANAC	43	28	72-23-35	FAN FRAME ASSEMBLY - FAN FRAME HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		140.00	SR Technics Switzerland
11542	301-792-302-0	EASA;FAA;CAAC;ANAC										
11542	305-355-901-0	EASA;FAA;ANAC										
11542	337-060-801-0	EASA;FAA;ANAC										
11542	338-077-001-0	EASA;FAA;ANAC										
11542	340-005-202-0	EASA;FAA;CAAC;ANAC										
11542	340-005-301-0	EASA;FAA;CAAC;ANAC										
11542	340-005-302-0	EASA;FAA;CAAC;ANAC										
11542	340-005-401-0	EASA;FAA;CAAC;ANAC										
11542	340-005-402-0	EASA;FAA;CAAC;ANAC										
11542	340-005-502-0	EASA;FAA;CAAC;ANAC										
11542	340-005-602-0	EASA;FAA;CAAC;ANAC										
11542	340-005-801-0	EASA;FAA;CAAC;ANAC										
11542	340-005-802-0	EASA;FAA;CAAC;ANAC										
11542	340-006-202-0	EASA;FAA;CAAC;ANAC										
11542	340-006-301-0	EASA;FAA;CAAC;ANAC										
11542	340-006-502-0	EASA;FAA;CAAC;ANAC										
11542	340-006-503-0	EASA;FAA;CAAC;ANAC										
11542	340-006-504-0	EASA;FAA;CAAC;ANAC										
11542	340-006-602-0	EASA;FAA;CAAC;ANAC										
11542	340-006-603-0	EASA;FAA;CAAC;ANAC										
11542	340-006-604-0	EASA;FAA;CAAC;ANAC										
11542	340-006-702-0	EASA;FAA;CAAC;ANAC										
11542	340-006-703-0	EASA;FAA;CAAC;ANAC										
11542	340-006-802-0	EASA;FAA;CAAC;ANAC										
11542	340-006-803-0	EASA;FAA;CAAC;ANAC										
11542	340-007-304-0	EASA;FAA;CAAC;ANAC										
11542	340-007-404-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	340-008-703-0	EASA;FAA;CAAC;ANAC										
11542	340-008-801-0	EASA;FAA;CAAC;ANAC										
11542	340-008-902-0	EASA;FAA;CAAC;ANAC										
11542	340-008-903-0	EASA;FAA;CAAC;ANAC										
11542	340-008-904-0	EASA;FAA;CAAC;ANAC										
11542	340-009-003-0	EASA;FAA;CAAC;ANAC										
11542	340-009-004-0	EASA;FAA;CAAC;ANAC										
11542	340-013-703-0	EASA;FAA;CAAC;ANAC										
11542	340-015-003-0	EASA;FAA;CAAC;ANAC										
11542	340-015-004-0	EASA;FAA;CAAC;ANAC										
11542	340-017-002-0	EASA;FAA;CAAC;ANAC										
11542	340-017-305-0	EASA;FAA;CAAC;ANAC										
11542	340-017-306-0	EASA;FAA;CAAC;ANAC										
11542	340-017-502-0	EASA;FAA;CAAC;ANAC										
11542	340-017-601-0	EASA;FAA;CAAC;ANAC										
11542	340-017-602-0	EASA;FAA;CAAC;ANAC										
11542	340-017-804-0	EASA;FAA;CAAC;ANAC										
11542	340-017-805-0	EASA;FAA;CAAC;ANAC										
11542	340-017-806-0	EASA;FAA;CAAC;ANAC										
11542	340-019-903-0	EASA;FAA;CAAC;ANAC										
11542	340-020-001-0	EASA;FAA;CAAC;ANAC										
11542	340-020-105-0	EASA;FAA;CAAC;ANAC										
11542	340-020-203-0	EASA;FAA;CAAC;ANAC										
11542	340-020-303-0	EASA;FAA;CAAC;ANAC										
11542	340-020-403-0	EASA;FAA;CAAC;ANAC										
11542	340-020-404-0	EASA;FAA;CAAC;ANAC										
11542	340-022-501-0	EASA;FAA;CAAC;ANAC										
11542	340-022-502-0	EASA;FAA;CAAC;ANAC										
11542	340-022-901-0	EASA;FAA;CAAC;ANAC										
11542	340-023-301-0	EASA;FAA;CAAC;ANAC										
11542	340-023-302-0	EASA;FAA;CAAC;ANAC										
11542	340-023-404-0	EASA;FAA;CAAC;ANAC										
11542	340-023-405-0	EASA;FAA;CAAC;ANAC										
11542	340-025-402-0	EASA;FAA;CAAC;ANAC										
11542	340-025-503-0	EASA;FAA;CAAC;ANAC										
11542	340-087-804-0	EASA;FAA;CAAC;ANAC										
11542	340-088-503-0	EASA;FAA;CAAC;ANAC										
11542	340-088-602-0	EASA;FAA;CAAC;ANAC										
11542	340-088-901-0	EASA;FAA;CAAC;ANAC										
11542	340-089-001-0	EASA;FAA;CAAC;ANAC										
11542	340-090-301-0	EASA;FAA;CAAC;ANAC										
11542	340-090-402-0	EASA;FAA;CAAC;ANAC										
11542	340-090-501-0	EASA;FAA;CAAC;ANAC										
11542	340-090-601-0	EASA;FAA;CAAC;ANAC										
11542	340-090-602-0	EASA;FAA;CAAC;ANAC										
11542	340-090-603-0	EASA;FAA;CAAC;ANAC										
11542	340-090-701-0	EASA;FAA;CAAC;ANAC										
11542	340-090-902-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	340-091-001-0	EASA;FAA;CAAC;ANAC										
11542	340-091-403-0	EASA;FAA;CAAC;ANAC										
11542	340-093-701-0	EASA;FAA;CAAC;ANAC										
11542	340-095-501-0	EASA;FAA;CAAC;ANAC										
11542	340-095-602-0	EASA;FAA;CAAC;ANAC										
11542	340-095-603-0	EASA;FAA;CAAC;ANAC										
11542	340-095-703-0	EASA;FAA;CAAC;ANAC										
11542	340-096-003-0	EASA;FAA;CAAC;ANAC										
11542	340-096-004-0	EASA;FAA;CAAC;ANAC										
11542	340-096-005-0	EASA;FAA;ANAC										
11542	340-096-006-0	EASA;FAA;CAAC;ANAC										
11542	340-099-001-0	EASA;FAA;CAAC;ANAC										
11542	340-099-101-0	EASA;FAA;CAAC;ANAC										
11542	340-099-902-0	EASA;FAA;CAAC;ANAC										
11542	340-099-903-0	EASA;FAA;CAAC;ANAC										
11542	340-103-902-0	EASA;FAA;CAAC;ANAC										
11542	340-103-903-0	EASA;FAA;CAAC;ANAC										
11542	340-104-301-0	EASA;FAA;CAAC;ANAC										
11542	340-104-601-0	EASA;FAA;CAAC;ANAC										
11542	340-105-903-0	EASA;FAA;CAAC;ANAC										
11542	340-106-005-0	EASA;FAA;CAAC;ANAC										
11542	340-106-006-0	EASA;FAA;CAAC;ANAC										
11542	340-106-007-0	EASA;FAA;CAAC;ANAC										
11542	340-106-203-0	EASA;FAA;CAAC;ANAC										
11542	340-106-302-0	EASA;FAA;CAAC;ANAC										
11542	340-106-504-0	EASA;FAA;CAAC;ANAC										
11542	340-106-602-0	EASA;FAA;CAAC;ANAC										
11542	340-106-704-0	EASA;FAA;CAAC;ANAC										
11542	340-109-601-0	EASA;FAA;CAAC;ANAC										
11542	340-109-602-0	EASA;FAA;CAAC;ANAC										
11542	340-112-113-0	EASA;FAA;CAAC;ANAC										
11542	340-115-302-0	EASA;FAA;CAAC;ANAC										
11542	340-115-303-0	EASA;FAA;CAAC;ANAC										
11542	340-118-303-0	EASA;FAA;CAAC;ANAC										
11542	340-118-702-0	EASA;FAA;CAAC;ANAC										
11542	340-118-704-0	EASA;FAA;CAAC;ANAC										
11542	340-118-705-0	EASA;FAA;ANAC										
11542	340-120-501-0	EASA;FAA;CAAC;ANAC										
11542	340-120-601-0	EASA;FAA;CAAC;ANAC										
11542	340-120-702-0	EASA;FAA;CAAC;ANAC										
11542	340-120-803-0	EASA;FAA;CAAC;ANAC										
11542	340-120-901-0	EASA;FAA;CAAC;ANAC										
11542	340-121-001-0	EASA;FAA;CAAC;ANAC										
11542	340-121-101-0	EASA;FAA;CAAC;ANAC										
11542	340-121-201-0	EASA;FAA;CAAC;ANAC										
11542	340-121-401-0	EASA;FAA;CAAC;ANAC										
11542	340-121-502-0	EASA;FAA;CAAC;ANAC										
11542	340-121-602-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
11542	340-121-702-0	EASA;FAA;CAAC;ANAC										
11542	340-121-802-0	EASA;FAA;CAAC;ANAC										
11542	340-122-501-0	EASA;FAA;CAAC;ANAC										
11542	340-122-502-0	EASA;FAA;CAAC;ANAC										
11542	340-122-503-0	EASA;FAA;CAAC;ANAC										
11542	340-122-504-0	EASA;FAA;CAAC;ANAC										
11542	340-123-401-0	EASA;FAA;CAAC;ANAC										
11542	340-123-703-0	EASA;FAA;CAAC;ANAC										
11542	340-123-704-0	EASA;FAA;CAAC;ANAC										
11542	340-123-803-0	EASA;FAA;CAAC;ANAC										
11542	340-123-902-0	EASA;FAA;CAAC;ANAC										
11542	340-124-001-0	EASA;FAA;CAAC;ANAC										
11542	340-124-101-0	EASA;FAA;CAAC;ANAC										
11542	340-124-202-0	EASA;FAA;CAAC;ANAC										
11542	340-124-302-0	EASA;FAA;CAAC;ANAC										
11542	340-124-402-0	EASA;FAA;CAAC;ANAC										
11542	340-124-501-0	EASA;FAA;CAAC;ANAC										
11542	340-124-502-0	EASA;FAA;CAAC;ANAC										
11542	340-124-604-0	EASA;FAA;CAAC;ANAC										
11542	340-124-605-0	EASA;FAA;CAAC;ANAC										
11542	340-124-701-0	EASA;FAA;CAAC;ANAC										
11542	340-124-801-0	EASA;FAA;CAAC;ANAC										
11542	340-124-802-0	EASA;FAA;CAAC;ANAC										
11542	340-124-803-0	EASA;FAA;ANAC										
11542	340-125-702-0	EASA;FAA;CAAC;ANAC										
11542	340-125-703-0	EASA;FAA;CAAC;ANAC										
11542	340-126-102-0	EASA;FAA;CAAC;ANAC										
11542	340-126-104-0	EASA;FAA;CAAC;ANAC										
11542	340-126-107-0	EASA;FAA;ANAC										
11542	340-126-701-0	EASA;FAA;CAAC;ANAC										
11542	340-126-702-0	EASA;FAA;CAAC;ANAC										
11542	340-126-802-0	EASA;FAA;CAAC;ANAC										
11542	340-128-302-0	EASA;FAA;CAAC;ANAC										
11542	340-128-303-0	EASA;FAA;CAAC;ANAC										
11542	340-130-001-0	EASA;FAA;CAAC;ANAC										
11542	340-130-701-0	EASA;FAA;CAAC;ANAC										
11542	340-131-208-0	EASA;FAA;CAAC;ANAC										
11542	340-134-302-0	EASA;FAA;CAAC;ANAC										
11542	340-150-702-0	EASA;FAA;CAAC;ANAC										
11542	340-159-301-0	EASA;FAA;CAAC;ANAC										
11542	649-002-265-0	EASA;FAA;CAAC;ANAC										
11542	649-771-090-0	EASA;FAA;CAAC;ANAC										
11542	649-771-092-0	EASA;FAA;CAAC;ANAC										
11542	649-771-093-0	EASA;FAA;CAAC;ANAC										
11542	649-786-799-0	EASA;FAA;CAAC;ANAC										
11542	J534P04	EASA;FAA;CAAC;ANAC										
11542	J534P08	EASA;FAA;CAAC;ANAC										
11542	J534P54	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
12552	ALL450-001-0	EASA;FAA;CAAC;ANAC	3	21	71-00-01	CFM56-5B ADAPTER RING KIT V-GROOVE	Package B	SPEC-PROC-002	MAJOR DAMAGE-REPLACE		1075.00	SR Technics Switzerland
12552	ALL450-003-0	EASA;FAA;CAAC;ANAC			71-00-01		Package B	SPEC-PROC-002	INSPECTION V-GROOVE		1075.00	SR Technics Switzerland
13451	301-566-807-0	EASA;FAA;CAAC;ANAC	22	28	72-23-10	FAN FRAME ASSEMBLY - AGB STRAIGHT MOUNT PIN	Package A	CLN/INSP	CLEANING AND INSPECTION		145.00	SR Technics Switzerland
13451	336-030-701-0	EASA;FAA;CAAC;ANAC										
13451	J626P09	EASA;FAA;ANAC										
13451	J626P10	EASA;FAA;ANAC										
13451	J626P11	EASA;FAA;ANAC										
13459	301-417-104-0	EASA;FAA;CAAC;ANAC	20	28	72-23-12	FAN FRAME STRUTS INTERNAL TUBING	Package A	CLN/INSP	CLEANING AND INSPECTION		605.00	SR Technics Switzerland
13459	301-464-713-0	EASA;FAA;CAAC;ANAC										
13459	336-009-504-0	EASA;FAA;CAAC;ANAC										
13459	336-009-505-0	EASA;FAA;CAAC;ANAC										
13459	336-028-701-0	EASA;FAA;CAAC;ANAC										
13459	337-113-201-0	EASA;FAA;CAAC;ANAC										
13459	337-114-602-0	EASA;FAA;CAAC;ANAC										
13459	337-115-002-0	EASA;FAA;CAAC;ANAC										
13459	337-115-052-0	EASA;FAA;CAAC;ANAC										
13459	340-029-901-0	EASA;FAA;CAAC;ANAC										
13459	340-030-202-0	EASA;FAA;CAAC;ANAC										
13459	340-030-702-0	EASA;FAA;CAAC;ANAC										
13459	340-031-101-0	EASA;FAA;CAAC;ANAC										
13459	340-031-401-0	EASA;FAA;CAAC;ANAC										
13459	340-031-901-0	EASA;FAA;CAAC;ANAC										
13473	336-053-701-0	EASA;FAA;CAAC;ANAC	26	28	72-23-16	FAN FRAME ASSEMBLY - VARIABLE BLEED VALVE FEEDBACK	Package A	CLN/INSP	CLEANING AND INSPECTION		260.00	SR Technics Switzerland
13473	336-057-802-0	EASA;FAA;CAAC;ANAC										
13473	340-074-402-0	EASA;FAA;CAAC;ANAC										
13473	340-074-505-0	EASA;FAA;CAAC;ANAC										
13473	340-079-204-0	EASA;FAA;CAAC;ANAC										
13473	340-079-303-0	EASA;FAA;CAAC;ANAC										
13473	340-079-403-0	EASA;FAA;CAAC;ANAC										
13473	340-085-202-0	EASA;FAA;CAAC;ANAC										
13473	340-085-302-0	EASA;FAA;CAAC;ANAC										
13473	340-085-401-0	EASA;FAA;CAAC;ANAC										
13473	340-085-402-0	EASA;FAA;CAAC;ANAC										
13473	340-168-301-0	EASA;FAA;CAAC;ANAC										
13473	340-168-601-0	EASA;FAA;CAAC;ANAC										
13473	340-168-701-0	EASA;FAA;CAAC;ANAC										
13903	336-042-501-0	EASA;FAA;CAAC;ANAC	18	28	72-54-10	LOW PRESSURE TURBINE - THERMAL INSULATION BLANKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		125.00	SR Technics Switzerland
13903	336-042-540-0	EASA;FAA;CAAC;ANAC			72-54-10		Package B	001	PATCH REPAIR OF INSULATION BLANKETS		230.00	SR Technics Switzerland
13903	336-042-560-0	EASA;FAA;CAAC;ANAC										
13903	336-042-640-0	EASA;FAA;CAAC;ANAC										
13903	336-042-680-0	EASA;FAA;CAAC;ANAC										
13903	336-042-701-0	EASA;FAA;CAAC;ANAC										
13903	336-042-740-0	EASA;FAA;CAAC;ANAC										
13903	338-072-002-0	EASA;FAA;CAAC;ANAC										
13903	338-072-021-0	EASA;FAA;CAAC;ANAC										
13903	338-072-042-0	EASA;FAA;CAAC;ANAC										
13903	338-072-061-0	EASA;FAA;CAAC;ANAC										
13903	338-072-081-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
13903	338-086-702-0	EASA;FAA;CAAC;ANAC										
13903	338-086-752-0	EASA;FAA;CAAC;ANAC										
15379	336-043-302-0	EASA;FAA;CAAC;ANAC	5	28	72-56-01	CFM56-5B/7B INSULTION BLANKET	Package A	CLN/INSP	CLEANING AND INSPECTION		385.00	SR Technics Switzerland
15379	338-107-002-0	EASA;FAA;CAAC;ANAC			72-56-01		Package AD	029	REPLACEMENT OF INSULATION ASSEMBLY		240.00	SR Technics Switzerland
15379	338-107-003-0	EASA;FAA;CAAC;ANAC										
15379	338-107-102-0	EASA;FAA;CAAC;ANAC										
15379	338-107-103-0	EASA;FAA;CAAC;ANAC										
15379	338-107-202-0	EASA;FAA;CAAC;ANAC										
15379	338-107-203-0	EASA;FAA;CAAC;ANAC										
15379	340-101-604-0	EASA;FAA;CAAC;ANAC										
15379	340-101-704-0	EASA;FAA;CAAC;ANAC										
15379	340-156-503-0	EASA;FAA;CAAC;ANAC										
15379	340-156-603-0	EASA;FAA;CAAC;ANAC										
15379	340-156-703-0	EASA;FAA;CAAC;ANAC										
19228	056-000-221-0	EASA;FAA;CAAC;ANAC	28	21	72-56-01	LOW PRESSURE TURBINE REAR FRAME - BEARING NO.5 OIL S	Package A	CLN/INSP	CLEANING AND INSPECTION		650.00	SR Technics Switzerland
19228	056-000-302-6	EASA;FAA;CAAC;ANAC			72-56-01		Package AK	036	REPAIR OF CRACKS TACK WELDING OF THE OIL SUPPLY TUBE BY WELD BUILD UP		995.00	SR Technics Switzerland
19228	334-007-367-0	EASA;FAA;CAAC;ANAC			72-56-01		Package S	018	FULL OR PARTIAL REPLACEMENT OF THE OIL SCAVENGE TUBE ASSEMBLY		1190.00	SR Technics Switzerland
19228	336-052-111-0	EASA;FAA;CAAC;ANAC			72-56-01		Package SB00	72-0570	INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WITH NEW OIL SCAVENGE TUBE		345.00	SR Technics Switzerland
19228	338-103-405-0	EASA;FAA;CAAC;ANAC										
19228	340-166-101-0	EASA;FAA;CAAC;ANAC										
21823	338-063-602-0	EASA;FAA;CAAC;ANAC	32	28	72-54-04	LOW PRESSURE TURBINE - SHROUD SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		700.00	SR Technics Switzerland
21823	338-122-202-0	EASA;FAA;CAAC;ANAC;CAA UK										
23002	301-581-006-0	EASA;FAA;CAAC;ANAC	20	28	72-54-20	LOW PRESSURE TURBINE - HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		320.00	SR Technics Switzerland
23002	301-581-007-0	EASA;FAA;CAAC;ANAC										
23002	305-074-104-0	EASA;FAA;CAAC;ANAC										
23002	336-026-002-0	EASA;FAA;CAAC;ANAC										
23002	336-026-052-0	EASA;FAA;CAAC;ANAC										
23002	336-031-201-0	EASA;FAA;CAAC;ANAC										
23002	336-031-301-0	EASA;FAA;CAAC;ANAC										
23002	336-031-401-0	EASA;FAA;CAAC;ANAC										
23002	336-031-501-0	EASA;FAA;CAAC;ANAC										
23002	336-044-102-0	EASA;FAA;CAAC;ANAC										
23002	336-044-202-0	EASA;FAA;CAAC;ANAC										
23002	336-049-301-0	EASA;FAA;CAAC;ANAC										
23002	336-049-603-0	EASA;FAA;CAAC;ANAC										
23002	336-053-602-0	EASA;FAA;CAAC;ANAC										
23002	336-055-106-0	EASA;FAA;CAAC;ANAC										
23002	336-063-001-0	EASA;FAA;CAAC;ANAC										
23002	338-063-501-0	EASA;FAA;CAAC;ANAC										
23002	338-065-501-0	EASA;FAA;CAAC;ANAC										
23002	338-069-901-0	EASA;FAA;CAAC;ANAC										
23002	338-069-951-0	EASA;FAA;CAAC;ANAC										
23002	338-086-101-0	EASA;FAA;CAAC;ANAC										
23002	338-111-801-0	EASA;FAA;CAAC;ANAC										
23002	338-111-901-0	EASA;FAA;CAAC;ANAC										
23002	338-116-402-0	EASA;FAA;CAAC;ANAC										
23002	338-116-502-0	EASA;FAA;CAAC;ANAC										
23002	338-116-503-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
23002	338-116-602-0	EASA;FAA;CAAC;ANAC										
23002	338-116-603-0	EASA;FAA;CAAC;ANAC										
23002	338-116-702-0	EASA;FAA;CAAC;ANAC										
23002	338-121-701-0	EASA;FAA;CAAC;ANAC										
23002	338-121-702-0	EASA;FAA;CAAC;ANAC										
23002	338-180-201-0	EASA;FAA;CAAC;ANAC										
23002	340-304-901-0	EASA;FAA;ANAC										
23002	340-306-301-0	EASA;FAA;CAAC;ANAC										
23002	649-051-001-0	EASA;FAA;CAAC;ANAC										
23180	1387M47G01	EASA;FAA;CAAC;ANAC	13	28	72-53-02	HPT SHROUD - NOZZLE SUPPORT AFT	Package A	CLN/INSP	CLEANING AND INSPECTION		235.00	SR Technics Switzerland
23180	1523M72G01	EASA;FAA;CAAC;ANAC			72-53-02		Package A	INSP-001	PERFORM HEAT INITIAL CONTOUR		235.00	SR Technics Switzerland
23180	2002M71G01	EASA;FAA;CAAC;ANAC										
55101	321-451-602-0	EASA;FAA;CAAC;ANAC	5	21	78-36-85	HOLD-OPEN ROD COMPONENT	Package A	CLN/INSP	CLEANING AND INSPECTION		365.00	SR Technics Switzerland
55101	321-451-604-0	EASA;FAA;CAAC;ANAC										
55101	321-451-605-0	EASA;FAA;CAAC;ANAC										
55101	321-451-606-0	EASA;FAA;CAAC;ANAC										
55101	321-451-654-0	EASA;FAA;CAAC;ANAC										
55101	321-451-655-0	EASA;FAA;CAAC;ANAC										
55101	321-455-202-0	EASA;FAA;CAAC;ANAC										
62444	301-298-111-0	EASA;FAA;CAAC;ANAC	19	28	72-22-15	NO.1 AND NO.2 BEARING SUPPORT - PHONIC WHEEL	Package A	CLN/INSP	CLEANING AND INSPECTION		375.00	SR Technics Switzerland
62444	301-298-113-0	EASA;FAA;CAAC;ANAC										
62444	340-034-701-0	EASA;FAA;CAAC;ANAC										
65986	1318M20G03	EASA;FAA;CAAC;ANAC	25	28	72-32-11	COMPRESSOR FRONT STATOR - VARIABLE VANE ACTUATION	Package A	CLN/INSP	CLEANING AND INSPECTION		500.00	SR Technics Switzerland
65986	1318M20G04	EASA;FAA;CAAC;ANAC			72-32-11		Package A	INSP-001	SECURE LOOSE STRAIGHT PIN		500.00	SR Technics Switzerland
65986	1318M21G03	EASA;FAA;CAAC;ANAC			72-32-11		Package A	INSP-001	REPLACE FLANGED BUSHINGS		500.00	SR Technics Switzerland
65986	1318M22G03	EASA;FAA;CAAC;ANAC			72-32-11		Package A	INSP-001	ISPECTION FOR SUSPECTED CRACKS		500.00	SR Technics Switzerland
65986	1318M23G03	EASA;FAA;CAAC;ANAC										
65986	1318M50G03	EASA;FAA;CAAC;ANAC										
65986	1318M51G01	EASA;FAA;CAAC;ANAC										
65986	1318M51G03	EASA;FAA;CAAC;ANAC										
65986	1318M52G01	EASA;FAA;CAAC;ANAC										
65986	1318M52G03	EASA;FAA;CAAC;ANAC										
65986	1318M53G03	EASA;FAA;CAAC;ANAC										
65986	9524M85P02	EASA;FAA;CAAC;ANAC										
68796	1887M11G01	EASA;FAA;CAAC;ANAC	31	28	72-00-52	ENGINE MODULES/ASSEMBLIES - HIGH PRESSURE TURBINE F	Package A	CLN/INSP	CLEANING AND INSPECTION	EDDY CURRENT INSPECTION (ECI)	3710.00	SR Technics Switzerland
68796	9324M21G01	EASA;FAA;CAAC;ANAC			72-00-52		Package B	001	REP-001 REPLACE MARKED CLINCH N	72-52-02	290.00	SR Technics Switzerland
72544	305-165-501-0	EASA;FAA;CAAC;ANAC	13	28	72-63-05	ACCESSORY GEARBOX - LUBRICATION UNIT DRIVE SHAFT	Package A	CLN/INSP	CLEANING AND INSPECTION		190.00	SR Technics Switzerland
72544	335-312-603-0	EASA;FAA;CAAC;ANAC										
134895	740123	EASA;FAA;CAAC;ANAC	5	21	24-19-10	CFM56-5B QAD ADAPTER KIT	Package A	CLN/INSP	CLEANING AND INSPECTION		850.00	SR Technics Switzerland
134895	740123A	EASA;FAA;CAAC;ANAC										
135026	238-0451-509	EASA;FAA;CAAC;ANAC	18	35	78-11-05	EXHAUST - CENTERBODY ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		3430.00	SR Technics Switzerland
135026	238-0451-511	EASA;FAA;CAAC;ANAC										
135026	238-0451-513	EASA;FAA;CAAC;ANAC										
135026	238-0451-515	EASA;FAA;CAAC;ANAC										
135026	238-0451-523	EASA;FAA;CAAC;ANAC										
135150	1348M21P01	EASA;FAA;CAAC;ANAC	10	21	77-23-10	T3 SENSOR, COMPRESSOR OUTLET TEMPERATURE	Package C	TEST	INSPECTION AND TEST		1015.00	SR Technics Switzerland
135150	1348M21P04	EASA;FAA;CAAC;ANAC										
135150	1348M21P05	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
135150	1853M47P02	EASA;FAA;CAAC;ANAC										
135150	8TC19AAJ1	EASA;FAA;CAAC;ANAC										
135150	8TC19AAK1	EASA;FAA;CAAC;ANAC										
135150	8TC19AAP1	EASA;FAA;CAAC;ANAC										
135150	8TC19AAR1	EASA;FAA;CAAC;ANAC										
135170	301-795-702-0	EASA;FAA;CAAC;ANAC	15	21	77-21-14	THERMOCOUPLE WIRING HARNESS	Package B	TEST	PRE TEST	TESTING AND FAULT ISOLATION	485.00	SR Technics Switzerland
135170	CA170-00	EASA;FAA;CAAC;ANAC			77-21-14		Package C	TEST	TEST		1045.00	SR Technics Switzerland
135170	CA170-01	EASA;FAA;CAAC;ANAC			77-21-14		Package SB00	CA211-77-002	FRONT TRANSIENT PROTECTION BOARD FUSE	INSPECTION AND RE IN CONJUNCTION WITH PACKAGE O	505.00	SR Technics Switzerland
135170	CA170-02	EASA;FAA;CAAC;ANAC										
135170	CA171-00	EASA;FAA;CAAC;ANAC										
135170	CA171-01	EASA;FAA;CAAC;ANAC										
135170	CA171-02	EASA;FAA;CAAC;ANAC										
135170	CA172-02	EASA;FAA;CAAC;ANAC										
135170	CA172-03	EASA;FAA;CAAC;ANAC										
135170	CA172-04	EASA;FAA;CAAC;ANAC										
135170	CA211-00	EASA;FAA;CAAC;ANAC										
135170	CA212-00	EASA;FAA;CAAC;ANAC;DGCA CIVIL AVIATION OF INDONESIA										
135170	CA213-00	EASA;FAA;CAAC;ANAC										
135170	TC254-01	EASA;FAA;CAAC;ANAC										
135170	TC254-02	EASA;FAA;CAAC;ANAC										
135170	TC255-01	EASA;FAA;CAAC;ANAC										
135170	TC255-02	EASA;FAA;CAAC;ANAC										
135170	TC255-03	EASA;FAA;CAAC;ANAC										
135170	TC255-04	EASA;FAA;CAAC;ANAC										
135170	TC315-00	EASA;FAA;CAAC;ANAC										
135170	TC315-01	EASA;FAA;CAAC;ANAC										
135170	TC315-02	EASA;FAA;CAAC;ANAC										
135170	TC316-00	EASA;FAA;CAAC;ANAC										
135170	TC316-01	EASA;FAA;CAAC;ANAC										
135170	TC316-02	EASA;FAA;CAAC;ANAC										
138941	335-190-201-0	EASA;FAA;CAAC;ANAC	33	28	72-21-07	FAN AND BOOSTER - BOOSTER BLADES LOCK ASSEMBLY, ST, Package A	CLN/INSP		CLEANING AND INSPECTION		275.00	SR Technics Switzerland
138941	335-190-202-0	EASA;FAA;CAAC;ANAC			72-21-07		Package B	001	REPLACEMENT OF THE SELF-LOCKING THREADED INSERTS		165.00	SR Technics Switzerland
138941	335-190-301-0	EASA;FAA;CAAC;ANAC										
138941	335-190-302-0	EASA;FAA;CAAC;ANAC										
138941	335-190-401-0	EASA;FAA;CAAC;ANAC										
138941	335-190-402-0	EASA;FAA;CAAC;ANAC										
138941	338-006-201-0	EASA;FAA;CAAC;ANAC										
138941	338-006-202-0	EASA;FAA;CAAC;ANAC										
138941	338-006-301-0	EASA;FAA;CAAC;ANAC										
138941	338-006-302-0	EASA;FAA;CAAC;ANAC										
138941	338-006-401-0	EASA;FAA;CAAC;ANAC										
138941	338-006-402-0	EASA;FAA;CAAC;ANAC										
138941	338-006-501-0	EASA;FAA;CAAC;ANAC										
138941	338-006-502-0	EASA;FAA;CAAC;ANAC										
138945	1523M38P06	EASA;FAA;CAAC;ANAC	22	28	72-31-20	COMPRESSOR ROTOR - SELF-WRENCHING HOOK BOLTS	Package A	CLN/INSP	CLEANING AND INSPECTION	TECHNICAL INSTRUCTION (TI)	45.00	SR Technics Switzerland
138945	1523M39P07	EASA;FAA;CAAC;ANAC										
138945	2116M22P01	EASA;FAA;CAAC;ANAC										
138945	9115M80P06	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
138945	9977M25P01	EASA;FAA;CAAC;ANAC										
138947	1385M33G02	EASA;FAA;CAAC;ANAC	5	28	72-32-10	CFM56 ARM ASSY-VANE ACTUATION	Package A	CLN/INSP	CLEANING & INSPECTION		55.00	SR Technics Switzerland
138947	1385M33G03	EASA;FAA;CAAC;ANAC			72-32-10		Package SB00	72-0171	FAN & BOOSTER, MOD.FROM -5B/2 TO -5B/2P		35.00	SR Technics Switzerland
138947	1385M34G01	EASA;FAA;CAAC;ANAC										
138947	1385M34G02	EASA;FAA;CAAC;ANAC										
138947	1834M58G01	EASA;FAA;CAAC;ANAC										
138947	1834M58G02	EASA;FAA;CAAC;ANAC										
138947	1834M59G01	EASA;FAA;CAAC;ANAC										
138947	1834M59G02	EASA;FAA;CAAC;ANAC										
138947	9511M79G01	EASA;FAA;CAAC;ANAC										
138947	9511M79G02	EASA;FAA;CAAC;ANAC										
138947	9523M35G01	EASA;FAA;CAAC;ANAC										
138947	9523M35G03	EASA;FAA;CAAC;ANAC										
138947	9938M48G05	EASA;FAA;CAAC;ANAC										
138947	9938M48G06	EASA;FAA;CAAC;ANAC										
138953	1316M84G01	EASA;FAA;CAAC;ANAC	27	28	72-42-06	COMBUSTION CHAMBER - SELFLOCKING GANG CHANNEL NUT	Package A	CLN/INSP	CLEANING & INSPECTION		110.00	SR Technics Switzerland
138953	9945M19G03	EASA;FAA;CAAC;ANAC			72-42-06		Package B	001	REPLACEMENT OF SELFLOCKING GANG CHANNEL NUT ASSY NUTS		600.00	SR Technics Switzerland
138953	9945M19G04	EASA;FAA;CAAC;ANAC										
138962	305-158-701-0	EASA;FAA;CAAC;ANAC	17	28	72-62-05	TRANSFER GEARBOX - VESPEL NUTS	Package A	CLN/INSP	CLEANING AND INSPECTION		415.00	SR Technics Switzerland
138962	305-158-801-0	EASA;FAA;CAAC;ANAC										
138962	335-322-201-0	EASA;FAA;CAAC;ANAC										
138962	335-322-501-0	EASA;FAA;CAAC;ANAC										
138962	SL40703M45-15FG	EASA;FAA;CAAC;ANAC										
138980	301-297-909-0	EASA;FAA;CAAC;ANAC	23	28	72-22-16	NO.1 AND NO.2 BEARING SUPPORT - KEYWASHERS	Package A	CLN/INSP	CLEANING AND INSPECTION		450.00	SR Technics Switzerland
138980	301-298-408-0	EASA;FAA;CAAC;ANAC			72-22-16		Package B	INSP-001	BLEND RING KEYWASHER		165.00	SR Technics Switzerland
138980	301-537-803-0	EASA;FAA;CAAC;ANAC			72-22-16		Package C	INSP-001	BLEND RETAINER RING		1045.00	SR Technics Switzerland
138980	301-544-203-0	EASA;FAA;CAAC;ANAC			72-22-16		Package D	INSP-001	REPLACE ANTI ROTAIN PIN		585.00	SR Technics Switzerland
138980	305-398-901-0	EASA;FAA;CAAC;ANAC										
139000	AMB34-4001	EASA;FAA;CAAC;ANAC	14	21	71-21-08	FWD ENGINE MOUNT - BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		395.00	SR Technics Switzerland
139000	AMB34-4002	EASA;FAA;CAAC;ANAC			71-21-08		Package SB00	RA 32071-159	BEAM SNOUT INSPECTION AND REWORK		250.00	SR Technics Switzerland
139000	P2A0300-1	EASA;FAA;CAAC;ANAC										
139000	P2A0300-2	EASA;FAA;CAAC;ANAC										
139012	301-298-802-6	EASA;FAA;CAAC;ANAC	18	28	72-00-03	ENGINE MODULES/ASSEMBLIES - LPT MAJOR MODULE - SHIM	Package B		GRINDING SPACER THICKNESS		185.00	SR Technics Switzerland
139012	301-298-803-0	EASA;FAA;CAAC;ANAC										
139012	301-298-804-0	EASA;FAA;CAAC;ANAC										
139012	301-298-805-0	EASA;FAA;CAAC;ANAC										
139012	301-298-806-0	EASA;FAA;CAAC;ANAC										
139012	301-298-807-0	EASA;FAA;CAAC;ANAC										
139012	301-298-808-0	EASA;FAA;CAAC;ANAC										
139012	301-298-809-0	EASA;FAA;ANAC										
139012	301-298-810-0	EASA;FAA;CAAC;ANAC										
139012	301-298-811-0	EASA;FAA;CAAC;ANAC										
139012	301-298-812-0	EASA;FAA;CAAC;ANAC										
139012	301-298-813-0	EASA;FAA;CAAC;ANAC										
139012	301-298-814-0	EASA;FAA;CAAC;ANAC										
139012	301-298-815-0	EASA;FAA;CAAC;ANAC										
139012	301-298-816-0	EASA;FAA;CAAC;ANAC										
139012	301-298-817-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139012	301-298-818-0	EASA;FAA;CAAC;ANAC										
139012	301-298-819-0	EASA;FAA;CAAC;ANAC										
139015	305-115-704-0	EASA;FAA;CAAC;ANAC	25	28	72-63-21	ACCESSORY GEARBOX - SEALOL SEALS	Package A	CLN/INSP	CLEANING AND INSPECTION		130.00	SR Technics Switzerland
139015	305-115-709-0	EASA;FAA;CAAC;ANAC			72-63-21		Package B	001	LAPPING OF SURFACES OF MATING RING AND CARBON RING		435.00	SR Technics Switzerland
139015	305-140-801-0	EASA;FAA;CAAC;ANAC			72-63-21		Package C	002	REPLACEMENT OF DEFECTIVE COMPONENTS		205.00	SR Technics Switzerland
139015	335-310-706-0	EASA;FAA;CAAC;ANAC			72-63-21		Package SB00	72-0660	INTRODUCTION OF NEW MAGNETIC SEAL AND NEW SEALOL SEAL W REWORK OF OLD SEALOL SEAL TO		375.00	SR Technics Switzerland
139015	335-310-707-0	EASA;FAA;CAAC;ANAC										
139015	335-310-708-0	EASA;FAA;CAAC;ANAC										
139015	335-320-304-0	EASA;FAA;CAAC;ANAC										
139015	335-320-305-0	EASA;FAA;CAAC;ANAC										
139015	340-155-304-0	EASA;FAA;CAAC;ANAC										
139015	340-155-305-0	EASA;FAA;CAAC;ANAC										
139015	340-190-001-0	EASA;FAA;CAAC;ANAC										
139015	340-194-201-0	EASA;FAA;CAAC;ANAC										
139019	305-145-601-0	EASA;FAA;CAAC;ANAC	25	28	72-63-09	ACCESSORY GEARBOX - HANDCRANKING COVER PLUG	Package A	CLN/INSP	CLEANING AND INSPECTION		725.00	SR Technics Switzerland
139019	305-166-101-0	EASA;FAA;CAAC;ANAC			72-63-09		Package SB01	72-0156	INTRODUCTION OF A NEW AGB HANDCRANKING COVER		465.00	SR Technics Switzerland
139019	305-166-102-0	EASA;FAA;CAAC;ANAC										
139020	305-415-401-0	EASA;FAA;CAAC;ANAC	19	28	72-63-18	ACCESSORY GEARBOX - PIN-STRAIGHT	Package A	CLN/INSP	CLEANING AND INSPECTION		370.00	SR Technics Switzerland
139020	340-077-702-0	EASA;FAA;CAAC;ANAC			72-63-18		Package C	002	REPLACEMENT OF THE BUSHING AND RECONDITIONING OF THE CHROMIUM PLATE ON THE PIN SHANK		615.00	SR Technics Switzerland
139020	340-077-903-0	EASA;FAA;CAAC;ANAC										
139020	340-078-002-0	EASA;FAA;CAAC;ANAC										
139020	340-085-902-0	EASA;FAA;CAAC;ANAC										
139021	301-495-102-0	EASA;FAA;CAAC;ANAC	20	28	72-63-14	ACCESSORY GEARBOX - QAD RING ADAPTER	Package A	CLN/INSP	CLEANING AND INSPECTION		500.00	SR Technics Switzerland
139021	305-126-601-0	EASA;FAA;CAAC;ANAC			72-63-14		Package B	001	RECONDITIONING OF LUBRICANT VARNISH ON SPHERICAL SEATING SURFACES		740.00	SR Technics Switzerland
139021	335-311-700-0	EASA;FAA;CAAC;ANAC			72-63-14		Package C	002	RECONDITIONING OF THE SOLID-FILM LUBRICANT COATING		930.00	SR Technics Switzerland
139021	335-311-701-0	EASA;FAA;CAAC;ANAC										
139021	9009M29P01	EASA;FAA;CAAC;ANAC										
139023	301-367-605-0	EASA;FAA;CAAC;ANAC	18	28	72-55-11	LOW PRESSURE TURBINE SHAFT - ASSEMBLY BOLTS	Package A	CLN/INSP	CLEANING AND INSPECTION		160.00	SR Technics Switzerland
139023	J952P22A	EASA;FAA;CAAC;ANAC										
139024	338-072-601-0	EASA;FAA;CAAC;ANAC	37	21	72-54-14	LOW PRESSURE TURBINE - SUPPORT BRACKET	Package A	CLN/INSP	CLEANING AND INSPECTION		125.00	SR Technics Switzerland
139024	338-072-801-0	EASA;FAA;CAAC;ANAC			72-54-14		Package AE	ASSEMBLY	MOUNT BRACKET REPLACE BUSHING		120.00	SR Technics Switzerland
139024	338-119-202-0	EASA;FAA;CAAC;ANAC			72-54-14		Package E	003	REPAIR OF CRACKS		155.00	SR Technics Switzerland
139024	338-119-204-0	EASA;FAA;CAAC;ANAC										
139024	340-029-703-0	EASA;FAA;CAAC;ANAC										
139024	340-029-706-0	EASA;FAA;CAAC;ANAC										
139024	340-029-707-0	EASA;FAA;CAAC;ANAC										
139024	340-029-708-0	EASA;FAA;CAAC;ANAC										
139024	340-084-102-0	EASA;FAA;CAAC;ANAC										
139024	340-084-104-0	EASA;FAA;CAAC;ANAC										
139024	340-084-152-0	EASA;FAA;CAAC;ANAC										
139030	338-011-201-0	EASA;FAA;CAAC;ANAC	25	28	72-23-17	FAN FRAME ASSEMBLY - OIL TANK MOUNT PARTS	Package A	CLN/INSP	CLEANING AND INSPECTION		270.00	SR Technics Switzerland
139030	338-011-402-0	EASA;FAA;CAAC;ANAC			72-23-17		Package N	052	REPLACEMENT OF WORN SPHERICAL BEARING ON OIL TANK LINK R EASA / FAA APPROVED SRT DESIGN		1465.00	SR Technics Switzerland
139030	338-014-801-0	EASA;FAA;CAAC;ANAC										
139030	338-015-101-0	EASA;FAA;CAAC;ANAC;CAA UK										
139030	338-045-001-0	EASA;FAA;CAAC;ANAC										
139030	338-079-901-0	EASA;FAA;CAAC;ANAC										
139030	338-079-951-0	EASA;FAA;CAAC;ANAC										
139030	340-086-003-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139030	340-086-004-0	EASA;FAA;CAAC;ANAC										
139030	340-086-201-0	EASA;FAA;CAAC;ANAC										
139030	340-086-202-0	EASA;FAA;CAAC;ANAC										
139030	340-086-302-0	EASA;FAA;CAAC;ANAC										
139030	340-086-303-0	EASA;FAA;CAAC;ANAC										
139030	340-168-401-0	EASA;FAA;CAAC;ANAC										
139035	338-068-007-0	EASA;FAA;CAAC;ANAC	54	28	72-23-08	FAN FRAME ASSEMBLY - FAN CASE ACOUSTICAL PANELS	Package A	CLN/INSP	CLEANING AND INSPECTION		285.00	SR Technics Switzerland
139035	338-068-008-0	EASA;FAA;CAAC;ANAC			72-23-08		Package C	002	LOCAL REPAIR OF THE TEDLAR FILM BY PAINTING		1265.00	SR Technics Switzerland
139035	338-068-010-0	EASA;FAA;CAAC;ANAC			72-23-08		Package C	003	REPLACE THE COMPONENTS AT THE ATTACHMENT POINTS OF THE ACOUSTICAL PANELS		1265.00	SR Technics Switzerland
139035	338-068-108-0	EASA;FAA;CAAC;ANAC			72-23-08		Package C	006	EROSION REPAIR BY EPOXY ADHESIVE		1265.00	SR Technics Switzerland
139035	338-068-109-0	EASA;FAA;CAAC;ANAC			72-23-08		Package C	010	REPAIR OF THE FORWARD MIDDLE AND AFT ACCUSTICAL PANELS BY RESIN INJECTION		1265.00	SR Technics Switzerland
139035	338-068-111-0	EASA;FAA;CAAC;ANAC			72-23-08		Package I	008	REPLACEMENT OF MID ACOUSTICAL PANEL BONDED DAMPER(S)		780.00	SR Technics Switzerland
139035	338-068-208-0	EASA;FAA;CAAC;ANAC			72-23-08		Package J	009	REPAIR OF FLANK OF THE FORWARD ACOUSTICAL PANELS WITH EPOXY ADHESIVE		330.00	SR Technics Switzerland
139035	338-068-209-0	EASA;FAA;CAAC;ANAC			72-23-08		Package L	011	RECONDITIONING OF FWD, MID, AFT ACC. PANELS BY WET LAY-UP PROCESS		2970.00	SR Technics Switzerland
139035	338-068-211-0	EASA;FAA;CAAC;ANAC			72-23-08		Package N	013	REPLACE BOSSES AND DAMPING	CONFIG. 1	1040.00	SR Technics Switzerland
139035	338-068-307-0	EASA;FAA;CAAC;ANAC			72-23-08		Package N	013	REPLACE BOSSES AND DAMPING	CONFIG. 2	1040.00	SR Technics Switzerland
139035	338-068-308-0	EASA;FAA;CAAC;ANAC			72-23-08		Package SB00	72-0071	FAN FRAME - REPLACEMENT OF BONDED SEALS WITH SEAL ASSEMBLIES ON AFT ACOUSTICAL PANELS		165.00	SR Technics Switzerland
139035	338-068-310-0	EASA;FAA;CAAC;ANAC			72-23-08		Package SB02	72-0865	REWORK OLD OF THE ACOUSTICAL PANEL ASS		1925.00	SR Technics Switzerland
139035	338-068-408-0	EASA;FAA;CAAC;ANAC			72-23-08		Package SB03	72-1017	INTRODUCTION OF NEW ACOUSTICAL PANEL ASSEMBLIES AND REWORK OF THE OLD ACOUSTICAL PANI		600.00	SR Technics Switzerland
139035	338-068-409-0	EASA;FAA;CAAC;ANAC										
139035	338-068-411-0	EASA;FAA;CAAC;ANAC										
139035	338-073-008-0	EASA;FAA;CAAC;ANAC										
139035	338-073-009-0	EASA;FAA;CAAC;ANAC										
139035	338-073-010-0	EASA;FAA;CAAC;ANAC										
139035	338-073-011-0	EASA;FAA;CAAC;ANAC										
139035	338-073-012-0	EASA;FAA;CAAC;ANAC										
139035	338-073-013-0	EASA;FAA;CAAC;ANAC										
139035	338-078-804-0	EASA;FAA;CAAC;ANAC										
139035	338-078-806-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-078-807-0	EASA;FAA;CAAC;ANAC										
139035	338-078-808-0	EASA;FAA;CAAC;ANAC										
139035	338-079-504-0	EASA;FAA;CAAC;ANAC										
139035	338-079-506-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-079-507-0	EASA;FAA;CAAC;ANAC										
139035	338-079-508-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-079-705-0	EASA;FAA;CAAC;ANAC										
139035	338-079-706-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	338-079-707-0	EASA;FAA;CAAC;ANAC										
139035	338-079-708-0	EASA;FAA;CAAC;ANAC										
139035	340-082-501-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	340-082-504-0	EASA;FAA;CAAC;ANAC										
139035	340-082-506-0	EASA;FAA;CAAC;ANAC										
139035	340-084-201-0	EASA;FAA;CAAC;ANAC										
139035	340-084-302-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	340-085-101-0	EASA;FAA;CAAC;ANAC										
139035	340-085-103-0	EASA;FAA;CAAC;ANAC										
139035	340-085-120-0	EASA;FAA;CAAC;ANAC;CAA UK										
139035	340-085-150-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139035	340-116-401-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	338-070-102-0	EASA;FAA;CAAC;ANAC	44	28	72-23-07	FAN FRAME ASSEMBLY - FAN DUCT PANELS	Package A	CLN/INSP	CLEANING AND INSPECTION		465.00	SR Technics Switzerland
139040	338-070-202-0	EASA;FAA;CAAC;ANAC			72-23-07		Package B	001	CRACK REPAIR BY WELD BUILDUP		1295.00	SR Technics Switzerland
139040	338-070-302-0	EASA;FAA;CAAC;ANAC			72-23-07		Package C	002	REPLACEMENT OF THE ELASTOMER DAMPING PADS ON THE FAN		920.00	SR Technics Switzerland
139040	338-070-402-0	EASA;FAA;CAAC;ANAC										
139040	338-070-502-0	EASA;FAA;CAAC;ANAC										
139040	340-075-702-0	EASA;FAA;CAAC;ANAC										
139040	340-075-703-0	EASA;FAA;CAAC;ANAC										
139040	340-075-705-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-075-802-0	EASA;FAA;CAAC;ANAC										
139040	340-075-803-0	EASA;FAA;CAAC;ANAC										
139040	340-075-805-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-075-902-0	EASA;FAA;CAAC;ANAC										
139040	340-075-903-0	EASA;FAA;CAAC;ANAC										
139040	340-075-905-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-075-953-0	EASA;FAA;CAAC;ANAC										
139040	340-076-002-0	EASA;FAA;CAAC;ANAC										
139040	340-076-003-0	EASA;FAA;CAAC;ANAC										
139040	340-076-005-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-102-0	EASA;FAA;CAAC;ANAC										
139040	340-076-103-0	EASA;FAA;CAAC;ANAC										
139040	340-076-105-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-153-0	EASA;FAA;CAAC;ANAC										
139040	340-076-202-0	EASA;FAA;CAAC;ANAC										
139040	340-076-203-0	EASA;FAA;CAAC;ANAC										
139040	340-076-205-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-253-0	EASA;FAA;CAAC;ANAC										
139040	340-076-302-0	EASA;FAA;CAAC;ANAC										
139040	340-076-303-0	EASA;FAA;CAAC;ANAC										
139040	340-076-305-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-402-0	EASA;FAA;CAAC;ANAC										
139040	340-076-403-0	EASA;FAA;CAAC;ANAC										
139040	340-076-405-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-502-0	EASA;FAA;CAAC;ANAC										
139040	340-076-503-0	EASA;FAA;CAAC;ANAC										
139040	340-076-505-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-553-0	EASA;FAA;CAAC;ANAC										
139040	340-076-602-0	EASA;FAA;CAAC;ANAC										
139040	340-076-603-0	EASA;FAA;CAAC;ANAC										
139040	340-076-605-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-076-702-0	EASA;FAA;CAAC;ANAC										
139040	340-076-703-0	EASA;FAA;CAAC;ANAC										
139040	340-076-705-0	EASA;FAA;CAAC;ANAC;CAA UK										
139040	340-084-002-0	EASA;FAA;CAAC;ANAC										
139040	340-084-003-0	EASA;FAA;CAAC;ANAC;CAA UK										
139055	338-006-102-0	EASA;FAA;CAAC;ANAC	28	28	72-21-10	FAN AND BOOSTER - FAN BLADES SPACERS	Package A	CLN/INSP	CLEANING AND INSPECTION		85.00	SR Technics Switzerland
139055	340-001-215-0	EASA;FAA;CAAC;ANAC			72-21-10		Package B	001	SPOT TOUCH-UP OR FULL REPAIR OF THE SULFURIC ANODIZING		160.00	SR Technics Switzerland
139055	340-001-216-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139055	340-001-217-0	EASA;FAA;CAAC;ANAC										
139055	340-001-261-0	EASA;FAA;CAAC;ANAC										
139055	340-001-262-0	EASA;FAA;CAAC;ANAC										
139056	301-295-106-0	EASA;FAA;CAAC;ANAC	24	28	72-23-05	FAN FRAME ASSEMBLY - INNER/OUTER HOUSING/SUPPORT R	Package A	CLN/INSP	CLEANING AND INSPECTION		810.00	SR Technics Switzerland
139056	301-295-909-0	EASA;FAA;CAAC;ANAC			72-23-05		Package C	002	REPAIR THE OUTER LOCATING DIAMETER OF THE OUTER RADIAL DRIVE SHAFT HOUSING		2000.00	SR Technics Switzerland
139056	340-029-803-0	EASA;FAA;CAAC;ANAC			72-23-05		Package E	004	REPAIR OF THE OUTER LOCATING DIAMETER OF THE INNER RADIAL DRIVE SHAFT HOUSING		2000.00	SR Technics Switzerland
139056	340-032-604-0	EASA;FAA;CAAC;ANAC			72-23-05		Package SB00	72-0934	REPL. OF SUSPECTED BATCH OF RADIAL DRIVE SHAFT ASSY AND ASSOCIATED RADIAL DRIVE SHAFT OU		160.00	SR Technics Switzerland
139056	340-032-606-0	EASA;FAA;CAAC;ANAC;CAA UK										
139056	340-050-004-0	EASA;FAA;CAAC;ANAC										
139056	340-050-005-0	EASA;FAA;CAAC;ANAC										
139340	1476M79P01	EASA;FAA;CAAC;ANAC	5	28	72-52-07	CFM56 HPT ROTOR FR. SHAFT DAMPER SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		480.00	SR Technics Switzerland
139340	1476M79P02	EASA;FAA;CAAC;ANAC										
139340	1476M79P03	EASA;FAA;CAAC;ANAC										
139344	1385M91P01	EASA;FAA;CAAC;ANAC	21	28	72-52-09	HIGH PRESSURE TURBINE ROTOR - HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		380.00	SR Technics Switzerland
139344	1498M46P01	EASA;FAA;CAAC;ANAC			72-52-09		Package SB00	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CF AND CFM56-5B6/2 TO CFM56-5B6/2P		395.00	SR Technics Switzerland
139344	1522M86P01	EASA;FAA;CAAC;ANAC										
139344	1847M57P01	EASA;FAA;CAAC;ANAC										
139344	1847M57P02	EASA;FAA;CAAC;ANAC										
139344	2410M52P01	EASA;FAA;CAAC;ANAC										
139360	1559M14G05	EASA;FAA;CAAC;ANAC	42	28	72-32-03	COMPRESSOR FRONT STATOR - VANE SECTORS	Package A		BASIC REPAIR STAGE 4.5		215.00	SRTAS
139360	1559M14G06	EASA;FAA;CAAC;ANAC			72-32-03		Package A	CLN 001	CLEANING		215.00	SRTAS
139360	1559M14G07	EASA;FAA;CAAC;ANAC			72-32-03		Package A	INSP 001	VISUAL/DIMENSIONAL INSPECTION		215.00	SRTAS
139360	1559M14G08	EASA;FAA;CAAC;ANAC			72-32-03		Package B		FULL REPAIR STAGE 4		535.00	SRTAS
139360	1559M15G01	EASA;FAA;CAAC;ANAC			72-32-03		Package B	001	REPLACEMENT OF THE OUTER PLATFORM WEAR COATING		535.00	SRTAS
139360	1559M15G02	EASA;FAA;CAAC;ANAC			72-32-03		Package B	002	AIRFOIL LEADING AND TRAILING EDGES BLEND REPAIR		535.00	SRTAS
139360	1559M15G03	EASA;FAA;CAAC;ANAC			72-32-03		Package G		ADDITIONAL WORKSCOPE STAGE 4		175.00	SRTAS
139360	1559M15G04	EASA;FAA;CAAC;ANAC			72-32-03		Package G	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	175.00	SRTAS
139360	1834M94G01	EASA;FAA;CAAC;ANAC			72-32-03		Package H		ADDITIONAL WORKSCOPE STAGE 4		920.00	SRTAS
139360	1834M94G02	EASA;FAA;CAAC;ANAC			72-32-03		Package H	006	INNER PLATFORM J-HOOK REPAIR		920.00	SRTAS
139360	1834M94G03	EASA;FAA;CAAC;ANAC			72-32-03		Package I		FULL REPAIR STAGE 5		555.00	SRTAS
139360	1834M94G04	EASA;FAA;CAAC;ANAC			72-32-03		Package I	001	REPLACEMENT OF THE OUTER PLATFORM WEAR COATING		555.00	SRTAS
139360	2031M14G05	EASA;FAA;CAAC;ANAC			72-32-03		Package I	002	AIRFOIL LEADING AND TRAILING EDGES BLEND REPAIR		555.00	SRTAS
139360	2031M14G06	EASA;FAA;CAAC;ANAC			72-32-03		Package N		ADDITIONAL WORKSCOPE STAGE 5		100.00	SRTAS
139360	2031M14G07	EASA;FAA;CAAC;ANAC			72-32-03		Package N	005	INNER BAND SEAL SLOT WELD REPAIR	IN CONJUNCTION WITH PACKAGE A	100.00	SRTAS
139360	2031M14G08	EASA;FAA;CAAC;ANAC			72-32-03		Package O		ADDITIONAL WORKSCOPE STAGE 5		955.00	SRTAS
139360	P244G05	EASA;FAA;CAAC;ANAC			72-32-03		Package O	006	INNER PLATFORM J-HOOK REPAIR		955.00	SRTAS
139360	P244G06	EASA;FAA;CAAC;ANAC										
139360	P244G07	EASA;FAA;CAAC;ANAC										
139360	P244G08	EASA;FAA;CAAC;ANAC										
139360	P245G01	EASA;FAA;CAAC;ANAC										
139360	P245G02	EASA;FAA;CAAC;ANAC										
139360	P245G03	EASA;FAA;CAAC;ANAC										
139360	P245G04	EASA;FAA;CAAC;ANAC										
139360	P264G01	EASA;FAA;CAAC;ANAC										
139360	P264G02	EASA;FAA;CAAC;ANAC										
139360	P264G03	EASA;FAA;CAAC;ANAC										
139360	P264G04	EASA;FAA;CAAC;ANAC										
139360	P264G05	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139360	P264G06	EASA;FAA;CAAC;ANAC										
139360	P264G07	EASA;FAA;CAAC;ANAC										
139360	P264G08	EASA;FAA;CAAC;ANAC										
139360	P265G01	EASA;FAA;CAAC;ANAC										
139360	P265G02	EASA;FAA;CAAC;ANAC										
139360	P265G03	EASA;FAA;CAAC;ANAC										
139360	P265G04	EASA;FAA;CAAC;ANAC										
139360	P265G05	EASA;FAA;CAAC;ANAC										
139360	P265G06	EASA;FAA;CAAC;ANAC										
139360	P265G07	EASA;FAA;CAAC;ANAC										
139360	P265G08	EASA;FAA;CAAC;ANAC										
139378	301-333-307-0	EASA;FAA;CAAC;ANAC	32	28	72-55-20	LOW PRESSURE TURBINE SHAFT - LOCATING SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		365.00	SR Technics Switzerland
139378	301-333-404-0	EASA;FAA;CAAC;ANAC;CAA UK										
139378	305-415-103-0	EASA;FAA;CAAC;ANAC										
139378	337-111-801-0	EASA;FAA;CAAC;ANAC										
139378	337-111-802-0	EASA;FAA;CAAC;ANAC										
139378	337-111-803-0	EASA;FAA;CAAC;ANAC										
139378	337-111-901-0	EASA;FAA;CAAC;ANAC										
139378	337-111-902-0	EASA;FAA;CAAC;ANAC										
139378	337-111-903-0	EASA;FAA;CAAC;ANAC										
139378	340-161-101-0	EASA;FAA;CAAC;ANAC										
139378	340-161-103-0	EASA;FAA;CAAC;ANAC										
139378	340-161-201-0	EASA;FAA;CAAC;ANAC										
139378	340-161-203-0	EASA;FAA;CAAC;ANAC										
139390	305-136-605-0	EASA;FAA;CAAC;ANAC	19	28	72-62-02	TRANSFER GEARBOX - BEVEL GEARSHAFTS	Package A	CLN/INSP	CLEANING AND INSPECTION		1195.00	SR Technics Switzerland
139390	305-136-704-0	EASA;FAA;CAAC;ANAC			72-62-02		Package SB00	72-0364	RETROFIT OF -WITH SUSPECTED TGB		495.00	SR Technics Switzerland
139390	305-163-301-0	EASA;FAA;CAAC;ANAC										
139390	305-163-401-0	EASA;FAA;CAAC;ANAC										
139390	340-049-501-0	EASA;FAA;CAAC;ANAC										
139390	340-049-601-0	EASA;FAA;CAAC;ANAC										
139401	305-138-805-0	EASA;FAA;CAAC;ANAC	23	28	72-63-02	ACCESSORY GEARBOX - MOUNTING DRIVE PADS	Package A	CLN/INSP	CLEANING AND INSPECTION		505.00	SR Technics Switzerland
139401	305-138-807-0	EASA;FAA;CAAC;ANAC			72-63-02		Package B	001	REPLACEMENT OF THE KEY-LOCKED STUDS		830.00	SR Technics Switzerland
139401	305-139-002-0	EASA;FAA;CAAC;ANAC			72-63-02		Package C	002	REPLACEMENT OF THE RING-LOCKED NIPPLES		1050.00	SR Technics Switzerland
139401	305-139-003-0	EASA;FAA;CAAC;ANAC			72-63-02		Package E	004	REPLACE THE SWAGED SELF-LOCKING INSERTS		635.00	SR Technics Switzerland
139401	305-139-203-0	EASA;FAA;CAAC;ANAC			72-63-02		Package H	007	RECONDITIONING OR SPOT TOUCH-UP OF THE NON-MACHINED SURFACES BY OXIDE FILM COATING		635.00	SR Technics Switzerland
139401	305-139-204-0	EASA;FAA;CAAC;ANAC										
139401	305-139-406-0	EASA;FAA;CAAC;ANAC										
139401	305-139-407-0	EASA;FAA;CAAC;ANAC										
139401	305-139-602-0	EASA;FAA;CAAC;ANAC										
139401	305-139-603-0	EASA;FAA;CAAC;ANAC										
139401	305-139-701-0	EASA;FAA;CAAC;ANAC										
139401	305-139-801-0	EASA;FAA;CAAC;ANAC										
139401	305-140-001-0	EASA;FAA;CAAC;ANAC										
139401	305-142-601-0	EASA;FAA;CAAC;ANAC										
139401	335-301-000-0	EASA;FAA;CAAC;ANAC										
139401	335-301-200-0	EASA;FAA;CAAC;ANAC										
139401	340-047-802-0	EASA;FAA;CAAC;ANAC										
139401	340-047-804-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139401	340-047-805-0	EASA;FAA;CAAC;ANAC										
139401	340-047-807-0	EASA;FAA;CAAC;ANAC										
139401	340-048-102-0	EASA;FAA;CAAC;ANAC										
139401	340-048-103-0	EASA;FAA;CAAC;ANAC										
139401	340-048-104-0	EASA;FAA;CAAC;ANAC										
139401	340-048-602-0	EASA;FAA;CAAC;ANAC										
139401	340-048-802-0	EASA;FAA;CAAC;ANAC										
139401	340-055-602-0	EASA;FAA;CAAC;ANAC										
139423	305-137-101-0	EASA;FAA;CAAC;ANAC	35	28	72-63-03	ACCESSORY GEARBOX - GEARSHAFTS	Package A	CLN/INSP	CLEANING AND INSPECTION		1210.00	SR Technics Switzerland
139423	305-137-203-0	EASA;FAA;CAAC;ANAC			72-63-03		Package C	002	REPLACEMENT OF THE OIL RETAINING RING ON THE 40-TOOTH INPUT DRIVE GEARSHAFT		1350.00	SR Technics Switzerland
139423	305-137-501-0	EASA;FAA;CAAC;ANAC			72-63-03		Package E	004	REPLACE THE OIL RETAINING SLEEVES ON THE AGB 70-TOOTH GEARSHAFT		810.00	SR Technics Switzerland
139423	305-137-602-0	EASA;FAA;CAAC;ANAC										
139423	305-137-701-0	EASA;FAA;CAAC;ANAC										
139423	305-137-802-0	EASA;FAA;CAAC;ANAC										
139423	305-137-902-0	EASA;FAA;CAAC;ANAC										
139423	305-138-202-0	EASA;FAA;CAAC;ANAC										
139423	305-146-302-0	EASA;FAA;CAAC;ANAC										
139423	305-146-402-0	EASA;FAA;CAAC;ANAC										
139423	305-151-501-0	EASA;FAA;CAAC;ANAC										
139423	305-163-501-0	EASA;FAA;CAAC;ANAC										
139423	305-165-301-0	EASA;FAA;CAAC;ANAC										
139423	305-165-401-0	EASA;FAA;CAAC;ANAC										
139423	305-165-601-0	EASA;FAA;CAAC;ANAC										
139423	305-167-001-0	EASA;FAA;CAAC;ANAC										
139423	335-302-902-0	EASA;FAA;CAAC;ANAC										
139423	335-303-002-0	EASA;FAA;CAAC;ANAC										
139423	335-303-201-0	EASA;FAA;CAAC;ANAC										
139423	335-303-502-0	EASA;FAA;CAAC;ANAC										
139423	335-303-503-0	EASA;FAA;CAAC;ANAC										
139423	335-303-506-0	EASA;FAA;CAAC;ANAC										
139423	335-303-601-0	EASA;FAA;CAAC;ANAC										
139423	335-324-101-0	EASA;FAA;CAAC;ANAC										
139423	340-048-301-0	EASA;FAA;CAAC;ANAC										
139423	340-051-602-0	EASA;FAA;CAAC;ANAC										
139423	340-051-801-0	EASA;FAA;CAAC;ANAC										
139423	340-051-901-0	EASA;FAA;CAAC;ANAC										
139423	340-052-802-0	EASA;FAA;CAAC;ANAC										
139423	340-055-202-0	EASA;FAA;CAAC;ANAC										
139423	340-151-101-0	EASA;FAA;CAAC;ANAC										
139423	340-151-501-0	EASA;FAA;CAAC;ANAC										
139423	340-154-301-0	EASA;FAA;CAAC;ANAC										
139424	305-140-501-0	EASA;FAA;CAAC;ANAC	5	28	72-63-25	ACCESSORY GEARBOX HARDWARE MODULE 63	Package A	CLN/INSP	CLEANING & INSPECTION		365.00	SR Technics Switzerland
139424	305-147-001-0	EASA;FAA;CAAC;ANAC			72-63-25		Package B	02	APPLY ALODINE		310.00	SR Technics Switzerland
139424	305-159-001-0	EASA;FAA;CAAC;ANAC										
139440	336-002-203-0	EASA;FAA;CAAC;ANAC	48	28	72-54-06	LOW PRESSURE TURBINE - ROTATING AIR SEAL	Package A	CLN/INSP	CLEANING AND INSPECTION		595.00	SR Technics Switzerland
139440	336-002-302-0	EASA;FAA;CAAC;ANAC;TCCA			72-54-06		Package AN	SPM 70-41-11	REMOVE HIGH METAL		260.00	SR Technics Switzerland
139440	336-003-002-0	EASA;FAA;CAAC;ANAC			72-54-06		Package C	001	REPAIR OF THE TITANIUM/ALUMINIUM OXIDE COATING ON THE SEAL PRICE PER STAGE		3285.00	SR Technics Switzerland
139440	336-003-102-0	EASA;FAA;CAAC;ANAC			72-54-06		Package D	002	REPAIR OF RETAINING RING MATING FACE		2860.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139440	338-111-502-0	EASA;FAA;CAAC;ANAC			72-54-06		Package E	003	TOUCH-UP OF SEAL TEETH		1045.00	SR Technics Switzerland
139440	338-111-603-0	EASA;FAA;CAAC;ANAC										
139440	338-111-701-0	EASA;FAA;CAAC;ANAC										
139440	338-111-703-0	EASA;FAA;CAAC;ANAC										
139440	340-304-002-0	EASA;FAA;ANAC										
139440	340-304-101-0	EASA;FAA;CAAC;ANAC										
139440	340-304-301-0	EASA;FAA;CAAC;ANAC										
139447	337-123-301-0	EASA;FAA;CAAC;ANAC	15	28	72-23-27	NO.1 AND NO.2 BEARING SUPPORT - RETAINER WASHER	Package A	CLN/INSP	CLEANING AND INSPECTION		105.00	SR Technics Switzerland
139447	340-032-501-0	EASA;FAA;ANAC										
139448	338-000-405-0	EASA;FAA;CAAC;ANAC	29	28	72-54-01	LOW PRESSURE TURBINE - BLADES STG 1	Package B		FULL REPAIR		320.00	SRTAS
139448	338-000-461-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	11	WELD REPAIR RUB BETWEEN SEAL TEETH		320.00	SRTAS
139448	338-000-481-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	2	AIRFOIL BLEND REPAIR		320.00	SRTAS
139448	338-000-482-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	3	RE-SETTING THE PRE-TWIST ANGLE		320.00	SRTAS
139448	338-108-204-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	4	REPAIR OF SEAL TEETH BY PLASMA SPRAYING		320.00	SRTAS
139448	338-108-206-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	40	LASER CLADDING OF HARD FACING AND MATING FACES OF THE TIP SHROUD		320.00	SRTAS
139448	338-108-207-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	5	REPAIR OF THE SEAL TEETH ON THE BLADE TIP SHROUD BY WELD BUILD-UP WITH COAST METAL 64		320.00	SRTAS
139448	338-108-208-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	55	OVER-COATING OF APVS COATING		320.00	SRTAS
139448	338-108-210-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	7	REPAIR OF THE HARDFACING AND MATING FACES ON THE TIP SHROUDS, BY WELD BUILD-UP WITH COA		320.00	SRTAS
139448	338-115-703-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	8	REPAIR OF VAPOUR PHASE ALUMINAZATION		320.00	SRTAS
139448	338-115-705-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	9	CORROSION REMOVAL ON ROOT BY BLENDING		320.00	SRTAS
139448	338-115-706-0	EASA;FAA;CAAC;ANAC			72-54-01		Package B	INSP 001	VISUAL & DIMENSIONAL INSPECTION		320.00	SRTAS
139448	338-115-707-0	EASA;FAA;CAAC;ANAC			72-54-01		Package C		ADDITIONAL REPAIR		145.00	SRTAS
139448	338-115-709-0	EASA;FAA;CAAC;ANAC			72-54-01		Package C	5A	DIMENSIONAL RESTORATION OF THE SEAL TEETH		145.00	SRTAS
139448	340-302-001-0	EASA;FAA;CAAC;ANAC										
139448	340-310-001-0	EASA;FAA;CAAC;ANAC										
139485	1585M80G01	EASA;FAA;CAAC;ANAC	5	28	72-09-02	CFM56-ALL MGB/IGB/TGB GEARBOX NOZZLE	Package A	CLN/INSP	CLEANING AND INSPECTION		460.00	SR Technics Switzerland
139485	305-142-702-0	EASA;FAA;CAAC;ANAC										
139485	305-142-802-0	EASA;FAA;CAAC;ANAC										
139485	305-142-901-0	EASA;FAA;CAAC;ANAC										
139485	305-143-002-0	EASA;FAA;CAAC;ANAC										
139485	305-143-102-0	EASA;FAA;CAAC;ANAC										
139485	305-143-201-0	EASA;FAA;CAAC;ANAC										
139485	305-143-301-0	EASA;FAA;CAAC;ANAC										
139485	305-143-401-0	EASA;FAA;CAAC;ANAC										
139485	305-143-502-0	EASA;FAA;CAAC;ANAC										
139485	305-146-802-0	EASA;FAA;CAAC;ANAC										
139485	305-147-102-0	EASA;FAA;CAAC;ANAC										
139485	9542M72G03	EASA;FAA;CAAC;ANAC										
139485	9973M28G02	EASA;FAA;CAAC;ANAC										
139490	338-075-801-0	EASA;FAA;CAAC;ANAC	28	28	72-54-02	LOW PRESSURE TURBINE - BLADES STG 2 - 4	Package AH		STG 4 - ADDITIONAL WORKSCOPE		145.00	SRTAS
139490	338-082-802-0	EASA;FAA;CAAC;ANAC			72-54-02		Package AH	017A	DIMENSIONAL RESTORATION ON BLADES THAT ARE WITHIN SERVICEABLE LIMITS BY REQUEST		145.00	SRTAS
139490	338-082-803-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B		STG 2 - FULL REPAIR		465.00	SRTAS
139490	338-082-804-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	002	PLASMA SPRAY SEAL TEETH ZIRCONIUM OXIDE-YTTRIUM (3 PARTS PER SET)		465.00	SRTAS
139490	338-082-852-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	003	RESET PRE TWIST ANGLE		465.00	SRTAS
139490	338-082-853-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	004	AIRFOIL BLEND REPAIR		465.00	SRTAS
139490	338-082-854-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	006	REPAIR OF THE HARDFACING AND MATING FACES ON THE TIP SHROUDS		465.00	SRTAS
139490	338-084-003-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	011	BLEND TO REMOVE ROOT SULPHIDATION/ CORROSION		465.00	SRTAS
139490	338-084-023-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	018	REPAIR APVS COATING		465.00	SRTAS

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139490	338-084-052-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	020	WELD REPAIR SEAL TEETH WITH COAST METAL 64		465.00	SRTAS
139490	338-084-072-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	041	LASER CLADDING OF HARDFACING AND MATING FACES OF BLADE TIP SHROUDS WITH COAST METAL 64		465.00	SRTAS
139490	338-086-203-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	055	OVER COATING OF VAPOUR PHASE ALUMINAZATION		465.00	SRTAS
139490	338-086-228-0	EASA;FAA;CAAC;ANAC			72-54-02		Package B	INSP-001	VISUAL / DIMENSIONAL INSPECTION		465.00	SRTAS
139490	338-086-253-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C		STG 3 - FULL REPAIR		295.00	SRTAS
139490	338-086-278-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	002	REPAIR OF SEAL TEETH BY PLASMA SPRAYING WITH ZIRCONIUM OXIDE-YTTRIUM		295.00	SRTAS
139490	338-108-304-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	003	RESET PRE TWIST ANGLE		295.00	SRTAS
139490	338-108-305-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	005	AIRFOIL BLEND REPAIR		295.00	SRTAS
139490	338-108-403-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	007	WELD REPAIR SHROUD NOTCHES AND HARD FACES WITH COAST METAL 64		295.00	SRTAS
139490	338-108-503-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	017	WELD REPAIR SEAL TEETH WITH COAST METAL 64		295.00	SRTAS
139490	338-108-504-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	028	REMOVAL OF OXIDES AND OXYSULPHIDES BY CHEMICAL CLEANING		295.00	SRTAS
139490	338-108-553-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	039	CORROSION REMOVAL FROM BLADE ROOT SURFACES		295.00	SRTAS
139490	338-108-554-0	EASA;FAA;CAAC;ANAC			72-54-02		Package C	INSP-001	VISUAL / DIMENSIONAL		295.00	SRTAS
139490	338-115-902-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D		STG 4 - FULL REPAIR		305.00	SRTAS
139490	338-116-102-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	002	REPAIR OF SEAL TEETH BY PLASMA SPRAYING WITH ZIRCONIUM OXIDE-YTTRIUM		305.00	SRTAS
139490	338-116-103-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	003	RESET PRE TWIST ANGLE		305.00	SRTAS
139490	338-116-152-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	005	AIRFOIL BLEND REPAIR		305.00	SRTAS
139490	338-116-153-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	008	WELD REPAIR SHROUD NOTCHES AND HARD FACES WITH T800		305.00	SRTAS
139490	338-116-303-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	009	REPLACE RBD 191 WITH T800 ON TIP SHROUDS		305.00	SRTAS
139490	338-116-304-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	017	WELD REPAIR SEAL TEETH WITH COAST METAL 64		305.00	SRTAS
139490	340-302-101-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	028	REMOVAL OF OXIDES AND OXYSULPHIDES BY CHEMICAL CLEANING		305.00	SRTAS
139490	340-302-201-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	039	CORROSION REMOVAL FROM BLADE ROOT SURFACES		305.00	SRTAS
139490	340-302-202-0	EASA;FAA;CAAC;ANAC			72-54-02		Package D	INSP-001	VISUAL / DIMENSIONAL		305.00	SRTAS
139490	340-302-301-0	EASA;FAA;CAAC;ANAC			72-54-02		Package N		STG 2 - ADDITIONAL WORKSCOPE		145.00	SRTAS
139490	340-310-101-0	EASA;FAA;CAAC;ANAC			72-54-02		Package N	020A	DIMENSIONAL RESTORATION OF THE SEAL TEETH ON BLADES THAT ARE WITHIN SERVICEABLE LIMITS B'		145.00	SRTAS
139490	340-310-202-0	EASA;FAA;CAAC;ANAC			72-54-02		Package X		STG 3 - ADDITIONAL WORKSCOPE		145.00	SRTAS
139490	340-310-301-0	EASA;FAA;CAAC;ANAC			72-54-02		Package X	017A	DIMENSIONAL RESTORATION ON BLADES THAT ARE WITHIN SERVICEABLE LIMITS BY REQUEST		145.00	SRTAS
139533	238-0207-503	EASA;FAA;CAAC;ANAC	23	21	71-21-08	FWD ENGINE MOUNT - SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		1210.00	SR Technics Switzerland
139533	238-0207-505	EASA;FAA;CAAC;ANAC			71-21-08		Package F	005	PART NUMBER AND SERIAL NUMBER REPAIR .		80.00	SR Technics Switzerland
139533	238-0207-506	EASA;FAA;CAAC;ANAC			71-21-08		Package G	006	REPLACE BEARING - SUPPORT ASSEMBLY		1205.00	SR Technics Switzerland
139533	238-0207-507	EASA;FAA;CAAC;ANAC			71-21-08		Package P	015	BLEND REPAIR - SUPPORT ASSEMBLY		495.00	SR Technics Switzerland
139533	238-0207-508	EASA;FAA;CAAC;ANAC										
139533	238-0207-509	EASA;FAA;CAAC;ANAC;CAA UK										
139533	238-0207-510	EASA;FAA;CAAC;ANAC;CAA UK										
139533	238-0207-511	EASA;FAA;CAAC;ANAC										
139533	238-0207-512	EASA;FAA;CAAC;ANAC										
139533	238-0207-513	EASA;FAA;CAAC;ANAC										
139533	238-0207-514	EASA;FAA;CAAC;ANAC										
139533	238-0207-515	EASA;FAA;CAAC;ANAC										
139533	238-0207-521	EASA;FAA;CAAC;ANAC										
139533	238-0207-522	EASA;FAA;CAAC;ANAC										
139537	8862-01-1150-707-9	EASA;FAA;ANAC	6	21	26-10-82	MODEL 801RDS FIRE/OVERHEAT DETECTOR	Package B	TEST	BENCH TEST		175.00	SR Technics Switzerland
139537	8862-101	EASA;FAA;CAAC;ANAC										
139537	8862-101-1150-707-9	EASA;FAA;ANAC										
139550	335-191-202-0	EASA;FAA;CAAC;ANAC	37	28	72-21-02	FAN AND BOOSTER - BOOSTER BLADES, STAGES 2-4	Package A	CLN/INSP	CLEANING AND INSPECTION		45.00	SR Technics Switzerland
139550	335-191-203-0	EASA;FAA;CAAC;ANAC			72-21-02		Package E		WEIGH AND MATCH BLADE		45.00	SR Technics Switzerland
139550	335-191-204-0	EASA;FAA;CAAC;ANAC										
139550	335-191-205-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139550	335-191-302-0	EASA;FAA;CAAC;ANAC										
139550	335-191-303-0	EASA;FAA;CAAC;ANAC										
139550	335-191-304-0	EASA;FAA;CAAC;ANAC										
139550	335-191-305-0	EASA;FAA;CAAC;ANAC										
139550	338-002-206-0	EASA;FAA;CAAC;ANAC										
139550	338-002-207-0	EASA;FAA;CAAC;ANAC										
139550	338-002-208-0	EASA;FAA;CAAC;ANAC										
139550	338-002-209-0	EASA;FAA;CAAC;ANAC										
139550	338-002-218-0	EASA;FAA;CAAC;ANAC										
139550	338-002-219-0	EASA;FAA;CAAC;ANAC										
139550	338-002-220-0	EASA;FAA;CAAC;ANAC										
139550	338-002-221-0	EASA;FAA;CAAC;ANAC										
139550	338-002-306-0	EASA;FAA;CAAC;ANAC										
139550	338-002-307-0	EASA;FAA;CAAC;ANAC										
139550	338-002-308-0	EASA;FAA;CAAC;ANAC										
139550	338-002-309-0	EASA;FAA;CAAC;ANAC										
139550	338-002-318-0	EASA;FAA;CAAC;ANAC										
139550	338-002-319-0	EASA;FAA;CAAC;ANAC										
139550	338-002-320-0	EASA;FAA;CAAC;ANAC										
139550	338-002-321-0	EASA;FAA;CAAC;ANAC										
139550	338-002-406-0	EASA;FAA;CAAC;ANAC										
139550	338-002-407-0	EASA;FAA;CAAC;ANAC										
139550	338-002-408-0	EASA;FAA;CAAC;ANAC										
139550	338-002-409-0	EASA;FAA;CAAC;ANAC										
139550	338-002-418-0	EASA;FAA;CAAC;ANAC										
139550	338-002-419-0	EASA;FAA;CAAC;ANAC										
139550	338-002-420-0	EASA;FAA;CAAC;ANAC										
139550	338-002-421-0	EASA;FAA;CAAC;ANAC										
139550	338-002-518-0	EASA;FAA;CAAC;ANAC										
139550	338-002-519-0	EASA;FAA;CAAC;ANAC										
139550	338-002-520-0	EASA;FAA;CAAC;ANAC										
139550	338-002-521-0	EASA;FAA;CAAC;ANAC										
139550	338-002-534-0	EASA;FAA;CAAC;ANAC										
139550	338-002-535-0	EASA;FAA;CAAC;ANAC										
139550	338-002-536-0	EASA;FAA;CAAC;ANAC										
139550	338-002-537-0	EASA;FAA;CAAC;ANAC										
139550	338-002-542-0	EASA;FAA;CAAC;ANAC										
139550	338-002-543-0	EASA;FAA;CAAC;ANAC										
139550	338-002-544-0	EASA;FAA;CAAC;ANAC										
139550	338-002-545-0	EASA;FAA;CAAC;ANAC										
139550	340-057-201-0	EASA;FAA;CAAC;ANAC										
139550	340-057-202-0	EASA;FAA;CAAC;ANAC										
139550	340-057-203-0	EASA;FAA;CAAC;ANAC										
139550	340-057-204-0	EASA;FAA;CAAC;ANAC										
139550	340-057-301-0	EASA;FAA;CAAC;ANAC										
139550	340-057-302-0	EASA;FAA;CAAC;ANAC										
139550	340-057-303-0	EASA;FAA;CAAC;ANAC										
139550	340-057-304-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
139550	340-057-401-0	EASA;FAA;CAAC;ANAC										
139550	340-057-402-0	EASA;FAA;CAAC;ANAC										
139550	340-057-403-0	EASA;FAA;CAAC;ANAC										
139550	340-057-404-0	EASA;FAA;CAAC;ANAC										
139550	340-057-409-0	EASA;FAA;CAAC;ANAC										
139550	340-057-410-0	EASA;FAA;CAAC;ANAC										
140037	338-083-003-0	EASA;FAA;CAAC;ANAC	22	28	72-54-08	LOW PRESSURE TURBINE - NOZZLE SEGMENTS STG 2	Package A		BASIC REPAIR	PN338-083-104-0 338-083-154-0 FOR :	270.00	SRTAS
140037	338-083-004-0	EASA;FAA;CAAC;ANAC			72-54-08		Package A	INSP-001	VISUAL / DIMENSIONAL		270.00	SRTAS
140037	338-083-053-0	EASA;FAA;CAAC;ANAC			72-54-08		Package C		MINOR REPAIR		1580.00	SRTAS
140037	338-083-054-0	EASA;FAA;CAAC;ANAC			72-54-08		Package C	1	AIRFOIL BLEND REPAIR		1580.00	SRTAS
140037	338-083-104-0	EASA;FAA;CAAC;ANAC			72-54-08		Package C	18	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		1580.00	SRTAS
140037	338-083-105-0	EASA;FAA;CAAC;ANAC			72-54-08		Package C	32	RD 15-94412 - OVERCOATING OF APVS PROTECTION		1580.00	SRTAS
140037	338-083-154-0	EASA;FAA;CAAC;ANAC			72-54-08		Package C	4	REPAIR OF APVS COATING		1580.00	SRTAS
140037	338-083-155-0	EASA;FAA;CAAC;ANAC			72-54-08		Package C	INSP-001	VISUAL / DIMENSIONAL		1580.00	SRTAS
140037	338-083-204-0	EASA;FAA;CAAC;ANAC			72-54-08		Package D		FULL REPAIR		3305.00	SRTAS
140037	338-083-205-0	EASA;FAA;CAAC;ANAC			72-54-08		Package D	1	AIRFOIL BLEND REPAIR.		3305.00	SRTAS
140037	338-083-254-0	EASA;FAA;CAAC;ANAC			72-54-08		Package D	15	RD 15-94438 - RECONDITIONING BY DIFFUSION BRAZING OF THE MATING SURFACES WITH THE OSAS		3305.00	SRTAS
140037	338-083-255-0	EASA;FAA;CAAC;ANAC			72-54-08		Package D	18	REPLACE HONEYCOMB LINER (HONEYCOMB MATERIAL INCLUDED IN PRICE)		3305.00	SRTAS
140037	338-109-104-0	EASA;FAA;CAAC;ANAC			72-54-08		Package D	20	FULL BRAZING REPAIR		3305.00	SRTAS
140037	338-109-105-0	EASA;FAA;CAAC;ANAC			72-54-08		Package D	4	REPAIR OF APVS COATING.		3305.00	SRTAS
140037	338-109-106-0	EASA;FAA;CAAC;ANAC			72-54-08		Package D	INSP-001	VISUAL / DIMENSIONAL		3305.00	SRTAS
140037	338-109-107-0	EASA;FAA;CAAC;ANAC			72-54-08		Package E		ADDITIONAL WORKSCOPE		840.00	SRTAS
140037	338-109-108-0	EASA;FAA;CAAC;ANAC			72-54-08		Package E	19	WELD REPAIR OF ANTI-ROTATION SLOT AND HARD FACE SURFACES.		840.00	SRTAS
140037	338-109-109-0	EASA;FAA;CAAC;ANAC			72-54-08		Package F	72-0328	REWORK FOR OVERSPEED IMPROVEMENT (INCLUDES HONEYCOMB (WHEN PERFORMED INDEPENDENT		835.00	SRTAS
140037	338-109-150-0	EASA;FAA;CAAC;ANAC			72-54-08		Package G	72-0328	REWORK FOR OVERSPEED IMPROVEMENT (INCLUDES HONEYCOMB (WHEN PERFORMED AS PART OF M		700.00	SRTAS
140037	338-109-151-0	EASA;FAA;CAAC;ANAC			72-54-08		Package H	29	REPLACEMENT OF THE HONEYCOMB LINER		960.00	SRTAS
140037	338-109-204-0	EASA;FAA;CAAC;ANAC										
140037	338-109-205-0	EASA;FAA;CAAC;ANAC										
140037	338-109-206-0	EASA;FAA;CAAC;ANAC										
140037	338-109-207-0	EASA;FAA;CAAC;ANAC										
140037	338-109-208-0	EASA;FAA;CAAC;ANAC										
140037	338-109-209-0	EASA;FAA;CAAC;ANAC										
140037	338-109-250-0	EASA;FAA;CAAC;ANAC										
140037	338-109-251-0	EASA;FAA;CAAC;ANAC										
140037	338-109-304-0	EASA;FAA;CAAC;ANAC										
140037	338-109-305-0	EASA;FAA;CAAC;ANAC										
140037	338-109-306-0	EASA;FAA;CAAC;ANAC										
140037	338-109-307-0	EASA;FAA;CAAC;ANAC										
140037	338-109-308-0	EASA;FAA;CAAC;ANAC										
140037	338-109-309-0	EASA;FAA;CAAC;ANAC										
140037	338-109-350-0	EASA;FAA;CAAC;ANAC										
140037	338-109-351-0	EASA;FAA;CAAC;ANAC										
140037	340-303-001-0	EASA;FAA;CAAC;ANAC										
140037	340-303-101-0	EASA;FAA;CAAC;ANAC										
140037	340-303-201-0	EASA;FAA;CAAC;ANAC										
140121	1276M85P05	EASA;FAA;CAAC;ANAC	19	28	72-32-15	COMPRESSOR STATOR SUPPORT PLATE AND LINK	Package A	CLN/INSP	CLEANING AND INSPECTION		720.00	SR Technics Switzerland
140121	1276M86P05	EASA;FAA;CAAC;ANAC			72-32-15		Package SB00	72-0114	BELLCRANK VANE ACTUATION LINK BUSHING REPLACEMENT		2375.00	SR Technics Switzerland
140121	1591M23P02	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
140121	1591M24G01	EASA;FAA;CAAC;ANAC										
140121	9511M34P01	EASA;FAA;CAAC;ANAC										
140149	338-067-007-0	EASA;FAA;CAAC;ANAC	28	28	72-23-03	FAN FRAME ASSEMBLY - OUTLET GUIDE VANE	Package A	INSP-001	CLEANING AND INSPECTION		360.00	SR Technics Switzerland
140149	338-067-009-0	EASA;FAA;CAAC;ANAC			72-23-03		Package H	007	REPLACEMENT OF THE METALLIC LEADING EDGE ON A COMPOSITE FAN OUTLET GUIDE VANE		725.00	SR Technics Switzerland
140149	338-067-014-0	EASA;FAA;CAAC;ANAC										
140149	338-067-015-0	EASA;FAA;CAAC;ANAC										
140245	338-061-302-0	EASA;FAA;CAAC;ANAC	47	28	72-54-11	LOW PRESSURE TURBINE - COOLING MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION		605.00	SR Technics Switzerland
140245	338-061-352-0	EASA;FAA;CAAC;ANAC			72-54-11		Package B	001	REPLACEMENT OF ONE OR SEVERAL COOLING AIR TUBES		1130.00	SR Technics Switzerland
140245	338-119-301-0	EASA;FAA;CAAC;ANAC			72-54-11		Package F	005	REPLACEMENT OF THE FORWARD AND / OR REAR LUGS		845.00	SR Technics Switzerland
140245	340-027-505-0	EASA;FAA;CAAC;ANAC			72-54-11		Package H	007	SMOOTHING OF BRAZE		585.00	SR Technics Switzerland
140245	340-027-506-0	EASA;FAA;CAAC;ANAC			72-54-11		Package K	006	REPAIR OF CRACKS ON LUG BY TIG WELDING		460.00	SR Technics Switzerland
140245	340-027-507-0	EASA;FAA;CAAC;ANAC			72-54-11		Package L	004	REPLACEMENT OF SLEEVE		3240.00	SR Technics Switzerland
140245	340-027-508-0	EASA;FAA;CAAC;ANAC										
140245	340-027-555-0	EASA;FAA;CAAC;ANAC										
140245	340-027-556-0	EASA;FAA;CAAC;ANAC										
140245	340-027-557-0	EASA;FAA;CAAC;ANAC										
140245	340-038-251-0	EASA;FAA;CAAC;ANAC;CAA UK										
140245	340-038-307-0	EASA;FAA;CAAC;ANAC										
140245	340-038-351-0	EASA;FAA;CAAC;ANAC;CAA UK										
140245	340-311-401-0	EASA;FAA;CAAC;ANAC										
140245	340-311-402-0	EASA;FAA;CAAC;ANAC										
144718	1498M53G01	EASA;FAA;CAAC;ANAC	27	28	72-41-07	COMBUSTION CASE - COMPRESSOR STATOR SUPPORT CDP I	Package A	CLN/INSP	CLEANING AND INSPECTION		1060.00	SR Technics Switzerland
144718	1834M52P01	EASA;FAA;CAAC;ANAC			72-41-07		Package B	001	DIMENSIONAL RESTORATION		4605.00	SR Technics Switzerland
144718	1834M52P02	EASA;FAA;CAAC;ANAC			72-41-07		Package C		MEASURE NEW - / OVHLD PARTS		120.00	SR Technics Switzerland
144718	1993M20G01	EASA;FAA;CAAC;ANAC			72-41-07		Package SB00	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P,CFM56-5B2/2 TO CFM56-5B2/2P, CFM		730.00	SR Technics Switzerland
144718	2428M60G01	EASA;FAA;CAAC;ANAC										
144741	305-397-203-0	EASA;FAA;CAAC;ANAC	21	21	72-23-26	FAN FRAME ASSEMBLY - AIR TUBE	Package A	CLN/INSP	CLEANING AND INSPECTION		690.00	SR Technics Switzerland
144741	338-171-501-0	EASA;FAA;CAAC;ANAC			72-23-26		Package B	001	SPOT TOUCH-UP OR FULL REPAIR OF SULFURIC ANODIZING		165.00	SR Technics Switzerland
144741	340-032-401-0	EASA;FAA;CAAC;ANAC										
144755	338-001-905-0	EASA;FAA;CAAC;ANAC	37	28	72-21-04	FAN AND BOOSTER - BOOSTER SPOOL	Package A	CLN/INSP	CLEANING AND INSPECTION		2020.00	SR Technics Switzerland
144755	338-001-906-0	EASA;FAA;CAAC;ANAC			72-21-04		Package B	001	REPLACEMENT OF THE HI-LOCK FASTENERS AND/OR THE SEALING FLANGE		2335.00	SR Technics Switzerland
144755	340-000-814-0	EASA;FAA;CAAC;ANAC			72-21-04		Package C	002	SPOT TOUCH-UP OR FULL REPAIR OF THE CHROMIC OR SULFURIC ANODIZING ON THE SEALING FLANGE		435.00	SR Technics Switzerland
144755	340-000-815-0	EASA;FAA;CAAC;ANAC			72-21-04		Package E		REMOVE BOOSTER SPOOL FWD FLANGE PLUG		435.00	SR Technics Switzerland
144755	340-000-816-0	EASA;FAA;CAAC;ANAC			72-21-04		Package K	010	TOUCH UP OF SEAL TEETH		2595.00	SR Technics Switzerland
144755	340-000-824-0	EASA;FAA;CAAC;ANAC										
144755	340-000-825-0	EASA;FAA;CAAC;ANAC										
144755	340-000-826-0	EASA;FAA;CAAC;ANAC										
144756	338-002-701-0	EASA;FAA;CAAC;ANAC	25	28	72-21-04	FAN AND BOOSTER - SEALING FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		605.00	SR Technics Switzerland
144756	338-002-702-0	EASA;FAA;CAAC;ANAC			72-21-04		Package C	002	SPOT TOUCH-UP FULL OR RECONDITIONING OF THE CHROMIC OR SULFURIC ANODIZING		840.00	SR Technics Switzerland
144756	338-002-703-0	EASA;FAA;CAAC;ANAC										
144756	340-003-103-0	EASA;FAA;CAAC;ANAC										
144787	337-002-910-0	EASA;FAA;CAAC;ANAC	62	28	72-55-01	LOW PRESSURE TURBINE SHAFT - ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		1500.00	SR Technics Switzerland
144787	338-010-003-0	EASA;FAA;CAAC;ANAC			72-55-01		Package A	INSP	BORESCOPE INSPECTION (BSI)		1500.00	SR Technics Switzerland
144787	338-010-004-0	EASA;FAA;CAAC;ANAC			72-55-01		Package B	INSP-001	OUTER PAINTED SURFACE - CORROSION	BLENDING AND TOUCHUP REPAIR	1040.00	SR Technics Switzerland
144787	338-010-005-0	EASA;FAA;CAAC;ANAC			72-55-01		Package C	INSP-001	INNER SURFACE - CORROSION	BLASTING AND TOUCHUP REPAIR	1305.00	SR Technics Switzerland
144787	338-010-006-0	EASA;FAA;CAAC;ANAC			72-55-01		Package D	001	FULL REPAIR OF THE ALUMINUM PAINT		3950.00	SR Technics Switzerland
144787	340-074-703-0	EASA;FAA;CAAC;ANAC			72-55-01		Package H	014	BLENDING OF THE FORWARD ANTI-ROTATION LUGS		985.00	SR Technics Switzerland
144787	340-074-705-0	EASA;FAA;CAAC;ANAC			72-55-01		Package Q	016	CLEANING AND PACKAGING		435.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
144787	340-074-706-0	EASA;FAA;CAAC;ANAC			72-55-01		Package S	018	REPAIR OF THE LOCATING DIAMETER WITH AIR/OIL SEPARATOR		2635.00	SR Technics Switzerland
144787	340-074-707-0	EASA;FAA;CAAC;ANAC			72-55-01		Package SB00	72-0559	INSPECTION OF THE FORWARD LPT SHAFT FOR MISSING PAINT	IN CONJUNCTION WITH PACKAGE A	1030.00	SR Technics Switzerland
144787	340-074-720-0	EASA;FAA;CAAC;ANAC			72-55-01		Package SB01	AD 2002-13-03	MAGNETIC PARTICLE INSPECTION (MPI)	IN CONJUNCTION WITH PACKAGE A	760.00	SR Technics Switzerland
144787	340-074-721-0	EASA;FAA;CAAC;ANAC										
144787	340-074-722-0	EASA;FAA;CAAC;ANAC										
144787	340-074-723-0	EASA;FAA;CAAC;ANAC;CAA UK										
144788	336-025-102-0	EASA;FAA;CAAC;ANAC	27	28	72-56-03	LOW PRESSURE TURBINE REAR FRAME - OIL COLLECTOR	Package A	CLN/INSP	CLEANING AND INSPECTION		605.00	SR Technics Switzerland
144788	338-170-601-0	EASA;FAA;CAAC;ANAC										
144788	340-175-802-0	EASA;FAA;CAAC;ANAC										
144788	340-175-803-0	EASA;FAA;CAAC;ANAC										
144793	336-065-403-0	EASA;FAA;CAAC;ANAC	52	21	72-54-18	LOW PRESSURE TURBINE - AIR SUPPLY TUBE AND MANIFOLD	Package A	CLN/INSP	CLEANING AND INSPECTION		505.00	SR Technics Switzerland
144793	336-504-604-0	EASA;FAA;CAAC;ANAC			72-54-18		Package C	002	REPLACEMENT OF THE CLIP BY BRAZING		715.00	SR Technics Switzerland
144793	337-110-303-0	EASA;FAA;CAAC;ANAC			72-54-18		Package D	003	REPLACEMENT OF THE INLET FITTING AND/OR THE END FITTING BY WELDING		3015.00	SR Technics Switzerland
144793	338-118-602-0	EASA;FAA;CAAC;ANAC			72-54-18		Package E	004	REPLACEMENT OF THE END FITTING AND/OR THE FLANGE ON THE AIR SUPPLY TUBE		2865.00	SR Technics Switzerland
144793	340-027-602-0	EASA;FAA;CAAC;ANAC			72-54-18		Package F	002	REPLACEMENT OF THE OUTLET AND/OR INLET END FITTING AND/OR TECHNICAL INSTRUCTION		3035.00	SR Technics Switzerland
144793	340-027-603-0	EASA;FAA;CAAC;ANAC			72-54-18		Package O	014	HOSE AND TUBE ASSEMBLIES REPAIR 014 - EXTERNAL TUBE ASSEM GENERAL EXTERNAL TUBING REPAI		1005.00	SR Technics Switzerland
144793	340-027-604-0	EASA;FAA;CAAC;ANAC										
144793	340-091-603-0	EASA;FAA;CAAC;ANAC										
144793	340-091-604-0	EASA;FAA;CAAC;ANAC										
144793	340-091-605-0	EASA;FAA;CAAC;ANAC										
144794	336-009-602-0	EASA;FAA;ANAC	39	28	72-53-11	STAGE 1 LPT NOZZLE - INTERMEDIATE FLANGE	Package A	CLN/INSP	CLEANING AND INSPECTION		770.00	SR Technics Switzerland
144794	338-111-201-0	EASA;FAA;CAAC;ANAC			72-53-11		Package B	001	REPAIR OF THERMAL COATING ON MATING FACE & RABBET DIA WIT AREA A EFF. M		3685.00	SR Technics Switzerland
144794	338-111-202-0	EASA;FAA;CAAC;ANAC										
604609	642W9821-501	EASA;FAA;CAAC;ANAC	21	21	71-50-03	JUNCTION BOX TO THRUST REVERSER CHANNEL A AND CHAI	Package C	TEST	PRE TEST	TESTING AND FAULT ISOLATION	385.00	SR Technics Switzerland
604609	642W9853-501	EASA;FAA;CAAC;ANAC			71-50-03		Package D	LIGHT	REPAIR AND FINAL TEST	NO CONNECTIONS ARE AFFECTED	1265.00	SR Technics Switzerland
604609	642W9853-503	EASA;FAA;CAAC;ANAC			71-50-03		Package E	MEDIUM	REPAIR AND FINAL TEST	LESS THAN OR EQUAL TO 50% OF T	3575.00	SR Technics Switzerland
604609	642W9854-501	EASA;FAA;CAAC;ANAC			71-50-03		Package F	HEAVY	REPAIR AND FINAL TEST	MORE THAN 50% OF CONNECTIONS	4710.00	SR Technics Switzerland
604609	642W9854-505	EASA;FAA;CAAC;ANAC										
604609	642W9872-501	EASA;FAA;CAAC;ANAC										
604609	642W9873-501	EASA;FAA;CAAC;ANAC										
604609	642W9881-501	EASA;FAA;CAAC;ANAC										
604609	642W9882-501	EASA;FAA;CAAC;ANAC										
604609	642W9884-501	EASA;FAA;CAAC;ANAC										
614157	9542M62P02	EASA;FAA;CAAC;ANAC	12	28	72-61-13	INLET GEARBOX & NO.3 BEARING - REAR INSULATION BLANKE	Package A	CLN/INSP	CLEANING AND INSPECTION		1115.00	SR Technics Switzerland
614157	9542M62P03	EASA;FAA;CAAC;ANAC										
618231	9725M81P02	EASA;FAA;CAAC;ANAC	5	28	72-61-15	CFM56 INLET GEARBOX HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		365.00	SR Technics Switzerland
618231	9972M39P01	EASA;FAA;CAAC;ANAC										
619936	336-031-901-0	EASA;FAA;CAAC;ANAC	30	28	72-56-07	LOW PRESSURE TURBINE REAR FRAME - FLANGE ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		740.00	SR Technics Switzerland
619936	337-087-302-0	EASA;FAA;CAAC;ANAC			72-56-07		Package B	001	REPLACEMENT OF THE EQUIPMENT		985.00	SR Technics Switzerland
619936	338-171-801-0	EASA;FAA;CAAC;ANAC			72-56-07		Package C	002	REAR COVER, FILLER WELDING OF CRACKS		3510.00	SR Technics Switzerland
619936	338-171-802-0	EASA;FAA;CAAC;ANAC			72-56-07		Package D	003	REPLACEMENT OF THE SLEF LOCKING NUTS		730.00	SR Technics Switzerland
619936	338-171-902-0	EASA;FAA;CAAC;ANAC			72-56-07		Package E	004	CONFIG.2/3 CIRCULAR STAMP ON THE FLANGE		470.00	SR Technics Switzerland
619936	340-157-501-0	EASA;FAA;CAAC;ANAC			72-56-07		Package F	005	REPAIR OF DENTS	CONFIG.1	510.00	SR Technics Switzerland
619936	340-157-502-0	EASA;FAA;CAAC;ANAC			72-56-07		Package F	005	REPAIR OF DENTS	CONFIG.2/3	510.00	SR Technics Switzerland
619936	340-165-601-0	EASA;FAA;CAAC;ANAC			72-56-07		Package G		REPAIR ILLEGIBLE PART IDENTIFICATION NUMBERS		190.00	SR Technics Switzerland
619936	340-168-802-0	EASA;FAA;CAAC;ANAC										
619936	340-168-803-0	EASA;FAA;CAAC;ANAC										
622278	337-004-103-0	EASA;FAA;CAAC;ANAC	30	28	72-00-63	ENGINE MODULES/ASSEMBLIES - ACCESSORY GEARBOX MOI	Package A	CLN/INSP	CLEANING AND INSPECTION	INCLUDING CONSERVATION	4835.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
622278	337-004-104-0	EASA;FAA;CAAC;ANAC										
622278	337-004-105-0	EASA;FAA;CAAC;ANAC										
622278	338-089-701-0	EASA;FAA;CAAC;ANAC										
622278	338-089-702-0	EASA;FAA;CAAC;ANAC										
622278	338-089-703-0	EASA;FAA;CAAC;ANAC										
622278	340-046-503-0	EASA;FAA;CAAC;ANAC										
622278	340-046-504-0	EASA;FAA;CAAC;ANAC										
622278	340-046-505-0	EASA;FAA;CAAC;ANAC										
622278	340-046-508-0	EASA;FAA;CAAC;JCAB;ANAC										
622278	340-046-509-0	EASA;FAA;CAAC;JCAB;ANAC										
622278	340-046-528-0	EASA;FAA;JCAB;ANAC										
622278	340-188-601-0	EASA;FAA;CAAC;ANAC										
622278	340-188-603-0	EASA;FAA;CAAC;ANAC										
624071	301-360-006-0	EASA;FAA;CAAC;ANAC	23	28	72-23-14	FAN FRAME ASSEMBLY - ACCESSORY DRIVE MOUNT LINK AS	Package A	CLN/INSP	CLEANING AND INSPECTION		555.00	SR Technics Switzerland
624071	301-360-020-0	EASA;FAA;CAAC;ANAC			72-23-14		Package K	010	REPLACEMENT OF SPHERICAL BEARING ON MOUNT LINKS	72-09-04	960.00	SR Technics Switzerland
624071	305-356-606-0	EASA;FAA;CAAC;ANAC										
624071	305-356-620-0	EASA;FAA;CAAC;ANAC										
624071	336-042-801-0	EASA;FAA;CAAC;ANAC										
624071	336-042-810-0	EASA;FAA;CAAC;ANAC										
624071	338-077-601-0	EASA;FAA;CAAC;ANAC										
624071	338-077-651-0	EASA;FAA;CAAC;ANAC										
624071	340-029-401-0	EASA;FAA;CAAC;ANAC										
624071	340-029-501-0	EASA;FAA;CAAC;ANAC										
624071	340-029-502-0	EASA;FAA;CAAC;ANAC;CAA UK										
624071	340-032-801-0	EASA;FAA;CAAC;ANAC										
624071	340-103-802-0	EASA;FAA;CAAC;ANAC										
624071	340-168-001-0	EASA;FAA;CAAC;ANAC										
624071	340-168-101-0	EASA;FAA;CAAC;ANAC										
624071	340-168-201-0	EASA;FAA;CAAC;ANAC										
624071	340-168-501-0	EASA;FAA;CAAC;ANAC										
629621	1522M71P01	EASA;FAA;CAAC;ANAC	20	28	72-53-05	HPT SHROUD - MISCELLANEOUS	Package A	CLN/INSP	CLEANING AND INSPECTION		135.00	SR Technics Switzerland
629621	1667M72P01	EASA;FAA;CAAC;ANAC										
629938	1318M40G02	EASA;FAA;CAAC;ANAC	25	28	72-32-14	COMPRESSOR FRONT STATOR - VANE ACTUATOR TIE RODS	Package A	CLN/INSP	CLEANING AND INSPECTION		165.00	SR Technics Switzerland
629938	1318M40G03	EASA;FAA;CAAC;ANAC			72-32-14		Package B	001	INLET GUIDE VANE STAGE 1 AND STAGE 2 LINK SPHERICAL BEARING REPLACEMENT		335.00	SR Technics Switzerland
629938	1318M40G06	EASA;FAA;CAAC;ANAC			72-32-14		Package C	002	STAGE 3 LINK SPHERICAL BEARING REPLACEMENT		560.00	SR Technics Switzerland
629938	1318M41G02	EASA;FAA;CAAC;ANAC										
629938	1590M22P03	EASA;FAA;CAAC;ANAC										
629938	1590M22P04	EASA;FAA;CAAC;ANAC										
629938	1590M22P09	EASA;FAA;CAAC;ANAC										
629938	1590M33P01	EASA;FAA;CAAC;ANAC;CAA UK										
631917	642-2003-501	EASA;FAA;CAAC;ANAC	5	21	71-21-08	CFM56-5B MOUNT FWD ATTACHEMENT PINS	Package A	CLN/INSP	CLEANING & INSPECTION		365.00	SR Technics Switzerland
634090	1317M56G06	EASA;FAA;CAAC;ANAC	49	28	72-42-04	COMBUSTION CHAMBER (SAC) - OUTER LINER	Package A	CLN/INSP	CLEANING AND INSPECTION		980.00	SR Technics Switzerland
634090	1317M56G07	EASA;FAA;CAAC;ANAC			72-42-04		Package AA	026	APPL. OF THIN TBC ON OUTER LINER WITH LARGE DIAMETER MULTI-HOLES		3995.00	SR Technics Switzerland
634090	1317M56G08	EASA;FAA;CAAC;ANAC			72-42-04		Package AB	027	CRACK WELD/RESIZE REPAIR	+9 days TAT	6845.00	SR Technics Switzerland
634090	1317M56G09	EASA;FAA;CAAC;ANAC			72-42-04		Package AE	OS 255085	AIRFLOW TEST OF LARGE DIAMETER MULTI-HOLES ON OUTER LINER PANEL		2990.00	SR Technics Switzerland
634090	1317M56G10	EASA;FAA;CAAC;ANAC			72-42-04		Package C	002	REPAIR OF THE PLASMA SPRAY WEAR COATING ON THE OUTER LINER SEAL		12985.00	SR Technics Switzerland
634090	1317M56G11	EASA;FAA;CAAC;ANAC			72-42-04		Package C	003	REMOVAL OF THE THERMAL BARRIER COATING FROM THE OUTER LINER		12985.00	SR Technics Switzerland
634090	1317M56G12	EASA;FAA;CAAC;ANAC			72-42-04		Package C	004	(THIN) APPLY THE THERMAL BARRIER COATING ON THE OUTER LINER		12985.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
634090	1317M56G13	EASA;FAA;CAAC;ANAC			72-42-04		Package C	005	REMOVAL OF THE COMBUSTION CHAMBER OUTER LINER LUG RING		12985.00	SR Technics Switzerland
634090	1317M56G14	EASA;FAA;ANAC			72-42-04		Package C	007	BOLT HOLE DRILLING REPAIR		12985.00	SR Technics Switzerland
634090	1968M44G02	EASA;FAA;CAAC;ANAC			72-42-04		Package C	008	WELD REPAIR AND RESIZING OF COMBUSTION CHAMBER OUTER LINERS THAT HAVE I718 LUG RINGS		12985.00	SR Technics Switzerland
634090	1968M44G03	EASA;FAA;CAAC;ANAC			72-42-04		Package C	009	IGNITER SLEEVE, IGNITER FERRULE RETAINER AND IGNITER FERRULE REPAIR/REPLACEMENT		12985.00	SR Technics Switzerland
634090	1968M44G04	EASA;FAA;CAAC;ANAC			72-42-04		Package C	014	COMBUSTION CHAMBER OUTER LINER IGNITER FERRULE REPLACEMENT REPAIR		12985.00	SR Technics Switzerland
634090	1968M44G05	EASA;FAA;CAAC;ANAC			72-42-04		Package C	016	(THICK) THERMAL BARRIER COATING REPLACEMENT		12985.00	SR Technics Switzerland
634090	1968M44G06	EASA;FAA;CAAC;ANAC			72-42-04		Package C	017	IGNITER PORT LOCALIZED SIZING REPAIR AND INSPECTION		12985.00	SR Technics Switzerland
634090	1968M44G08	EASA;FAA;CAAC;ANAC			72-42-04		Package C	020	WELD REPAIR AND RESIZING OF THE OUTER LINER WITHOUT LUG RING REMOVAL		12985.00	SR Technics Switzerland
634090	1968M44G09	EASA;FAA;ANAC			72-42-04		Package F	012	WELDED PATCH REPAIR		2995.00	SR Technics Switzerland
634090	1968M45G03	EASA;FAA;CAAC;ANAC			72-42-04		Package G	013	INCO 718 PLASMA SPRAY REPAIR OF THE LUG RING AFT SURFACE		2480.00	SR Technics Switzerland
634090	1968M45G04	EASA;FAA;CAAC;ANAC			72-42-04		Package I	015	AFT SEAL FLANGE WELD REPAIR		4465.00	SR Technics Switzerland
634090	1968M63G05	EASA;FAA;CAAC;ANAC			72-42-04		Package S	018	AFT SUPPORT RING REPLACEMENT		4660.00	SR Technics Switzerland
634090	1968M63G06	EASA;FAA;CAAC;ANAC			72-42-04		Package SB00	72-0584	INSPECTION OF INNER AND OUTER LINER NUGGET THICKNESS	IN CONJUNCTION WITH PACKAGE C	385.00	SR Technics Switzerland
634090	1968M63G07	EASA;FAA;CAAC;ANAC			72-42-04		Package SB01	72-0656	COMBUSTION CHAMBER OUTER LINER REWORK	RECOATING WITH THICK THERMAL I	5695.00	SR Technics Switzerland
634090	1968M63G08	EASA;FAA;CAAC;ANAC			72-42-04		Package SB02	72-0336	INNER AND OUTER LINER THICKER TBC FIELD REWORK		1085.00	SR Technics Switzerland
634090	1968M63G09	EASA;FAA;CAAC;ANAC			72-42-04		Package SB04	72-0825	ALTERATION / THIN THERMAL BARRIER COATING APPLICATION		2715.00	SR Technics Switzerland
634090	1968M63G11	EASA;FAA;CAAC;ANAC			72-42-04		Package SB04	72-0831	ALTERATION / THIN THERMAL BARRIER COATING APPLICATION		2715.00	SR Technics Switzerland
634090	1968M63G12	EASA;FAA;CAAC;ANAC			72-42-04		Package SB05	72-0799	REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HO THICK TBC, +9 days TAT		10005.00	SR Technics Switzerland
634090	1968M63G15	EASA;FAA;CAAC;ANAC			72-42-04		Package SB06	72-0826	REWORK OF PRE-TECH INSERTION OUTER CC LINER WITH MULTI-HH +9 days TAT		3995.00	SR Technics Switzerland
634090	1968M63G16	EASA;FAA;CAAC;ANAC			72-42-04		Package SB08	72-0799	REWORK OF COMBUSTION CHAMBER OUTER LINER WITH MULTI-HO THIN TBC, +9 days TAT		10005.00	SR Technics Switzerland
634090	1968M63G19	EASA;FAA;CAAC;ANAC			72-42-04		Package SB09	72-1086	OUTER COMBUSTION CHAMBER LINER REMARKING		495.00	SR Technics Switzerland
634090	2256M22G01	EASA;FAA;CAAC;ANAC			72-42-04		Package SB11	72-1099	OUTER CC LINER WELD BUILDUP INSPECTION AT IGNITER PORT	2256M22G03	1285.00	SR Technics Switzerland
634090	2256M22G02	EASA;FAA;CAAC;ANAC			72-42-04		Package V	021	AFT SEAL FLANGE WELD REPAIR		4800.00	SR Technics Switzerland
634090	2256M22G03	EASA;FAA;ANAC			72-42-04		Package X	023	INSTALLATION OF A LUG RING WITH HIGH TEMPERATURE BRAZE ALLOY		8815.00	SR Technics Switzerland
634090	2256M22G04	EASA;FAA;CAAC;ANAC			72-42-04		Package Y	024	WELD PATCH REPAIR FOR THE TECH INSERTION OUTER LINER		3135.00	SR Technics Switzerland
634090	2414M75G02	EASA;FAA;CAAC;ANAC			72-42-04		Package Z	025	APPL. OF THICK TBC ON OUTER LINER WITH LARGE DIAMETER MULTI-HOLES		3995.00	SR Technics Switzerland
634090	2414M75G03	EASA;FAA;CAAC;ANAC										
634090	2414M75G04	EASA;FAA;CAAC;ANAC										
634090	2414M75G06	EASA;FAA;CAAC;ANAC										
634090	2414M75G07	EASA;FAA;CAAC;ANAC										
634090	2414M75G08	EASA;FAA;CAAC;ANAC										
634090	2480M42G01	EASA;FAA;ANAC										
634090	2480M42G02	EASA;FAA;ANAC										
635513	336-092-208-0	EASA;FAA;CAAC;ANAC	19	28	72-00-56	ENGINE MODULES/ASSEMBLIES - LOW PRESSURE TURBINE f	Package A	INSP-001	CLEANING COKING SUPPL/SCAV. TUBES	PN340-035-901-0 FOR SHOP VISIT ON	255.00	SR Technics Switzerland
635513	338-071-401-0	EASA;FAA;CAAC;ANAC			72-00-56		Package C	SPEC-PROC	REPLACE THE TURBINE FRAM MODULE		2160.00	SR Technics Switzerland
635513	340-035-901-0	EASA;FAA;ANAC			72-00-56		Package D		CRACK INSPECTION NIPPEL AREA BRG NO 5 HOUSING		175.00	SR Technics Switzerland
635513	340-035-903-0	EASA;FAA;ANAC			72-00-56		Package SB00	72-0521	INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD		870.00	SR Technics Switzerland
635513	340-035-904-0	EASA;FAA;ANAC			72-00-56		Package SB01	EASA-2014-0130	TIME LIMITS - ENGINE STATIONARY PARTS - LIFE LIMITS		275.00	SR Technics Switzerland
635513	340-035-905-0	EASA;FAA;ANAC										
635513	340-035-906-0	EASA;FAA;ANAC										
635513	340-035-907-0	EASA;FAA;ANAC										
635513	340-035-908-0	EASA;FAA;ANAC										
635520	1887M16G01	EASA;FAA;CAAC;ANAC	18	28	72-00-32	ENGINE MODULES/ASSEMBLIES - COMPRESSOR FRONT STAT	Package A	CLN/INSP	CLEANING AND INSPECTION	PN9324M76G02 FOR SHOP VISIT ONI	485.00	SR Technics Switzerland
635520	1887M16G02	EASA;FAA;CAAC;ANAC			72-00-32		Package B	INSP-001	REMOVE PAD LOCAL SCAPS		865.00	SR Technics Switzerland
635520	9324M66G01	EASA;FAA;ANAC			72-00-32		Package M	ASSEMBLY	GRINDING STAGE 1-5 HONEYCOMBS		4845.00	SR Technics Switzerland
635520	9324M66G02	EASA;FAA;ANAC										
635520	9324M76G01	EASA;FAA;CAAC;ANAC										
635520	9324M76G02	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
635864	9324M54G04	EASA;FAA;CAAC;ANAC	18	28	72-00-61	ENGINE MODULES/ASSEMBLIES - INLET GEARBOX AND NO3 B	Package SB00	72-0776	INTRODUCTION OF NO.3 BALL BEARING WITH NITRIDE HARDENING		160.00	SR Technics Switzerland
635864	9324M54G05	EASA;FAA;CAAC;ANAC										
635864	9324M54G06	EASA;FAA;CAAC;ANAC										
635864	9324M54G07	EASA;FAA;ANAC										
636431	338-071-201-0	EASA;FAA;CAAC;ANAC	22	28	72-00-54	ENGINE MODULES/ASSEMBLIES - LOW PRESSURE TURBINE I	Package A	CLN/INSP	CLEANING AND INSPECTION		485.00	SR Technics Switzerland
636431	338-092-301-0	EASA;FAA;CAAC;ANAC			72-00-54		Package B	INSP-001	MINOR MODULE MEASUREMENT RAIL "O"		165.00	SR Technics Switzerland
636431	338-092-319-0	EASA;FAA;CAAC;ANAC			72-00-54		Package C	002	TEMPORARY REPLACEMENT OF BROKEN STUD OF T 49.5 EGT SENSOR ASSEMBLY PLATE		1305.00	SR Technics Switzerland
636432	338-071-301-0	EASA;FAA;CAAC;ANAC	4	28	72-00-55	CFM56 LPT SHAFT MINOR MODUL	Package A	CLN/INSP	CLEANING & INSPECTION		410.00	SR Technics Switzerland
636432	338-071-302-0	EASA;FAA;ANAC			72-00-55		Package B	INSP-001	LPT SHAFT BLEND AND PAINT REPAIR		495.00	SR Technics Switzerland
636432	338-071-305-0	EASA;FAA;ANAC			72-00-55		Package K	010	RECONDITIONING OF SHAFT PAINT	72-00-03	325.00	SR Technics Switzerland
636432	338-071-306-0	EASA;FAA;ANAC			72-00-55		Package O	014	BLENDING ANTI-ROTATION-LUG	72-55-01	510.00	SR Technics Switzerland
636432	340-035-801-0	EASA;FAA;ANAC										
636432	340-035-804-0	EASA;FAA;ANAC										
636432	340-035-805-0	EASA;FAA;CAAC;ANAC										
636616	338-118-004-0	EASA;FAA;CAAC;ANAC	5	28	72-54-07	CFM56 LPT CASE RING SECTOR SEGMENTS	Package A	CLN/INSP	CLEANING AND INSPECTION		415.00	SR Technics Switzerland
636616	338-118-104-0	EASA;FAA;CAAC;ANAC			72-54-07		Package B	025	CRACK REPAIR ON SHIELD SHROUD SECTOR		1080.00	SR Technics Switzerland
636616	338-118-204-0	EASA;FAA;CAAC;ANAC										
636616	338-118-304-0	EASA;FAA;CAAC;ANAC										
640894	1444M33G02	EASA;FAA;CAAC;ANAC	22	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION	PN1969M83G01 340-021-801-0 FOR S	335.00	SR Technics Switzerland
640894	1467M24G01	EASA;FAA;CAAC;ANAC			72-09-03		Package A	TEST	PRESSURE TEST		335.00	SR Technics Switzerland
640894	1605M78G03	EASA;FAA;CAAC;ANAC			72-09-03		Package B	001	BLENDING		240.00	SR Technics Switzerland
640894	1813M50G01	EASA;FAA;CAAC;ANAC			72-09-03		Package G	006	REFACE SPHERICAL SEATINGS		405.00	SR Technics Switzerland
640894	1817M21G02	EASA;FAA;CAAC;ANAC			72-09-03		Package H	007	REFACE INTERNAL SEATING FACE		405.00	SR Technics Switzerland
640894	1817M38G01	EASA;FAA;CAAC;ANAC			72-09-03		Package SB00	79-0020	INSPECTION AND CLEANING OF THE AFT SUMP OIL TUBES	IN CONJUNCTION WITH PACKAGE A	145.00	SR Technics Switzerland
640894	1867M25G01	EASA;FAA;CAAC;ANAC			72-09-03		Package SB01	72-0072	MODIFICATION OF PS3 HOSE		205.00	SR Technics Switzerland
640894	1867M50G01	EASA;FAA;CAAC;ANAC			72-09-03		Package SB03	72-0416	INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY - WIRE HOLE		545.00	SR Technics Switzerland
640894	1870M60G01	EASA;FAA;CAAC;ANAC										
640894	1882M92G01	EASA;FAA;CAAC;ANAC										
640894	1892M13G01	EASA;FAA;CAAC;ANAC										
640894	1895M76G01	EASA;FAA;CAAC;ANAC										
640894	1896M60G01	EASA;FAA;CAAC;ANAC										
640894	1958M29G01	EASA;FAA;CAAC;ANAC										
640894	1958M69G01	EASA;FAA;CAAC;ANAC										
640894	1958M71G01	EASA;FAA;CAAC;ANAC										
640894	1971M27G01	EASA;FAA;CAAC;ANAC										
640894	2283M19G01	EASA;FAA;CAAC;ANAC										
640894	2283M20G01	EASA;FAA;CAAC;ANAC										
640894	2283M26G01	EASA;FAA;CAAC;ANAC										
640894	305-872-701-0	EASA;FAA;CAAC;ANAC										
640894	335-104-308-0	EASA;FAA;CAAC;ANAC										
640894	335-104-309-0	EASA;FAA;CAAC;ANAC										
640894	336-098-601-0	EASA;FAA;CAAC;ANAC										
640894	337-153-101-0	EASA;FAA;CAAC;ANAC										
640894	337-153-901-0	EASA;FAA;CAAC;ANAC										
640894	337-153-903-0	EASA;FAA;CAAC;ANAC										
640894	338-012-403-0	EASA;FAA;CAAC;ANAC										
640894	338-025-104-0	EASA;FAA;CAAC;ANAC										
640894	338-047-802-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640894	338-049-602-0	EASA;FAA;CAAC;ANAC										
640894	338-049-802-0	EASA;FAA;CAAC;ANAC										
640894	338-052-602-0	EASA;FAA;CAAC;ANAC										
640894	338-059-901-0	EASA;FAA;CAAC;ANAC										
640894	338-106-602-0	EASA;FAA;CAAC;ANAC										
640894	338-106-603-0	EASA;FAA;CAAC;ANAC										
640894	340-005-103-0	EASA;FAA;CAAC;ANAC										
640894	340-010-201-0	EASA;FAA;CAAC;ANAC										
640894	340-010-801-0	EASA;FAA;CAAC;ANAC										
640894	340-011-402-0	EASA;FAA;CAAC;ANAC										
640894	340-134-002-0	EASA;FAA;CAAC;ANAC										
640894	340-134-052-0	EASA;FAA;CAAC;ANAC										
640894	340-177-801-0	EASA;FAA;CAAC;ANAC										
640894	340-178-001-0	EASA;FAA;CAAC;ANAC;CAA UK										
640894	649-430-000-0	EASA;FAA;CAAC;ANAC										
640894	649-430-030-0	EASA;FAA;CAAC;ANAC										
640894	649-430-070-0	EASA;FAA;CAAC;ANAC										
640894	649-430-073-0	EASA;FAA;CAAC;ANAC										
640894	649-430-212-0	EASA;FAA;CAAC;ANAC										
640894	649-430-242-0	EASA;FAA;CAAC;ANAC										
640894	649-433-150-0	EASA;FAA;CAAC;ANAC										
640894	649-433-253-0	EASA;FAA;CAAC;ANAC										
640894	649-433-404-0	EASA;FAA;CAAC;ANAC										
640894	649-434-030-0	EASA;FAA;CAAC;ANAC										
640894	649-434-093-0	EASA;FAA;CAAC;ANAC										
640894	649-434-095-0	EASA;FAA;CAAC;ANAC										
640894	649-434-220-0	EASA;FAA;ANAC										
640894	649-434-231-0	EASA;FAA;CAAC;ANAC										
640894	649-434-242-0	EASA;FAA;CAAC;ANAC										
640894	649-434-254-0	EASA;FAA;CAAC;ANAC										
640894	649-434-404-0	EASA;FAA;CAAC;ANAC										
640894	649-438-013-0	EASA;FAA;CAAC;ANAC										
640894	649-438-014-0	EASA;FAA;CAAC;ANAC										
640894	649-439-013-0	EASA;FAA;CAAC;ANAC										
640894	9383M48G01	EASA;FAA;CAAC;ANAC										
640894	J534P10	EASA;FAA;CAAC;ANAC										
640894	R287P06	EASA;FAA;ANAC										
640894	R287P08	EASA;FAA;ANAC										
640895	1324M91G01	EASA;FAA;CAAC;ANAC	29	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		335.00	SR Technics Switzerland
640895	1443M92G01	EASA;FAA;CAAC;ANAC			72-09-03		Package G		REPAIR AND PRESSURE TEST		1205.00	SR Technics Switzerland
640895	1527M69G02	EASA;FAA;CAAC;ANAC			72-09-03		Package SB00	72-0416	INTRODUCTION OF NEW AND REWORKED PS3 AIR TUBES AND TUBE NIPPLE WITH SAFETY - WIRE HOLE		545.00	SR Technics Switzerland
640895	1605M38G02	EASA;FAA;CAAC;ANAC										
640895	1605M94G01	EASA;FAA;CAAC;ANAC										
640895	1621M50G01	EASA;FAA;CAAC;ANAC										
640895	1645M19G01	EASA;FAA;CAAC;ANAC										
640895	1645M43G02	EASA;FAA;CAAC;ANAC										
640895	1677M61G01	EASA;FAA;CAAC;ANAC										
640895	1787M42G02	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	1788M44G01	EASA;FAA;CAAC;ANAC										
640895	1813M94G01	EASA;FAA;CAAC;ANAC										
640895	1817M21G01	EASA;FAA;CAAC;ANAC										
640895	1817M35G01	EASA;FAA;CAAC;ANAC										
640895	1867M38G01	EASA;FAA;CAAC;ANAC										
640895	1867M57G01	EASA;FAA;CAAC;ANAC										
640895	1867M69G01	EASA;FAA;CAAC;ANAC										
640895	1869M33G01	EASA;FAA;CAAC;ANAC										
640895	1870M53G01	EASA;FAA;CAAC;ANAC										
640895	1870M61G01	EASA;FAA;CAAC;ANAC										
640895	1870M97G01	EASA;FAA;CAAC;ANAC										
640895	1871M15G01	EASA;FAA;CAAC;ANAC										
640895	1871M35G01	EASA;FAA;CAAC;ANAC										
640895	1882M86G01	EASA;FAA;CAAC;ANAC										
640895	1892M61G01	EASA;FAA;CAAC;ANAC										
640895	1892M62G01	EASA;FAA;CAAC;ANAC										
640895	1892M80G01	EASA;FAA;CAAC;ANAC										
640895	1896M46G01	EASA;FAA;CAAC;ANAC										
640895	1896M47G01	EASA;FAA;CAAC;ANAC										
640895	1898M42G01	EASA;FAA;CAAC;ANAC										
640895	1898M58G01	EASA;FAA;CAAC;ANAC										
640895	1958M58G01	EASA;FAA;CAAC;ANAC										
640895	1970M21G01	EASA;FAA;CAAC;ANAC										
640895	1970M89G01	EASA;FAA;CAAC;ANAC										
640895	1971M28G01	EASA;FAA;CAAC;ANAC										
640895	1971M49G01	EASA;FAA;CAAC;ANAC										
640895	1971M74G01	EASA;FAA;CAAC;ANAC										
640895	2046M13G01	EASA;FAA;CAAC;ANAC										
640895	2046M41G01	EASA;FAA;CAAC;ANAC										
640895	2283M22G01	EASA;FAA;CAAC;ANAC										
640895	2283M23G01	EASA;FAA;CAAC;ANAC										
640895	2283M38G01	EASA;FAA;CAAC;TCCA										
640895	2497M71G01	EASA;FAA;ANAC										
640895	305-397-001-0	EASA;FAA;CAAC;ANAC										
640895	336-451-005-0	EASA;FAA;CAAC;ANAC										
640895	336-451-205-0	EASA;FAA;CAAC;ANAC										
640895	336-455-405-0	EASA;FAA;CAAC;ANAC										
640895	336-457-407-0	EASA;FAA;CAAC;ANAC										
640895	336-457-606-0	EASA;FAA;CAAC;ANAC										
640895	336-489-402-0	EASA;FAA;CAAC;ANAC										
640895	336-489-604-0	EASA;FAA;CAAC;ANAC										
640895	337-026-804-0	EASA;FAA;CAAC;ANAC										
640895	337-027-203-0	EASA;FAA;CAAC;ANAC										
640895	337-029-705-0	EASA;FAA;CAAC;ANAC										
640895	337-029-902-0	EASA;FAA;CAAC;ANAC										
640895	337-152-702-0	EASA;FAA;CAAC;ANAC										
640895	337-153-503-0	EASA;FAA;CAAC;ANAC										
640895	337-154-101-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	338-011-706-0	EASA;FAA;CAAC;ANAC										
640895	338-011-809-0	EASA;FAA;CAAC;ANAC										
640895	338-011-908-0	EASA;FAA;CAAC;ANAC										
640895	338-012-006-0	EASA;FAA;CAAC;ANAC										
640895	338-023-402-0	EASA;FAA;CAAC;ANAC										
640895	338-023-603-0	EASA;FAA;CAAC;ANAC										
640895	338-023-803-0	EASA;FAA;CAAC;ANAC										
640895	338-023-804-0	EASA;FAA;ANAC										
640895	338-026-403-0	EASA;FAA;CAAC;ANAC										
640895	338-026-607-0	EASA;FAA;CAAC;ANAC										
640895	338-029-204-0	EASA;FAA;CAAC;ANAC										
640895	338-029-407-0	EASA;FAA;CAAC;ANAC										
640895	338-047-204-0	EASA;FAA;CAAC;ANAC										
640895	338-047-402-0	EASA;FAA;CAAC;ANAC										
640895	338-048-002-0	EASA;FAA;CAAC;ANAC										
640895	338-048-204-0	EASA;FAA;CAAC;ANAC										
640895	338-048-403-0	EASA;FAA;CAAC;ANAC										
640895	338-048-604-0	EASA;FAA;CAAC;ANAC										
640895	338-048-802-0	EASA;FAA;CAAC;ANAC										
640895	338-052-202-0	EASA;FAA;CAAC;ANAC										
640895	338-052-203-0	EASA;FAA;CAAC;ANAC										
640895	338-052-802-0	EASA;FAA;CAAC;ANAC										
640895	338-052-803-0	EASA;FAA;CAAC;ANAC										
640895	338-053-002-0	EASA;FAA;CAAC;ANAC										
640895	338-056-502-0	EASA;FAA;CAAC;ANAC										
640895	338-057-601-0	EASA;FAA;ANAC										
640895	338-057-651-0	EASA;FAA;CAAC;ANAC										
640895	338-057-701-0	EASA;FAA;CAAC;ANAC										
640895	338-057-751-0	EASA;FAA;CAAC;ANAC										
640895	338-057-753-0	EASA;FAA;CAAC;ANAC										
640895	338-059-951-0	EASA;FAA;CAAC;ANAC										
640895	338-125-003-0	EASA;FAA;CAAC;ANAC										
640895	338-126-004-0	EASA;FAA;CAAC;ANAC										
640895	338-126-103-0	EASA;FAA;CAAC;ANAC										
640895	338-126-153-0	EASA;FAA;CAAC;ANAC										
640895	338-129-101-0	EASA;FAA;CAAC;ANAC										
640895	338-129-251-0	EASA;FAA;CAAC;ANAC										
640895	338-130-801-0	EASA;FAA;CAAC;ANAC										
640895	340-005-104-0	EASA;FAA;CAAC;ANAC										
640895	340-005-105-0	EASA;FAA;CAAC;ANAC										
640895	340-006-103-0	EASA;FAA;CAAC;ANAC										
640895	340-007-005-0	EASA;FAA;CAAC;ANAC										
640895	340-007-102-0	EASA;FAA;CAAC;ANAC										
640895	340-007-203-0	EASA;FAA;CAAC;ANAC										
640895	340-008-504-0	EASA;FAA;CAAC;ANAC										
640895	340-009-303-0	EASA;FAA;CAAC;ANAC										
640895	340-010-401-0	EASA;FAA;CAAC;ANAC										
640895	340-010-402-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	340-010-603-0	EASA;FAA;CAAC;ANAC										
640895	340-011-001-0	EASA;FAA;CAAC;ANAC										
640895	340-011-202-0	EASA;FAA;CAAC;ANAC										
640895	340-011-601-0	EASA;FAA;CAAC;ANAC										
640895	340-011-804-0	EASA;FAA;CAAC;ANAC										
640895	340-012-402-0	EASA;FAA;CAAC;ANAC										
640895	340-014-203-0	EASA;FAA;CAAC;ANAC										
640895	340-014-406-0	EASA;FAA;CAAC;ANAC										
640895	340-014-602-0	EASA;FAA;CAAC;ANAC										
640895	340-015-103-0	EASA;FAA;CAAC;ANAC										
640895	340-016-101-0	EASA;FAA;CAAC;ANAC										
640895	340-016-151-0	EASA;FAA;CAAC;ANAC										
640895	340-016-201-0	EASA;FAA;CAAC;ANAC										
640895	340-016-251-0	EASA;FAA;CAAC;ANAC										
640895	340-016-452-0	EASA;FAA;CAAC;ANAC										
640895	340-016-602-0	EASA;FAA;CAAC;ANAC										
640895	340-016-652-0	EASA;FAA;CAAC;ANAC										
640895	340-016-701-0	EASA;FAA;CAAC;ANAC										
640895	340-016-751-0	EASA;FAA;CAAC;ANAC										
640895	340-018-103-0	EASA;FAA;CAAC;ANAC										
640895	340-021-002-0	EASA;FAA;CAAC;ANAC										
640895	340-021-003-0	EASA;FAA;CAAC;ANAC										
640895	340-021-802-0	EASA;FAA;CAAC;ANAC										
640895	340-021-803-0	EASA;FAA;CAAC;ANAC										
640895	340-021-852-0	EASA;FAA;CAAC;ANAC										
640895	340-021-853-0	EASA;FAA;CAAC;ANAC										
640895	340-022-003-0	EASA;FAA;CAAC;ANAC										
640895	340-022-201-0	EASA;FAA;CAAC;ANAC										
640895	340-023-507-0	EASA;FAA;CAAC;ANAC										
640895	340-088-803-0	EASA;FAA;CAAC;ANAC										
640895	340-138-401-0	EASA;FAA;CAAC;ANAC										
640895	340-138-801-0	EASA;FAA;CAAC;ANAC										
640895	340-138-951-0	EASA;FAA;CAAC;ANAC										
640895	340-8801-515	EASA;FAA;CAAC;ANAC										
640895	649-430-004-0	EASA;FAA;CAAC;ANAC										
640895	649-430-006-0	EASA;FAA;ANAC										
640895	649-430-036-0	EASA;FAA;ANAC										
640895	649-430-069-0	EASA;FAA;CAAC;ANAC										
640895	649-430-201-0	EASA;FAA;CAAC;ANAC										
640895	649-430-203-0	EASA;FAA;CAAC;ANAC										
640895	649-430-219-0	EASA;FAA;CAAC;ANAC										
640895	649-430-233-0	EASA;FAA;CAAC;ANAC										
640895	649-433-030-0	EASA;FAA;CAAC;ANAC										
640895	649-433-034-0	EASA;FAA;CAAC;ANAC										
640895	649-433-036-0	EASA;FAA;CAAC;ANAC										
640895	649-433-047-0	EASA;FAA;CAAC;ANAC										
640895	649-433-051-0	EASA;FAA;CAAC;ANAC										
640895	649-433-086-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640895	649-433-087-0	EASA;FAA;CAAC;ANAC										
640895	649-433-093-0	EASA;FAA;CAAC;ANAC										
640895	649-433-094-0	EASA;FAA;CAAC;ANAC										
640895	649-433-095-0	EASA;FAA;CAAC;ANAC										
640895	649-433-147-0	EASA;FAA;CAAC;ANAC										
640895	649-433-219-0	EASA;FAA;CAAC;ANAC										
640895	649-433-220-0	EASA;FAA;ANAC										
640895	649-433-231-0	EASA;FAA;CAAC;ANAC										
640895	649-433-233-0	EASA;FAA;CAAC;ANAC										
640895	649-433-254-0	EASA;FAA;CAAC;ANAC										
640895	649-434-034-0	EASA;FAA;CAAC;ANAC										
640895	649-434-036-0	EASA;FAA;CAAC;ANAC										
640895	649-434-087-0	EASA;FAA;CAAC;ANAC										
640895	649-434-091-0	EASA;FAA;CAAC;ANAC										
640895	649-434-094-0	EASA;FAA;CAAC;ANAC										
640895	649-434-147-0	EASA;FAA;CAAC;ANAC										
640895	649-434-219-0	EASA;FAA;CAAC;ANAC										
640895	649-434-233-0	EASA;FAA;CAAC;ANAC										
640895	649-434-251-0	EASA;FAA;CAAC;ANAC										
640895	649-434-253-0	EASA;FAA;CAAC;ANAC										
640895	649-438-000-0	EASA;FAA;CAAC;ANAC										
640895	649-438-002-0	EASA;FAA;CAAC;ANAC										
640895	649-438-004-0	EASA;FAA;CAAC;ANAC										
640895	649-438-005-0	EASA;FAA;CAAC;ANAC										
640895	649-438-011-0	EASA;FAA;CAAC;ANAC										
640895	649-438-012-0	EASA;FAA;CAAC;ANAC										
640895	649-438-101-0	EASA;FAA;CAAC;ANAC										
640895	649-438-102-0	EASA;FAA;CAAC;ANAC										
640895	649-438-200-0	EASA;FAA;CAAC;ANAC										
640895	649-438-201-0	EASA;FAA;CAAC;ANAC										
640895	649-439-005-0	EASA;FAA;CAAC;ANAC										
640895	649-439-012-0	EASA;FAA;CAAC;ANAC										
640895	649-439-102-0	EASA;FAA;CAAC;ANAC										
640895	649-439-200-0	EASA;FAA;CAAC;ANAC										
640895	9393M42G03	EASA;FAA;CAAC;ANAC										
640895	9393M46G08	EASA;FAA;CAAC;ANAC										
640896	1605M10G02	EASA;FAA;CAAC;ANAC	33	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		335.00	SR Technics Switzerland
640896	1605M63G01	EASA;FAA;CAAC;ANAC			72-09-03		Package G		REPAIR AND PRESSURE TEST		2225.00	SR Technics Switzerland
640896	1645M11G01	EASA;FAA;CAAC;ANAC										
640896	1645M31G03	EASA;FAA;CAAC;ANAC										
640896	1677M12G02	EASA;FAA;CAAC;ANAC										
640896	1677M20G01	EASA;FAA;CAAC;ANAC										
640896	1677M89G01	EASA;FAA;CAAC;ANAC										
640896	1677M91G01	EASA;FAA;CAAC;ANAC										
640896	1788M40G01	EASA;FAA;CAAC;ANAC										
640896	1813M24G01	EASA;FAA;CAAC;ANAC										
640896	1813M96G01	EASA;FAA;CAAC;ANAC										
640896	1817M52G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640896	1817M66G01	EASA;FAA;CAAC;ANAC										
640896	1867M39G01	EASA;FAA;CAAC;ANAC										
640896	1867M67G01	EASA;FAA;CAAC;ANAC										
640896	1870M24G01	EASA;FAA;CAAC;ANAC										
640896	1870M28G01	EASA;FAA;CAAC;ANAC										
640896	1870M45G01	EASA;FAA;CAAC;ANAC										
640896	1870M46G01	EASA;FAA;CAAC;ANAC										
640896	1870M57G01	EASA;FAA;CAAC;ANAC										
640896	1870M70G01	EASA;FAA;CAAC;ANAC										
640896	1870M71G01	EASA;FAA;CAAC;ANAC										
640896	1870M72G01	EASA;FAA;CAAC;ANAC										
640896	1870M73G01	EASA;FAA;CAAC;ANAC										
640896	1870M75G01	EASA;FAA;CAAC;ANAC										
640896	1882M68G01	EASA;FAA;CAAC;ANAC										
640896	1882M70G01	EASA;FAA;CAAC;ANAC										
640896	1882M72G01	EASA;FAA;CAAC;ANAC										
640896	1882M74G01	EASA;FAA;CAAC;ANAC										
640896	1892M16G01	EASA;FAA;CAAC;ANAC										
640896	1892M18G01	EASA;FAA;CAAC;ANAC										
640896	1892M47G01	EASA;FAA;CAAC;ANAC										
640896	1892M89G01	EASA;FAA;CAAC;ANAC										
640896	1895M58G01	EASA;FAA;CAAC;ANAC										
640896	1897M24G01	EASA;FAA;CAAC;ANAC										
640896	1897M68G01	EASA;FAA;CAAC;ANAC										
640896	1897M72G01	EASA;FAA;CAAC;ANAC										
640896	1897M74G01	EASA;FAA;CAAC;ANAC										
640896	1897M76G01	EASA;FAA;CAAC;ANAC										
640896	1898M13G01	EASA;FAA;CAAC;ANAC										
640896	1958M57G01	EASA;FAA;CAAC;ANAC										
640896	1971M75G01	EASA;FAA;CAAC;ANAC										
640896	2046M11G01	EASA;FAA;CAAC										
640896	2046M12G01	EASA;FAA;CAAC;ANAC										
640896	2046M16G01	EASA;FAA;ANAC										
640896	2046M30G01	EASA;FAA;CAAC;ANAC										
640896	2046M59G01	EASA;FAA;CAAC;ANAC										
640896	2046M71G01	EASA;FAA;CAAC;ANAC										
640896	2046M77G01	EASA;FAA;CAAC;ANAC										
640896	2283M24G01	EASA;FAA;CAAC;ANAC										
640896	2557M32G01	EASA;FAA;CAAC;ANAC										
640896	336-401-402-0	EASA;FAA;CAAC;ANAC										
640896	336-401-403-0	EASA;FAA;CAAC;ANAC										
640896	336-493-204-0	EASA;FAA;CAAC;ANAC										
640896	337-153-702-0	EASA;FAA;CAAC;ANAC										
640896	338-012-104-0	EASA;FAA;CAAC;ANAC										
640896	338-012-206-0	EASA;FAA;CAAC;ANAC										
640896	338-015-604-0	EASA;FAA;CAAC;ANAC										
640896	338-015-803-0	EASA;FAA;CAAC;ANAC										
640896	338-019-505-0	EASA;FAA;CAAC;J.CAB;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640896	338-019-703-0	EASA;FAA;CAAC;ANAC										
640896	338-024-004-0	EASA;FAA;CAAC;ANAC										
640896	338-037-202-0	EASA;FAA;CAAC;ANAC										
640896	338-039-603-0	EASA;FAA;CAAC;ANAC										
640896	338-047-002-0	EASA;FAA;CAAC;ANAC										
640896	338-128-501-0	EASA;FAA;CAAC;ANAC										
640896	340-006-004-0	EASA;FAA;CAAC;ANAC										
640896	340-006-005-0	EASA;FAA;CAAC;ANAC										
640896	340-006-104-0	EASA;FAA;CAAC;ANAC										
640896	340-009-202-0	EASA;FAA;CAAC;ANAC										
640896	340-009-401-0	EASA;FAA;CAAC;ANAC										
640896	340-012-802-0	EASA;FAA;CAAC;ANAC										
640896	340-014-007-0	EASA;FAA;CAAC;ANAC										
640896	340-015-801-0	EASA;FAA;CAAC;ANAC										
640896	340-015-852-0	EASA;FAA;CAAC;ANAC										
640896	340-015-906-0	EASA;FAA;CAAC;ANAC										
640896	340-015-956-0	EASA;FAA;CAAC;ANAC										
640896	340-016-002-0	EASA;FAA;CAAC;ANAC										
640896	340-016-003-0	EASA;FAA;CAAC;ANAC										
640896	340-016-052-0	EASA;FAA;CAAC;ANAC										
640896	340-016-053-0	EASA;FAA;CAAC;ANAC										
640896	340-016-802-0	EASA;FAA;CAAC;ANAC										
640896	340-016-852-0	EASA;FAA;CAAC;ANAC										
640896	340-020-501-0	EASA;FAA;CAAC;ANAC										
640896	340-020-502-0	EASA;FAA;CAAC;ANAC										
640896	340-130-401-0	EASA;FAA;CAAC;ANAC										
640896	340-130-501-0	EASA;FAA;CAAC;ANAC										
640896	642-9848-501	EASA;FAA;CAAC;ANAC										
640896	649-430-071-0	EASA;FAA;ANAC										
640896	649-433-091-0	EASA;FAA;CAAC;ANAC										
640896	649-433-146-0	EASA;FAA;CAAC;ANAC										
640896	649-433-242-0	EASA;FAA;CAAC;ANAC										
640896	649-439-011-0	EASA;FAA;CAAC;ANAC										
640897	1645M25G03	EASA;FAA;CAAC;ANAC	32	21	72-09-03	GENERAL PROCEDURES - HOSE AND TUBE ASSEMBLIES	Package A	CLN/INSP	CLEANING AND INSPECTION		325.00	SR Technics Switzerland
640897	1677M55G01	EASA;FAA;CAAC;ANAC			72-09-03		Package G		REPAIR AND PRESSURE TEST		5050.00	SR Technics Switzerland
640897	1716M87G01	EASA;FAA;CAAC;ANAC			72-09-03		Package U		RE-ETCH PART NUMBER		145.00	SR Technics Switzerland
640897	1788M85G03	EASA;FAA;CAAC;ANAC										
640897	1813M52G01	EASA;FAA;CAAC;ANAC										
640897	1813M60G01	EASA;FAA;CAAC;ANAC										
640897	1817M67G01	EASA;FAA;CAAC;ANAC										
640897	1867M43G01	EASA;FAA;CAAC;ANAC										
640897	1867M71G01	EASA;FAA;CAAC;ANAC										
640897	1869M45G01	EASA;FAA;CAAC;ANAC										
640897	1870M27G01	EASA;FAA;CAAC;ANAC										
640897	1870M44G01	EASA;FAA;CAAC;ANAC										
640897	1870M86G01	EASA;FAA;CAAC;ANAC										
640897	1870M90G01	EASA;FAA;CAAC;ANAC										
640897	1870M98G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640897	1871M46G01	EASA;FAA;CAAC;ANAC										
640897	1882M76G01	EASA;FAA;CAAC;ANAC										
640897	1888M49G01	EASA;FAA;CAAC;ANAC										
640897	1888M52G01	EASA;FAA;CAAC;ANAC										
640897	1895M60G01	EASA;FAA;CAAC;ANAC										
640897	1895M65G01	EASA;FAA;ANAC										
640897	1896M69G01	EASA;FAA;CAAC;ANAC										
640897	1897M39G01	EASA;FAA;CAAC;ANAC										
640897	1897M51G01	EASA;FAA;CAAC;ANAC										
640897	1897M69G01	EASA;FAA;CAAC;ANAC										
640897	1898M20G01	EASA;FAA;CAAC;ANAC										
640897	1898M35G01	EASA;FAA;CAAC;ANAC										
640897	1898M38G01	EASA;FAA;CAAC;ANAC										
640897	1958M70G01	EASA;FAA;CAAC;ANAC										
640897	1970M36G01	EASA;FAA;CAAC;ANAC										
640897	1971M90G01	EASA;FAA;CAAC;ANAC										
640897	2046M55G01	EASA;FAA;CAAC;ANAC										
640897	2046M79G01	EASA;FAA;CAAC;ANAC										
640897	2174M16G01	EASA;FAA;CAAC;ANAC										
640897	2174M17G01	EASA;FAA;CAAC;ANAC										
640897	2174M18G01	EASA;FAA;ANAC										
640897	2174M19G01	EASA;FAA;CAAC;ANAC										
640897	2175M39G01	EASA;FAA;CAAC;ANAC										
640897	2175M40G01	EASA;FAA;CAAC;ANAC										
640897	2175M41G01	EASA;FAA;CAAC;ANAC										
640897	2175M42G01	EASA;FAA;CAAC;ANAC										
640897	2175M45G01	EASA;FAA;ANAC										
640897	2175M48G01	EASA;FAA;CAAC;ANAC										
640897	2480M87G01	EASA;FAA;CAAC;ANAC										
640897	2497M63G01	EASA;FAA;CAAC;ANAC										
640897	2497M70G01	EASA;FAA;ANAC										
640897	336-462-002-0	EASA;FAA;CAAC;ANAC										
640897	336-462-003-0	EASA;FAA;CAAC;ANAC										
640897	336-462-051-0	EASA;FAA;CAAC;ANAC										
640897	336-462-052-0	EASA;FAA;CAAC;ANAC										
640897	336-462-071-0	EASA;FAA;CAAC;ANAC										
640897	338-025-003-0	EASA;FAA;CAAC;ANAC										
640897	338-166-604-0	EASA;FAA;CAAC;ANAC										
640897	338-166-804-0	EASA;FAA;CAAC;ANAC										
640897	338-166-904-0	EASA;FAA;CAAC;ANAC										
640897	338-169-302-0	EASA;FAA;CAAC;ANAC										
640897	340-015-302-0	EASA;FAA;CAAC;ANAC										
640897	340-105-302-0	EASA;FAA;CAAC;ANAC										
640897	340-105-352-0	EASA;FAA;CAAC;ANAC										
640897	649-431-650-0	EASA;FAA;CAAC;ANAC										
640897	649-433-251-0	EASA;FAA;CAAC;ANAC										
640897	649-433-252-0	EASA;FAA;CAAC;ANAC										
640897	649-433-330-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640897	649-434-330-0	EASA;FAA;CAAC;ANAC										
640897	649-438-302-0	EASA;FAA;CAAC;ANAC										
640950	305-364-002-0	EASA;FAA;CAAC;ANAC	17	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		1055.00	SR Technics Switzerland
640950	305-364-103-0	EASA;FAA;CAAC;ANAC										
640950	337-108-201-0	EASA;FAA;CAAC;ANAC										
640950	340-257-001-0	EASA;FAA;CAAC;ANAC										
640951	305-365-702-0	EASA;FAA;CAAC;ANAC	16	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		1055.00	SR Technics Switzerland
640951	305-365-704-0	EASA;FAA;CAAC;ANAC										
640951	305-366-203-0	EASA;FAA;CAAC;ANAC										
640951	305-366-204-0	EASA;FAA;CAAC;ANAC										
640951	337-010-702-0	EASA;FAA;CAAC;ANAC										
640951	337-010-703-0	EASA;FAA;CAAC;ANAC										
640951	337-010-761-0	EASA;FAA;CAAC;ANAC										
640951	337-108-301-0	EASA;FAA;CAAC;ANAC										
640951	337-108-302-0	EASA;FAA;CAAC;ANAC										
640951	337-108-351-0	EASA;FAA;CAAC;ANAC										
640951	337-205-401-0	EASA;FAA;CAAC;ANAC										
640951	337-205-501-0	EASA;FAA;CAAC;ANAC										
640951	337-205-601-0	EASA;FAA;CAAC;ANAC										
640951	340-257-101-0	EASA;FAA;CAAC;ANAC										
640952	1361M71P02	EASA;FAA;CAAC;ANAC	17	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		1060.00	SR Technics Switzerland
640952	1361M71P05	EASA;FAA;CAAC;ANAC			72-09-01		Package SB00	72-0590	REDUCED INSPECTION INTERVAL FOR THE ELECTRICAL MASTER CHIP DETECTOR		1465.00	SR Technics Switzerland
640952	1364M91P01	EASA;FAA;CAAC;ANAC			72-09-01		Package SB01	EASA-2020-004	SB 72-0952-001		510.00	SR Technics Switzerland
640952	1364M91P02	EASA;FAA;CAAC;ANAC			72-09-01		Package SB01	FAA 2021-10-0	SB 72-0952-001		510.00	SR Technics Switzerland
640952	1364M91P05	EASA;FAA;CAAC;ANAC										
640952	1460M51P05	EASA;FAA;CAAC;ANAC										
640952	1460M52P01	EASA;FAA;CAAC;ANAC										
640952	1460M52P03	EASA;FAA;CAAC;ANAC										
640952	1460M52P05	EASA;FAA;CAAC;ANAC										
640952	1665M98P02	EASA;FAA;CAAC;ANAC										
640952	2124M95P01	EASA;FAA;CAAC;ANAC										
640952	2124M95P02	EASA;FAA;CAAC;ANAC										
640952	2411M39P01	EASA;FAA;CAAC;ANAC										
640952	2411M39P02	EASA;FAA;ANAC										
640952	9542M61P03	EASA;FAA;CAAC;ANAC										
640953	305-351-905-0	EASA;FAA;CAAC;ANAC	17	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		1295.00	SR Technics Switzerland
640953	305-352-004-0	EASA;FAA;CAAC;ANAC			72-09-01		Package SB01	72-0937	MARKING MANAGEMENT OF ROLLER BEARING#5		155.00	SR Technics Switzerland
640953	337-108-401-0	EASA;FAA;CAAC;ANAC										
640953	337-220-301-0	EASA;FAA;CAAC;ANAC										
640953	337-220-351-0	EASA;FAA;CAAC;ANAC										
640953	340-252-801-0	EASA;FAA;CAAC;ANAC										
640953	340-252-802-0	EASA;FAA;CAAC;ANAC										
640953	340-252-901-0	EASA;FAA;CAAC;ANAC										
640953	340-252-902-0	EASA;FAA;CAAC;ANAC										
640953	340-253-001-0	EASA;FAA;CAAC;ANAC										
640953	340-253-002-0	EASA;FAA;CAAC;ANAC										
640953	340-257-201-0	EASA;FAA;CAAC;ANAC										
640954	305-355-717-0	EASA;FAA;CAAC;ANAC	19	28	72-09-01	GENERAL PROCEDURE - MAIN ENGINE AND GEARBOX BEARING	Package A	CLN/INSP	CLEANING AND INSPECTION		1195.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
640954	305-355-718-0	EASA;FAA;CAAC;ANAC			72-09-01		Package SB03	72-A0393	REPLACEMENT OF NO.4 ROLLER BEARING		275.00	SR Technics Switzerland
640954	305-355-720-0	EASA;FAA;CAAC;ANAC			72-09-01		Package SB10	72-0452	NO.4 ROLLER BRG NEW OUTER RACE MATERIAL		275.00	SR Technics Switzerland
640954	335-352-301-0	EASA;FAA;CAAC;ANAC			72-09-01		Package SB12	72-0425	NEW MATERIAL FOR ROLLER BRG NO.4		275.00	SR Technics Switzerland
640954	335-352-302-0	EASA;FAA;CAAC;ANAC										
640954	335-352-303-0	EASA;FAA;CAAC;ANAC										
640954	335-352-304-0	EASA;FAA;CAAC;ANAC										
640954	335-352-305-0	EASA;FAA;CAAC;ANAC										
640954	340-167-901-0	EASA;FAA;CAAC;ANAC										
640954	340-167-902-0	EASA;FAA;CAAC;ANAC										
640954	340-167-904-0	EASA;FAA;CAAC;ANAC										
640954	340-167-906-0	EASA;FAA;CAAC;ANAC										
641535	1523M41G02	EASA;FAA;CAAC;ANAC	27	28	72-51-07	HIGH PRESSURE TURBINE NOZZLE - FWD INNER SUPPORT	Package A	CLN/INSP	CLEANING AND INSPECTION		2520.00	SR Technics Switzerland
641535	1668M61G01	EASA;FAA;CAAC;ANAC			72-51-07		Package C	5	HONEYCOMB REPAIR		9970.00	SR Technics Switzerland
641535	1668M61G03	EASA;FAA;CAAC;ANAC			72-51-07		Package E	4	REPAIR THE DIMENSIONS OF THE AFT FLANGE AND INDUCER DIAMETER SEAL SURFACE		3040.00	SR Technics Switzerland
641535	1668M61G05	EASA;FAA;CAAC;ANAC			72-51-07		Package H	7	REPAIR OF THE HPT NOZZLE FRONT INNER SUPPORT		2375.00	SR Technics Switzerland
641535	1808M15G01	EASA;FAA;CAAC;ANAC			72-51-07		Package M	12	CHROME CARBIDE EROSION COATING REPAIR		2660.00	SR Technics Switzerland
641535	1808M15G03	EASA;FAA;CAAC;ANAC			72-51-07		Package R	17	REPAIR OF CRACKS ON THE CAST INDUCER AFT SURFACE		3040.00	SR Technics Switzerland
641535	1808M15G04	EASA;FAA;CAAC;ANAC			72-51-07		Package SB01	72-0592	WITH IMPROVED EROSION COATING		2550.00	SR Technics Switzerland
641535	1808M15G05	EASA;FAA;CAAC;ANAC			72-51-07		Package SB03	72-0886	FORWARD INNER NOZZLE SUPPORT REWORK	2131M81G05, 2131M81G06	10040.00	SR Technics Switzerland
641535	1808M15G06	EASA;FAA;CAAC;ANAC										
641535	1808M15G08	EASA;FAA;CAAC;ANAC										
641535	1808M15G12	EASA;FAA;CAAC;ANAC										
641535	1808M15G13	EASA;FAA;CAAC;ANAC										
641535	1808M15G16	EASA;FAA;CAAC;ANAC										
641535	1873M94G05	EASA;FAA;CAAC;ANAC										
641535	1893M96G02	EASA;FAA;ANAC										
641535	2071M27G02	EASA;FAA;CAAC;ANAC										
641535	2071M28G01	EASA;FAA;CAAC;ANAC										
641535	2071M28G02	EASA;FAA;CAAC;ANAC										
641535	2071M28G04	EASA;FAA;CAAC;ANAC										
641535	2071M28G05	EASA;FAA;CAAC;ANAC										
641535	2071M28G07	EASA;FAA;CAAC;ANAC										
641535	2071M28G10	EASA;FAA;CAAC;ANAC										
641535	2131M81G05	EASA;FAA;CAAC;ANAC										
641535	2131M81G06	EASA;FAA;CAAC;ANAC										
641535	2131M82G01	EASA;FAA;CAAC;ANAC										
642820	1498M52G03	EASA;FAA;CAAC;ANAC	31	28	72-41-01	COMBUSTION CASE - ASSY	Package A	CLN/INSP	CLEANING AND INSPECTION	PN1784M91G02 FOR SHOP VISIT ONI	4660.00	SR Technics Switzerland
642820	1498M52G05	EASA;FAA;CAAC;ANAC			72-41-01		Package AA	026	INNER WALL BLEND REPAIR		4150.00	SR Technics Switzerland
642820	1498M52G06	EASA;FAA;CAAC;ANAC			72-41-01		Package AB	027	REPAIR OF DAMAGED JACKSCREW HOLES		1060.00	SR Technics Switzerland
642820	1498M52G08	EASA;FAA;CAAC;ANAC			72-41-01		Package B	INSP-001	BLENDING REPAIR		2770.00	SR Technics Switzerland
642820	1498M52G10	EASA;FAA;CAAC;ANAC			72-41-01		Package C	002	OUTLET GUIDE VANES BLENDING REPAIR	BLENDING OF L/E OR T/E	4475.00	SR Technics Switzerland
642820	1498M52G11	EASA;FAA;CAAC;ANAC			72-41-01		Package D	INSP-001	REMOVAL OF BROKEN BOLT(S)		1730.00	SR Technics Switzerland
642820	1498M52G12	EASA;FAA;CAAC;ANAC			72-41-01		Package D	INSP-001	REPLACEMENT OF CRIMPED NUTS		1730.00	SR Technics Switzerland
642820	1668M39G02	EASA;FAA;CAAC;ANAC			72-41-01		Package E	006	DIMENSIONAL RESTORATION OF COMBUSTION CASE FLANGES AND DIAMETERS		5950.00	SR Technics Switzerland
642820	1668M39G03	EASA;FAA;CAAC;ANAC			72-41-01		Package F	001	COMBUSTION CASE REPAIR OF THREADED HOLES		3190.00	SR Technics Switzerland
642820	1668M39G04	EASA;FAA;CAAC;ANAC			72-41-01		Package I	008	REPAIR OF FRETTING ON THE HIGH PRESSURE TURBINE COOLING DUCT PAD		9245.00	SR Technics Switzerland
642820	1668M39G05	EASA;FAA;CAAC;ANAC			72-41-01		Package P	015	REPAIR OF THE AFT CASE INNER DIAMETER		7925.00	SR Technics Switzerland
642820	1784M18G01	EASA;FAA;CAAC;ANAC			72-41-01		Package Q	016	DIAMETER M AND DIAMETER S REPAIR WITH T800 COATING		7925.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
642820	1784M18G02	EASA;FAA;CAAC;ANAC			72-41-01		Package SB00	72-0171	CONVERSION OF CFM56-5B1/2 TO CFM56-5B1/2P, CFM56-5B2/2 TO CF AND CFM56-5B6/2 TO CFM56-5B6/2P,		615.00	SR Technics Switzerland
642820	1784M82G04	EASA;FAA;CAAC;ANAC			72-41-01		Package SB02	72-0145	INTRODUCTION OF NEW COMBUSTION CASE CONFIGURATION		1755.00	SR Technics Switzerland
642820	1784M82G07	EASA;FAA;CAAC;ANAC			72-41-01		Package SB04	IA 219077	INSPECTION OF THE COMBUSTION CHAMBER		320.00	SR Technics Switzerland
642820	1784M82G08	EASA;FAA;CAAC;ANAC			72-41-01		Package X	023	THERMAL SPRAY REPAIR FOR THE INNER BAND WALL OF THE OUTLET GUIDE VANE		7150.00	SR Technics Switzerland
642820	1784M82G09	EASA;FAA;CAAC;ANAC										
642820	1784M91G01	EASA;FAA;CAAC;ANAC										
642820	1784M91G02	EASA;FAA;CAAC;ANAC										
642820	1784M91G03	EASA;FAA;CAAC;ANAC										
642820	1784M91G04	EASA;FAA;CAAC;ANAC										
642820	1784M91G05	EASA;FAA;CAAC;ANAC										
642820	1784M91G06	EASA;FAA;CAAC;ANAC										
642820	1784M91G07	EASA;FAA;CAAC;ANAC										
642820	1784M91G08	EASA;FAA;CAAC;ANAC										
642820	1784M91G11	EASA;FAA;CAAC;ANAC										
642820	1784M91G12	EASA;FAA;CAAC;ANAC										
642820	1784M91G13	EASA;FAA;CAAC;ANAC										
642820	1784M91G16	EASA;FAA;CAAC;ANAC										
642820	1784M91G17	EASA;FAA;ANAC										
642820	2002M81G01	EASA;FAA;CAAC;ANAC										
642820	2002M81G02	EASA;FAA;CAAC;ANAC										
642820	2002M81G03	EASA;FAA;CAAC;ANAC										
642820	2002M81G04	EASA;FAA;CAAC;ANAC										
642820	2002M81G05	EASA;FAA;CAAC;ANAC										
642820	2002M81G06	EASA;FAA;CAAC;ANAC										
642820	2002M81G07	EASA;FAA;CAAC;ANAC										
642820	2002M81G08	EASA;FAA;CAAC;ANAC										
642820	2002M81G09	EASA;FAA;CAAC;ANAC										
642820	2002M92G01	EASA;FAA;CAAC;ANAC										
642820	2002M92G02	EASA;FAA;CAAC;ANAC										
642820	2002M92G03	EASA;FAA;CAAC;ANAC										
642820	2002M92G05	EASA;FAA;CAAC;ANAC										
642820	2002M92G06	EASA;FAA;CAAC;ANAC										
642820	2002M92G07	EASA;FAA;CAAC;ANAC										
642820	2002M92G08	EASA;FAA;CAAC;ANAC										
648440	301-544-407-0	EASA;FAA;CAAC;ANAC	7	21	72-22-07	NO.1 AND NO.2 BEARING SUPPORT OIL TUBES	Package A	CLN/INSP	PRESSURE TEST		305.00	SR Technics Switzerland
648440	337-010-901-0	EASA;FAA;CAAC;ANAC			72-22-07		Package B	001	BLENDING		310.00	SR Technics Switzerland
648440	337-010-902-0	EASA;FAA;CAAC;ANAC										
648440	337-011-202-0	EASA;FAA;CAAC;ANAC										
648440	337-011-303-0	EASA;FAA;CAAC;ANAC										
648440	338-062-501-0	EASA;FAA;CAAC;ANAC										
648440	338-067-302-0	EASA;FAA;CAAC;ANAC										
648440	338-067-351-0	EASA;FAA;CAAC;ANAC										
648440	340-026-302-0	EASA;FAA;CAAC;ANAC										
648459	301-348-412-0	EASA;FAA;CAAC;ANAC	14	28	72-22-17	NO.1 AND NO.2 BEARING SUPPORT - PROBE SLEEVE	Package A	CLN/INSP	CLEANING AND INSPECTION		245.00	SR Technics Switzerland
648459	337-011-802-0	EASA;FAA;CAAC;ANAC										
648459	340-027-051-0	EASA;FAA;CAAC;ANAC										
648461	305-047-401-0	EASA;FAA;CAAC;ANAC	3	28	72-22-20	CFM56 NO.1 & NO.2 BEARING SUPPORT HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		145.00	SR Technics Switzerland
648461	AS3217-207	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
648461	AS3217-253	EASA;FAA;CAAC;ANAC										
648461	AS3218-247	EASA;FAA;CAAC;ANAC										
648461	J204P0475	EASA;FAA;CAAC;ANAC										
648461	J204P0925	EASA;FAA;CAAC;ANAC										
648461	J205P1100	EASA;FAA;CAAC;ANAC										
648494	305-367-103-0	EASA;FAA;CAAC;ANAC	5	28	72-22-10	CFM56 OIL SEPARATOR DUCT	Package A	CLN/INSP	CLEANING & INSPECTION		100.00	SR Technics Switzerland
648494	305-367-104-0	EASA;FAA;CAAC;ANAC										
648697	305-371-802-0	EASA;FAA;CAAC;ANAC	7	28	72-56-08	CFM56 FLAME ARRESTOR ASSEMBLY	Package A	CLN/INSP	CLEANING AND INSPECTION		395.00	SR Technics Switzerland
648697	305-371-803-0	EASA;FAA;CAAC;ANAC										
648698	336-049-702-0	EASA;FAA;CAAC;ANAC	4	21	72-56-05	CFM56 BEARING 5 DRAIN TUBE / OVERBOARD S	Package A	CLN/INSP	CLEANING & INSPECTION		200.00	SR Technics Switzerland
648698	338-107-801-0	EASA;FAA;CAAC;ANAC										
648706	336-022-402-0	EASA;FAA;CAAC;ANAC	4	21	72-53-10	CFM56 STAGE 1 LOW PRESSURE TURBINE NOZZLE	Package A	CLN/INSP	CLEANING & INSPECTION		40.00	SR Technics Switzerland
648706	336-022-503-0	EASA;FAA;CAAC;ANAC										
648706	340-256-401-0	EASA;FAA;CAAC;ANAC										
648706	340-256-501-0	EASA;FAA;CAAC;ANAC										
648714	1359M84P06	EASA;FAA;CAAC;ANAC	12	28	72-51-10	HIGH PRESSURE TURBINE NOZZLE - EXTERNAL PRESSURE SI	Package A	CLN/INSP	CLEANING AND INSPECTION		530.00	SR Technics Switzerland
648714	1359M84P08	EASA;FAA;CAAC;ANAC										
648724	2531M86P01	EASA;FAA;CAAC	7	28	72-31-10	CFM56 COMPRESSOR ROTOR BLADE LOCKS	Package A	CLN/INSP	CLEANING AND INSPECTION		225.00	SR Technics Switzerland
648724	2531M86P03	EASA;FAA;CAAC										
648724	2531M87P01	EASA;FAA;CAAC										
648724	2949M01P02	EASA;FAA										
648724	2949M03P01	EASA;FAA;CAAC										
648724	9984M27P01	EASA;FAA;CAAC										
648724	9984M27P02	EASA;FAA										
648724	9984M27P03	EASA;FAA										
648724	9984M27P04	EASA;FAA;CAAC										
648724	9984M27P07	EASA;FAA										
648724	9984M27P08	EASA;FAA										
648724	9984M28P01	EASA;FAA										
648724	9984M28P02	EASA;FAA;CAAC										
648724	9984M29P01	EASA;FAA										
648724	9984M29P02	EASA;FAA;CAAC										
648724	9984M29P03	EASA;FAA										
648731	1476M52P01	EASA;FAA;CAAC;ANAC	5	28	72-32-13	CFM56 BUSHING, COMPR. STATOR ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		60.00	SR Technics Switzerland
648731	1476M52P02	EASA;FAA;CAAC;ANAC										
648731	1476M52P04	EASA;FAA;CAAC;ANAC										
648731	9131M66P03	EASA;FAA;CAAC;ANAC										
648731	9131M68P02	EASA;FAA;CAAC;ANAC										
648731	9513M97P01	EASA;FAA;CAAC;ANAC										
648731	9513M98P01	EASA;FAA;CAAC;ANAC										
648731	9513M99P01	EASA;FAA;CAAC;ANAC										
648731	9944M24P01	EASA;FAA;CAAC;ANAC										
648731	9945M71P02	EASA;FAA;CAAC;ANAC										
648731	9945M74P06	EASA;FAA;CAAC;ANAC										
648731	9955M10P01	EASA;FAA;CAAC;ANAC										
650669	335-108-701-0	EASA;FAA;CAAC;ANAC	7	28	72-23-37	CFM56-5B SLIDES	Package A	CLN/INSP	CLEANING & INSPECTION		305.00	SR Technics Switzerland
650669	335-108-801-0	EASA;FAA;CAAC;ANAC										
650669	335-108-901-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
652060	2050M55P01	EASA;FAA;CAAC;ANAC	5	28	72-32-09	CFM56 COMPRESSOR STATOR VSV TRUNNION BUSHINGS	Package A	CLN/INSP	CLEANING & INSPECTION		35.00	SR Technics Switzerland
652060	2050M55P02	EASA;FAA;CAAC;ANAC										
652060	2102M23P04	EASA;FAA;CAAC;ANAC										
652060	2102M23P08	EASA;FAA;CAAC;ANAC										
652453	335-107-102-0	EASA;FAA;CAAC;ANAC	4	21	72-23-36	CFM56 SCOOP	Package A	CLN/INSP	CLEANING & INSPECTION		295.00	SR Technics Switzerland
652453	335-108-101-0	EASA;FAA;CAAC;ANAC										
652453	335-108-102-0	EASA;FAA;CAAC;ANAC										
652453	336-095-501-0	EASA;FAA;CAAC;ANAC										
653347	336-472-901-0	EASA;FAA;CAAC;ANAC	14	28	72-23-17	FAN FRAME ASSEMBLY - OEL TANK MOUNT PARTS	Package A	CLN/INSP	CLEANING AND INSPECTION		115.00	SR Technics Switzerland
653347	337-040-403-0	EASA;FAA;CAAC;ANAC										
653347	337-043-001-0	EASA;FAA;CAAC;ANAC										
653347	338-011-603-0	EASA;FAA;CAAC;ANAC										
653347	649-148-149-0	EASA;FAA;CAAC;ANAC										
653347	649-781-842-0	EASA;FAA;CAAC;ANAC										
654965	305-156-502-0	EASA;FAA;CAAC;ANAC	4	21	72-62-12	CFM56-5B TRANSFER GBX BRACKET ASSY	Package A	CLN/INSP	CLEANING & INSPECTION		65.00	SR Technics Switzerland
654965	305-156-603-0	EASA;FAA;CAAC;ANAC										
655267	305-156-301-0	EASA;FAA;CAAC;ANAC	4	28	72-63-16	CFM56 ACCESSORY GEARBOX BRACKETS	Package A	CLN/INSP	CLEANING & INSPECTION		80.00	SR Technics Switzerland
655267	305-156-502-0	EASA;FAA;CAAC;ANAC			72-63-16		Package B		REPLACE RIVETED PARTS		55.00	SR Technics Switzerland
655267	305-156-901-0	EASA;FAA;CAAC;ANAC										
655267	336-479-401-0	EASA;FAA;CAAC;ANAC										
655267	336-527-202-0	EASA;FAA;CAAC;ANAC										
655267	336-527-302-0	EASA;FAA;CAAC;ANAC										
655267	337-049-202-0	EASA;FAA;CAAC;ANAC										
655267	337-050-601-0	EASA;FAA;CAAC;ANAC										
655267	338-036-202-0	EASA;FAA;CAAC;ANAC										
655267	338-045-801-0	EASA;FAA;CAAC;ANAC										
655267	338-050-202-0	EASA;FAA;CAAC;ANAC										
655267	338-053-602-0	EASA;FAA;CAAC;ANAC										
655267	338-103-601-0	EASA;FAA;CAAC;ANAC										
655267	338-103-701-0	EASA;FAA;CAAC;ANAC										
655267	338-106-701-0	EASA;FAA;CAAC;ANAC										
655267	340-089-105-0	EASA;FAA;CAAC;ANAC										
655267	340-089-106-0	EASA;FAA;CAAC;ANAC										
655267	340-091-105-0	EASA;FAA;CAAC;ANAC										
655267	340-091-106-0	EASA;FAA;CAAC;ANAC										
655267	340-104-802-0	EASA;FAA;CAAC;ANAC										
655267	340-119-401-0	EASA;FAA;CAAC;ANAC										
655267	340-126-403-0	EASA;FAA;CAAC;ANAC										
656317	9513M60P02	EASA;FAA;CAAC;ANAC	11	28	72-52-09	CFM56 COUNTER WEIGHTS	Package A	CLN/INSP	CLEANING AND INSPECTION		165.00	SR Technics Switzerland
656317	9513M61P03	EASA;FAA;CAAC;ANAC										
656317	9513M61P04	EASA;FAA;CAAC;ANAC										
656317	9513M62P04	EASA;FAA;CAAC;ANAC										
656317	9513M62P05	EASA;FAA;CAAC;ANAC										
656317	9513M62P06	EASA;FAA;CAAC;ANAC										
656317	9524M49P04	EASA;FAA;CAAC;ANAC										
656317	9524M49P05	EASA;FAA;CAAC;ANAC										
656317	9524M49P06	EASA;FAA;CAAC;ANAC										
656317	9524M50P06	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
656317	9524M50P07	EASA;FAA;CAAC;ANAC										
656317	9524M50P08	EASA;FAA;CAAC;ANAC										
656317	9524M50P09	EASA;FAA;CAAC;ANAC										
656383	305-147-501-0	EASA;FAA;CAAC;ANAC	3	21	72-62-1	TRANSFER GEARBOX OIL NOZZLE PLUGS	Package A	CLN/INSP	CLEANING & INSPECTION		65.00	SR Technics Switzerland
656384	301-301-600-0	EASA;FAA;CAAC;ANAC	5	28	72-62-20	TRANSFER GEARBOX HARDWARE	Package A	CLN/INSP	CLEANING AND INSPECTION		385.00	SR Technics Switzerland
656384	305-120-700-0	EASA;FAA;CAAC;ANAC										
656384	305-158-401-6	EASA;FAA;CAAC;ANAC										
656384	305-158-412-0	EASA;FAA;CAAC;ANAC										
656384	305-158-506-0	EASA;FAA;CAAC;ANAC										
656384	335-319-501-0	EASA;FAA;CAAC;ANAC										
656384	335-321-801-6	EASA;FAA;CAAC;ANAC										
656384	649-363-131-0	EASA;FAA;CAAC;ANAC										
657873	1605M68P001A	EASA;FAA;CAAC;ANAC	14	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND E	Package A	CLN/INSP	CLEANING AND INSPECTION		60.00	SR Technics Switzerland
657873	1867M59G01	EASA;FAA;CAAC;ANAC										
657873	1867M73G01	EASA;FAA;CAAC;ANAC										
657873	1867M78G01	EASA;FAA;CAAC;ANAC										
657873	1868M20P001A	EASA;FAA;CAAC;ANAC										
657873	1870M31P001A	EASA;FAA;CAAC;ANAC										
657873	1894M47P001A	EASA;FAA;CAAC;ANAC										
657873	1894M63P001A	EASA;FAA;CAAC;ANAC										
657873	1958M27G01	EASA;FAA;CAAC;ANAC										
657873	1958M30G01	EASA;FAA;CAAC;ANAC										
657873	1969M92G01	EASA;FAA;CAAC;ANAC										
657873	1970M94G01	EASA;FAA;CAAC;ANAC										
657873	2174M42P01	EASA;FAA;CAAC;ANAC										
657873	238-0910-19	EASA;FAA;CAAC;ANAC										
657873	238-0910-37	EASA;FAA;CAAC;ANAC										
657873	238-0910-5	EASA;FAA;CAAC;ANAC										
657873	238-0950-15	EASA;FAA;CAAC;ANAC										
657873	238-0950-285	EASA;FAA;CAAC;ANAC										
657873	238-0950-63	EASA;FAA;CAAC;ANAC										
657873	642-5671-501	EASA;FAA;CAAC;ANAC										
657873	642-5672-501	EASA;FAA;CAAC;ANAC										
657873	642-5673-501	EASA;FAA;CAAC;ANAC										
657873	642-5829-501	EASA;FAA;CAAC;ANAC										
657873	642-9831-503	EASA;FAA;ANAC										
657873	642-9878-501	EASA;FAA;CAAC;ANAC										
657873	642-9928-501	EASA;FAA;CAAC;ANAC										
657873	642-9936-501	EASA;FAA;CAAC;ANAC										
657874	1621M35G01	EASA;FAA;ANAC	14	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND E	Package A	CLN/INSP	CLEANING AND INSPECTION		85.00	SR Technics Switzerland
657874	1677M98G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-11	120.00	SR Technics Switzerland
657874	1813M14G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		120.00	SR Technics Switzerland
657874	1813M15G01	EASA;FAA;CAAC;ANAC			72-09-04		Package V	SPM 70-43-01	SHOCK-MOUNT REPLACE ELASTOMER		400.00	SR Technics Switzerland
657874	1867M32G01	EASA;FAA;CAAC;ANAC										
657874	1867M44G01	EASA;FAA;CAAC;ANAC										
657874	1867M58G01	EASA;FAA;CAAC;ANAC										
657874	1867M60G01	EASA;FAA;CAAC;ANAC										
657874	1867M79G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657874	1867M81G01	EASA;FAA;CAAC;ANAC										
657874	1867M83G01	EASA;FAA;CAAC;ANAC										
657874	1867M84G01	EASA;FAA;CAAC;ANAC										
657874	1867M87G01	EASA;FAA;CAAC;ANAC										
657874	1869M13G01	EASA;FAA;CAAC;ANAC										
657874	1870M16G01	EASA;FAA;CAAC;ANAC										
657874	1870M33G01	EASA;FAA;CAAC;ANAC										
657874	1870M64G01	EASA;FAA;CAAC;ANAC										
657874	1870M78G01	EASA;FAA;CAAC;ANAC										
657874	1870M82G01	EASA;FAA;CAAC;ANAC										
657874	1892M21G01	EASA;FAA;CAAC;ANAC										
657874	1892M43G01	EASA;FAA;CAAC;ANAC										
657874	1894M44G01	EASA;FAA;CAAC;ANAC										
657874	1894M86G01	EASA;FAA;CAAC;ANAC										
657874	1894M88G01	EASA;FAA;CAAC;ANAC										
657874	1894M91G01	EASA;FAA;CAAC;ANAC										
657874	1894M94G01	EASA;FAA;CAAC;ANAC										
657874	1895M59G01	EASA;FAA;CAAC;ANAC										
657874	1958M55G01	EASA;FAA;CAAC;ANAC										
657874	1970M99G01	EASA;FAA;CAAC;ANAC										
657874	2174M33P01	EASA;FAA;CAAC;ANAC										
657874	2174M45G01	EASA;FAA;CAAC;ANAC										
657874	2174M46G01	EASA;FAA;CAAC;ANAC										
657874	2174M59G01	EASA;FAA;CAAC;ANAC										
657874	2175M12G01	EASA;FAA;CAAC;ANAC										
657874	2283M78G01	EASA;FAA;CAAC;ANAC										
657874	238-0660-501	EASA;FAA;CAAC;ANAC										
657874	238-0823-503	EASA;FAA;CAAC;ANAC										
657874	238-0856-159	EASA;FAA;CAAC;ANAC										
657874	238-0950-351	EASA;FAA;CAAC;ANAC										
657874	2423M79G01	EASA;FAA;ANAC;CAA UK										
657874	2468M14G01	EASA;FAA;ANAC										
657874	305-070-901-0	EASA;FAA;CAAC;ANAC										
657874	336-480-505-0	EASA;FAA;CAAC;ANAC										
657874	336-544-204-0	EASA;FAA;CAAC;ANAC										
657874	336-545-002-0	EASA;FAA;CAAC;ANAC										
657874	336-547-902-0	EASA;FAA;CAAC;ANAC										
657874	338-025-402-0	EASA;FAA;CAAC;ANAC										
657874	338-038-402-0	EASA;FAA;CAAC;ANAC										
657874	340-009-006-0	EASA;FAA;ANAC										
657874	340-022-504-0	EASA;FAA;ANAC										
657874	340-023-303-0	EASA;FAA;ANAC										
657874	340-023-406-0	EASA;FAA;ANAC										
657874	340-090-804-0	EASA;FAA;CAAC;ANAC										
657874	340-097-102-0	EASA;FAA;CAAC;ANAC										
657874	340-097-201-0	EASA;FAA;CAAC;ANAC										
657874	340-097-203-0	EASA;FAA;CAAC;ANAC										
657874	340-097-501-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657874	340-123-904-0	EASA;FAA;ANAC										
657874	340-124-003-0	EASA;FAA;CAAC;ANAC										
657874	340-125-704-0	EASA;FAA;ANAC										
657874	340-128-304-0	EASA;FAA;ANAC										
657874	340-130-002-0	EASA;FAA;ANAC										
657874	642-5613-501	EASA;FAA;CAAC;ANAC										
657874	642-5676-501	EASA;FAA;CAAC;ANAC										
657874	642-5702-501	EASA;FAA;CAAC;ANAC										
657874	642-5705-501	EASA;FAA;CAAC;ANAC										
657874	642-9830-501	EASA;FAA;CAAC;ANAC										
657874	642-9831-501	EASA;FAA;CAAC;ANAC										
657874	642-9831-505	EASA;FAA;CAAC;ANAC										
657874	642-9834-501	EASA;FAA;CAAC;ANAC										
657874	642-9849-503	EASA;FAA;CAAC;ANAC										
657874	642-9851-503	EASA;FAA;CAAC;ANAC										
657874	642-9857-503	EASA;FAA;CAAC;ANAC										
657874	642-9868-501	EASA;FAA;CAAC;ANAC										
657874	642-9892-501	EASA;FAA;CAAC;ANAC										
657874	642-9896-501	EASA;FAA;CAAC;ANAC										
657874	642-9897-501	EASA;FAA;CAAC;ANAC										
657874	642-9898-503	EASA;FAA;CAAC;ANAC										
657874	642-9920-501	EASA;FAA;CAAC;ANAC										
657874	642-9921-501	EASA;FAA;CAAC;ANAC										
657874	642-9924-501	EASA;FAA;CAAC;ANAC										
657874	642-9925-501	EASA;FAA;CAAC;ANAC										
657874	642-9927-501	EASA;FAA;CAAC;ANAC										
657874	642-9929-501	EASA;FAA;CAAC;ANAC										
657874	642-9945-501	EASA;FAA;CAAC;ANAC										
657875	1444M20G03	EASA;FAA;CAAC;ANAC	15	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND E	Package A	CLN/INSP	CLEANING AND INSPECTION		80.00	SR Technics Switzerland
657875	1677M30G03	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-11	155.00	SR Technics Switzerland
657875	1677M48G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		155.00	SR Technics Switzerland
657875	1788M89G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		155.00	SR Technics Switzerland
657875	1817M25G01	EASA;FAA;CAAC;ANAC			72-09-04		Package C	001	REPLACEMENT OF ANGLE BRACKET TAB		55.00	SR Technics Switzerland
657875	1867M19G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB03	RA32029-14	HIGH PRESSURE LINE 9 O'CLOCK CLAMP CHANGE		300.00	SR Technics Switzerland
657875	1867M34G01	EASA;FAA;CAAC;ANAC			72-09-04		Package V	SPM 70-43-01	SHOCK-MOUNT REPLACE ELASTOMER		95.00	SR Technics Switzerland
657875	1867M82G01	EASA;FAA;CAAC;ANAC										
657875	1869M14G01	EASA;FAA;CAAC;ANAC										
657875	1869M31G01	EASA;FAA;CAAC;ANAC										
657875	1869M32G01	EASA;FAA;CAAC;ANAC										
657875	1870M12G01	EASA;FAA;CAAC;ANAC										
657875	1870M29G01	EASA;FAA;CAAC;ANAC										
657875	1870M30G01	EASA;FAA;CAAC;ANAC										
657875	1870M34G01	EASA;FAA;CAAC;ANAC										
657875	1870M49G01	EASA;FAA;CAAC;ANAC										
657875	1870M58G01	EASA;FAA;CAAC;ANAC										
657875	1870M65G01	EASA;FAA;CAAC;ANAC										
657875	1870M69G01	EASA;FAA;CAAC;ANAC										
657875	1870M76G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	1870M77G01	EASA;FAA;CAAC;ANAC										
657875	1870M83G01	EASA;FAA;CAAC;ANAC										
657875	1870M91G01	EASA;FAA;CAAC;ANAC										
657875	1871M72G01	EASA;FAA;CAAC;ANAC										
657875	1892M27G01	EASA;FAA;CAAC;ANAC										
657875	1892M42G01	EASA;FAA;CAAC;ANAC										
657875	1892M48G01	EASA;FAA;CAAC;ANAC										
657875	1892M54G01	EASA;FAA;CAAC;ANAC										
657875	1892M68G01	EASA;FAA;CAAC;ANAC										
657875	1892M75G01	EASA;FAA;CAAC;ANAC										
657875	1892M82G01	EASA;FAA;CAAC;ANAC										
657875	1892M97G01	EASA;FAA;CAAC;ANAC										
657875	1894M12G01	EASA;FAA;CAAC;ANAC										
657875	1894M16G01	EASA;FAA;CAAC;ANAC										
657875	1894M21G01	EASA;FAA;CAAC;ANAC										
657875	1894M39G01	EASA;FAA;CAAC;ANAC										
657875	1894M42G01	EASA;FAA;CAAC;ANAC										
657875	1894M54G01	EASA;FAA;CAAC;ANAC										
657875	1894M55G01	EASA;FAA;CAAC;ANAC										
657875	1894M60G01	EASA;FAA;CAAC;ANAC										
657875	1894M66G01	EASA;FAA;CAAC;ANAC										
657875	1894M67G01	EASA;FAA;CAAC;ANAC										
657875	1894M84G01	EASA;FAA;CAAC;ANAC										
657875	1894M87G01	EASA;FAA;CAAC;ANAC										
657875	1894M90G01	EASA;FAA;CAAC;ANAC										
657875	1894M92G01	EASA;FAA;CAAC;ANAC										
657875	1895M79G01	EASA;FAA;CAAC;ANAC										
657875	1895M84G01	EASA;FAA;CAAC;ANAC										
657875	1895M85G01	EASA;FAA;CAAC;ANAC										
657875	1895M90G01	EASA;FAA;CAAC;ANAC										
657875	1896M38G01	EASA;FAA;CAAC;ANAC										
657875	1896M90G01	EASA;FAA;CAAC;ANAC										
657875	1897M49G01	EASA;FAA;CAAC;ANAC										
657875	1897M50G01	EASA;FAA;CAAC;ANAC										
657875	1897M57G01	EASA;FAA;CAAC;ANAC										
657875	1897M70G01	EASA;FAA;CAAC;ANAC										
657875	1898M64G01	EASA;FAA;CAAC;ANAC										
657875	1898M80G01	EASA;FAA;CAAC;ANAC										
657875	1898M86G01	EASA;FAA;CAAC;ANAC										
657875	1958M11G01	EASA;FAA;CAAC;ANAC										
657875	1958M13G01	EASA;FAA;CAAC;ANAC										
657875	1958M24G01	EASA;FAA;CAAC;ANAC										
657875	1958M31G01	EASA;FAA;CAAC;ANAC										
657875	1958M34G01	EASA;FAA;CAAC;ANAC										
657875	1958M40G01	EASA;FAA;CAAC;ANAC										
657875	1958M44G01	EASA;FAA;CAAC;ANAC										
657875	1958M45G01	EASA;FAA;CAAC;ANAC										
657875	1958M53G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	1958M76G01	EASA;FAA;CAAC;ANAC										
657875	1969M26G01	EASA;FAA;CAAC;ANAC										
657875	1969M93G01	EASA;FAA;CAAC;ANAC										
657875	1970M10G01	EASA;FAA;CAAC;ANAC										
657875	1970M28G01	EASA;FAA;CAAC;ANAC										
657875	1970M38G01	EASA;FAA;CAAC;ANAC										
657875	1970M68G01	EASA;FAA;CAAC;ANAC										
657875	1970M98G01	EASA;FAA;CAAC;ANAC										
657875	1971M11G01	EASA;FAA;CAAC;ANAC										
657875	1971M12G01	EASA;FAA;CAAC;ANAC										
657875	1971M14P01	EASA;FAA;CAAC;ANAC										
657875	1971M78G01	EASA;FAA;CAAC;ANAC										
657875	1971M79G01	EASA;FAA;CAAC;ANAC										
657875	1971M86G01	EASA;FAA;CAAC;ANAC										
657875	1971M98G01	EASA;FAA;CAAC;ANAC										
657875	2046M73G01	EASA;FAA;CAAC;ANAC										
657875	2174M26G01	EASA;FAA;CAAC;ANAC										
657875	2174M31G01	EASA;FAA;CAAC;ANAC										
657875	2174M32G01	EASA;FAA;CAAC;ANAC										
657875	2174M39G01	EASA;FAA;CAAC;ANAC										
657875	2174M41G01	EASA;FAA;CAAC;ANAC										
657875	2174M43G01	EASA;FAA;CAAC;ANAC										
657875	2174M47G01	EASA;FAA;CAAC;ANAC										
657875	2174M51G01	EASA;FAA;CAAC;ANAC										
657875	2174M52G01	EASA;FAA;CAAC;ANAC										
657875	2174M54G01	EASA;FAA;CAAC;ANAC										
657875	2174M58G01	EASA;FAA;CAAC;ANAC										
657875	2175M10G01	EASA;FAA;CAAC;ANAC										
657875	2175M11G01	EASA;FAA;CAAC;ANAC										
657875	2175M15G01	EASA;FAA;CAAC;ANAC										
657875	2175M63G01	EASA;FAA;CAAC;ANAC										
657875	2283M10G01	EASA;FAA;ANAC										
657875	2283M65G01	EASA;FAA;CAAC;ANAC										
657875	238-0557-501	EASA;FAA;CAAC;ANAC										
657875	238-0654-503	EASA;FAA;CAAC;ANAC										
657875	238-0655-503	EASA;FAA;CAAC;ANAC										
657875	238-0704-505	EASA;FAA;CAAC;ANAC										
657875	238-0708-507	EASA;FAA;CAAC;ANAC										
657875	238-0825-503	EASA;FAA;CAAC;ANAC										
657875	238-0856-139	EASA;FAA;CAAC;ANAC										
657875	238-0856-3	EASA;FAA;CAAC;ANAC										
657875	238-0910-35	EASA;FAA;CAAC;ANAC										
657875	238-0950-237	EASA;FAA;CAAC;ANAC										
657875	238-0950-311	EASA;FAA;CAAC;ANAC										
657875	2464M87G01	EASA;ANAC;TCCA;CAA UK										
657875	2678M59G01	EASA;FAA;ANAC										
657875	332A2911-1	EASA;FAA;CAAC;ANAC										
657875	332A2920-142	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	332A2920-92	EASA;FAA;CAAC;ANAC										
657875	332A2930-89	EASA;FAA;CAAC;ANAC										
657875	332A2931-3	EASA;FAA;CAAC;ANAC										
657875	336-479-603-0	EASA;FAA;CAAC;ANAC										
657875	336-515-803-0	EASA;FAA;CAAC;ANAC										
657875	336-523-002-0	EASA;FAA;CAAC;ANAC										
657875	336-544-303-0	EASA;FAA;CAAC;ANAC										
657875	336-544-406-0	EASA;FAA;CAAC;ANAC										
657875	336-544-503-0	EASA;FAA;CAAC;ANAC										
657875	336-544-603-0	EASA;FAA;CAAC;ANAC										
657875	336-544-706-0	EASA;FAA;CAAC;ANAC										
657875	336-544-707-0	EASA;FAA;CAAC;ANAC										
657875	336-544-902-0	EASA;FAA;CAAC;ANAC										
657875	338-014-504-0	EASA;FAA;CAAC;ANAC										
657875	338-014-601-0	EASA;FAA;CAAC;ANAC										
657875	338-017-301-0	EASA;FAA;CAAC;ANAC										
657875	338-017-502-0	EASA;FAA;CAAC;ANAC										
657875	338-022-101-0	EASA;FAA;CAAC;ANAC										
657875	338-023-203-0	EASA;FAA;CAAC;ANAC										
657875	338-024-404-0	EASA;FAA;CAAC;ANAC										
657875	338-024-405-0	EASA;FAA;ANAC										
657875	338-024-601-0	EASA;FAA;CAAC;ANAC										
657875	338-027-801-0	EASA;FAA;CAAC;ANAC										
657875	338-038-601-0	EASA;FAA;CAAC;ANAC										
657875	338-039-402-0	EASA;FAA;CAAC;ANAC										
657875	338-055-202-0	EASA;FAA;CAAC;ANAC										
657875	338-056-201-0	EASA;FAA;CAAC;ANAC										
657875	338-126-605-0	EASA;FAA;CAAC;ANAC										
657875	338-168-604-0	EASA;FAA;CAAC;ANAC										
657875	340-019-106-0	EASA;FAA;CAAC;ANAC										
657875	340-020-309-0	EASA;FAA;ANAC										
657875	340-097-002-0	EASA;FAA;CAAC;ANAC										
657875	340-097-405-0	EASA;FAA;CAAC;ANAC										
657875	340-097-502-0	EASA;FAA;CAAC;ANAC										
657875	340-097-601-0	EASA;FAA;CAAC;ANAC										
657875	340-097-701-0	EASA;FAA;CAAC;ANAC										
657875	340-119-303-0	EASA;FAA;CAAC;ANAC										
657875	340-119-501-0	EASA;FAA;CAAC;ANAC										
657875	340-119-602-0	EASA;FAA;CAAC;ANAC										
657875	340-119-701-0	EASA;FAA;CAAC;ANAC										
657875	340-139-102-0	EASA;FAA;CAAC;ANAC										
657875	340-8134-523	EASA;FAA;CAAC;ANAC										
657875	642-5652-501	EASA;FAA;CAAC;ANAC										
657875	642-5653-501	EASA;FAA;CAAC;ANAC										
657875	642-5657-503	EASA;FAA;CAAC;ANAC										
657875	642-5657-505	EASA;FAA;CAAC;ANAC										
657875	642-5663-501	EASA;FAA;CAAC;ANAC										
657875	642-5664-503	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657875	642-5665-501	EASA;FAA;CAAC;ANAC										
657875	642-5703-501	EASA;FAA;CAAC;ANAC										
657875	642-5826-501	EASA;FAA;CAAC;ANAC										
657875	642-5827-501	EASA;FAA;CAAC;ANAC										
657875	642-5856-501	EASA;FAA;CAAC;ANAC										
657875	642-5862-501	EASA;FAA;CAAC;ANAC										
657875	642-9825-501	EASA;FAA;CAAC;ANAC										
657875	642-9835-501	EASA;FAA;CAAC;ANAC										
657875	642-9836-501	EASA;FAA;CAAC;ANAC										
657875	642-9838-505	EASA;FAA;CAAC;ANAC										
657875	642-9840-501	EASA;FAA;CAAC;ANAC										
657875	642-9841-501	EASA;FAA;CAAC;ANAC										
657875	642-9844-501	EASA;FAA;CAAC;ANAC										
657875	642-9846-501	EASA;FAA;CAAC;ANAC										
657875	642-9847-501	EASA;FAA;CAAC;ANAC										
657875	642-9855-501	EASA;FAA;CAAC;ANAC										
657875	642-9855-502	EASA;FAA;CAAC;ANAC										
657875	642-9855-503	EASA;FAA;CAAC;ANAC										
657875	642-9856-501	EASA;FAA;CAAC;ANAC										
657875	642-9857-505	EASA;FAA;CAAC;ANAC										
657875	642-9858-502	EASA;FAA;CAAC;ANAC										
657875	642-9869-501	EASA;FAA;CAAC;ANAC										
657875	642-9871-503	EASA;FAA;CAAC;ANAC										
657875	642-9877-503	EASA;FAA;CAAC;ANAC										
657875	642-9879-501	EASA;FAA;CAAC;ANAC										
657875	642-9887-501	EASA;FAA;CAAC;ANAC										
657875	642-9890-501	EASA;FAA;CAAC;ANAC										
657875	642-9894-501	EASA;FAA;CAAC;ANAC										
657875	642-9895-501	EASA;FAA;CAAC;ANAC										
657875	642-9899-503	EASA;FAA;CAAC;ANAC										
657875	642-9912-501	EASA;FAA;CAAC;ANAC										
657875	642-9915-501	EASA;FAA;CAAC;ANAC										
657875	642-9917-501	EASA;FAA;CAAC;ANAC										
657875	642-9919-501	EASA;FAA;CAAC;ANAC										
657875	642-9923-501	EASA;FAA;CAAC;ANAC										
657875	642-9926-501	EASA;FAA;CAAC;ANAC										
657875	642-9930-501	EASA;FAA;CAAC;ANAC										
657875	642-9934-501	EASA;FAA;CAAC;ANAC										
657875	642-9943-501	EASA;FAA;CAAC;ANAC										
657875	642-9944-501	EASA;FAA;CAAC;ANAC										
657875	642-9950-503	EASA;FAA;CAAC;ANAC										
657875	642-9971-501	EASA;FAA;CAAC;ANAC										
657875	9134M25P121	EASA;FAA;CAAC;ANAC										
657875	9134M25P125	EASA;FAA;CAAC;ANAC										
657876	1677M58G01	EASA;FAA;CAAC;ANAC	20	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - ENGINE AND E	Package A	CLN/INSP	CLEANING AND INSPECTION		265.00	SR Technics Switzerland
657876	1677M63G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-11	425.00	SR Technics Switzerland
657876	1716M29G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT ANTI SIPHON	SPM 70-42-XY	425.00	SR Technics Switzerland
657876	1817M10G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		425.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657876	1817M53G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		425.00	SR Technics Switzerland
657876	1867M49G01	EASA;FAA;CAAC;ANAC			72-09-04		Package C	001	REPLACEMENT OF ANGLE BRACKET TAB		165.00	SR Technics Switzerland
657876	1871M24G03	EASA;FAA;CAAC;ANAC			72-09-04		Package SB00	72-0344	INTRODUCTION OF A NEW PROTECTION STRIP ON THE BRACKET.		275.00	SR Technics Switzerland
657876	1871M34G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB02	73-0138	ENGINE FUEL AND CONTROL - REWORK OF PARKING BSV BRACKET		275.00	SR Technics Switzerland
657876	1871M48G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB04	RA32036-10	NACELLE - PNEUMATIC - UPPER 9TH STAGE HIGH PRESSURE (HP) DUCT SUPPORT LINK REMOVAL		275.00	SR Technics Switzerland
657876	1871M48G03	EASA;FAA;CAAC;ANAC			72-09-04		Package SB05	72-0341	MODIFICATION OF THE BRACKET INSTALLED ON HPTCC AIR TUBE FLANGE		275.00	SR Technics Switzerland
657876	1871M75G03	EASA;FAA;CAAC;ANAC			72-09-04		Package SB06	RA32071-152	FAN CASE B1 FLANGE REPLURE-TORQUE BOLTS		275.00	SR Technics Switzerland
657876	1892M37G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB07	RA32036-13	INSP OF THE UPPER HIGH PRES. DUCT		275.00	SR Technics Switzerland
657876	1892M63P01	EASA;FAA;CAAC;ANAC			72-09-04		Package V	SPM 70-43-01	SHOCK-MOUNT REPLACE ELASTOMER		130.00	SR Technics Switzerland
657876	1894M15G01	EASA;FAA;CAAC;ANAC										
657876	1894M95G01	EASA;FAA;CAAC;ANAC										
657876	1894M98G01	EASA;FAA;CAAC;ANAC										
657876	1895M16G01	EASA;FAA;CAAC;ANAC										
657876	1895M91G01	EASA;FAA;CAAC;ANAC										
657876	1898M98G01	EASA;FAA;CAAC;ANAC										
657876	1958M60G01	EASA;FAA;CAAC;ANAC										
657876	1970M78G01	EASA;FAA;CAAC;ANAC										
657876	1970M90G01	EASA;FAA;CAAC;ANAC										
657876	1971M25G01	EASA;FAA;CAAC;ANAC										
657876	2174M34G01	EASA;FAA;CAAC;ANAC										
657876	2174M40G01	EASA;FAA;CAAC;ANAC										
657876	2175M34G01	EASA;FAA;CAAC;ANAC										
657876	2283M34G01	EASA;FAA;CAAC;ANAC										
657876	238-0513-505	EASA;FAA;CAAC;ANAC										
657876	238-0553-501	EASA;FAA;CAAC;ANAC										
657876	238-0554-501	EASA;FAA;CAAC;ANAC										
657876	238-0556-501	EASA;FAA;CAAC;ANAC										
657876	238-0856-121	EASA;FAA;CAAC;ANAC										
657876	238-0856-127	EASA;FAA;CAAC;ANAC										
657876	238-0856-131	EASA;FAA;CAAC;ANAC										
657876	238-0856-135	EASA;FAA;CAAC;ANAC										
657876	238-0856-143	EASA;FAA;CAAC;ANAC										
657876	238-0856-147	EASA;FAA;CAAC;ANAC										
657876	238-0856-151	EASA;FAA;CAAC;ANAC										
657876	238-0856-173	EASA;FAA;CAAC;ANAC										
657876	238-0856-179	EASA;FAA;CAAC;ANAC										
657876	321-455-302-0	EASA;FAA;CAAC;ANAC										
657876	321-455-654-0	EASA;FAA;CAAC;ANAC										
657876	336-084-701-0	EASA;FAA;CAAC;ANAC										
657876	336-084-751-0	EASA;FAA;CAAC;ANAC										
657876	336-091-201-0	EASA;FAA;CAAC;ANAC										
657876	336-469-605-0	EASA;FAA;CAAC;ANAC										
657876	336-477-901-0	EASA;FAA;CAAC;ANAC										
657876	336-495-706-0	EASA;FAA;CAAC;ANAC										
657876	338-011-002-0	EASA;FAA;CAAC;ANAC										
657876	338-011-101-0	EASA;FAA;CAAC;ANAC										
657876	338-012-601-0	EASA;FAA;CAAC;ANAC										
657876	338-012-602-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657876	338-012-701-0	EASA;FAA;CAAC;ANAC										
657876	338-012-702-0	EASA;FAA;CAAC;ANAC										
657876	338-012-902-0	EASA;FAA;CAAC;ANAC										
657876	338-013-302-0	EASA;FAA;CAAC;ANAC										
657876	338-013-402-0	EASA;FAA;CAAC;ANAC										
657876	338-013-901-0	EASA;FAA;CAAC;ANAC										
657876	338-014-104-0	EASA;FAA;CAAC;ANAC										
657876	338-014-106-0	EASA;FAA;CAAC;ANAC										
657876	338-014-203-0	EASA;FAA;CAAC;ANAC										
657876	338-015-202-0	EASA;FAA;CAAC;ANAC										
657876	338-016-403-0	EASA;FAA;CAAC;ANAC										
657876	338-016-902-0	EASA;FAA;CAAC;ANAC										
657876	338-021-604-0	EASA;FAA;CAAC;ANAC										
657876	338-021-605-0	EASA;FAA;CAAC;ANAC										
657876	338-027-402-0	EASA;FAA;CAAC;ANAC										
657876	338-032-002-0	EASA;FAA;ANAC										
657876	338-032-702-0	EASA;FAA;CAAC;ANAC										
657876	338-033-104-0	EASA;FAA;CAAC;ANAC										
657876	338-033-602-0	EASA;FAA;CAAC;ANAC										
657876	338-037-003-0	EASA;FAA;CAAC;ANAC										
657876	338-039-802-0	EASA;FAA;CAAC;ANAC										
657876	338-040-003-0	EASA;FAA;CAAC;ANAC										
657876	338-041-402-0	EASA;FAA;ANAC										
657876	338-042-202-0	EASA;FAA;CAAC;ANAC										
657876	338-042-802-0	EASA;FAA;CAAC;ANAC										
657876	338-053-204-0	EASA;FAA;CAAC;ANAC										
657876	338-054-001-0	EASA;FAA;CAAC;ANAC										
657876	338-054-303-0	EASA;FAA;CAAC;ANAC										
657876	338-056-701-0	EASA;FAA;CAAC;ANAC										
657876	338-058-401-0	EASA;FAA;CAAC;ANAC										
657876	338-058-601-0	EASA;FAA;CAAC;ANAC										
657876	338-059-402-0	EASA;FAA;CAAC;ANAC										
657876	338-059-403-0	EASA;FAA;CAAC;ANAC										
657876	338-122-903-0	EASA;FAA;CAAC;ANAC										
657876	338-125-503-0	EASA;FAA;CAAC;ANAC										
657876	338-125-603-0	EASA;FAA;CAAC;ANAC										
657876	340-006-704-0	EASA;FAA;CAAC;ANAC										
657876	340-006-804-0	EASA;FAA;CAAC;ANAC										
657876	340-007-303-0	EASA;FAA;CAAC;ANAC										
657876	340-013-004-0	EASA;FAA;CAAC;ANAC										
657876	340-017-201-0	EASA;FAA;CAAC;ANAC										
657876	340-019-802-0	EASA;FAA;CAAC;ANAC										
657876	340-020-205-0	EASA;FAA;CAAC;ANAC										
657876	340-025-405-0	EASA;FAA;CAAC;ANAC										
657876	340-075-203-0	EASA;FAA;CAAC;ANAC										
657876	340-075-303-0	EASA;FAA;CAAC;ANAC										
657876	340-086-102-0	EASA;FAA;ANAC										
657876	340-086-103-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
657876	340-087-904-0	EASA;FAA;CAAC;ANAC										
657876	340-087-905-0	EASA;FAA;CAAC;ANAC										
657876	340-088-903-0	EASA;FAA;CAAC;ANAC										
657876	340-090-304-0	EASA;FAA;CAAC;ANAC										
657876	340-095-705-0	EASA;FAA;CAAC;ANAC										
657876	340-105-609-0	EASA;FAA;CAAC;ANAC										
657876	340-106-402-0	EASA;FAA;CAAC;ANAC										
657876	340-118-101-0	EASA;FAA;CAAC;ANAC										
657876	340-119-803-0	EASA;FAA;CAAC;ANAC										
657876	340-120-602-0	EASA;FAA;CAAC;ANAC										
657876	340-120-902-0	EASA;FAA;CAAC;ANAC										
657876	340-121-202-0	EASA;FAA;CAAC;ANAC										
657876	340-140-102-0	EASA;FAA;CAAC;ANAC										
657876	340-140-902-0	EASA;FAA;CAAC;ANAC										
657876	340-159-501-0	EASA;FAA;CAAC;ANAC										
657876	642-3031-503	EASA;FAA;CAAC;ANAC										
657876	642-9827-501	EASA;FAA;CAAC;ANAC										
657876	642-9829-502	EASA;FAA;CAAC;ANAC										
657876	642-9829-503	EASA;FAA;CAAC;ANAC										
657876	642-9866-503	EASA;FAA;CAAC;ANAC										
657876	642-9867-505	EASA;FAA;CAAC;ANAC										
657876	642-9876-503	EASA;FAA;CAAC;ANAC										
657876	649-400-055-0	EASA;FAA;CAAC;ANAC										
657876	649-400-056-0	EASA;FAA;CAAC;ANAC										
657876	AMBK4-4014	EASA;FAA;CAAC;ANAC										
657876	P40560	EASA;FAA;CAAC;ANAC										
657876	P40570	EASA;FAA;CAAC;ANAC										
663441	30377-300	EASA;FAA;ANAC	13	28	72-00-00	ENGINE GENERAL - COMMON PARTS - MISCELLANEOUS CLAIM	Package A	CLN/INSP	CLEANING AND INSPECTION		220.00	SR Technics Switzerland
663441	30377-500	EASA;FAA;ANAC										
663441	30377-600	EASA;FAA;ANAC										
663441	30398-200	EASA;FAA;ANAC										
663441	30398-400	EASA;FAA;ANAC										
663441	30550-400	EASA;FAA;ANAC										
663441	30659-200	EASA;FAA;ANAC										
663441	30659-400	EASA;FAA;ANAC										
663441	30679-450	EASA;FAA;ANAC										
663441	30679-500	EASA;FAA;ANAC										
663441	30679-600	EASA;FAA;ANAC										
663441	30759-200	EASA;FAA;ANAC										
663441	30766-400	EASA;FAA;ANAC										
663441	31046-150	EASA;FAA;ANAC										
663441	31073-150	EASA;FAA;ANAC										
663441	34H40-600	EASA;FAA;ANAC										
663441	50U366	EASA;FAA;ANAC										
663441	50U367	EASA;FAA;ANAC										
663441	50U368	EASA;FAA;ANAC										
663441	50U370	EASA;FAA;ANAC										
663441	50U372	EASA;FAA;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
663441	50U373	EASA;FAA;ANAC										
663441	50U374	EASA;FAA;ANAC										
663441	51U749	EASA;FAA;ANAC										
663441	51U888	EASA;FAA;ANAC										
663441	58T561	EASA;FAA;ANAC										
663441	57T938	EASA;FAA;CAAC;ANAC										
663441	58T054	EASA;FAA;ANAC										
663441	58T886	EASA;FAA;ANAC										
663441	59T331	EASA;FAA;ANAC										
663441	728879-2	EASA;FAA;ANAC										
663891	J905P08A	EASA;FAA;CAAC;ANAC	3	0	72-09-04	BOLT INSPECTION CFM56 ENGINE	Package A	CLN/INSP	CLEANING & INSPECTION		140.00	SR Technics Switzerland
663891	J905P10A	EASA;FAA;CAAC;ANAC										
664002	1895M53P01	EASA;FAA;CAAC;ANAC	5	21	72-XX_XX	CFM56 TL FOR MISCELLANEOUS CFM PARTS	Package A	CLN/INSP	CLEANING & INSPECTION		65.00	SR Technics Switzerland
664002	338-007-401-0	EASA;FAA;ANAC										
664002	338-025-303-0	EASA;FAA;CAAC;ANAC										
664002	340-094-606-0	EASA;FAA;CAAC;ANAC										
664002	340-094-607-0	EASA;FAA;CAAC;ANAC										
664002	340-094-608-0	EASA;FAA;CAAC;ANAC										
664002	340-094-609-0	EASA;FAA;CAAC;ANAC										
664002	340-094-610-0	EASA;FAA;CAAC;ANAC										
664002	340-146-701-0	EASA;FAA;CAAC;ANAC										
664002	9993M72P01	EASA;FAA;CAAC;ANAC										
665444	336-056-201-0	EASA;FAA;ANAC	4	28	72-21-00	BALANCE WEIGHT	Package A	CLN	CLEANING & INSPECTION		70.00	SR Technics Switzerland
665444	336-056-202-0	EASA;FAA;ANAC										
665444	336-056-203-0	EASA;FAA;ANAC										
665444	336-056-204-0	EASA;FAA;ANAC										
667723	1834M53P01	EASA;FAA;CAAC;ANAC	10	28	72-31-20	CFM56 HPC HARDWARE BALANCE WEIGTHS	Package A	CLN/INSP	CLEANING AND INSPECTION		70.00	SR Technics Switzerland
667723	1834M53P02	EASA;FAA;CAAC;ANAC										
667723	1834M54P01	EASA;FAA;CAAC;ANAC										
667723	1993M73P01	EASA;FAA;CAAC;ANAC										
667723	1993M73P02	EASA;FAA;CAAC;ANAC										
667723	1993M74P01	EASA;FAA;CAAC;ANAC										
667723	1993M74P02	EASA;FAA;CAAC;ANAC										
671086	336-482-301-0	EASA;FAA;CAAC;ANAC	7	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		150.00	SR Technics Switzerland
671086	336-522-703-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPAIR BRACKETS AS REQUIRED		200.00	SR Technics Switzerland
671086	337-154-601-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE HELICOIL INSERT	SPM 70-42-14	200.00	SR Technics Switzerland
671086	338-013-101-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERTS AND NUTS	SPM 70-42-XX	200.00	SR Technics Switzerland
671086	338-016-002-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		200.00	SR Technics Switzerland
671086	338-016-201-0	EASA;FAA;CAAC;ANAC			72-09-04		Package C	01	REPLACE TAB (FOR 321 STEEL)		85.00	SR Technics Switzerland
671086	338-016-603-0	EASA;FAA;CAAC;ANAC			72-09-04		Package D	SPM	SHOCK-MOUNT REPLACE ELASTOMER		145.00	SR Technics Switzerland
671086	338-021-303-0	EASA;FAA;CAAC;ANAC										
671086	338-022-301-0	EASA;FAA;ANAC										
671086	338-027-302-0	EASA;FAA;CAAC;ANAC										
671086	338-028-301-0	EASA;FAA;CAAC;ANAC										
671086	338-028-601-0	EASA;FAA;CAAC;ANAC										
671086	338-029-702-0	EASA;FAA;CAAC;ANAC										
671086	338-030-803-0	EASA;FAA;CAAC;ANAC										
671086	338-031-003-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671086	338-031-702-0	EASA;FAA;CAAC;ANAC										
671086	338-032-502-0	EASA;FAA;ANAC										
671086	338-032-803-0	EASA;FAA;CAAC;ANAC										
671086	338-033-903-0	EASA;FAA;CAAC;ANAC										
671086	338-034-102-0	EASA;FAA;CAAC;ANAC										
671086	338-034-302-0	EASA;FAA;CAAC;ANAC										
671086	338-034-403-0	EASA;FAA;ANAC										
671086	338-034-703-0	EASA;FAA;ANAC										
671086	338-035-701-0	EASA;FAA;CAAC;ANAC										
671086	338-036-003-0	EASA;FAA;CAAC;ANAC										
671086	338-037-601-0	EASA;FAA;CAAC;ANAC										
671086	338-037-901-0	EASA;FAA;CAAC;ANAC										
671086	338-038-101-0	EASA;FAA;CAAC;ANAC										
671086	338-040-201-0	EASA;FAA;ANAC										
671086	338-041-201-0	EASA;FAA;CAAC;ANAC										
671086	338-041-602-0	EASA;FAA;CAAC;ANAC										
671086	338-041-802-0	EASA;FAA;CAAC;ANAC										
671086	338-042-001-0	EASA;FAA;CAAC;ANAC										
671086	338-042-401-0	EASA;FAA;ANAC										
671086	338-042-602-0	EASA;FAA;CAAC;ANAC										
671086	338-043-201-0	EASA;FAA;CAAC;ANAC										
671086	338-043-202-0	EASA;FAA;CAAC;ANAC										
671086	338-043-401-0	EASA;FAA;CAAC;ANAC										
671086	338-043-601-0	EASA;FAA;CAAC;ANAC										
671086	338-043-801-0	EASA;FAA;ANAC										
671086	338-044-001-0	EASA;FAA;CAAC;ANAC										
671086	338-046-401-0	EASA;FAA;ANAC										
671086	338-050-301-0	EASA;FAA;CAAC;ANAC										
671086	338-057-301-0	EASA;FAA;CAAC;ANAC										
671086	338-059-501-0	EASA;FAA;CAAC;ANAC										
671086	338-059-601-0	EASA;FAA;CAAC;ANAC										
671086	338-088-701-0	EASA;FAA;ANAC										
671086	338-130-102-0	EASA;FAA;CAAC;ANAC										
671086	340-019-002-0	EASA;FAA;CAAC;ANAC										
671086	340-143-701-0	EASA;FAA;CAAC;ANAC										
671086	VTF02460	EASA;FAA;CAAC;ANAC										
671089	1348M59P01	EASA;FAA;CAAC;ANAC	4	28	72-09-04	CFM56 ENGINE HARDWARE	Package A	CLN/INSP	CLEANING & INSPECTION		250.00	SR Technics Switzerland
671089	1467M96G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	01	REPLACE TAB (FOR 321 STEEL)		75.00	SR Technics Switzerland
671089	1527M36G01	EASA;FAA;CAAC;ANAC			72-09-04		Package C	INSP-001	REPLACE INSERT SPM	70-42-XX	195.00	SR Technics Switzerland
671089	1870M22G01	EASA;FAA;CAAC;ANAC			72-09-04		Package D	INSP-001	REPLACE RIVETED PARTS		170.00	SR Technics Switzerland
671089	1892M84G01	EASA;FAA;CAAC;ANAC			72-09-04		Package E	INSP-001	WELDING HINGED BRACKETS		250.00	SR Technics Switzerland
671089	1892M98G01	EASA;FAA;CAAC;ANAC			72-09-04		Package F	INSP-001	REPLACE INSERT ANTI SIPHON	SPM 70-42-11	185.00	SR Technics Switzerland
671089	1894M28G01	EASA;FAA;CAAC;ANAC			72-09-04		Package G	INSP-001	REPLACE HELICOIL INSERT	SPM 70-42-14	75.00	SR Technics Switzerland
671089	1894M80G01	EASA;FAA;CAAC;ANAC			72-09-04		Package L	011	REPLACE KEY LOCKED INSERT		100.00	SR Technics Switzerland
671089	1895M89G01	EASA;FAA;CAAC;ANAC			72-09-04		Package M	051	BRACKET PIN REPLACE		155.00	SR Technics Switzerland
671089	1896M53G01	EASA;FAA;CAAC;ANAC			72-09-04		Package N	REPAIR	SPM SHOCK-MOUNT REPLACE ELASTOMER		85.00	SR Technics Switzerland
671089	1898M66G01	EASA;FAA;CAAC;ANAC			72-09-04		Package SB00	SB 75-0044	INTRO OF A NEW INLET AIRSCOOP ASSY AND REWORK OF THE OLD ONE		615.00	SR Technics Switzerland
671089	1958M12G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671089	1958M64G01	EASA;FAA;CAAC;ANAC										
671089	1970M27G01	EASA;FAA;CAAC;ANAC										
671089	2046M34G01	EASA;FAA;CAAC;ANAC										
671089	2174M25G01	EASA;FAA;ANAC										
671089	2174M35G01	EASA;FAA;CAAC;ANAC										
671089	2174M37G01	EASA;FAA;CAAC;ANAC										
671089	2174M38G01	EASA;FAA;ANAC										
671089	2174M44G01	EASA;FAA;CAAC;ANAC										
671089	2174M49G01	EASA;FAA;CAAC;ANAC										
671089	2175M13G01	EASA;FAA;CAAC;ANAC										
671089	238-0505-503	EASA;FAA;CAAC;ANAC										
671089	238-0607-503	EASA;FAA;CAAC;ANAC										
671089	238-0608-503	EASA;FAA;CAAC;ANAC										
671089	238-0610-511	EASA;FAA;CAAC;ANAC										
671089	24765-01	EASA;FAA;CAAC;ANAC										
671089	321-450-701-6	EASA;FAA;CAAC;ANAC										
671089	321-450-802-0	EASA;FAA;CAAC;ANAC										
671089	321-451-100-0	EASA;FAA;CAAC;ANAC										
671089	321-451-452-0	EASA;FAA;CAAC;ANAC										
671089	332A2910-101	EASA;FAA;CAAC;ANAC										
671089	332A2910-106	EASA;FAA;CAAC;ANAC										
671089	332A2910-111	EASA;FAA;CAAC;ANAC										
671089	332A2910-113	EASA;FAA;CAAC;ANAC										
671089	332A2910-130	EASA;FAA;CAAC;ANAC										
671089	332A2910-132	EASA;FAA;CAAC;ANAC										
671089	332A2910-134	EASA;FAA;CAAC;ANAC										
671089	332A2910-136	EASA;FAA;CAAC;ANAC										
671089	332A2910-143	EASA;FAA;CAAC;ANAC										
671089	332A2910-147	EASA;FAA;ANAC										
671089	332A2910-149	EASA;FAA;ANAC										
671089	332A2910-24	EASA;FAA;CAAC;ANAC										
671089	332A2910-41	EASA;FAA;CAAC;ANAC										
671089	332A2910-74	EASA;FAA;CAAC;ANAC										
671089	332A2911-9	EASA;FAA;CAAC;ANAC										
671089	332A2920-157	EASA;FAA;CAAC;ANAC										
671089	332A2920-185	EASA;FAA;CAAC;ANAC										
671089	332A2920-187	EASA;FAA;ANAC										
671089	332A2920-193	EASA;FAA;ANAC										
671089	332A2920-197	EASA;FAA;CAAC;ANAC										
671089	332A2920-199	EASA;FAA;CAAC;ANAC										
671089	332A2920-224	EASA;FAA;CAAC;ANAC										
671089	332A2920-225	EASA;FAA;ANAC										
671089	332A2920-229	EASA;FAA;CAAC;ANAC										
671089	332A2920-230	EASA;FAA;CAAC;ANAC										
671089	332A2920-236	EASA;FAA;ANAC										
671089	332A2920-245	EASA;FAA;CAAC;ANAC										
671089	332A2920-55	EASA;FAA;CAAC;ANAC										
671089	332A2921-1	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671089	332A2930-104	EASA;FAA;CAAC;ANAC										
671089	332A2930-11	EASA;FAA;CAAC;ANAC										
671089	332A2930-50	EASA;FAA;ANAC										
671089	332A2930-83	EASA;FAA;CAAC;ANAC										
671089	332A2930-88	EASA;FAA;ANAC										
671089	332A2930-90	EASA;FAA;CAAC;ANAC										
671089	336-512-905-0	EASA;FAA;CAAC;ANAC										
671089	336-512-906-0	EASA;FAA;CAAC;ANAC										
671089	338-018-302-0	EASA;FAA;CAAC;ANAC										
671089	338-021-402-0	EASA;FAA;CAAC;ANAC										
671089	338-023-003-0	EASA;FAA;CAAC;ANAC										
671089	338-024-802-0	EASA;FAA;CAAC;ANAC										
671089	338-027-501-0	EASA;FAA;CAAC;ANAC										
671089	338-027-502-0	EASA;FAA;CAAC;ANAC										
671089	338-028-704-0	EASA;FAA;CAAC;ANAC										
671089	338-038-604-0	EASA;FAA;CAAC;ANAC										
671089	338-046-101-0	EASA;FAA;CAAC;ANAC										
671089	338-055-401-0	EASA;FAA;CAAC;ANAC										
671089	338-163-505-0	EASA;FAA;CAAC;ANAC										
671089	340-017-402-0	EASA;FAA;CAAC;ANAC										
671089	340-097-304-0	EASA;FAA;CAAC;ANAC										
671089	340-097-802-0	EASA;FAA;CAAC;ANAC										
671089	340-114-301-0	EASA;FAA;CAAC;ANAC										
671089	340-140-503-0	EASA;FAA;CAAC;ANAC										
671089	642-3031-501	EASA;FAA;CAAC;ANAC										
671089	642-5651-501	EASA;FAA;CAAC;ANAC										
671089	642-5656-501	EASA;FAA;CAAC;ANAC										
671089	642-5675-501	EASA;FAA;CAAC;ANAC										
671089	642-5677-501	EASA;FAA;CAAC;ANAC										
671089	642-5681-501	EASA;FAA;CAAC;ANAC										
671089	642-5681-503	EASA;FAA;CAAC;ANAC										
671089	642-5715-507	EASA;FAA;CAAC;ANAC										
671089	642-5752-501	EASA;FAA;CAAC;ANAC										
671089	642-5753-501	EASA;FAA;CAAC;ANAC										
671089	642-5927-502	EASA;FAA;CAAC;ANAC										
671089	642-9826-501	EASA;FAA;CAAC;ANAC										
671089	642-9828-503	EASA;FAA;CAAC;ANAC										
671089	642-9829-501	EASA;FAA;CAAC;ANAC										
671089	642-9833-501	EASA;FAA;CAAC;ANAC										
671089	642-9837-501	EASA;FAA;CAAC;ANAC										
671089	642-9843-501	EASA;FAA;CAAC;ANAC										
671089	642-9845-501	EASA;FAA;CAAC;ANAC										
671089	642-9850-501	EASA;FAA;CAAC;ANAC										
671089	642-9863-501	EASA;FAA;CAAC;ANAC										
671089	642-9870-503	EASA;FAA;CAAC;ANAC										
671089	642-9889-501	EASA;FAA;CAAC;ANAC										
671089	642-9893-501	EASA;FAA;CAAC;ANAC										
671089	642-9913-501	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
671089	642-9916-501	EASA;FAA;CAAC;ANAC										
671089	642-9918-501	EASA;FAA;CAAC;ANAC										
671089	642-9922-501	EASA;FAA;CAAC;ANAC										
671089	642-9951-503	EASA;FAA;CAAC;ANAC										
671095	301-534-311-0	EASA;FAA;CAAC;ANAC	7	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		105.00	SR Technics Switzerland
671095	336-480-401-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE HELICOIL INSERT	SPM 70-42-14	80.00	SR Technics Switzerland
671095	336-486-001-0	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-XX	80.00	SR Technics Switzerland
671095	337-138-303-0	EASA;FAA;CAAC;ANAC			72-09-04		Package C	INSP-001	REPLACE RIVETED PARTS		80.00	SR Technics Switzerland
671095	338-015-302-0	EASA;FAA;CAAC;ANAC			72-09-04		Package D	SPM	SHOCK-MOUNT REPLACE ELASTOMER		80.00	SR Technics Switzerland
671095	338-027-201-0	EASA;FAA;ANAC										
671095	338-028-001-0	EASA;FAA;CAAC;ANAC										
671095	338-030-504-0	EASA;FAA;CAAC;ANAC										
671095	338-033-504-0	EASA;FAA;CAAC;ANAC										
671095	338-035-201-0	EASA;FAA;ANAC										
671095	338-040-801-0	EASA;FAA;ANAC										
671095	338-041-002-0	EASA;FAA;CAAC;ANAC										
671095	338-045-401-0	EASA;FAA;CAAC;ANAC										
671095	338-045-601-0	EASA;FAA;ANAC										
671095	338-050-801-0	EASA;FAA;CAAC;ANAC										
671095	338-057-401-0	EASA;FAA;CAAC;ANAC										
671095	340-002-202-0	EASA;FAA;CAAC;ANAC										
671095	340-116-001-0	EASA;FAA;CAAC;ANAC										
671095	340-131-301-0	EASA;FAA;CAAC;ANAC										
671095	340-132-201-0	EASA;FAA;CAAC;ANAC										
671095	340-143-501-0	EASA;FAA;CAAC;ANAC										
671095	340-143-702-0	EASA;FAA;ANAC										
671095	642-5828-501	EASA;FAA;CAAC;ANAC										
671175	340-031-802-0	EASA;FAA;CAAC;ANAC	7	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING AND INSPECTION		65.00	SR Technics Switzerland
671175	340-088-701-0	EASA;FAA;CAAC;ANAC										
672453	1870M26P01	EASA;FAA;CAAC;ANAC	4	21	72-09-04	CFM56 ENGINE HARDWARE INSPECTION MOD.82	Package A	CLN/INSP	CLEANING & INSPECTION		100.00	SR Technics Switzerland
672453	1898M50G01	EASA;FAA;CAAC;ANAC										
672453	340-078-202-0	EASA;FAA;ANAC										
672453	649-791-260-0	EASA;FAA;CAAC;ANAC										
672775	1348M88G05	EASA;FAA;CAAC;ANAC	10	28	72-41-04	CFM56 MANIFOLD-FUEL SUPPLY/DRAIN	Package A	CLN/INSP	CLEANING AND INSPECTION		540.00	SR Technics Switzerland
672775	1348M88G07	EASA;FAA;CAAC;ANAC			72-41-04		Package B	INSP-001	BLENDING DRAIN TUBE		970.00	SR Technics Switzerland
672775	1348M88G08	EASA;FAA;CAAC;ANAC			72-41-04		Package B	INSP-001	BLENDING SUPPLY TUB		970.00	SR Technics Switzerland
672775	1444M50G11	EASA;FAA;CAAC;ANAC			72-41-04		Package B	INSP-001	PRESSURE TEST DRAIN		970.00	SR Technics Switzerland
672775	1444M50G13	EASA;FAA;CAAC;ANAC			72-41-04		Package B	INSP-001	PRESSURE TEST SUPPLY		970.00	SR Technics Switzerland
672775	1444M51G17	EASA;FAA;CAAC;ANAC			72-41-04		Package D	002	TUBE FITTING NUT		475.00	SR Technics Switzerland
672775	1444M51G18	EASA;FAA;CAAC;ANAC			72-41-04		Package E		REPLACE DEFECTIVE FUEL NOZZLE SHROUD		350.00	SR Technics Switzerland
672775	1605M65G01	EASA;FAA;CAAC;ANAC			72-41-04		Package SB00	73-0044	DELETION AT THE FUEL NOZZLE DRAIN SHROUDS		870.00	SR Technics Switzerland
672775	1621M82G01	EASA;FAA;CAAC;ANAC			72-41-04		Package SB01	73-0052	FIELD REWORK OF SAC INNER AND OUTER FUEL MAIFOLDS		3375.00	SR Technics Switzerland
672775	1813M58G02	EASA;FAA;CAAC;ANAC										
672775	1867M63G01	EASA;FAA;CAAC;ANAC										
672775	1867M64G01	EASA;FAA;CAAC;ANAC										
672775	1867M68G01	EASA;FAA;CAAC;ANAC										
672775	1870M11G01	EASA;FAA;CAAC;ANAC										
672775	1871M74G01	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672775	1882M60G03	EASA;FAA;CAAC;ANAC										
672775	1882M60G04	EASA;FAA;CAAC;ANAC										
672775	1882M61G03	EASA;FAA;CAAC;ANAC										
672775	1882M61G04	EASA;FAA;CAAC;ANAC										
672775	1882M62G03	EASA;FAA;CAAC;ANAC										
672775	1882M62G04	EASA;FAA;CAAC;ANAC										
672775	1882M63G03	EASA;FAA;CAAC;ANAC										
672775	1882M63G04	EASA;FAA;CAAC;ANAC										
672775	1892M95G01	EASA;FAA;CAAC;ANAC										
672775	1895M12G01	EASA;FAA;CAAC;ANAC										
672775	1895M12G02	EASA;FAA;CAAC;ANAC										
672775	1895M19G01	EASA;FAA;CAAC;ANAC										
672775	1895M44G01	EASA;FAA;CAAC;ANAC										
672775	1895M45G01	EASA;FAA;CAAC;ANAC										
672775	1895M80G06	EASA;FAA;CAAC;ANAC										
672775	1895M80G08	EASA;FAA;CAAC;ANAC										
672775	1895M81G06	EASA;FAA;CAAC;ANAC										
672775	1895M81G11	EASA;FAA;CAAC;ANAC										
672775	1895M82G06	EASA;FAA;CAAC;ANAC										
672775	1895M82G08	EASA;FAA;CAAC;ANAC										
672775	1895M83G06	EASA;FAA;CAAC;ANAC										
672775	1895M83G13	EASA;FAA;CAAC;ANAC										
672775	1895M83G14	EASA;FAA;CAAC;ANAC										
672775	1958M81G01	EASA;FAA;CAAC;ANAC										
672775	1958M82G01	EASA;FAA;CAAC;ANAC										
672775	1958M86G01	EASA;FAA;CAAC;ANAC										
672775	1971M10G01	EASA;FAA;CAAC;ANAC										
672775	1971M17G01	EASA;FAA;CAAC;ANAC										
672775	1971M18G01	EASA;FAA;CAAC;ANAC										
672775	1971M63G01	EASA;FAA;CAAC;ANAC										
672775	1971M63G02	EASA;FAA;CAAC;ANAC										
672775	1971M95G01	EASA;FAA;CAAC;ANAC										
672775	1971M96G01	EASA;FAA;CAAC;ANAC										
672775	2046M62G01	EASA;FAA;CAAC;ANAC										
672775	2046M63G01	EASA;FAA;CAAC;ANAC										
672775	2283M70G01	EASA;FAA;CAAC;ANAC										
672775	2283M73G01	EASA;FAA;CAAC;ANAC										
672775	9393M59G05	EASA;FAA;CAAC;ANAC										
672775	9393M60G07	EASA;FAA;CAAC;ANAC										
672775	9394M34G01	EASA;FAA;CAAC;ANAC										
672788	1443M74G02	EASA;FAA;CAAC;ANAC	3	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING & INSPECTION		150.00	SR Technics Switzerland
672788	1443M77G02	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPAIR BRACKETS AS REQUIRED		200.00	SR Technics Switzerland
672788	1645M33G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE HELICOIL INSERTS		200.00	SR Technics Switzerland
672788	1645M33G03	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERTS OR NUTS		200.00	SR Technics Switzerland
672788	1867M33G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	WELDING HINGED BRACKETS		200.00	SR Technics Switzerland
672788	1867M33G02	EASA;FAA;CAAC;ANAC			72-09-04		Package C	01	REPLACE TAB (FOR 321 STEEL)		85.00	SR Technics Switzerland
672788	1867M35G01	EASA;FAA;CAAC;ANAC			72-09-04		Package D	SPM	SHOCK-MOUNT REPLACE ELASTOMER		145.00	SR Technics Switzerland
672788	1867M35G02	EASA;FAA;CAAC;ANAC			72-09-04		Package SB00	73-0044	DELETION AT THE FUEL NOZZLE DRAIN SHROUD		150.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672788	1867M45G01	EASA;FAA;CAAC;ANAC										
672788	1867M62G01	EASA;FAA;CAAC;ANAC										
672788	1868M21G01	EASA;FAA;CAAC;ANAC										
672788	1868M22G01	EASA;FAA;CAAC;ANAC										
672788	1869M28G01	EASA;FAA;CAAC;ANAC										
672788	1869M29G01	EASA;FAA;CAAC;ANAC										
672788	1870M37G01	EASA;FAA;CAAC;ANAC										
672788	1871M23G01	EASA;FAA;CAAC;ANAC										
672788	1871M80G01	EASA;FAA;CAAC;ANAC										
672788	1892M72G01	EASA;FAA;CAAC;ANAC										
672788	1892M81G01	EASA;FAA;CAAC;ANAC										
672788	1892M85G01	EASA;FAA;CAAC;ANAC										
672788	1892M86G01	EASA;FAA;CAAC;ANAC										
672788	1892M94G01	EASA;FAA;CAAC;ANAC										
672788	1894M19G01	EASA;FAA;CAAC;ANAC										
672788	1894M50G01	EASA;FAA;CAAC;ANAC										
672788	1894M76G01	EASA;FAA;CAAC;ANAC										
672788	1895M20G01	EASA;FAA;CAAC;ANAC										
672788	1895M23G01	EASA;FAA;CAAC;ANAC										
672788	1895M36G01	EASA;FAA;CAAC;ANAC										
672788	1895M37G01	EASA;FAA;CAAC;ANAC										
672788	1896M66G01	EASA;FAA;CAAC;ANAC										
672788	1896M70G01	EASA;FAA;CAAC;ANAC										
672788	1898M61G01	EASA;FAA;CAAC;ANAC										
672788	1958M54G01	EASA;FAA;CAAC;ANAC										
672788	1969M24G01	EASA;FAA;CAAC;ANAC										
672788	2174M30G01	EASA;FAA;CAAC;ANAC										
672788	2174M36G01	EASA;FAA;CAAC;ANAC										
672788	2174M53G01	EASA;FAA;ANAC										
672788	2175M38G01	EASA;FAA;CAAC;ANAC										
672788	2175M84G01	EASA;FAA;CAAC;ANAC										
672788	336-044-801-0	EASA;FAA;CAAC;ANAC										
672788	338-039-002-0	EASA;FAA;CAAC;ANAC										
672788	338-057-803-0	EASA;FAA;CAAC;ANAC										
672788	340-180-401-0	EASA;FAA;CAAC;ANAC										
672788	340-180-601-0	EASA;FAA;CAAC;ANAC										
672793	1869M44G01	EASA;FAA;CAAC;ANAC	4	21	72-09-04	SPM 70-42-XX	Package A	CLN/INSP	CLEANING & INSPECTION		105.00	SR Technics Switzerland
672793	1898M82G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE HELOCOIL INSERT		80.00	SR Technics Switzerland
672793	1958M37G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE INSERT	SPM 70-42-XX	80.00	SR Technics Switzerland
672793	2046M76G01	EASA;FAA;CAAC;ANAC			72-09-04		Package B	INSP-001	REPLACE RIVETED PARTS		80.00	SR Technics Switzerland
672793	338-056-901-0	EASA;FAA;CAAC;ANAC			72-09-04		Package C	SPM	SHOCK-MOUNT REPLACE ELASTOMER		80.00	SR Technics Switzerland
672793	338-122-301-0	EASA;FAA;CAAC;ANAC										
672793	340-097-202-0	EASA;FAA;CAAC;ANAC										
672801	1871M51G01	EASA;FAA;CAAC;ANAC	6	21	72-09-04	CFM56 ENGINE BRACKETS	Package A	CLN/INSP	CLEANING & INSPECTION		70.00	SR Technics Switzerland
672801	1894M72P001A	EASA;FAA;CAAC;ANAC										
672807	337-114-052-0	EASA;FAA;CAAC;ANAC	6	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING & INSPECTION		335.00	SR Technics Switzerland
672807	338-012-303-0	EASA;FAA;CAAC;ANAC			72-09-03		Package G	REPAIR	REPAIR AND PRESSURE TEST		1205.00	SR Technics Switzerland
672807	649-430-111-0	EASA;FAA;CAAC;ANAC										

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
672818	338-082-101-0	EASA;FAA;CAAC;ANAC	7	21	72-23-18	PW4 TUBES (REPAIR MEDIUM)	Package A	00	CLEANING & INSPECTION		655.00	SR Technics Switzerland
672818	338-082-201-0	EASA;FAA;CAAC;ANAC			72-23-18		Package B	01	REPLACE SELF-LOCKING NUTS		325.00	SR Technics Switzerland
672818	340-026-402-0	EASA;FAA;CAAC;ANAC										
672818	340-030-601-0	EASA;FAA;CAAC;ANAC										
672818	340-032-102-0	EASA;FAA;CAAC;ANAC										
672818	340-034-402-0	EASA;FAA;CAAC;ANAC										
672819	1898M65G01	EASA;FAA;CAAC;ANAC	6	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING & INSPECTION		415.00	SR Technics Switzerland
672819	340-026-602-0	EASA;FAA;CAAC;ANAC			72-09-03		Package G	REPAIR	REPAIR & PRESSURE TEST		1010.00	SR Technics Switzerland
672819	340-034-202-0	EASA;FAA;CAAC;ANAC										
672820	337-036-917-0	EASA;FAA;CAAC;ANAC	7	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSE	Package A	CLN/INSP	CLEANING & INSPECTION		415.00	SR Technics Switzerland
672820	340-023-202-0	EASA;FAA;CAAC;ANAC			72-09-03		Package G	REPAIR	REPAIR & PRESSURE TEST		1010.00	SR Technics Switzerland
672820	649-430-021-0	EASA;FAA;CAAC;ANAC										
672820	649-432-111-0	EASA;FAA;CAAC;ANAC										
672820	649-434-051-0	EASA;FAA;CAAC;ANAC										
672822	340-026-502-0	EASA;FAA;CAAC;ANAC	7	21	72-09-03	CFM56 MANIFOLD/TUBE/HOSES	Package A	CLN/INSP	CLEANING & INSPECTION		305.00	SR Technics Switzerland
672822	340-200-002-0	EASA;FAA;CAAC;ANAC			72-09-03		Package G	REPAIR	REPAIR & PRESSURE TEST		640.00	SR Technics Switzerland
672822	J1238P04	EASA;FAA;CAAC;ANAC										
673122	238-0226-507	EASA;FAA;CAAC;ANAC	4	28	72-23-02	CFM56-5B FWD MOUNT SUPPORT ASSEMBLY	Package A	CLN/INSP	CLEANING & INSPECTION		145.00	SR Technics Switzerland
673122	238-0226-508	EASA;FAA;CAAC;ANAC										
673677	321-450-603-0	EASA;FAA;CAAC;ANAC	8	28	71-00-01	INNER FLANGE ASSY	Package A	CLN/INSP	PREREQUISIT INSPECTION AND REPAIR		655.00	SR Technics Switzerland
673677	321-456-602-0	EASA;FAA;CAAC;ANAC			71-00-01		Package B	SPM 70-43-11	REPLACE RIVETS		225.00	SR Technics Switzerland
673762			3	28	72-00-00	REPLACEMENT OF HELICOIL ON ENGINE/MODULE	Package B		REPLACE INSERTS ENGINE		300.00	SR Technics Switzerland
673762					72-00-00		Package C		REPLACE INSERTS MODULE		300.00	SR Technics Switzerland
673762					72-00-00		Package D		REPLACE INSERTS TEST CELL		330.00	SR Technics Switzerland
673762					72-00-00		Package E		REPLACE INSERTS QTL		300.00	SR Technics Switzerland
140213	LPT MAJOR MODUL		30	28	72-00-03	ENGINE MODULES/ASSEMBLIES - LPT MAJOR MODULE	Package A	CLN/INSP	CLEANING AND INSPECTION	-	410.00	SR Technics Switzerland
140213					72-00-03		Package AE	051	REPLACEMENT OF BROKEN STUDS OF T49.5 EGT SENSOR FIXATION	-	19855.00	SR Technics Switzerland
140213					72-00-03		Package B	001	REPLACEMENT/REWORK OF RIVETED PARTS	72-54-07	715.00	SR Technics Switzerland
140213					72-00-03		Package C	002	TEMPORARY REPLACEMENT OF BROKEN STUD ON T 49.5 EGT SENS	-	1225.00	SR Technics Switzerland
140213					72-00-03		Package D	INSP-001	LPT SHAFT BLEND AND PAINT REPAIR	-	495.00	SR Technics Switzerland
140213					72-00-03		Package F	001	STUD REPLACEMENT	72-00-03	1325.00	SR Technics Switzerland
140213					72-00-03		Package K	010	RECONDITIONING OF THE LPT SHAFT PAINT AT MAJOR MODULE 3	-	325.00	SR Technics Switzerland
140213					72-00-03		Package O	014	BLENDING ANTI-ROTATION-LUG	-	510.00	SR Technics Switzerland
140213					72-00-03		Package SB01	72-0521	INSPECTION OF NO.5 BEARING SUPPORT NIPPLE WELD	-	1050.00	SR Technics Switzerland
140213					72-00-03		Package SB02	72-0473	REPLACEMENT OF BROKEN STUD OF T49.5 EGT SENSOR BRACKET	-	1350.00	SR Technics Switzerland
140213					72-00-03		Package SB03	72-0570	INTRODUCTION OF THE NEW OR REWORKED LPT REAR FRAME WIT	-	310.00	SR Technics Switzerland
140213					72-00-03		Package SB04	72-0589	REIDENTIFICATION OF LPT CASE IN FIELD	-	240.00	SR Technics Switzerland
140213					72-00-03		Package SB05	EASA-2014-0130	TIME LIMITS INSPECTIONS	-	290.00	SR Technics Switzerland
9017	HPT ROTOR ASSY		23	28	72-52-00	HIGH PRESSURE TURBINE ROTOR - ASSEMBLY	Package B	ASSEMBLY	HIGH SPEED GRINDING BLADE RADIUS K AND MACHINE NOTCHES ON HPT BLADES TIP		3075.00	SR Technics Switzerland
9017					72-52-00		Package C	SPEC.PROC-002	PREGRINDING BLADE SET		4135.00	SR Technics Switzerland
9017					72-52-00		Package SB00	72-0171	HPC ROTOR, MOD FROM -5B/2 TO -5B/2P	HIGH SPEED GRINDING BLADE RADI	4135.00	SR Technics Switzerland
9017					72-52-00		Package SB01	72-0263	CONVERSION OF 5BN TO 5BN/P N =1,2,4,5,6	HIGH SPEED GRINDING BLADE RADI	4135.00	SR Technics Switzerland
139963	COMPRESSOR ROTOR ASS		23	28	72-31-00	COMPRESSOR ROTOR - ASSEMBLY	Package B	ASSEMBLY-001	HIGH SPEED GRINDING OF BLADE TIP		10240.00	SR Technics Switzerland
139963					72-31-00		Package SB00	72-0171	HPC ROTOR, MOD FROM -5B/2 TO -5B/2P	HIGH SPEED GRINDING OF BLADE T	10240.00	SR Technics Switzerland
139963					72-31-00		Package SB01	72-0263	CONVERSION OF 5BN TO 5BN/P N =1,2,4,5,6	HIGH SPEED GRINDING OF BLADE T	10240.00	SR Technics Switzerland
648803	SCREW-NUT-SPACER-SETB		10	21	72-09-04	GENERAL PROCEDURE - ENGINE HARDWARE - SCREWS, NUT	Package B	LIGHT	REFURBISHMENT OF REMOVED SET OF PARTS	3 OR LESS OF FOLLOW. ENG. MODL	3845.00	SR Technics Switzerland
648803					72-09-04		Package C	MEDIUM	REFURBISHMENT OF REMOVED SET OF PARTS	TOP CASE REPAIR OR NOT LIGHT C	19295.00	SR Technics Switzerland

Capabilities and Fixed Prices Catalogue 2025 for

CFM56-5B

Prices for labor only / General Conditions of Business for Parts
Repair (GCBPR) apply



valid until December 31, 2025

Quot. No.	MPN	Capability release label	Item	TAT	ATA	Part Description	Package	Rep. No.	Repair Description	Remark	Price per ea (USD)	Repair Facility
648803				72-09-04			Package D	HEAVY	REFURBISHMENT OF REMOVED SET OF PARTS	L FLANGE (MOD.23 TO MOD.32) COM	38270.00	SR Technics Switzerland