

NEW REPAIR CAPABILITY ANNOUNCEMENT

CFM56-7B: ATA 72-23-22, Repair 001- Spherical Bearing Replacement

“ADDING VALUE TO YOUR ASSETS”

Relevant for CFM56-7B Operators / Lessors / MRO Engine Shops / Parts traders & brokers

Background:

- Due to internal wear causing a slight internal displacement, spherical bearing needs to be replaced.
- With the latest revision of the CFM56-7B ESM, Safran introduced the replacement repair of the thrust mount spherical bearing, as Source Demonstration Repair 001 / Rep No. 15-94728
- Engine type applicability 7B & 7BE

Benefits:

This repair will provide the following benefits for the customer and SRT:

- **Unique MRO** issuing FAA certificate
- **Cost savings** through inhouse repair vs. replacement
- **TAT optimization** due to no external vendor & logistics costs
- **Competitive** Repair Pricing



DIMENSIONAL INSPECTION



BEARING REMOVED



NEW BEARING INSTALLED